

Surveyor: Ank DOI: 20/6/18 Date/Time: 20/6/18

Registered in Merimen: -

Pre-assign / CCU / FTE



Insured Vehicle No. : SJS 9506 E  
Name of Insured : JJM CAR SERVICES  
Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_  
Excess Sec II :SS \_\_\_\_\_ D.O.A : 19-6-18  
Is driver the owner? ( YES / NO ) Nature of Accident :

Claim No. : SNM18D03134/001/6  
Policy No. : DMTC5MT49871J00  
Make / Model : 7-AXIO  
Place of Accident : WOODVALE CONDO ENTRANCE

If NO, Driver Name / Age : \_\_\_\_\_ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO  
Driver Tel No. : \_\_\_\_\_ (VL: YES / NO) Insured Liability : % Final ? Yes / No

SJC 8664 X → → → →



INSRS:  
WSP: CD46/04045  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS:  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS:  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS:  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_

Date/Time	STAGE	DATE / PIC
	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
	Call OI: <u>20/07/18 - vic</u>	
	After call Itr to OI: <u>25/07/18 - vic</u>	
	<b>Documentation Check List:</b>	
	Notification Itr (if non-pickup)	<input type="checkbox"/>
	After call Itr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_

FINALIZATION Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: \_\_\_\_\_

Repair Cost: PIP \$S 1,777.40 ( 2 days) Reduction: 17 % Email  Call

FINAL SETTLEMENT Date/Time: 07/08/18 Confirm with: WILLIAM Email  Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : NIL If NO or B 28, Ass. Lia : OID REBUTED

Repair Cost: (w/acc) \$S 1,837.62

Loss of Rental (LOR): \$S 200.00 ( 2 days) X \$ 115.00

Loss of Use (LOU): \$S 100.00 (\$ 50 x 2 days)

Loss of Income (LOI): \$S - (\$ - x - days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search \$S 7.49

Medical: \$S -

Disbursement: \$S - (e.g. Tow/ Independent)

Legal Cost \$S -

Total: \$S 2,175.11 Global Sum \$S: 2,170.00

FINAL PAYMENT Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: \$S 2,170.00 Name 1: COMPUTERTECH ENGINEERING PTB LTD

Payee 2: (Strike if N.A.) \$S - Name 2: -

Payee 3: (Strike if N.A.) \$S - Name 3: -

COPY SENT

REF: Kalvin

REF:

ASSIGNMENT

Veh No: SHC 8664x Yr Regn: 7 Jan 2016

From: Date: Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: at Workshop m/s of Insured: Policy No. Claims No. Sum Insured: Excess: (Client's Record) Make of Veh:

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/O / Prime Mover / Truck / Trailer or Make: Hyundai I40 C.G. 168r Colour: Blue A/C: Insured / Std / NI / NA Sp. Reading: 290927 T/Radio: Insured / Std / NI / NA Eng/No: C/No: KMHLB414A44083092 Gen. Cond: Good / Fair / Poor / Burnt Steering: In order / Jammed / Leaked / Burnt or Brake: In order / Jammed / Leaked / Burnt or Modi: Nil / S/Rim / STD / Rim or Tyre Size: F: 205/60R16 R: 7

(Policy Condition) Remark: The veh had commenced its repair at the time of inspection.

Table with 2 columns: N/S, O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI / TOYO / YOKO or W/steake

Front R/Bal. 7 mm L/Bal. 7 mm D.O.A. 19/6/18 Rear R/Bal. 7 mm L/Bal. 7 mm D.O.I. 20/6/18

Survey held at CDHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or o/s R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: IDAC Accident Rpt: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No Est. Repairs: 2 days Res.: Yes or No Lum Sum: - % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT

Table with 2 columns: Date / Time, Action / Instruction

Date/Time, File Pass to? [ ] : Preli. Report [ ] : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation: \$ + RS. SI

Add Fee: [ ] : Site Insp (\$) [ ] : Interview (\$) [ ] : Tech. Invs (\$)

) Photos

) Others

Report Format :

Empty box for additional information or signature.

## Mei Kwan (LKKAuto)

---

**From:** Lucas Lee <lucas.lee@sg.cntaiping.com>  
**Sent:** Monday, 2 July, 2018 4:57 PM  
**To:** Mei Kwan (LKKAuto)  
**Subject:** RE: Direct Settlement - Accident Involving SJS9506E (OI : CTI - SNM18D03134C02) and SHC8664X (TP : LKK REF - CC3/CTI18011272/K1ha3) on 19/06/2018

**Categories:** HMK

Dear Mei Kwan,

Insured has not reported the case yet.

Lucas Lee  
Claims Department (Motor)  
**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Direct (65) 6389 6181  
Fax (65) 6222 7175/6224 7478  
Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]  
**Sent:** Monday, 2 July, 2018 4:14 PM  
**To:** Claims Dept of CTI  
**Cc:** Vic (LKKAuto); Hsiao Tong (LKKAuto); Admin A; Irene Tay; Lucas Lee  
**Subject:** RE: Direct Settlement - Accident Involving SJS9506E (OI : CTI - SNM18D03134C02) and SHC8664X (TP : LKK REF - CC3/CTI18011272/K1ha3) on 19/06/2018

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

This is a TP direct settlement case.

We had inspected TP vehicle SHC 8664X at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Vic and he can be contacted at DID: 6841 2096.

*To check availability of the case handler , you may contact the undersigned.*

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



中国太平  
CHINA TAIPING

中国太平保险(新加坡)有限公司  
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Tel: 6389 6111 Fax: 6222 1033  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)  
Co. Reg. No. 200208384E

Our Reference: **SNM18D03134/C01/6**

Date : **26 JUNE 2018**

via Ordinary & Registered Mail

**JJM CAR SERVICES  
15 WOODLANDS DRIVE 72  
#08-41 WOODSVALE  
SINGAPORE 738096**

Dear Sir / Madam

**ACCIDENT INVOLVING SJS9506E AND SHC8664X ON 19 JUNE 2018  
ALONG WOODSVALE CONDO ENTRANCE**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC8664X**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will soon contact you for more information about the accident. Kindly render your assistance and co-operation accordingly.

We understand that you or your driver has not filed an accident report within 24 hours as per Motor Claims Framework. We would urge you to comply with the condition to file your accident report with your vehicle (whether damaged or not) to us IMMEDIATELY through **LKK Auto Consultants Pte Ltd** or any of our **authorized workshops**. You may log onto our website [www.sg.cntaiping.com](http://www.sg.cntaiping.com) for location of the respective workshops.

We regret to advice that we and/or **LKK Auto Consultants Pte Ltd** will not be handling the third party claim and your NO CLAIM DISCOUNT will be penalized upon renewal of your policy if you fail to comply with the condition of reporting.

Yours truly,  
Claims Department

*(This is a computer generated letter and no signature is required.)*

CC : LKK Auto Consultants Pte Ltd  
Attn : VIC  
Ref : CC3/CT118011272/K1HA3  
Contact No : 68412096  
via Email : [VIC@LKKAUTO.COM](mailto:VIC@LKKAUTO.COM)

CC : Agent - (AN0571A) - M9 AUTOMOBILE PTE LTD

F02/LKKDSANR-2013



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/CTH18011272/K1ha3

03<sup>rd</sup> July 2018

**JJM CAR SERVICES**

15 WOODLANDS DRIVE 72  
#08-41 WOODSVALE  
SINGAPORE 738096

Dear Sir / Madam,

**ACCIDENT INVOLVING SJS 9506E AND SHC 8664X ON 19/06/2018 ALONG/ AT WOODSVALE CONDO ENTRANCE**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Our record shows that to date, you/your driver have not reported the accident to us. We would appreciate it if you could urgently file a report at any of **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** Authorized workshops/reporting centre. You may refer to your Certificate of Insurance for the list of the reporting centre.

Please note you had been notified via post from CHINA TAIPING INSURANCE SINGAPORE PTE LTD dated **26<sup>th</sup> Jun 2018**.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter (by **10<sup>th</sup> July 2018**).


Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Vic Alpeh Sanghilan  
Case Handler  
DID: 6841 2096  
FAX: 6741 4108  
Email : vicalpeh@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd  
(Motor Claims Dept)*



member of COMFORTDELGRO

Date/Time: 19.06.2018 16:50 Page : 1

nam: ARC Repair TP(CLS0)1 **JOB CARD** Sales Order: JC NO305177402

TOWER AS COMFORT TRANSPORTATION PTE LTD TOWER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P) QUANTITY CARD NO.	REGN NO. SHC8664X	MILEAGE
	MAKE HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 19.06.2018 13:20
	YR OF MANU. 07.01.2016	TARGET DATE
	CHASSIS CODE KMHLB41UMGU083092	COMPLETION DATE/TIME:

*CHINA*

JOB DESCRIPTION

Accident Date: 19.06.2018  
 NATURE: 3P 19.06.2018

/NO                      LABOR CODE                      DESCRIPTION

CHECKED & PASSED OUT BY: \_\_\_\_\_

\_\_\_\_\_  
 SERVICE ADVISOR

\_\_\_\_\_  
 CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: SHC8664X                      LKE

Vehicle No.: SHC8664X

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

VEHICLE NO : SHC 8664X  
 MAKE :  
 MODEL : HYUNDAI i40

DATE 19/6/2018 16:08

*KK/kalvin - Pby P*  
*Like CHINA*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door (RH) <i>— NK</i>			\$ 1,403.00
	SUB TOTAL			\$ 1,403.00
	LESS 20%			\$ 280.60
	DISCOUNTED TOTAL			\$ 1,122.40
	Front Door Comfort Logo (RH) <i>— NK</i>			\$ 75.00 <b>Nett</b>
	Front Door Advertisement Logo (RH) <i>— NK</i>			\$ 100.00 <b>Nett</b>
				\$ 175.00
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>350.00</del> <i>200</i>
	Spray Painting Charge			\$ <del>250.00</del> <i>200</i>
	Tuff Kote			\$ <del>50.00</del> <i>20</i>
	Transfer of Door			\$ <del>120.00</del> <i>20</i>
	TOTAL LABOUR			\$ 770.00
	ESTIMATE TOTAL			\$ 2,067.40

*Kalvin KKK*  
*20/6/18 1100h*  
*2 Pys*  
*PP*  
*Before first photo*

KK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary claim(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHC 8664X

DATE 19/6/2018 16:08

MAKE :

MODEL : HYUNDAI i40

*WKK/Kalvin*

*Pby P*

*Like*

*CHINA*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door ( <del>LH</del> /RH)			\$ 1,403.00
	<b>SUB TOTAL</b>			\$ 1,403.00
	<b>LESS 20% DISCOUNTED TOTAL</b>			\$ 280.60
				\$ 1,122.40
	Front Door Comfort Logo (RH)			\$ 75.00
	Front Door Advertisement Logo (RH)			\$ 100.00
				\$ 175.00
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>350.00</del> 200
	Spray Painting Charge			\$ <del>250.00</del> 200
	Tuff Kote			\$ <del>50.00</del> 20
	Transfer of Door			\$ <del>120.00</del> 20
	<b>TOTAL LABOUR</b>			\$ 770.00
	<b>ESTIMATE TOTAL</b>			\$ 2,067.40

*Kalvin LKK*  
*20/6/18 1100h*  
*2 Pp*  
*PP*  
*Before first photo*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "no prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

Date: 23.06.2018

REPAIR ESTIMATE

Time: 14:50:35

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS: COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305177402  
REGN NO : SHC8664X  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 07.01.2016  
DATE/TIME IN : 19.06.2018 13:20  
ACCIDENT DATE : 19.06.2018

JOB/PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0592-G I40VC PANEL ASSY-FR DR RH 1 L 1,403.00 20.00 1,122.40  
0002 28-01-0103-0003-A (I40)FRT DOOR LOGO SONATA 1 N 75.00 2.00- 75.00

SUB-TOTAL : 1,197.40

JOB NATURE

0000 20-05 RENEW ADVERTISEMENT STICKER- 100.00  
0001 L PANEL BEATING 200.00  
0002 23-502 SPRAYPAINT ON AFFECTED AREA 200.00  
0003 20-00 TUFF COAT ON AFFECTED PARTS. 20.00

SUB-TOTAL : 520.00

TOTAL : 1,717.40

\_\_\_\_\_  
MVA NAME & SIGNATURE  
DATE :

\_\_\_\_\_  
AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508989  
Fax: 6546 8156

Our Job Ref No 305177402  
Date : 23/06/18

## FINALIZATION FORM

To : LKK Fax : \_\_\_\_\_  
Attn : Mr KALVIN ANG  
Vehicle Reg No. SHC8664X CTPL 19.06.18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- SJS9506E
2. The finalized amount shall be:
 

(a) Spare Parts after List discount	<u>\$1,197.40</u>
(b) Labour Charges	<u>\$520.00</u>
<b>Total for Part-By-Part Repair Cost</b>	<b><u>\$1,717.40</u></b>
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	<u>                    </u>
<b>Final Lumpsum Repair cost</b>	<u>                    </u>

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM KWOK ENG  
Tel : 62148316  
Fax : 65468156

Signature :   
Name : Calvin  
Date : 25/6/18

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_



[Home](#) e-Services (/content/policehubhome/homepage.html)

[Log in](#)

# Status of Driving Licence

## Qualified Driving Licence

### Qualified Driving Licence Number

S7227366D

### Status of Qualified Driving Licence

Valid

### Class(es) of Qualified Driving Licence

3

### Expiry Date

Valid for life unless revoked,suspended or disqualified

## Provisional Driving Licence

### Provisional Driving Licence Number

S7227366D

### Status of Provisional Driving Licence

No Licence

### Class(es) of Provisional Driving Licence

### Expiry Date

-

[HOME \(https://www.police.gov.sg/\)](https://www.police.gov.sg/)

[ABOUT US \(https://www.police.gov.sg/about-us\)](https://www.police.gov.sg/about-us)

[SGSECURE \(https://www.police.gov.sg/sgsecure\)](https://www.police.gov.sg/sgsecure)

[I-WITNESS \(https://www.police.gov.sg/iwitness\)](https://www.police.gov.sg/iwitness)

[COMMUNITY PROGRAMMES \(https://www.police.gov.sg/community-programme\)](https://www.police.gov.sg/community-programme)

[RESOURCES \(https://www.police.gov.sg/resources\)](https://www.police.gov.sg/resources)

[NEWS & PUBLICATIONS \(https://www.police.gov.sg/news-and-publications\)](https://www.police.gov.sg/news-and-publications)

[JOIN US \(https://www.police.gov.sg/join-us\)](https://www.police.gov.sg/join-us)

[FAQS \(https://va.ecitizen.gov.sg/cfp/CustomPages/SPF/explorefaq.aspx\)](https://va.ecitizen.gov.sg/cfp/CustomPages/SPF/explorefaq.aspx)

[CONTACT US \(https://www.police.gov.sg/content/contact-us\)](https://www.police.gov.sg/content/contact-us)

[E-FEEDBACK \(/content/policehubfeedback/efeedback.html\)](/content/policehubfeedback/efeedback.html)

[SITEMAP \(https://www.police.gov.sg/sitemap\)](https://www.police.gov.sg/sitemap)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18011272/K1ha3n2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERSINGAPORE 079909

Date : 13-08-2018



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJS 9506E	Veh. Inspected	SHC 8664X
Policy No.	DMHCSN1749871700	Coverage (\$)	0.00
Claim No.	SNM18D03134/C01/6	Excess (\$)	0.00
Assign From		Assign Date	20/06/2018

### 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU083092	Colour	BLUE
Odometer	290923	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	7 mm
L/H Front Tyre	205/60 R16	WEST LAKE	7 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	19/06/2018	Inspection Date	20/06/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>2 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8664X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT DOOR (RH)	DENTED	1,403.00	1,403.00
	LESS 20% DISCOUNT		-280.60	-280.60
			1,122.40	1,122.40
<b>SPECIAL NETT ITEMS</b>				
1	FRONT DOOR COMFORT LOGO (RH) (SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (RH) (SN)	NECESSARY	100.00	100.00
			175.00	175.00
<b>LABOUR</b>				
	PANEL BEATING.		350.00	200.00
	SPRAY PAINTING CHARGE.		250.00	200.00
	TUFF KOTE.		50.00	20.00
	TRANSFER OF DOOR .	NOT NECESSARY	120.00	-
			770.00	420.00
<b>GRAND TOTAL</b>			<b>2,067.40</b>	<b>1,717.40</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,717.40</b>

Report Ref No. CC3/CTI18011272/K1ha3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.