

ASS. R.F.C. BY:

REF CSB/MSG18011292/R124d3⁹⁷ Special Instruction:

Surveyor: meihen ASSIGNMENT (Office)

From (Person): Lionel fun of MSIG Date/Time: 21/06/2018 @ 9.27am.

Estimated Cost: _____ Bill to: _____

OD WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: S1Z 5377A Insured: FBF 1321L

at Workshop m/s: MY CAR 1 Tel: 68442475

of 53 Ubi Ave 1 # 01-21

Policy No: MSD/VMS/18-378823-CA Claim No: MSC/V/18-000834

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 16/06/2018
(Client's Record)

Insp: Teamwork Garage

CA / REV / REP. / REV 24 HRS up H.O.D. Endorsement: _____

Date/Time: 12.14pm @ 21/6/18 Person Contacted: su Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	S1Z 5377A - NA/INC18010940/K4 DDA: 16/06/2018
	FBF 1321L - NA/INC18010940/K4 DDA: 16/06/2018
26/6/18	Disassembled
4/7/18	After repair

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jun 2018		21 Jun 2018 09:27 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MUHAMMAD NAUFAL BIN SAMAWI, ID: S9527980E, Tel: +6587497617		
Main Claimant:	YAP HOCK CHUAN (YE FUQUAN), ID: S8736580H		
Vehicle Reg. No.:	SJZ5377A	Date of Loss:	16/06/2018 22:00 - :59 [90 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-000834	Policy/Cover Note No.:	MSD/VMS/18-378823-CA (TP, Fire & Theft) Coverage: 11/02/2018 - 10/02/2019
Vehicle Reg. No. (Insured):	FBF1321L	Policy No. (Claimant):	
		Excess:	
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/06/2018]		
Driver/Custodian (Insured):	MUHAMMAD NAUFAL BIN SAMAWI (22 / Male), NRIC: S9527980E, Tel: +6587497617		
Adj Asg. Remarks:	on WP. SJE - DISAGEED Please appoint LKK AUTO CONSUTANTS to conduct the survey and Kindly contact Jeremy @ 9888 8885 / Carmen @ 8321 0988 or Yvonne @ 9129 6469 to arrange for survey. Liability : OI ACCIDENT NOT REPORTED		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/06/2018 13:18
Date Of Accident	16/06/2018 22:35
Exact Location Of Accident	JUNC OF SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ5377A
Insured/Policyholder	
Name Of Registered Owner	YAP HOCK CHUAN (YE FUQUAN)
NRIC No	S8736580H
Email Address	NAUHC_KCOH_PAY@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91192747
Alternative Phone No	OTHERS-91192747

Vehicle Particulars

Manufacturer	MINI
Model	COOPER S HB 1.6 AT HID SR ABS TC 2WD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101205793
Cover Note Number	

Driver

Name of Driver	YAP HOCK CHUAN (YE FUQUAN)
NRIC No	S8736580H
Date Of Birth	10/11/1987
Occupation	INDOOR
Date Of Driving Pass	14/03/2007
Driving Experience	11 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91192747
Fax Number	
Contact Number	OTHERS-91192747
EMail Address	NAUHC_KCOH_PAY@HOTMAIL.COM

Address	BLK 739 JURONG WEST STREET 73 #07-58
Postcode	640739
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance,	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TRAN THI THU DIEM GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KAMPONG JAVA NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 KAMPONG JAVA ROAD , POSTCODE: 228892 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2959999 - FAX NO: 63918499
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE POLICE REPORT : T/20180617/2040

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBF1321L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	YAP HOCK CHUAN (YE FUQUAN)
Approximate Age	
Injuries Sustain	SLIGHT
Injured person in which vehicle?	SJZ5377A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	TRAN THI THU DIEM
Approximate Age	
Injuries Sustain	SLIGHT
Injured person in which vehicle?	SJZ5377A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SJZ5377A		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	With Sun Roof		
Vehicle Scheme :	Normal		
Vehicle Make :	MINI		
Vehicle Model :	COOPER S HB 1.6 AT HID SR ABS TC 2WD		
Chassis No. :	WMWSV32080TY82782		
Propellant :	Petrol		
Engine No. :	A6581851		
Engine Capacity :	1598 cc		
Maximum Power Output :	135.0 kW (181 bhp)		
Maximum Laden Weight :	1605 kg		
Unladen Weight :	1155 kg		
Year Of Manufacture :	2010		
Original Registration Date :	03 Dec 2010		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$39,000.00		
COE Expiry Date :	02 Dec 2020		
Road Tax Expiry Date :	02 Dec 2018		
PARF Eligibility Expiry Date :	02 Dec 2020		
Inspection Due Date :	02 Dec 2019		
Intended Transfer Date :	26 Jun 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jun 2018		21 Jun 2018 09:27 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MUHAMMAD NAUFAL BIN SAMAWI , ID: S9527980E, Tel: +6587497617		
Main Claimant:	YAP HOCK CHUAN (YE FUQUAN) , ID: S8736580H		
Vehicle Reg. No.:	SJZ5377A	Date of Loss:	16/06/2018 22:00 - :59 [90 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-000834	Policy/Cover Note No.:	MSD/VMS/18-378823-CA (TP, Fire & Theft) Coverage: 11/02/2018 - 10/02/2019
Vehicle Reg. No. (Insured):	FBF1321L	Policy No. (Claimant):	
		Excess:	
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 22/06/2018]		
Driver/Custodian (Insured):	MUHAMMAD NAUFAL BIN SAMAWI (22 / Male), NRIC: S9527980E, Tel: +6587497617		
Adj Asg. Remarks:	on WP, SJE - DISAGEED Please appoint LKK AUTO CONSUTANTS to conduct the survey and Kindly contact Jeremy @ 9888 8885 / Carmen @ 8321 0988 or Yvonne @ 9129 6469 to arrange for survey. Liability : OI ACCIDENT NOT REPORTED		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJZ5377A (MSC/V/18-000834)**
[FBF1321L]
TP
YAP HOCK CHUAN (YE FUQUAN)
Jun 16 2018 10:00PM
[MUHAMMAD NAUFAL BIN SAMAWI]
Teamwork Garage Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser ▼
Letters/Correspondences			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail
1	20/06/18 10:16	Non Reporting Letter to OI		Load HTM
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail
1	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
2	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
3	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
4	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
5	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
6	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
7	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
8	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
9	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
10	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
11	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
12	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
13	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
14	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
15	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
16	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
17	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
18	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
19	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
20	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
21	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
22	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
23	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
24	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
25	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
26	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
27	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
28	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
29	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
30	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
31	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
32	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences				
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
33	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
34	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
35	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
36	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
37	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
38	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
39	26/06/18 13:48	General View		Load JPG <input checked="" type="checkbox"/>
40	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
41	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
42	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
43	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
44	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
45	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
46	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
47	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
48	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
49	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
50	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
51	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
52	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
53	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
54	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
55	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
56	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
57	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
58	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
59	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
60	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
61	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
62	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
63	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
64	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
65	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
66	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
67	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
68	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
69	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
70	26/06/18 13:49	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
71	06/07/18 16:35	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
72	06/07/18 16:35	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
73	06/07/18 16:35	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
74	06/07/18 16:35	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
75	06/07/18 16:35	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
76	06/07/18 16:35	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
77	06/07/18 16:35	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
78	06/07/18 16:35	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Letters/Correspondences				<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/06/18 10:13	TPD SJZ5377A - PRI & GIA REPORT	Load PDF	
2	20/06/18 10:13	TPD SJZ5377A - PRI	Load PDF	
3	20/06/18 10:18	Pre-Repair Survey	Load PDF	
4	20/06/18 16:00	Reject email to TP Lawyer & appoint LKK AUTO	Load PDF	
5	27/06/18 14:57	FBF1321L Police Report (1 of 3)	Load JPG	<input checked="" type="checkbox"/>
6	27/06/18 14:57	FBF1321L Police Report (2 of 3)	Load JPG	<input checked="" type="checkbox"/>
7	27/06/18 14:57	FBF1321L Police Report (3 of 3)	Load JPG	<input checked="" type="checkbox"/>
8	27/06/18 14:57	Reply to OI mother	Load HTM	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18011292/R1Z4D3S2

Date: 09/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMS/18-378823-CA
 Claimant Vehicle No: SJZ5377A Insured Vehicle No: FBF1321L
 Date of Loss: 16/06/2018 Nature of Claim: TP Claim No: MSC/V/18-000834

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ5377A**
 Make & Model: MINI COOPER S, 1.6 Engine No: A6581851
 Reg. Date: 03/12/2010 (Man. Year: 2010) Chassis No: WMWSV32080TY82782
 Colour: Black Odometer: 137629 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/35ZR18 Rear Tyre Size: 225/35ZR18
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/06/2018
 Date Inspected: 22/06/2018 Inspected At: MY CAR 1
 53 Ubi Ave 1 #01-21, Paya Ubi Industrial Park
 Singapore 408934
 Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,800.00 - \$7,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Jul 2018)
Parts: M1-COUPE	MINI COOPER S 1.6 (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJZ5377A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >