

INSURER: Stacy | CC 4 km 1299, K1639 | L&K: W.  
 INSL CASE OWNER: CC 4 km 1299, K1639 | AXA1801 | IDAC:

Surveyor: Kenneth | DOI: ASSIGNMENT 21/6/18 | Date / Time: 21/6/18  
 Registered in Merit: \_\_\_\_\_

Pre-assign / CCU / FTE: YP 6461H  
 Insured Vehicle No: \_\_\_\_\_ Claim No: 8800043 / 62930  
 Name of Insured: SPEEDY INDUSTRIAL SUPPLIES PM Policy No: PM20422  
 Insured Tel No: \_\_\_\_\_ HP: \_\_\_\_\_ Make / Model: HINO  
 Excess Sec II :SS \_\_\_\_\_ D.O.A: 21/6/18 Place of Accident: 1 WOODLANDS TERRACE  
 Is driver the owner? ( YES /  NO ) Nature of Accident: \_\_\_\_\_  
 If NO, Driver Name / Age: TEO LIM LHM OI GIA REPORT:  YES / NO : TP GIA REPORT:  YES / NO  
 Driver Tel No: \_\_\_\_\_ (V/L:  YES / NO ) Insured Liability: % Final ? Yes / No

SLC 5130 → → → → →  
 INSR: WSP: Cheng Hoe INSR: WSP: \_\_\_\_\_ INSR: WSP: \_\_\_\_\_ INSR: WSP: \_\_\_\_\_  
 Tel: \_\_\_\_\_ Tel: \_\_\_\_\_ Tel: \_\_\_\_\_ Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_ Liability: \_\_\_\_\_ Liability: \_\_\_\_\_ Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_ RMKS: \_\_\_\_\_ RMKS: \_\_\_\_\_ RMKS: \_\_\_\_\_

Date/Time	STAGE	DATE / PIC
<u>20/6/18</u>	<u>SLC 5130 - x</u>	<u>YP 6461H - x</u>
<u>vic</u>	<u>Smartclaim</u>	
	<u>DIAR</u>	
<u>30/7/18</u>	<u>Set mandate via SMART</u>	
	<u>Mandate approval via SMART</u>	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OE	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill	<input type="checkbox"/> <input type="checkbox"/>
	PIR	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos	<input type="checkbox"/> <input type="checkbox"/>
	Others	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 20/6/18 Sent By: Free

FINALIZATION Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: \_\_\_\_\_  
 Repair Cost: SS \_\_\_\_\_ ( \_\_\_\_\_ days) Reduction: % \_\_\_\_\_ Email  Call

FINAL SETTLEMENT Date/Time: 12/1/19 Confirms with: Jure Email  Call   
 Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: NK If NO or B 28, Ass. Lia: \_\_\_\_\_

Repair Cost: SS 3263.50  
 Loss of Rental (LOR): SS \_\_\_\_\_ ( \_\_\_\_\_ days)  
 Loss of Use (LOU): SS 480.00 (560 x 8 days)  
 Loss of Income (LOI): SS \_\_\_\_\_ ( \_\_\_\_\_ days)  
 LOR only  LOU only  LOR + LOU  LOR + LO  [Tick only one]  
 GIA/LTA Search: SS 8.00  
 Medical: SS -  
 Disbursement: SS - (e.g. Tow/Independent)  
 Legal Cost: SS -  
 Total: SS 3751.50 Global Sum SS: \_\_\_\_\_  
 1) Claim status: Normal/Reject/Private Settle  
 2) Report Format:  
 3) Survey fee:

FINAL PAYMENT Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: SS 3751.50 Name 1: Cheng Hoe Motor Pte Ltd  
 Payee 2: (Strike if N.A.) SS Name 2: \_\_\_\_\_  
 Payee 3: (Strike if N.A.) SS Name 3: \_\_\_\_\_

COPY SENT  
12/1/19

ASS. REC. BY:

REF: AAA

Kenneth

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/W/S/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Cheng Hoe

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: B65K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1-31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLC513D Yr Regn: 04, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or A

Make: Mazda 2 c.c. 1496

Colour: M. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 41493 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MM6DL2S7AGW196407

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: \_\_\_\_\_

BS: OUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal: 8 mm Rear R/Bal: 8 mm

L/Bal: 8 mm L/Bal: 8 mm

D.O.A. 20/6/18 D.O.I. 21/6/18

Survey held at \_\_\_\_\_

Des. of Damages: Acc o/s / Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>16</u>	<u>File parts to Customer</u>
	<u>LLP 830501 email with 6 working days</u>

(Ref: #1036.08 75%)

Date/Time, File Pass to?  : Prell. Report

: Final Report

Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:	
Transportation:	
S - RS - SI	
Fixtures	
Others	
TOTAL	

Add Fee:  : Site Insp (\$ )

: Interview (\$ )

: Tech Invs (\$ )

: Weekend (\$ )

Report Format :

Lump Sum / I.B.I: (\$ )

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

SLC 513D  
 TP/AXA

**M/S :** AXA INSURANCE (S) PTE LTD  
 8 SHENTON WAY  
 #27-02 AXA TOWER  
 SINGAPORE 068811

TEL: 63387288 FAX: 68804739  
 ATTN: Motor Claim Department

**Estimate No:** ES1890684/YISHUN  
**Date:** 21 Jun 2018  
**Policy No:** D18MTPV01005489  
**Veh Reg No:** SLC513D  
**Make/Model:** MAZDA MAZDA2  
 SEDAN 1.5L SP.6EAT  
**Chassis No:** MM6DL2SAAGW196407  
**Engine No:** P520347805  
**Reg. Date:** 28/04/2016

WS Ref: TP/AXA/YS  
 Claim Type: Third Party  
 Accident Date: 20/06/2018  
 TP Veh Reg No: YP6461H

*Not Authorised*  
*Recovery B4 claim*  
*1/2pm @ 6 days*

## Estimate Repair Cost to Vehicle No :SLC513D

Description	U/Price	Quantity	List Price	Amount
			SS	SS
<b>List Price</b>				
1 REAR BUMPER	909.00	1 PC	909.00	✓
2 RH TAILLAMP	376.40	1 PC	376.40	✓
3 REAR BUMPER RH SIDE RETAINER	21.70	1 PC	21.70	✗
4 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
5 REAR BOOT LOGO	55.40	1 PC	55.40	✓
6 REAR BOOT EMBLEM (SKYACTIV)	64.30	1 PC	64.30	✓
7 REAR BOOT EMBLEM (MAZDA2)	55.10	1 PC	55.10	✓
8 REAR BOOT RH REFLECTOR	198.40	1 PC	198.40	✓
9 REAR RH FENDER	844.00	1 PC	844.00	✓
10 REAR WINDSCREEN GLASS MOULDING	49.80	1 PC	49.80	✓
			2,595.10	
		Less 20%	519.02	2,076.08
<b>Special Net</b>				
11 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
			40.00	40.00
<b>Labour</b>				
12 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
13 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REFLECTOR, TO CUT, WELD & RENEW REAR RH FENDER & REALIGN THE SAME	900.00	1 LA	900.00	800
14 REMOVE & REFIX SEAT, CARPET, TOP ROOF LINING, ETC	120.00	1 LA	120.00	✓
15 PUTTY & RESPRAY ON REAR BUMPER, BOOT, REAR RH FENDER & REAR AFFECTED AREAS	800.00	1 LA	800.00	650
16 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,970.00	1,970.00
		<b>Total</b>	<b>SS 4,086.08</b>	
		<b>Add GST @ 7%</b>	<b>286.03</b>	
		<b>Total Amount Payable</b>	<b>SS 4,372.11</b>	

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

> **Back to OneMotoring**

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	3053M
<b>Vehicle Details</b>	
Vehicle No.:	SLC513D
Vehicle to be Exported:	No
Intended De-registration Date:	20 Jun 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 SEDAN 1.5L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	P520347805
Chassis No.:	MM6DL2SAAGW196407
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$14,419.00
Original Registration Date:	28 Apr 2016
First Registration Date:	28 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$9,419.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Apr 2026
PARF Rebate Amount:	\$7,064.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	27 Apr 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$44,001.00
COE Rebate Amount:	\$34,553.00
<b>Total Rebate Amount:</b>	<b>\$41,617.00</b>

The information contained herein is correct as at 20 Jun 2018

OK

## ◀ Service Request Details

Claim  
S8M00LIB

Reference  
None ✎

Loss Date  
June 20, 2018

Request Date  
June 21, 2018

Due Date  
June 28, 2018

Vendor Name  
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss  
Third Party Vehicle Damage

Services  
Pending verification - Direct Settlement

21062018 @ 1149am  
June Veh in  
Kenneth

### Actions

Next Step  
Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #  
SLC531D

Make  
TPVD

Model

Service Address

---

Primary Contact/Insured

---

SPEEDY INDUSTRIAL SUPPLIES PTE LTD  
3 KALLANG SECTOR, #07-06, 349278, Singapore  
65674755

Claim Handler

---

NG Stacey  
6568804351  
stacey.ng@axa.com.sg

Additional Instructions  
INSD GIA NOT REPORTED

- 
- Messages
  - Invoices
  - History
  - Documents
  - Assessment
  - Metrics
  - Notes

New Message

◀ Re:TP MANDATE IA -S8M00LIB

Type

🔔 Question

Message

Please proceed.

Reply



## CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761  
 Tel : 67556142 Fax : 67557719  
 Email: chmotor@singnet.com.sg

Date: 15 JUL 2019

AXA Insurance (S) Pte Ltd  
 C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. SLC513D & YP6461H ON 20/06/2018  
 NO.1 WLDS TERRACE (INSIDE PARKING LOT).**

We are authorized by SLC513D for their above matter.

Record reveals that you are the insurer of YP6461H. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 3263.50
2. Loss of Use (S\$ 60.00 /- x 8 days)	S\$ 480.00
3. Hire of Vehicle	S\$ 0.00
4. LTA Search Fee/GIA Reports	S\$ 8.00
	<b>TOTAL S\$ 3751.50</b>

Please let us have your reply soonest possible.

Thank you.

Yours faithfully





02 AUGUST 2019

**SPEEDY INDUSTRIAL SUPPLIES PTE LTD**  
3 KALLANG SECTOR  
#07-06  
SINGAPORE 349278

**Dear Sir/ Mdm**

**OUR REF : CC4/ASM18011299/Kwb3 // S8M00LIB**  
**YOUR REF : YP 6461H**  
**ACCIDENT INVOLVING YP 6461H AND SLC 513D ALONG/AT NO.1 WOODLANDS**  
**TERRACE ON 20/06/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a third party claim(s) from CHENG HOE MOTOR PL acting on behalf of the owner of SLC 513D against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

As Insurers, they shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com) within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Copy of the letter of authorization
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.


To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to [est@axa.com.sg](mailto:est@axa.com.sg) or deliver it by hand to AXA Customer Care Centre.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact as at Ms. Vivian Lau (LKK Handler) 6841 8625 or [vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com) Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Vivian Lau  
Case Handler  
DID: 6841 8625  
FAX: 6741 4108  
EMAIL: [vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)

cc AXA INSURANCE PTE LTD

## AUTHORIZATION TO ACT

(FOR PROPERTY DAMAGE CLAIM ONLY)

I, Lingjack Engrg Works Pte Ltd (the third party claimant")  
of No.1 Woodlands Terrace #03-01 S 738471 (address),  
owner of SLC513D (vehicle no.) hereby authorize

CHENG HOE MOTOR PTE LTD

("The workshop") to act for me with respect to my claim for  
repair costs and/or rental and/or loss of use ("claim") for my  
Vehicle No. SLC513D that was damaged pursuant to the  
accident which occurred on 20/6/2018 (date) along No. Woodlands  
Terrace (inside PARKING Lot) (location)  
involving Vehicle No/s YP6461H  
("The accident").

I further authorize the workshop to settle my above mentioned  
claim in a manner that they deem fit and the workshop is further  
authorized to receive payment further to settlement of my claim  
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach  
on my behalf is on a without prejudice and without admission of  
liability basis insofar as the driver/owner/insurers of the other  
vehicle/s is concerned.

Dated this 20 day of June (month) 20 19 (year)

  
**LINGJACK ENGINEERING WORKS PTE LTD**

No. 1 Woodlands Terrace #03-01


Lingjack Industrial Building Singapore 738471

Tel: (65) 6759 4163 Fax: (65) 6758 7513

E-mail: [combat@lingjack.com](mailto:combat@lingjack.com)

Website: [www.combat.sg](http://www.combat.sg)

Signed by "the third party claimant"



Signed by "the workshop"



This Discharge Voucher applies strictly for Claimant's claim for property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

### AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	YP 6461H (Insd veh)	Model: <u>MRT22 2</u>
	SLC 513D (TP veh)	
Date of Accident/ Time:	20/06/2018	

Repair Estimate	: \$	<u>4,372.11</u>	
Final Repair Cost	: \$	<u>3,263.50</u>	
Loss of Use	: \$	<u>480.00</u>	<u>08 days at \$ 60.00 per day</u>
Rental (if any)	: \$		<u>days at \$ per day</u>
LTA / GIA Search Fee	: \$	<u>8.00</u>	
Others:	: \$		
	: \$		
Final Settlement Sum	: \$	<u>3,751.50</u>	

Payee Name : CHENG HOE MOTOR PTE LTD

Is Third Party Workshop GIA Registered?  YES  NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: NIL  
 BOLA Liability: 100.00 (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks:


**NOTE:**

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a **full and final settlement** that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

  Signature of workshop representative / Workshop stamp Name of Representative: <u>Puan Lian Hua</u> Date: <u>12/9/19</u>	 Signature of Witness / Workshop stamp (if applicable) Name of Witness: <u>Feeda BK Md Osman</u> Date: <u>12/9/19</u>
 Signature of AXA's surveyor/representative: Name of AXA's surveyor / Representative: Date:	

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

## TAX INVOICE

M/S : AXA INSURANCE (S) PTE LTD  
8 SHENTON WAY  
#27-02 AXA TOWER  
SINGAPORE 068811  
TEL: 63387288 FAX: 68804739  
ATTN: Motor Claim Department

NO: CL8190521  
Date: 07 Jun 2019  
Policy No: D18MTPV01005489  
Veh Reg No: SLC513D  
Make/Model: MAZDA MAZDA2  
SEDAN 1.5L SP.6EAT  
Job No: JC1599807

WS Ref: TP/AXA/YS  
Claim Type: Third Party  
Accident Date: 20/06/2018  
TP Veh Reg No: YP6461H

Description	Quantity	List Price	Amount
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	SS 3,050.00	SS 3,050.00
		Total	SS 3,050.00
		Add GST @ 7%	213.50
		Total Amount payable	SS 3,263.50

For Cheng Hoe Motor Pte Ltd

E. & O. E.



AUTHORISED SIGNATURE


# A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS

COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358

TEL : 6538 7411 & FAX : 6534 1011

TO : CHENG HOE MOTOR PTE LTD		BILL NO: B050/2018	
YOUR REF:			
OUR REF : ACS.CH.LTA.2018 (JUNE 2018)		DATE : 6/7/18	
TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusals, attendance preparation examination of documents relating thereto; correspondence, attendance, perusals, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.			
<b>LTANET SEARCHES FOR THE MONTH JUNE 2018</b>			
S/NO	TP NO.	CHM	DOA
1	1/6/2018	CB6129C	SKD4615Z 13/4/2018
2	2/6/2018	XD8168S	XE1927J 1/6/2018
3	4/6/2018	SJF282C	SKJ7973M 2/6/2018
4	5/6/2018	SKN3286T	SLN2196P 25/5/2018
5	5/6/2018	SKB1301J	SKT8695G 1/6/2018
6	7/6/2018	YP1085T	SCJ3339R 5/6/2018
7	7/6/2018	YM6622B	GZ684G 4/6/2018
8	7/6/2018	YL7213Y	GBF4119K 26/4/2018
9	8/6/2018	SLV1615L	GBF5423A 7/6/2018
10	8/6/2018	GY6761H	SLW4723H 8/6/2018
11	8/6/2018	GBE8257Z	GY6700J 4/6/2018
12	8/6/2018	SJR9824S	SLN9201L 22/2/2018
13	9/6/2018	SJV7791U	SJH6332S 8/6/2018
14	9/6/2018	XD5527J	XD8322M 7/6/2018
15	11/6/2018	SLJ7058T	SJS3053J 8/6/2018
16	12/6/2018	SJL1703S	SKL9083H 11/6/2018
17	16/6/2018	SLX2491J	SJQ3430P 14/6/2018
18	16/6/2018	SLS9429X	SJW143G 14/6/2018
19	18/6/2018	GBD115H	SKJ9694E 18/6/2018
20	19/6/2018	GBC7018P	GBD9859M 13/6/2018
21	19/6/2018	SLC8852Y	SFP7498X 19/6/2018
22	19/6/2018	PA4391A	SJD6800D 19/6/2018
23	19/6/2018	GBH1479E	GBD8157J 16/6/2018
24	20/6/2018	YP6461H	SLC513D 20/6/2018
25	22/6/2018	SCN838R	SJR6381Y 21/6/2018
			sub-total c/f
			<u>5 200.00</u>
			
M/s. A SYED & PARTNERS ADVOCATES & SOLICITORS SINGAPORE			
We reserved the right to forward a subsequent bill for any disbursements omitted herein.			
E. & O.E.			



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18011299/Kwb3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:STACEY NG

Date : 19-09-2019



Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 6461H	Veh. Inspected	SLC 513D
Policy No.	P2120422	Coverage (\$)	0.00
Claim No.	S8M00LIB	Excess (\$)	0.00
Assign From		Assign Date	21/06/2018

## 2. Vehicle Particulars & Condition

Make & Model	MAZDA 2 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MM6DL2SAAGW196407	Colour	METALLIC BLUE
Odometer	41493	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	DUNLOP	8 mm
L/H Front Tyre	185/65 R15	DUNLOP	8 mm
R/H Rear Tyre	185/65 R15	DUNLOP	8 mm
L/H Rear Tyre	185/65 R15	DUNLOP	8 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	20/06/2018	Inspection Date	21/06/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 513D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER (CONSISTENT)	MTG CRACKED	909.00	909.00
1	RH TAILLAMP (CONSISTENT)	BROKEN	376.40	376.40
1	REAR BUMPER RH SIDE RETAINER (CONSISTENT)	SERVICEABLE	21.70	-
6	REAR BUMPER CLIPS @\$3.50 (CONSISTENT)	NECESSARY	21.00	21.00
1	REAR BOOT LOGO (CONSISTENT)	NECESSARY	55.40	55.40
1	REAR BOOT EMBLEM (SKYACTIV) (CONSISTENT)	NECESSARY	64.30	64.30
1	REAR BOOT EMBLEM (MAZDA2)(CONSISTENT)	NECESSARY	55.10	55.10
1	REAR BOOT RH REFLECTOR (CONSISTENT)	CRACKED	198.40	198.40
1	REAR RH FENDER (CONSISTENT)	BENT	844.00	844.00
1	REAR WINDSCREEN GLASS MOULDING (CONSISTENT)	NECESSARY	49.80	49.80
	LESS 20% DISCOUNT		-519.02	-514.68
			2,076.08	2,058.72
<b>SPECIAL NETT ITEMS</b>				
1	REAR WINDSCREEN GLASS GUM (SN) (CONSISTENT)	NECESSARY	40.00	40.00
			40.00	40.00
<b>LABOUR</b>				
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		120.00	120.00
	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,REFLECTOR ,TO CUT ,WELD & RENEW REAR RH FENDER & REALIGN THE SAME.		900.00	800.00
	REMOVE & REFIX SEAT ,CARPET ,TOP ROOF LINING ,ETC.		120.00	120.00
	PUTTY & RESPRAY ON REAR BUMPER ,BOOT ,REAR RH FENDER & REAR AFFECTED AREAS.		800.00	650.00
	RUSTPROOFING.		30.00	30.00
			-	-
			-	-
			-	-
			1,970.00	1,720.00
<b>GRAND TOTAL</b>			<b>4,086.08</b>	<b>3,818.72</b>

Report Ref No. CC4/ASM18011299/Kwb3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,050.00
---	--	--	----------

Report Ref No. CC4/ASM18011299/Kwb3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SIMAKOLIB
Reference	CC4/ASM18011299/Kwb3g2
Loss Date	20 June 2018
Report Date	21 Jun 2018 8:58:33 AM
Request Date	21 June 2018
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

**Actions**

Next Step: Wait for Approve Invoice

**Vehicle Information**

Incident Vehicle Registration #	5LCS31D
Make	TPWD
Model	
Service Address	

...

**Primary Contact/Insured**

SPEEDY INDUSTRIAL SUPPLIES PTE LTD  
 3 KALLANG SECTOR, #07-06, 349278, Singapore  
 65674755

**Claim Handler**

Ng Stacy  
 654894351  
 stacy.ng@aaa.com.sg

Additional Instructions: INSD GIA NOT REPORTED

Messages | Invoices | History | Documents | Assessment | Metrics | Notes

Document Type:

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Meizhen	

20  
DATE  
RECORDED  
2019

LKK AUTO CONSULTANTS  
PTE LTD (TP)

Subtype/ Assessor expense

Invoice

Invoice1 (1).pdf

20  
September  
2019

LKK AUTO CONSULTANTS  
PTE LTD (TP)

Others

Forms / Claim  
Documents

LDA SEARCH.pdf

20  
September  
2019

LKK AUTO CONSULTANTS  
PTE LTD (TP)

Others

Forms / Claim  
Documents

LKK Inspection (1).pdf

20  
September  
2019

LKK AUTO CONSULTANTS  
PTE LTD (TP)

Others

Forms / Claim  
Documents

LKK Adjustment 1a (2).pdf

20  
September  
2019

LKK AUTO CONSULTANTS  
PTE LTD (TP)

Satisfaction / Discharge Voucher

Forms / Claim  
Documents

PAYMENT BREAKDOWN, EXPRESS  
SETTLEMENT FORM.pdf

20  
September  
2019

LKK AUTO CONSULTANTS  
PTE LTD (TP)

FOA / Authority Letter

Forms / Claim  
Documents

AUTHORISATION TO ACT FORM.pdf

20  
September  
2019

LKK AUTO CONSULTANTS  
PTE LTD (TP)

Repairer

Invoice

WORKSHOP INVOICE.pdf

20  
September  
2019

LKK AUTO CONSULTANTS  
PTE LTD (TP)

Policy Holders / Insured

Letters and  
Correspondence

LETTER TO OJ.pdf

30 July 2019

LKK AUTO CONSULTANTS  
PTE LTD (TP)

Others

Reports &  
Statement

TP MANDATE (A-SLC 513D).pdf

30 July 2019

LKK AUTO CONSULTANTS  
PTE LTD (TP)

Others

Reports &  
Statement

MARKED ESTIMATE.pdf

30 July 2019

LKK AUTO CONSULTANTS  
PTE LTD (TP)

Others

Reports &  
Statement

LKK Reinspection Photos.pdf

30 July 2019

LKK AUTO CONSULTANTS  
PTE LTD (TP)

Others

Reports &  
Statement

LKK Inspection Photos.pdf

NAME	POPs / Claim Documents	Policy Schedule / Certificate of Insurance	AUTHOR	DATE
 P2120422_CL_TP_X5 NIL.pdf			MG Siscoy	25-JUN-2018
 TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKX AUTO CONSULTANTS PTE LTD (TP)	25 June 2018
 Immediate Advice.pdf	Reports & Statement	Estimate / Quotation	LKX AUTO CONSULTANTS PTE LTD (TP)	25 June 2018
 Ltr to Insured -non reporting.doc	Reports & Statement	Estimate / Quotation	LKX AUTO CONSULTANTS PTE LTD (TP)	25 June 2018
 TP PRI RECEIVED FROM WORKSHOP.meg	Letters and Correspondence	Workshop	DHAKAL Raghav	21 June 2018