



SERVICE REQUESTS

MESSAGES

CLAIMS

Claim	S8M00KVS
Reference	CS3/ASM18011300/Aes3e2 
Loss Date	13 June 2018
Report Date	14 Jun 2018 12:00:00 AM
Request Date	11 November 2020
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident SLV3483L
Vehicle
Registration #

Make TPVD TOYOTA

Model VELLFIRE 2.5L Z CVT

Service Address

, , ,

Primary Contact/Insured

TEO TEOW BOON
BLK 128B PUNGGOL FIELD WALK, #08-353,
822128, Singapore

Claim Handler



SERVICE REQUESTS

MESSAGES

CLAIMS

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

[+ Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Accident Statement	Reports & Statement		Merimen	
 ASM-LKKInvoice-AC2102163.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	13 April 2021
 LKKPreRepairInspection.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	13 April 2021
 Resurvey Photo-2.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	13 April 2021

English (SG) ▾

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

SUB-TYPE

AUTHOR

DATE
UPLOADED

SERVICE REQUESTS

MESSAGES

CLAIMS

Photos

LKK AUTO CONSULTANTS
PTE LTD (TP)13 April
2021

LKKPhoto.pdf

Evidence

Photos

LKK AUTO CONSULTANTS
PTE LTD (TP)13 April
2021

REPLY FROM WORKSHOP.msg

Forms / Claim
Documents

Others

KUMAR Shailendra

20 June
2018

EMAIL FROM WORKSHOP.msg

Forms / Claim
Documents

Others

KUMAR Shailendra

20 June
2018

SKU5984L INSD GIA REPORT.PDF

Reports &
Statement

GIA Report

RATAN BHOSALE Pragati

20 June
2018 EMAIL RECIEVED FROM WORKSHOP WITH
TP GIA REPORT.msgLetters and
Correspondence

Workshop

RATAN BHOSALE Pragati

20 June
2018

LIST OF SURVEYORS TO WORKSHOP.msg

Letters and
Correspondence

Workshop

RATAN BHOSALE Pragati

20 June
2018