

COMFORTDELGRO ENGINEERING PTE LTD

Date: 20.06.2018

REPAIR ESTIMATE

Time: 12:15:40

Page: 1

AXA-CP(P)

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305177598
REGN NO : SHA4893M
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 03.10.2017
DATE/TIME IN : 20.06.2018 11:00
ACCIDENT DATE : 19.06.2018

1220

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2292-G	FRONT BUMPER	1	490.50	25.00	367.87	X Repair
0002 04-01-0302-0574-G	FRT FENDER LH	1	933.10	25.00	699.82	X Repair
0003 04-01-0302-2297-G	FRT FENDER (HYBRID) LH	1	86.50	25.00	64.87	-

SUB-TOTAL : 1,132.56

JOB NATURE

0000 L	PANEL BEATING
0001 23-502	SPRAYPAINT ON AFFECTED AREA
0002 20-00	TUFF COAT ON AFFECTED PARTS.

~~560.00~~ 200~~500.00~~ 400~~40.00~~ X

SUB-TOTAL : 1,100.00

TOTAL : 2,232.56

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

Kelvin LKK
20/6/18 1530hrs.
2 Days
PIP
After Repair photo

AUTHORISED - YES/NO

LKK Auto Consultants henceforth the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: