- 75 TEVE	12 11 1 12 1			I (Office)	TimeTime	17/5/2018
	Kamaliah Kamis			10 00		-11-1-1
	THE PART OF THE PER			10 10		
	TTP RES / OD RES / E		IMATES		Insured:	
- 1	hide No. PC GG92	211			T=1:	
ut Workshop z	2/5					
00°	4HB&PFD6000001	rest.	1500	Chin No.	TP 11 23879	2018
53 72		(c) a. l		Excess:		
Sum Insured				AND THE SECOND	DOA	12/4/2018
Make of Veh. (Chent's Record					27.785	1=1.1
CA / REV	CA / REV / REP. / REV 24 HRS			H.O.D. Endustration		
Date Time	Date/Time Person Confessed			Vehicle ISAOUT		
Dista Times	Action/Instruction (3 8	thing le			
	PCGG9DH-X					
					Maria Caracteria	
	1-1-		7756			

Celone: Open File

Um Rus PC6692H

4 Vehicles do ta

Rohaizal (LKKAuto)

From:

Kamaliah KAMIS (SPF) < Kamaliah_KAMIS@spf.gov.sg>

Sent:

Tuesday, 22 May 2018 10:45 AM

To:

Bryan Ang (LKKAuto); Rohaizal (LKKAuto)

Cc: Subject: SPF-TP FAIT; Mohd Abdillah PALIL (SPF)
RE: Mechanical Inspection Report Request

Hi Sir,

Can I check if you received the following requests?

Best regards,

Kamaliah Kamis (Miss) Investigation Officer | Fatal Accident Investigation Team Traffic Police | Singapore Police Force DID: (85) 6547 6435 | FAX: (85) 6547 6352



HOME TEAM ... TRANSFORMATION 2025 ... One Home, One Team Building Our Future Together

WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addresses, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Kamaliah KAMIS (SPF)

Sent: Thursday, 17 May 2018 5:30 PM

To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Cc: SPF-TP FAIT <SPF-TP_FAIT@spf.gov.sg>; Mohd Abdillah PALIL (SPF) <Mohd_Abdillah_PALIL@spf.gov.sg>

Subject: Mechanical Inspection Report Request

Hi Sir,

May I seek your assistance to perform a detailed mechanical inspection of the vehicle below:

(a) Case IAFP-IB-20180515-Mechanical Inspection of Mini Bus, PC6692H (TP/IP/22879/2018)

On 12/04/2018 at about 9.30 am, the motor bus, PC 6692 H was travelling along Sims. Avenue on lane 2 of 5 lanes road and stopped at the signalized cross junction of Aljunied Road due to traffic red light. When the traffic light turned green, motor bus moved forward and made a right turn, hitting a pedestrian (Deceased) whom was crossing the signalised pedestrian crossing on a 'green' man. The Deceased suffered serious injuries and was conveyed to Tan Tock Seng Hospital via ambulance. On the 03/05/2018, the Deceased succumbed to his injuries and passed away at the hospital at 11.20 am.

PC6692H - Driver (Not injured)

10 In-Charge: SIO Farhan

(b) Case IAFP-IB-20180515-Mechanical Inspection of Motor Car, SHD9756C (TP/IP/26753/2018)

On 5 May 2018 (Saturday) at or about 8.54 p.m., Motor taxi was along Hougang Ave 8 towards Ave 2 on centre lane of 3 lanes road when his vehicle veered to his right, mounted centre and collided onto green railing. Rear left passenger sustained spinal injury and unconscious before conveyed to TTSH. Currently, she was still in life support and pending for spinal ops.

<u>SHD9756C</u> - Driver (Accused-Not injured) <u>SHD9756C</u> - Rear left passenger (Victim-Seriously injured)

IO In-Charge: SIO Abdillah

(c) Case IAFP-IB-20180425-Mechanical Inspection of motorcycle, FX7859X (TP/IP/25131/2018)

On 25 April 2018 (Wednesday) at or about 10.02 a.m., a National Parks Board (NParks) officer drove along Marina Gardens Drive to inspect the plants along the main road. When they were driving towards the side opening near lamp post 19F, they saw the Deceased and the motorcycle lying in the bushes after the side opening near the said lamp post. The Deceased sustained severe head injuries and was pronounced dead by attending paramedic Tan at 10.44 a.m.

FX7859X - Deceased

IO In-Charge: SIO Shahril

(d) Case IAFP-IB-20180515-Mechanical Inspection of Motor Lorry, YP6558M (TP/IP/26803/2018)

On 15/05/2018 at about 8.49 am, the motor lorry, YP6558M was travelling along Kaki Bukit Ave 1 towards the direction of Bedok Reservoir on lane on lane 2 of the 2-lanes road. Upon reaching the signalised cross junction of Kaki Bukit Ave 1 X Kaki Bukit Rd 4, traffic light in his direction was green only and he subsequently made a left turn. Halfway making a left turn into the signalised pedestrian crossing, a pedal cyclist (deceased) was cycling ahead of him from his left to right side while it was still green man. As it was too sudden, the motor lorry collided into the deceased's right portion. As a result of the accident, the deceased was conveyed to Changi General Hospital in an unconscious state. On the same day at about 9.46 am, the deceased was pronounced dead in the same hospital.

YP6558M - Driver (Not injured)
Bicycle - Pedal Cyclist (Deceased)

10 In-Charge: 10 Kamaliah

- These request has been <u>approved</u> by my management.
- Thank you Sir.

Cc: FAIT Team & IO Abdillah, fyip

Best regards,

Kamaliah Kamis (Miss) Investigation Officer | Fatal Accident Investigation Team Traffic Police | Singapore Police Force DID: (65) 6547 6435 | FAX: (65) 6547 6352 Celuie: Open Re

awnibus PC6692H

4 Vehicles do la

Rohaizal (LKKAuto)

From:

Kamaliah KAMIS (SPF) < Kamaliah_KAMIS@spf.gov.sg>

Sent:

Tuesday, 22 May 2018 10:45 AM <

To:

Bryan Ang (LKKAuto); Rohaizal (LKKAuto)

Cc:

SPF-TP FAIT; Mond Abdillah PALIL (SPF)

Subject:

RE: Mechanical Inspection Report Request

Hi Sir,

Can I check if you received the following requests?

Best regards,

Kamaliah Kamis (Miss) Investigation Officer | Fatal Accident Investigation Team Traffic Police | Singapore Police Force DID: (65) 6547 6435 | FAX: (65) 6547 6352



HOME TEAM
TRANSFORMATION 2025 ****
One Home, One Team
Building Our Future Together

WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Kamaliah KAMIS (SPF)

Sent: Thursday, 17 May 2018 5:30 PM

To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Cc: SPF-TP FAIT <SPF-TP FAIT@spf.gov.sg>; Mohd Abdillah PALIL (SPF) <Mohd_Abdillah_PALIL@spf.gov.sg>

Subject: Mechanical Inspection Report Request

HI SIr,

May I seek your assistance to perform a detailed mechanical inspection of the vehicle below:

(a) Case IAFP-IB-20180515-Mechanical Inspection of Mini Bus, PC6692H (TP/IP/22879/2018)

On 12/04/2018 at about 9.30 am, the motor bus, PC 6692 H was travelling along Sims. Avenue on lane 2 of 5 lanes road and stopped at the signalized cross junction of Aljunied Road due to traffic red light. When the traffic light turned green, motor bus moved forward and made a right turn, hitting a pedestrian (Deceased) whom was crossing the signalised pedestrian crossing on a 'green' man. The Deceased suffered serious injuries and was conveyed to Tan Tock Seng Hospital via ambulance. On the 03/05/2018, the Deceased succumbed to his injuries and passed away at the hospital at 11.20 am.

PC6692H - Driver (Not injured)

10 In-Charge: SIO Farhan

(b) Case IAFP-IB-20180515-Mechanical Inspection of Motor Car, SHD9756C (TP/IP/26753/2018)