401 201		ASSIGNMEN	Tionsce	2/6/2	Y210
$\widetilde{v}_T \equiv \widetilde{Q} \text{ and } \eta_T$	Kamaliah Kamie	SPE		- stele	5.479.59
	TP RES / OD RES / EVA) de	nira#	
To England Vehicle Liv. SRS. 5695U			Instituted		
at Workshop or	h			101	
×		0.5	TP	11P/31275/2018	
Folie, No. 19	HASPF06000000H	65		Interestin	
Sum insured:			Even	DOA SAS	voi
Make of Veh: (Chent's Record					
CA / REV / REP. / REV 24 HRS			11.0.D: Endorseren		
Date Tune Person Connoted				Trible INLOUT	
Date/Time	Action/instruction (1 Strote			
	SBS 5095U-X				
					-
			D:	W1100-	-
			(X)	101. X	

Celine Fong (LKKAuto)

From:

Kamaliah KAMIS (SPF) < Kamaliah_KAMIS@spf.gov.sg>

Sent:

Friday, 8 June 2018 2:37 PM

To:

Bryan Ang (LKKAuto); Rohaizal (LKKAuto)

Cc:

SPF-TP FAIT; Norhidawati AHMAD (SPF); MUHAMMAD FIRDAUS SULEIMAN (SPF)

Subject:

Mechanical Inspection Report Request

Hi Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the vehicle below:

(a) Case IAFP-IB-20180607 - Mechanical Inspection of Motorcycle, JRY8130 (TP/IP/33377/2018)

On 06/06/2018 at about 7.04 am, the Deceased was riding motor cycle JRY 8130 along Upper Jurong Road towards Pioneer Road North on the left most lane of 3 lanes road when he lost control of the motor cycle, skidded and landed on the grass patch. The Deceased suffered fatal injuries and passed away at scene. He was pronounced dead by paramedic, Tan Yew Yew at 7.18 am.

Vehicle to be inspected: JRY8130 - Rider (Deceased)

10 In-Charge: SIO Farhan

(b) Case IAFP-IB-20180607 - Mechanical Inspection of Motorcycle FBL1917L (TP/IP/32343/2018)

On 01/06/2018 at about 7.39 am, the Deceased was riding motor cycle FBL 1917 L along KJE (PIE) in between lane 1 and lane 2 of 4 lanes road when he lost control and skidded. The Deceased fell onto the road and went underneath a moving motor lorry (from the middle right portion) which was travelling on the lane 2. The Deceased suffered critical inujuries and was conveyed to NGTF hospital via ambulance. He passed away at the A & E Department at 8.44 am.

Vehicle to be inspected: FBL1917L - Rider (Deceased)

IO In-Charge: SIO Farhan

(c) Case IAFP-IB-20180607 - Mechanical Inspection of Motor Car, SJV9541L (TP/IP/20925/2018)

On 31 March 2018 at about 6.13pm, the said motor car was travelling along Jalan Kelabu when the driver claimed that his vehicle steering wheel got locked causing him to lost control of his vehicle and collided onto 3 parked vehicles. The vehicle is a Maserati Gran Turismo model.

As such, a mechanical inspection is required to rule if there is any mechanical issues as claimed by the driver.

Vehicle to be inspected: SJV9541L - Driver (Slight Injury)

10 In-Charge: SIO Firdaus

(d) Case IAFP-IB-20180607 - Mechanical Inspection of Motor Lorry, GY1421Y (TP/IP/32353/2018)

On 1/06/2018 at about 5.40 a.m., motor lorry driver was exiting out from car park driveway of Blk 109 Hougang Ave 1 into the main road when nearer to the stop line, he felt an impact from his left front portion

where a pedal cyclist had hit onto him. Pedal cyclist was unconscious after the accident and was conveyed to TTSH and pronounced dead on the same day at 9.35 am.

Vehicle to be inspected: GY1421Y - Involved Party (Not Injured)

IO In-Charge: SIO Vilton

(e) Case: IAFP-IB-20180607 - Mechanical Inspection of Motor Bus SBS5095U (TP/IP/31275/2018)

On 27 May at about 5.47 am, Motor Bus was travelling along Lavender Street when the motor bus collided onto a pedestrian who was crossing from the right to along Lavender Street. As a result of the accident, the pedestrian was sent to Singapore General Hospital where she later succumbed to her injuries

Vehicle to be inspected: SBS5095U - Driver (Potential Defendant)

10 In-Charge: SIO Yazid

(f) Case: IAFP-IB-20180607 - Mechanical Inspection of Trailer XD8794J/TRC7350P (TP/IP/31659/2018)

(g) Case: IAFP-IB-20180607 - Mechanical Inspection of Motorcycle JQV4563 (TP/IP/31659/2018)

On 29 May 2018 at about 6.23am along ECP towards AP, Motorcycle had collided onto the rear of a trailer. As a result of the accident, the rider was sent to Changi General Hospital where he later succumbed to his injuries.

Vehicle to be inspected: JQV4563 - motorcycle (Deceased)

Vehicle to be inspected: XD8794J/TRC7350P - trailer (Involved party)

10 In-Charge: SIO Yazid

(h) Case IAFP-IB-20180507-Mechanical Inspection of Motorcycle, FX9207P (TP/IP/31959/2018)

On 30 May 2018 (Wednesday) at about 11.23 p.m., the Deceased was believed to have skidded while riding his motorcycle along KJE towards the direction of BKE along the slip road into Woodlands Road near lamp post LP 102S15. The Deceased was conveyed to Ng Teng Fong General Hospital (NTFGH) by ambulance and was pronounced dead at NTFGH by Dr Ng Wei Ming at 12.43 a.m. on 31 May 2018.

Vehicle to be inspected: FX 9207 P - Rider (Deceased)

IO In-Charge: IO Clarence Lim

(i) Case IAFP-IB-20180507-Mechanical Inspection of Trailer, XD7462Z (TP/IP/24193/2018)

On 19 April 2018 (Thursday) at about 3.00 p.m., the trailer had collided into a height limit gantry along Sungei Kadut Avenue. Due to the collision, the damages on the height limit gantry was extensive.

Vehicle to be inspected: XD7462Z - Driver (Not injured)

IO In-Charge: IO Clarence Lim

- These request has been approved by my management.
- Thank you Sirs.

Cc: FAIT Team, OC Wati & SIO Firdaus, fyip

Best regards,

Kamaliah Kamis (Miss) Investigation Officer | Fatal Accident Investigation Team Traffic Police | Singapore Police Force DID: (65) 6547 6435 | FAX: (65) 6547 6352



WARNING: "Printeged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Color Open File / x M/Fb/ JBSS095V

a) Cate IAFO-10-20/50607- Medianol long of Mileony GY1421Y CTO/10/32353/20/5

On 1/06/2018 at about 5.40 a.m., motor lorry driver was exiting out from car park driveway of Blk 109

Hougang Ave 1 into the main road when nearer to the stop line, he felt an impact from his loss to TTSH and pronounced dead on the same day and the

Vehicle to be inspected: GY1421Y - Involved Party (Not Injured)

10 In-Charge: SIO Vilton

(e) Case: IAFP-IB-20180607 - Mechanical Inspection of Motor Bus SBS5095U (TP/IP/31275/2018)

On 27 May at about 5.47 am, Motor Bus was travelling along Lavender Street when the motor bus collided onto a pedestrian who was crossing from the right to along Lavender Street. As a result of the accident, the pedestrian was sent to Singapore General Hospital where she later succumbed to her injuries

Vehicle to be inspected: SBS5095U - Driver (Potential Defendant)

10 In-Charge: SIO Yazid

(f) Case: IAFP-IB-20180607 - Mechanical Inspection of Trailer XD8794J/TRC7350P (TP/IP/31659/2018)

(g) Case: IAFP-IB-20180607 - Mechanical Inspection of Motorcycle JQV4563 (TP/IP/31659/2018)

On 29 May 2018 at about 6.23am along ECP towards AP, Motorcycle had collided onto the rear of a trailer. As a result of the accident, the rider was sent to Changi General Hospital where he later succumbed to his injuries.

Vehicle to be inspected: JQV4563 - motorcycle (Deceased) Vehicle to be inspected: XD8794J/TRC7350P - trailer (Involved party)

10 In-Charge: SIO Yazid

(h) Case IAFP-I8-20180507-Mechanical Inspection of Motorcycle, FX9207P (TP/IP/31959/2018)

On 30 May 2018 (Wednesday) at about 11.23 p.m., the Deceased was believed to have skidded while riding his motorcycle along KJE towards the direction of BKE along the slip road into Woodlands Road near lamp post LP 102S15. The Deceased was conveyed to Ng Teng Fong General Hospital (NTFGH) by ambulance and was pronounced dead at NTFGH by Dr Ng Wei Ming at 12.43 a.m. on 31 May 2018.

Vehicle to be inspected: FX 9207 P - Rider (Deceased)

10 In-Charge: 10 Clarence Lim

Case IAFP-IB-20180507-Mechanical Inspection of Trailer, XD7462Z (TP/IP/24193/2018)

On 19 April 2018 (Thursday) at about 3.00 p.m., the trailer had collided into a height limit gantry along Sungei Kadut Avenue. Due to the collision, the damages on the height limit gantry was extensive.

Vehicle to be inspected: XD7462Z - Driver (Not injured)

IO In-Charge: IO Clarence Lim