

22/03/2002

ASS. REC. BY:

REF: es | GAI18011366 / Urd3 en

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): Rachel fun

of

GAI

Date/Time:

22/6/18 @ 11:50am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 6484E

Insured:

at Workshop n/s

De xing Motor

Tel:

6746 8582

of

81K 3006, Ubi Rd 1 # 01-356

Policy No:

Claim No:

CLMOMVM000000275

Sum Insured:

Excess:

\$750

Make of Veh:

(Client's Record)

D.O.A.

18/05/2018CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:08pm @ 22/6/18

Person Contacted:

Mrs. LeeVehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	List price
	<u>FBM 6884E - x</u>	
	<u>Mr: \$26K (marcus)</u>	
<u>22/6/18</u>	<u>Revert thru email</u>	<u>max 96408270</u>
<u>22/6/18</u>	<u>Rachel request w/s to L/s</u>	
<u>25/6/18</u>	<u>According Marcus, is a 2017 vehicle; Propose P/P & cost price.</u>	

12/10/18 Rachel approve on the supp at L/s \$10,500.00.
 Marcus ask to sent email to Patrick (refer email)

RECEIVED | 2018

(08/11/13) wel

ASS REC BY *Mercus*

REF:

GA / CS / GAL18011366 / Urd3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *FBM 6484E*

at Workshop mis

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess: *?*

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *\$ 26*

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / *(REV)* / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *FBM 6484E* Yr Regn: *1 / 18*

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Yamaha* MT-09 *847*Colour: *Blue* A/C: Insured / Std / NI / NASp. Reading: *7190* T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: *JYARN 438000010639*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or *ok*

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *120/70ZR17*R: *180/55ZR17*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front

Rear

R/Bal: *7* mm R/Bal: *7* mm

L/Bal: _____ mm L/Bal: _____ mm

D.O.A: *18/5/18* D.O.I: *22/6/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s frt, o/s body, etc.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*LTA #7659 max**25/6/18* *1:25* *max* *Tow shouldn't be given; Repairer (Max) agree**29/6/18* *Agree by surveyor & repairer to provide cost price est upon finalise*
*Sent authorise repair email to repairer.**5/9/18* *Called Max, vehicle still under repair; Pending for spare parts (2-3 weeks)**5/9/18* *Rachel called said when finalise offer repairer all-in \$6900 (if not, then only ask for best offer. If unnegotiable, inform Rachel Rachel will take over the case)**30/10/18* *4/5 \$10500 confirmed with patrick. 2pm. (Red: \$9600, 48%).*

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: *8**1) typist*☒ : Final ReportResurvey No. of Trip: *2*

Date/Time, File Return to?

*2)*Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee

Transportation

\$ - RS \$

Photos

Others

TOTAL

Report Format: *OD*Lump Sum / L.B.: (\$ *10,500.00*)*450**450*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18011366/Urd3

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 22-06-2018



Code : GAI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	FBM 6484E
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVM000000275	Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	22/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	18/05/2018	Inspection Date	22/06/2018
Survey held at	DE XING MOTOR PTE LTD BLK 3006 UBI ROAD 1 #01-356 SINGAPORE 408700		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Friday, 22 June 2018 11:50 AM
To: angela_dexing3@yahoo.com.sg
Cc: LKK Assignments; TENARISK Wendy; Tenarisk Andy; waiwai
Subject: FW: CLMOMVM000000275] FBM6484E OD CLAIMS
Attachments: FBM6484E0001.pdf; FBM6484E_18052018.pdf

Dear Mrs Loo
We will arrange for LKK to conduct survey.

Dear LKK
Please accept assignment. Attached estimates and GIA report.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Mrs Loo <angela_dexing3@yahoo.com.sg>
Sent: Friday, June 22, 2018 8:48 AM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: TENARISK Wendy <wendytan@tenarisk.com>; Tenarisk Andy <andytan@tenarisk.com>; waiwai <waiwaidx@gmail.com>
Subject: [External] CLMOMVM000000275] FBM6484E OD CLAIMS

Dear Madam,

We need the price quotation from the parts supplier as the model to the bike is new. Most of the parts need to be air flown.

Please arrange for surveyor.

Thanks & regards.

Mrs Loo
DE XING MOTOR PTE LTD
TEL: 67468582

----- Original Message -----

From: Tan, Rachel
To: Mrs Loo
Sent: Thursday, June 21, 2018 8:55 AM
Subject: CLMOMVM000000275] FBM6484E OD CLAIMS

Dear Mrs Loo

Claim No : CLMOMVM000000275
It has been more than 14 days from the Date of accident. Why now claiming OD?

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Mrs Loo <angela_dexing3@yahoo.com.sg>
Sent: Wednesday, June 20, 2018 5:03 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Subject: [External] FBM6484E OD CLAIMS

Dear Madam,

Please arrange for surveyor.

Thanks & regards

Mrs Loo
DE XING MOTOR PTE LTD
TEL: 67468582

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CLM0MVM000000275

Date: 22 June 2018

Our Ref: CS/GAI18011366/Urd3

The Motor Claims Department
GREAT AMERICAN INSURANCE COMPANY

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. FBM 6484E .


We thank you for the instruction on 22/06/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle 22/06/2018 at the premises of m/s: DE XING MOTOR PTE LTD and have the following to report:-

Repairer's Estimate (Gross)	: S\$ 18,928.00 .
Revised Estimate Amount	: S\$ 10,510.20 .
"Check" Items (Estimated)	: S\$ 4,976.80 .
Total Repair cost (Estimated)	: S\$ 15,487.00 .
Pre-Accident Value	: S\$ 26,000.00 .
COE/PARF value	: S\$ 7,659.00 .
Nett Value	: S\$ 18,341.00 .

Description of Damage:

The vehicle sustained damages
at the o/s body n/s front and front portion.



Comment:

We have not authorize repair.

Repair day: 8 days

Yours faithfully
MARCUS
Automotive Assessor

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Friday, June 22, 2018 3:19 PM
To: 'Tan, Rachel'
Cc: SUR
Subject: RE: CLMOMVM000000275] FBM6484E OD CLAIMS
Attachments: FBM 6484E GAI OD.pdf

Dear Rachel,

Enclosed preliminary advice FBM 6484E.
Repair day: 8 days

We have not authorize repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, June 22, 2018 12:10 PM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: CLMOMVM000000275] FBM6484E OD CLAIMS

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Friday, 22 June 2018 11:50 AM
To: angela_dexing3@yahoo.com.sg
Cc: LKK Assignments <assignments@lkkauto.com>; TENARISK Wendy <wendytan@tenarisk.com>; Tenarisk Andy <andytan@tenarisk.com>; waiwai <waiwaidx@gmail.com>
Subject: FW: CLMOMVM000000275] FBM6484E OD CLAIMS

Dear Mrs Loo

We will arrange for LKK to conduct survey.

Dear LKK

Please accept assignment. Attached estimates and GIA report.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Mrs Loo <angela_dexing3@yahoo.com.sg>

Sent: Friday, June 22, 2018 8:48 AM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Cc: TENARISK Wendy <wendytan@tenarisk.com>; Tenarisk Andy <andytan@tenarisk.com>; waiwai <waiwaidx@gmail.com>

Subject: [External] CLMOMVM000000275] FBM6484E OD CLAIMS

Dear Madam,

We need the price quotation from the parts supplier as the model to the bike is new. Most of the parts need to be air flown.

Please arrange for surveyor.

Thanks & regards.

Mrs Loo

DE XING MOTOR PTE LTD

TEL: 67468582

----- Original Message -----

From: Tan, Rachel

To: Mrs Loo

Sent: Thursday, June 21, 2018 8:55 AM

Subject: CLMOMVM000000275] FBM6484E OD CLAIMS

Dear Mrs Loo

Claim No : CLMOMVM000000275

It has been more than 14 days from the Date of accident. Why now claiming OD?

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Mrs Loo <angela_dexing3@yahoo.com.sg>

Sent: Wednesday, June 20, 2018 5:03 PM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Subject: [External] FBM6484E OD CLAIMS

Dear Madam,

Please arrange for surveyor.

Thanks & regards

Mrs Loo
DE XING MOTOR PTE LTD
TEL: 67468582

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Janice Lee (LKKAUTO)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Friday, June 22, 2018 6:07 PM
To: Janice Lee (LKKAUTO)
Cc: SUR
Subject: RE: CLMOMVM000000275] FBM6484E OD CLAIMS

Hi Janice

Please check if workshop can repair at Lump sum basis, and how much

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Sent: Friday, June 22, 2018 3:19 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: [External] RE: CLMOMVM000000275] FBM6484E OD CLAIMS

Dear Rachel,

Enclosed preliminary advice FBM 6484E.
Repair day: 8 days

We have not authorize repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, June 22, 2018 12:10 PM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: CLMOMVM000000275] FBM6484E OD CLAIMS

Dear Sir/Mdm,

Thank you for the assignment.

Janice Lee (LKKAUTO)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Monday, June 25, 2018 5:46 PM
To: Janice Lee (LKKAUTO)
Cc: SUR
Subject: RE: CLMOMVM000000275 - FBM6484E OD CLAIMS

Hi Janice

Please proceed. Excess \$750

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Sent: Monday, June 25, 2018 12:25 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: [External] RE: CLMOMVM000000275 - FBM6484E OD CLAIMS

Dear Rachel,

Enclosed amend preliminary advice for **FBM 6484E**.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Monday, June 25, 2018 12:09 PM
To: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: CLMOMVM000000275 - FBM6484E OD CLAIMS

Hi Janice

Towing fee \$35 given ? Shouldn't be.
Please amend on prelim report and send over.

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Friday, June 29, 2018 11:22 AM
To: 'dxmotor@singnet.com.sg'
Cc: SUR; 'waiwaidx@gmail.com'
Subject: FBM 6484E GAI OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **FBM 6484E (excess \$750/-)**. Please note that **the authorise is based on cost price.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CLM0MVM000000275

Date: 10 October 2018

Our Ref: CS/GAI18011366/Urd3

The Motor Claims Department
GREAT AMERICAN INSURANCE COMPANY

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. FBM 6484E .


We thank you for the instruction on 22/06/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle 22/06/2018 at the premises of m/s: DE XING MOTOR PTE LTD and have the following to report:-

Repairer's Estimate (Gross)	: <u>S\$ 20,100.00(Include Supplementary \$1,172.00).</u>
Revised Estimate Amount	: <u>S\$ 13,182.14(Include check item and supp).</u>
"Check" Items (Estimated)	: <u>S\$ _____.</u>
Total Repair cost (Estimated)	: <u>S\$ 13,182.14 _____.</u>
Pre-Accident Value	: <u>S\$ 26,000.00 _____.</u>
COE/PARF value	: <u>S\$ 7,659.00 _____.</u>
Nett Value	: <u>S\$ 18,341.00 _____.</u>

Description of Damage:

The vehicle sustained damages
at the o/s body n/s front and front portion.



Comment:

Repair day: 8 days

Yours faithfully

MARCUS

Automotive Assessor

Janice Lee (LKKAUTO)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Thursday, October 11, 2018 6:24 PM
To: Janice Lee (LKKAUTO)
Subject: RE: URGENT - OD SURVEY (CLMOMVM000000275 ; FBM6484E)

Hi Janice

Thank you, please proceed as per your recommendation. Excess \$750/-.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Sent: Wednesday, October 10, 2018 2:56 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Subject: [External] RE: URGENT - OD SURVEY

Dear Rachel,

Enclosed preliminary revised after resurvey.

This vehicle repair on Lump sum basis

The amount revised after resurvey is Lump Sum \$10,500.00.

Kindly let us have your approval and advice.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAUTO)
Sent: Thursday, September 20, 2018 11:33 AM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: URGENT - OD SURVEY

Dear Rachel,

Enclosed photo for FBM 6484E

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/05/2018 18:39
Date Of Accident	18/05/2018 07:30
Exact Location Of Accident	ALONG TOH GUAN EAST ROAD TOWARDS OLD TOH TUCK ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBM6484E
Insured/Policyholder	
Name Of Registered Owner	AMIR MUZAKKIR BIN ABDUL HAMID
NRIC No	S9050996I
Email Address	AMIRMUZAKKIR90@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91814585
Alternative Phone No	OFFICE-91814585
Vehicle Particulars	
Manufacturer	YAMAHA
Model	MT-09-847CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MOMVM000002326-00-000
Cover Note Number	
Driver	
Name of Driver	AMIR MUZAKKIR BIN ABDUL HAMID
NRIC No	S9050996I
Date Of Birth	24/12/1990
Occupation	INDOOR
Date Of Driving Pass	22/04/2009
Driving Experience	9 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91814585
Fax Number	
Contact Number	OFFICE-91814585
Email Address	AMIRMUZAKKIR90@GMAIL.COM

Address	BLK 347 WOODLANDS AVE 3 #11-111
Postcode	730347
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT PANJANG NORTH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 27 MARSILING DRIVE , POSTCODE: 730027 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-3689999 - FAX NO: 63682383
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GR8371Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	KATHAN RAMACHANDRAN
NRIC/Passport Number	G8318494P
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	YN3541R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	NG TIAN DAO
NRIC/Passport Number	S8329359D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	AMIR MUZAKKIR BIN ABDUL HAMID
Approximate Age	27
Injuries Sustain	PARTS OF LIMBS
Injured person in which vehicle?	FBM6484E
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 347 WOODLANDS AVE 3 #11-111
Postcode	730347

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 21/05/18
1250 hrs

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Tol Quan Rd East toward Old Tol Truck Rd
→

→

Weather condition: Clear
Road surface: Dry
Phone no.: 91814585
Email: amir.muzakkir90@gmail.com.

I/We declare the foregoing particulars are true in every respect.

BIRMINGHAM, Ala. (AP) —

Date & Time:

NRIC/FIN No.:

CERTIFICATE OF INSURANCE

- Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) - Motor Vehicles (Third Party Risks and Compensation) Rules, 1960
- Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia)

Policy Details

Certificate Number	: MOMVM000002326-00-000	Cover	: Motor Cycle (Comprehensive)
Policyholder Name	: Amir Muzakkir Bin Abdul Hamid	Chassis Number	: JYARN438000010639
NCD Entitlement	: 15% No Claim Discount	Engine Number	: N701E098573
Hire Purchase	: DE XING MOTOR PTE. LTD.	Registration Number	: FBM6484E
Period of Insurance	: From 19/01/2018 (00:00) To 18/01/2019 (23:59) (Both Dates Inclusive)		

Persons or Classes of Persons entitled to Drive

- a) The Primary Rider
- b) Any Named Rider as stated in the policy

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor or so has been Vehicle permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

Limitations as to Use

Use only for social, domestic and pleasure purposes and for Policyholder's business

This Policy does not cover:

- a) Use for Hire and Reward
- b) Use for racing, pace making, reliability trial or speed testing
- c) Use for carriage of goods (other than samples) in connection with any trade of business
- d) Use for any purpose in connection with Motor Trade

This Bike is Still Under
Hire Purchase with
DE XING MOTOR PTE LTD
No addrider or renewal
is allowed

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987(Malaysia), are not to be included under these headings

Excess (Section 1)	: SGD 750.00 - including Fire & Theft outside Singapore
Excess (Section 2)	: N/A


Driver Details

Primary Rider	: Amir Muzakkir Bin Abdul Hamid
Named Rider 1	: Amir Muhammad Bin Abdul Hamid
Named Rider 2	: N/A
Name of Intermediary	: Tena Risk Solutions Pte Ltd
Date of Issue	: 06/03/2018

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Signed for and on behalf of

Great American Insurance Company



Authorised Signatory

m1ow

德兴摩托私人有限公司
DE XING MOTOR PTE. LTD.
BLOCK 3006 UBI ROAD 1 #01-356, SINGAPORE 408700
TEL: 6746 8582 (3 LINES) FAX: 6743 9525
GST Reg. No. M2-0061652-9
RCB No. 198303312R

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0996I
Vehicle Details	
Vehicle No.:	FBM6484E
Vehicle to be Exported:	No
Intended De-registration Date:	22 Jun 2018
Vehicle Make:	YAMAHA
Vehicle Model:	MT-09 ABS TRACER
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	N701E098573
Chassis No.:	JYARN438000010639
Maximum Power Output:	-
Open Market Value:	\$10,151.00
Original Registration Date:	19 Jan 2018
First Registration Date:	19 Jan 2018
Transfer Count:	1
Actual ARF Paid:	\$3,401.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jan 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$8,001.00
COE Rebate Amount:	\$7,659.00
Total Rebate Amount:	\$7,659.00

The information contained herein is correct as at 22 Jun 2018

OK




Make or Model

Type
Any

Price From
Any

Price To
Any

Class
Any

Q SEARCH  VIEW ALL (/LISTING/NEWBIKES/LISTING/)

Q SEARCH 



REPORT ERROR  (/LISTING/LISTING/ERROR/NEWBIKE/262/)  ADD TO SHORTLIST

Like 0

Share

 SHARE (WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/NEWBIKE/YAMAHA-YAMAHA-MT-09/262/)



德興摩哆私人有限公司

DE XING MOTOR PTE. LTD.

Blk 3006 Ubi Road 1 #01-356 Singapore 408700
Tel : (65) 67468582 (4 Lines) Fax : (65) 67439525
Email : dxmotor@singnet.com.sg
Website : www.dxmotor.com
Co. Reg. No.: 198303312R



() Third-Party

(X) Own Damage

() List Price

() Cost Price

Bike No : FBM6484E (2SCL-060B)

Date of Acc : 19/05/2018

Make/ Model : YAMAHA MT-09 TRACER

Chassis No : JYARN438000010639

Year : 2017

Requested by : MR PATRICK

Not Authorise
nklr
naous
TU:62583581
EXCESS?
22/6/18
7-hephhs After repair with

S/ NO	Parts Description	Quantity	Unit Price	Total	Remarks
1	HANDLE BAR	1	\$192.00	\$192.00	Get ✓
2	RH/ LH HANDLEBAR BALANCER	2	\$60.00	\$120.00	O/S CU 1pc RH
3	TOP FORK BRACKET	1	\$400.00	\$400.00	Buy ✓
4	LOWER FORK BRACKET	1	\$608.00	\$608.00	Buy ✓
5	RH/LH FORK ASSEMBLY <i>mskl</i>	2	\$1,040.00	\$2,080.00	mskl O/S 2pc ✓
6	FRONT WHEEL RIM	1	\$768.00	\$768.00	10/3rd ✓
7	FRONT SHAFT	1	\$56.00	\$56.00	Buy ✓
8	RH/ LH FRONT DISC	2	\$204.80	\$409.60	Buy ✓
9	RH/ LH FRONT BRAKE CALIPER	2	\$512.00	\$1,024.00	CU ✓
10	FRONT MUDGUARD	1	\$208.00	\$208.00	CU ✓
11	METER ASSEMBLY	1	\$880.00	\$880.00	TA X
12	METER BRACKET	1	\$192.00	\$192.00	Tw ✓
13	HEADLAMP ASSEMBLY	1	\$1,040.00	\$1,040.00	CN ✓
14	RH/ LH HEADLAMP BRACKET	2	\$198.00	\$396.00	3rd ✓
15	FRONT HEADLIGHT COVER	1	\$105.00	\$105.00	CN ✓
16	FRONT TOP HEADLIGHT COVER	1	\$165.00	\$165.00	CU ✓
17	RH/ LH MIRROR	2	\$64.00	\$128.00	SCN/3rd ✓
18	BRAKE LEVER	1	\$78.00	\$78.00	Buy ✓
19	CLUTCH LEVER	1	\$78.00	\$78.00	17 X
20	RADIATOR ASSEMBLY	1	\$464.00	\$464.00	RM X
21	COOLANT RESERVIOR	1	\$35.20	\$35.20	17 X
22	RH FRONT SIGNAL	1	\$65.00	\$65.00	CU ✓
23	FRONT EXHAUST PIPE	1	\$1,440.00	\$1,440.00	10/3rd ✓
24	EXHAUST PIPE GASKET	4	\$8.00	\$32.00	CU ✓
25	MAINSTAY	1	\$208.00	\$208.00	2 X
26	SIDE STAY	1	\$72.00	\$72.00	17 X
27	RH FRONT FOOTREST	1	\$25.60	\$25.60	3rd ✓
28	RH FRONT FOOTREST BRACKET	1	\$40.00	\$40.00	Buy ✓
29	BRAKE PEDAL	1	\$72.00	\$72.00	Buy ✓
30	RH/ LH REAR SIDE COVER	2	\$240.00	\$480.00	2 X
31	RH/ LH HAND GUARD COVER	2	\$98.00	\$196.00	D.S ✓
32	RH/ LH FUEL TANK COVER <i>cm</i>	2	\$285.00	\$570.00	o/s 2pc RH ✓
33	LH COIL	1	\$480.00	\$480.00	RM X
34	LH COIL COVER	1	\$144.00	\$144.00	RM X
35	LH COIL GASKET	1	\$20.80	\$20.80	RM X
36	RH/ LH INNER CENTRE COVER	2	\$155.00	\$310.00	2nd ✓
37	RH/ LH INNER FRONT COVER	2	\$185.00	\$370.00	2nd ✓

102



德興摩哆私人有限公司 DE XING MOTOR PTE. LTD.

Blk 3006 Ubi Road 1 #01-356 Singapore 408700
Tel : (65) 67468582 (4 Lines) Fax : (65) 67439525
Email : dxmotor@singnet.com.sg
Website : www.dxmotor.com
Co. Reg. No.: 198303312R



CERT Reg No.: 2005-2-1439
ISO 9001: 2008

38	RH/ LH FRONT SIDE COVER	2	154	\$155.00	\$310.00	o/s on 1pc
39	RH/ LH FRONT SIDE COVER LOGO (YAMAHA)	2		\$22.00	\$44.00	ru
40	FRONT BRAKE PIPE	3		\$78.00	\$234.00	70 in 2 pcs 156
41	WINDSHIELD	1		\$240.00	\$240.00	cu
42	RH REAR HANDLEBAR	1		\$175.00	\$175.00	cu
43	RH CLUTCH COVER	1		\$144.00	\$144.00	at x 7m
44	RH CLUTCH COVER GASKET	1		\$20.80	\$20.80	at x 7m
45	RH CENTRE COVER	1		\$185.00	\$185.00	2pc
46	FRONT OUTER FUEL TANK COVER	1		\$265.00	\$265.00	2x
47	STEERING CONE ASSEMBLY	1		\$120.00	\$120.00	ru
48	FRONT BEARING	2		\$55.00	\$110.00	ru
49	COOLANT	1		\$80.00	\$80.00	ru 50%
50	RH/ LH CRASHBAR	2		\$320.00	\$640.00	cu 7 NIX
51	ENGINE OIL	4		\$120.00	\$480.00	ru 70% 50%
52	FRONT TYRE	1		\$180.00	\$180.00	pu 70%
53	REAR BOX	1		\$480.00	\$480.00	mis NIX
54	REAR BOX BRACKET	1		\$40.00	\$40.00	bul NIX
55	FRONT RIM SLIDER	1		\$220.00	\$220.00	cu 7 NIX
56	NUMBER PLATE	1		\$8.00	\$8.00	ru
57	LABOUR			\$950.00	\$950.00	200 800
58	TOW		70c	\$50.00	\$50.00	35x
59	engine oil sump		one 50c			
60	oil sump gasket		ru 25c			
	oil filter		DD 22			

oil cooler

no 620

Sub Total
Add 7% GST

\$18,928.00
\$1,324.96

Grand Total

\$20,252.96

Merch

90096608

20100

9640 8270

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE, SHOULD THERE BE ANY ADDITIONAL PARTS REQUIRED OR DAMAGED DURING OUR COURSE OF REPAIRS, WE WILL INFORM YOU ACCORDINGLY FOR NECESSARY ACTION. PRICES OF PARTS QUOTED ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE.

APPROVING OFFICER'S SIGNATURE & COMPANY'S STAMP

UK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Friday, October 12, 2018 12:33 PM
To: dxmotor@singnet.com.sg
Cc: SUR; waiwaidx@gmail.com; Marcus Chua (LKKAUTO)
Subject: RE: FBM 6484E GAI OD

Dear Patrick/ Max,

The amount of L/S \$10,500.00 (before excess) @ 8 Days has been approved by insurance.

Kindly let us have your confirmation.

Please arrange re-survey for after repair.

Any query, please contact Marcus directly

Thank you.

*Kindly acknowledge if you have received this email.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAUTO)
Sent: Friday, June 29, 2018 11:22 AM
To: dxmotor@singnet.com.sg
Cc: SUR <sur@lkkauto.com>; waiwaidx@gmail.com
Subject: FBM 6484E GAI OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **FBM 6484E (excess \$750/-)**. Please note that the authorise is based on cost price.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY			Ref : CS/GAI18011366/Urd3e2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date : 22-11-2018	
			Code : GAI	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		FBM 6484E
Policy No.	MOMVM000002326-00-000	Coverage (\$)	0.00	
Claim No.	CLMOMVM000000275	Excess (\$)	750.00	
Assign From	RACHEL TAN	Assign Date	22/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA MT-09	c.c	847	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JYARN438000010639	Colour	BLUE	
Odometer	7190	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70Z R17	BRIDGESTONE	7 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	180/55Z R17	BRIDGESTONE	7 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY, N/S FRONT AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/05/2018	Inspection Date	22/06/2018	
Survey held at	DE XING MOTOR PTE LTD BLK 3006 UBI ROAD 1 #01-356 SINGAPORE 408700			
5a. Remarks				
A)THE MARKET VALUE IS S\$26,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 6484E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	BENT	192.00	192.00
2	RH / LH HANDLEBAR BALANCER @\$60.00	O/S CUT	120.00	60.00
1	TOP FORK BRACKET	BENT	400.00	400.00
1	LOWER FORK BRACKET	BENT	608.00	608.00
2	RH/LH FORK ASSEMBLY @\$1040.00	N/S BENT / O/S DENTED	2,080.00	2,080.00
1	FRONT WHEEL RIN	DENTED / BENT	768.00	768.00
1	FRONT SHAFT	BENT	56.00	56.00
2	RH/LH FRONT DISC @\$204.80	BENT	409.60	409.60
2	RH/LH FRONT BRAKE CALIPER @\$512.00	CUT	1,024.00	1,024.00
1	FRONT MUDGUARD	CUT	208.00	208.00
1	METER ASSEMBLY	NOT NECESSARY	880.00	-
1	METER BRACKET	TWISTED	192.00	192.00
1	HEADLAMP ASSEMBLY	CRACKED	1,040.00	1,040.00
2	RH/LH HEADLAMP BRACKET @\$198.00	BENT	396.00	396.00
1	FRONT HEADLIGHT COVER	CRACKED	105.00	105.00
1	FRONT TOP HEADLIGHT COVER	CUT	165.00	165.00
2	RH/LH MIRROR @\$64.00	SCRATCHED / BROKEN	128.00	128.00
1	BRAKE LEVER	BENT	78.00	78.00
1	CLUTCH LEVER	NOT NECESSARY	78.00	-
1	RADIATOR ASSEMBLY	NOT NECESSARY	464.00	-
1	COOLANT RESERVOIR	NOT NECESSARY	35.20	-
1	RH FRONT SIGNAL	CUT	65.00	65.00
1	FRONT EXHAUST PIPE	DENTED / BENT	1,440.00	1,440.00
4	EXHAUST PIPE GASKET @\$8.00	NECESSARY	32.00	32.00
1	MAINSTAY	TO REPAIR SEE LABOUR	208.00	-
1	SIDE STAY	NOT NECESSARY	72.00	-
1	RH FRONT FOOTREST	BROKEN	25.60	25.60
1	RH FRONT FOOTREST BRACKET	BENT	40.00	40.00
1	BRAKE PEDAL	BENT	72.00	72.00

Report Ref No. CS/GAI18011366/Urd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	RH/LH REAR SIDE COVER @\$240.00	TO REPAIR SEE LABOUR	480.00	-
2	RH/LH HAND GUARD COVER @\$98.00	DISTORTED	196.00	196.00
2	RH/LH FUEL TANK COVER @\$285.00	CRACKED	570.00	570.00
1	LH COIL	NOT NECESSARY	480.00	-
1	LH COIL COVER	NOT NECESSARY	144.00	-
1	LH COIL GASKET	NOT NECESSARY	20.80	-
2	RH/LH INNER CENTRE COVER @\$155.00	CRACKED	310.00	310.00
2	RH/LH INNER FRONT COVER @\$185.00	CRACKED	370.00	370.00
2	RH/LH FRONT SIDE COVER @\$155.00	O/S CRACKED / N/S NOT NECESSARY	310.00	155.00
2	RH/LH FRONT SIDE COVER LOGO (YAMAHA) @\$22.00	NECESSARY	44.00	44.00
3	FRONT BRAKE PIPE @\$78.00	TORN-2PCS ONLY	234.00	156.00
1	WINDSHIELD	CUT	240.00	240.00
1	RH REAR HANDLEBAR	CUT	175.00	175.00
1	RH CLUTCH COVER	NOT NECESSARY	144.00	-
1	RH CLUTCH COVER GASKET	NOT NECESSARY	20.80	-
1	RH CENTRE COVER	CRACKED	185.00	185.00
1	FRONT OUTER FUEL TANK COVER	TO REPAIR SEE LABOUR	265.00	-
1	STEERING CONE ASSEMBLY	NECESSARY	120.00	120.00
2	FRONT BEARING @\$55.00	NECESSARY	110.00	110.00
2	RH/LH CRASHBAR @\$320.00 (CUT)	NOT INSURED	640.00	-
1	REAR BOX (MISSING)	NOT INSURED	480.00	-
1	REAR BOX BRACKET (BENT)	NOT INSURED	40.00	-
1	FRONT RIM SLIDER (CUT)	NOT INSURED	220.00	-
1	ENGINE OIL SUMP	CRACKED	505.00	505.00
1	OIL SUMP GASKET	NECESSARY	25.00	25.00
1	OIL FILTER	DENTED	22.00	22.00
1	OIL COOLER	DENTED	620.00	620.00
	LESS 10% DISCOUNT		-	-1,338.72
			18,352.00	12,048.48
	<u>SPECIAL NETT ITEMS</u>			
1	COOLANT (SN) (50%)	NECESSARY	80.00	40.00

Report Ref No. CS/GAI18011366/Urd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	ENGINE OIL @\$120.00 (SN)	NECESSARY	480.00	90.00
1	FRONT TYRE (SN) (70%)	PUNCTURE	180.00	126.00
1	NUMBER PLATE (SN)	NECESSARY	8.00	8.00
			748.00	264.00
	LABOUR			
	LABOUR. INCLUSIVE OF THE REPAIR OF MAINSTAY, RH/LH REAR SIDE COVER AND FRONT OUTER FUEL TANK COVER.		950.00	800.00
	TOW.	NOT NECESSARY	50.00	-
			1,000.00	800.00
GRAND TOTAL			20,100.00	13,112.48

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,500.00
LESS EXCESS			-750.00
NETT LIABILITY			9,750.00

Report Ref No. CS/GAI18011366/Urd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.