

ASS. REC. BY:

REF:

CS/AWA18011367/RISD3027

Special Instruction:

Surveyor:

RASHI

ASSIGNMENT (Office)

From (Person):

Stella Goh

of

AWAC

Date/Time:

22/6/18 @ 11:10am

Estimated Cost:

Bill to:

OD

TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLX 7175P

Insured:

YN 5410Y

at Workshop m/s

SK Automobile

Tel:

G784 5155

of

23 Kaki Bukit Ave 4 # 03-01

Policy No:

Claim No:

YN5410Y/BT

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/06/2018

CA / REV / REP. / REV 24 HRS

'wp'

Date/Time:

11-15am @ 22/6/18

Person Contacted:

Huey Lee

H.O.D. Endorsement:

Vehicle

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLX 7175P-X

YN 5410Y - NAIMSG 14019395 / n4

DOA: 13/10/2014

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLX 7175P
 at Workshop m/s: SK Automobile
 of 23, KORE MINT AVE 4 # 03-01
 Insured: ANA / TP / up
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLX 7175P Yr Regn: 2018 / APR
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai ELANTRA 1.6 c.c. 1591
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 2572 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMHD841CMJU646634
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or MAXXEN
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 20/06/18 D.O.I. 22/06/18
 Survey held at SK Automobile
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FRONT N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/11/18 Confirmed P/P \$ 2,802.40 @ 2 days with Rasul.
 (\$ 550/- Rd - 17%)

RECEIVED 30 NOV 2018

Date/Time, File Pass to?

30/11/18

1) Typist

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others:

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 2,802.40 P/PAdd Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

150

150

Nivitha (LKK Auto)

From: Goh, Stella <stella.goh@awac.com> on behalf of Motorsurvey
<Motorsurvey@awac.com>
Sent: Friday, 22 June 2018 11:10 AM
To: assignments@lkkauto.com
Cc: sur@lkkauto.com; SK Admin
Subject: TP Survey assignment for SLX7175P DOA: 20.06.2018 Our ref: YN5410Y/BT

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us have consensus in the appointment of Mr Adrian Ling as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

| | | |
|-------------------------------|---|-----------------------|
| 3 rd Party Vehicle | : | SLX 7175 P |
| Insured Vehicle | : | YN 5410 Y |
| Policy Number | : | AVCPSB0087351700 |
| Name of Workshop | : | SK AUTOMOBILE PTE LTD |
| Contact Number | : | 6789 5155 |
| Person to Contact | : | MS HUEY LEE |
| Estimated Cost of repairs | : | NA |

Regards,
Claims Division

Copy to SK Automobile Pte Ltd (Your Ref: SLX7175P) via Email.

Note -

- (X)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards
Motor Claims
Claims Group

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3227C

Vehicle Details

Vehicle No.: SLX7175P
Vehicle to be Exported: Yes
Intended De-registration Date: 21 Jun 2018
Vehicle Make: HYUNDAI
Vehicle Model: ELANTRA AD 1.6 GLS AT (AMS)
Primary Colour: Blue
Manufacturing Year: 2018
Engine No.: G4FGJU150774
Chassis No.: KMHD841CMJU646634
Maximum Power Output: 93.8 kW (125 bhp)
Open Market Value: \$11,641.00
Original Registration Date: 07 Apr 2018
First Registration Date: 07 Apr 2018
Transfer Count: 0
Actual ARF Paid: \$11,641.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 06 Apr 2028
PARF Rebate Amount: \$8,730.00

Intended COE Rebate Details

COE Expiry Date: 06 Apr 2028
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$38,830.00
COE Rebate Amount: \$31,064.00
Total Rebate Amount: \$39,794.00

The information contained herein is correct as at 21 Jun 2018

OK



SAVE UP TO \$20,000 ON OUR
BEST SELLERS BEFORE VES ON 1 JULY

BOOK A TEST DRIVE >



JAGUAR

T&Cs apply

Hyundai Elantra

Min Price ▼ to No Max ▼

Depreciation ▼

Vehicle Type ▼

Category ▼

Advanced Search

Home » New Cars » Hyundai Elantra Search Results

Hyundai Elantra Search Results (1 vehicles)

Sort by Model (Ascending) ▼ 15 ▼ results/page

| Car Model | Price | Dealer | Built In | User Rating |
|---|--|-----------------------------------|----------|-----------------|
| Hyundai Elantra | | Komoco Motors | Korea | 26 User Reviews |
|  360° | 1.6 GLS (A) \$79,999 \$7,400 /yr ? | * 15.6km/l 126bhp 6-speed (A) | | Editor's Review |
| | 1.6 GLS "S" (A) \$83,999 | * 15.6km/l 126bhp 6-speed (A) | | |
| | 1.6 GLS Elite (A) \$87,999 | * 15.6km/l 126bhp 6-speed (A) | | |

| Car Model | Price | Dealer | Built In | User Rating |
|-----------|-------|--------|----------|-------------|
| | | | | |

15 ▼ results/page

2 result(s) for **Hyundai Elantra** models no longer being sold by local distributors
View all [past Hyundai cars](#)



Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 30 November 2018 3:56 PM
To: 'SK Admin'; SUR; Rasul (LKKAuto); Admin A
Cc: 'simon koh'; 'JING XIONG KHOO'; 'Julie Johari'; 'KY Leong'
Subject: RE: SLX7175P -Pending Finalisation

Dear Huey Lee,

Confirmed final fig \$ 2,802.40 (part by part) @ 2 days of repairs before GST.

Final invoice and all supporting documents sent over to Allied World.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: SK Admin [mailto:admin@skauto.com.sg]
Sent: Thursday, 29 November 2018 10:06 AM
To: SUR <sur@lkkauto.com>; rasul@lkkauto.com; Admin A <admin-a@lkkauto.com>
Cc: simon koh <simon@skauto.com.sg>; JING XIONG KHOO <xionskauto@gmail.com>; Julie Johari <julie@skauto.com.sg>; KY Leong <kyleong@skauto.com.sg>
Subject: SLX7175P -Pending Finalisation

Dear Shirley / Rasul,

Vehicle No. : SLX7175P
D.O.A : 20/06/2018
Date of Inspection : 22/06/2018

| | |
|-------------|---------------|
| Part (-20%) | : \$ 2,342.40 |
| S/Nett | : \$ 30.00 |
| Labour | : \$ 430.00 |
| Total | : \$ 2,802.40 |

Refer to the above matter, attached before paint photos for your reference.

Kindly assist us to finalize.

Thanks for your kind attention.

--

Regards,
Huey Lee

SK Automobile Pte Ltd

• *Tel: 6789 5155 Fax: 6783 5155*

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by Interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---|
| Date Of Report | 21/06/2018 14:48 |
| Date Of Accident | 20/06/2018 16:00 |
| Exact Location Of Accident | OPEN SPACE CARPARK AT BLK 201D TAMPINES ST 21 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|--|--------------------------|
| Vehicle Registration Number | SLX7175P |
| Insured/Policyholder | |
| Name Of Registered Owner | MANIKAM SUPRAMANIAM |
| NRIC No | S0073227C |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-84840426 |
| Alternative Phone No | OFFICE-84840426 |
| Vehicle Particulars | |
| Manufacturer | HYUNDAI |
| Model | ELANTRA-1.6 AD GLS (A) |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own Insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | EQ INSURANCE COMPANY LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | DMPPHQ18-002090 |
| Cover Note Number | |
| Driver | |
| Name of Driver | MANIKAM SUPRAMANIAM |
| NRIC No | S0073227C |
| Date Of Birth | 14/07/1953 |
| Occupation | INDOOR |
| Date Of Driving Pass | 07/03/1983 |
| Driving Experience | 35 YEARS AND 3 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-84840426 |
| Fax Number | |
| Contact Number | OFFICE-84840426 |
| Email Address | NOEMAIL |

Address BLK 715 PASIR RIS ST 72 #04-21
 Postcode 510715
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - OPENING DOOR OF VEHICLE
 Weather Conditions DRIZZLING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACHED REPORT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN5410Y
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA (Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of this report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be filed outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRUC/TIN No.:



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20.06.2018 at about 16:00hrs, I was parking my vehicle at Open Space Carpark @ BLK 201D Tampines st 21. As I approaching my vehicle, I saw a long YN 6410Y had blocked my view. I approached the driver to move. As he finish loading/unloading his delivery, he moved very fast and forget to close his back door. The door swing off and hit onto my front vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

CPD Form 57-1 (Revised 01/18)



SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4 #03-01
Vicom Inspection Centre
Singapore 415933
Tel: 6789 5155 Fax : 6783 5155

| | | | |
|---|---------------------|------------------------|-------------------|
| TO | : AWAC | DATE | : 21-Jun-18 |
| ATTENTION | : MOTOR CLAIMS DEPT | JOB TYPE | : T/P CLAIM |
| ESTIMATE REPORT | : | | |
| <u>OWNER'S PARTICULAR</u> | | <u>VEHICLE DETAILS</u> | |
| NAME | : | VEHICLE NO | : SLX7175P |
| ADDRESS | : | MODEL | : HYUNDAI ELANTRA |
| TEL. NO. | : | CHASSIS NO | : |
| OWNER'S INSURANCE | : | | |
| POLICY NO. | : | | |
| <u>ACCIDENT DETAILS</u> | DATE : | | |
| | TIME : | | |
| THIRD PARTY REQUESTOR / CONTACT : DAUD / 93911482 | | | |

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

| S/N | DESCRIPTION | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|-------------------|-----|-----------------|------------------|
| 1 | BONNET | 1 | \$ 1,125.00 | \$ 1,125.00 |
| 2 | FRONT BONNET SEAL | 1 | \$ 58.00 | \$ 58.00 |
| 3 | HEADLAMP LH | 1 | \$ 1,745.00 | \$ 1,745.00 |

TOTAL PRICE \$ 2,928.00
LESS 20% \$ 585.60
SUB TOTAL PRICE \$ 2,342.40

| S/N | DESCRIPTION | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|----------------------------|-----|-------------|--------------|
| 1 | BONNET INSULATOR CLIPS SET | 1 | \$ 50.00 | \$ 30 50.00 |

TOTAL \$ 50.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

| | | | | |
|---|---|-----------|-----|--|
| 1 | SUPPORT PANEL. RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS. | \$ 400.00 | 200 | |
| 2 | SPRAY PAINTING ON DAMAGE AND AFFECTED AREA. | \$ 400.00 | 200 | |

| | | | | |
|---|--|----|------------------|-----|
| | ADJUST AND FOCUS FRONT LIGHTING SYSTEM. PERFORM HEADLAMP | | | |
| 3 | ADJUSTMENT TO POSITION | \$ | 80.00 | 30 |
| | REMOVE AND INSTALL BONNET | | | |
| 4 | MECHANISM | \$ | 80.00 | X11 |

TOTAL \$ 960.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 2,392.40
TOTAL LABOUR COST : \$ 960.00
TOTAL REPAIR COST : \$ 3,352.40

APPROVED DETAILS

EXCESS

NO. OF WORKING DAYS :

RE-SURVEY :

PART BY PART OR LUMP :

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

2 days

22/06/18 @ 1525

Rasul

90010068

P/P

[Signature]
26/6/18

Resurvey by part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|------------------------------|------------|---|
| ALLIED WORLD ASSURANCE COMPANY LTD | | Ref : CS/AWA18011367/R1sd3e2 | | |
| (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914 | | Date : 05-12-2018 | |  |
| | | Code : AWA | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | YN 5410Y | Veh. Inspected | SLX 7175P | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | YN5410Y/BT | Excess (\$) | 0.00 | |
| Assign From | STELLA GOH | Assign Date | 22/06/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HYUNDAI ELANTRA 1.6 | c.c | 1591 | |
| Engine No. | HIDDEN | Year of Reg. | 2018 | |
| Chassis No. | KMHD841CMJU646634 | Colour | BLUE | |
| Odometer | 2972 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | FAIR | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 195/65 R15 | NEXEN | 6 mm | |
| L/H Front Tyre | 195/65 R15 | NEXEN | 6 mm | |
| R/H Rear Tyre | 195/65 R15 | NEXEN | 6 mm | |
| L/H Rear Tyre | 195/65 R15 | NEXEN | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 20/06/2018 | Inspection Date | 22/06/2018 | |
| Survey held at | SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 2 Working Days | | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 7175P

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|---------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | BONNET | BENT | 1,125.00 | 1,125.00 |
| 1 | FRONT BONNET SEAL | NECESSARY | 58.00 | 58.00 |
| 1 | HEADLAMP LH | SCRATCHED | 1,745.00 | 1,745.00 |
| | LESS 20% DISCOUNT | | -585.60 | -585.60 |
| | | | 2,342.40 | 2,342.40 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | SET BONNET INSULATOR CLIPS (SN) | NECESSARY | 50.00 | 30.00 |
| | | | 50.00 | 30.00 |
| | <u>LABOUR</u> | | | |
| | SUPPORT PANEL RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS. | | 400.00 | 200.00 |
| | SPRAY PAINTING ON DAMAGE AND AFFECTED AREA. | | 400.00 | 200.00 |
| | ADJUST AND FOCUS FRONT LIGHTING SYSTEM.PERFORM HEADLAMP ADJUSTMENT TO POSITION. | | 80.00 | 30.00 |
| | REMOVE AND INSTALL BONNET MECHANISM. | NOT NECESSARY | 80.00 | - |
| | | | 960.00 | 430.00 |
| | GRAND TOTAL | | 3,352.40 | 2,802.40 |
| | RECOMMENDED COST OF REPAIRS | | | 2,802.40 |

Report Ref No. CS/AWA18011367/R1sd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.