

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	12	DVR WIRH CAMERA	Reviewing	200	DISTORTED	
	13	EXHAUST PIPE	Reviewing	980	DENTED	
	14	EXHAUST MUFFLER PROTECTOR	Reviewing	50	CUT	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTRR%	DISC QUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		13	1			CLUTCH LEVER			Cut	30		10		27	Reviewing	
		14	1			CLUTCH LEVER HOLDER			Cut	45		10		40.5	Reviewing	
		15	1			SIGNAL SWITCH			Cut	175		10		157.5	Reviewing	
		16	1			FUEL TANK COVER			Cracked	210		10		189	Reviewing	
		17	1			FRONT FOOTREST (L)			Broken	50		10		45	Reviewing	
		18	1			GEAR PEDAL			Bent	92		10		82.6	Reviewing	
		19	1			MAINSTAND			Repair	0		10		0	Reviewing	
		20	1			REAR SIGNAL LAMP			Cracked	50		10		45	Reviewing	
		21	1			FRONT FOOT REST (R)			Cut	50		10		45	Reviewing	
		22	1			FRONT FOOT REST GUARD LH			Bent	85		10		76.5	Reviewing	
		23	1			BRAKE PEDAL			Bent	130		10		117	Reviewing	
Labour																
	EDIT	SR NO	REPAIR/REPLACE (LABOUR)		PART NAME		LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)		COMMENT	REMOVE			
		1	ALIGNMENT REPAIR				150	0	0	Reviewing						
		2	TOWING 2 WAY				80	0	0	Reviewing						
		3	LABOUR				250	0	0	Reviewing						

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured	0		License Type		
Market Value	0		License Issue Date		mm/dd/yyyy
			License Expiration Date		mm/dd/yyyy
			Address	Singapore	
			Address type	Personal Correspondence	
			Gender	Unknown	
			Marital status	Unknown	
			Identification #	S8620358H	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	10/4/18 1:25 PM	4800	4800	Open	Share	Clone
DHIWAR Namrata	6/22/18 9:05 AM	6041	6041	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
Immediate Advice (with mandate) dd 170818.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 17, 2018
LKK Resurvey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 17, 2018
LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 17, 2018
PIR FROM TP.pdf	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 17, 2018
TP GIA.PDF	Reports & Statement	GIA Report	LOH Cynthia	June 25, 2018
TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	June 25, 2018
Immediate Advice.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	June 25, 2018
SKP7331J INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHIWAR Namrata	June 22, 2018
EMAIL FROM WORKSHOP WITH GIA REPORT.msg	Other	Other	DHIWAR Namrata	June 22, 2018
GA087777-Policy Schedule.pdf	Other	Other	GOH Jacy	June 21, 2018
GA087777-Certificate of Insurance.pdf	Other	Other	GOH Jacy	June 21, 2018