

(00000)

INS. CASE OWNER:

Norstah

CC 6

/AIG1801

1387, 4263

LKK:

IDAC:

Surveyor:

marcus

DOI:

ASSIGNMENT

2/6/18

Date / Time:

2/6/18

Registered in Merimen:

2/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLF 2770Z

Name of Insured:

Lim Yew Kwee Victor

Insured Tel No.:

HP:

22/6/18

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: Suganti Prawoto

Driver Tel No.:

(V/L YES / NO)

Claim No.:

908251441656

Policy No.:

70047645

Make / Model:

Honda

Place of Accident:

ECP Two's City

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SKK 9409H



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kim
Chwee

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

4/2/18
INT

11/2/18

11/2/18 @ 3.5pm

6/6/18

3veh cc. Old 2nd car.

Called OI, OI (Mr. Victor Lim) pick up. Confirm accident. Request video. He need to check with his wife to send email to OI & OI.

Just proceed to settle

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup):

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: GCS

Repair Cost:

96

SS 6,250

(5 days) Reduction:

54 %

Email

Call

FINAL SETTLEMENT

Date/Time: 29-6-18

Confirm with: N/A

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

28 (3cc-01)

NO or B 28, AAs, Lia:

Repair Cost:

villan

SS 6,813.50

Loss of Rental (LOR):

SS 6,400.00

(4 days) x 160

Loss of Use (LOU):

SS -

(5 x days)

Loss of Income (LOI):

SS -

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost:

SS -

Total:

SS 7,329.50

Global Sum SS:

FINAL PAYMENT

Date/Time: 29-6-18

Confirm with: N/A

Email

Call

Payee 1:

SS 7,329.50

Name 1:

VIM (THIRU) PATE PUL LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
9/3/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 320

ASS. REC. BY 140/045

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / P / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKK9409Hat Workshop n/s: Kim chuen

of _____

Insured: SLF 27708

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 30 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

55466

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction LTA 60 21746: + 6,390 (R&D: + 7,275 54%)Veh No: SKK9409HType: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Pilots / CarTruck / Trailer or GAMake: Kia Sorento 2199Colour: white A/C Insured: Std / NI / N/ASp. Reading: 192 T/Rail: Insured / Std / NI / N/A

Eng/No: _____

C/No: KNAPH8/BMJ5465077

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 235/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 9 mmR/Bal: 9 mmL/Bal: 9 mmL/Bal: 9 mmD.O.A. 22/6/18D.O.A. 22/6/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Restraint or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee

Transportation

\$ - RS - \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

ASS. REC. BY: MOULS

REF:

A16/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: SKK94091

at Workshop m/s Kim chue

of _____

Insured: SLF 27708

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 5-5466

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction LTA 60 217

6/7/18 home hpt
confd L/S & 6250 with Aln.

Veh No: SKK94091 Ragn: 6 18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or CA

Make: Kia Sorento cc 2199

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 192 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: KNAPH8/BMJ5465077

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____
R: 235/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. <u>9</u> mm	R/Bal. <u>9</u> mm
L/Bal. <u>9</u> mm	L/Bal. <u>9</u> mm
D.O.A. <u>22/6/18</u>	D.O.J. <u>22/6/18</u>

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ - RS. \$ _____

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18011383/Upb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 22-06-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLF 2770Z	Veh. Inspected	SKK 9409H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	22/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/06/2018	Inspection Date	22/06/2018	
Survey held at	KIM CHWEE AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

KIM CHWEE AUTO PTE LTD
1 Kaki Bukit Ave 6
#01-46/48/50 Autobay
SINGAPORE 417883

VEHICLE NO:SKK 9409H

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts price are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Admit
r/r
1/3 H 6250
5-ly.

QTY	PARTICULAR	AMOUNT
1 PCS	REAR WINDSCREEN MOULDING	ru \$181.00 ✓
1 PCS	TAILGATE 1445	ru \$1,655.00 ✓
1 PCS	TAILGATE REAR LOGO	ru \$66.00 ✓
1 PCS	TAILGATE 'SORENTO' EMBLEM	ru \$30.00 ✓
1 PCS	TAILGATE 'C&C' LOGO 45	ru \$50.00 ✓
1 PCS	TAILGATE 'DYNAMICS' EMBLEM 82	ru \$320.00 ✓
1 PCS	TAILGATE INNER LOCK	ru \$485.00 ✓
1 PCS	TAILGATE INNER TRIM BOARD	ad/cr \$450.00 ✓
1 SET	TAILGATE INNER TRIM BOARD CLIPS	ru \$50.00 ✓
1 PCS	TAILGATE WEATHERSTRIPS	lwi \$292.00 ✓
1 PCS	REAR BUMPER 685	ru/pe \$696.00 ✓
1 PCS	REAR BUMPER LOWER 565	ru/ro \$650.00 ✓
1 PCS	REAR BUMPER CENTRE	ru \$490.00 ✓
2 PCS	REAR BUMPER SIDE HOLDERS @\$65.00	ru \$130.00 ✓
1 SET	REAR BUMPER CLIPS	ru \$40.00 ✓
1 PCS	REAR BUMPER TOWING COVER	11 \$38.00 X
2 PCS	REAR BUMPER LAMPS @\$250.00	11 \$500.00 X
1 PCS	REAR BUMPER BEAM 366	3rd \$395.00 ✓
1 PCS	REAR END PANEL 681	ru \$682.00 ✓
1 PCS	REAR END PANEL TOP GARNISH 213	lwi \$420.00 ✓
2 PCS	TAILLAMPS @\$520.00	11 \$1,040.00 X
1 PCS	REAR EXHAUST	ru \$895.00 X
		\$9,555.00
		6296 \$666.4
	S.NETT	
1 SET	REAR BUMPER REVERSE SENSOR	2 hat \$280.00 200
1 PCS	REAR END PANEL SEALANT	ru \$50.00 ✓
1 PCS	REAR WINDSCREEN SEALANT	ru \$50.00 40
1 PCS	REAR WINDSCREEN INNER SEAL	ru \$50.00 40
1 PCS	REAR LICENSE PLATE HOLDER	11 \$50.00 X

LABOUR CHARGES:

TO CHECK WIRING

\$80.00 30

TO DISMENTLE & REPLACING REVERSE SENSOR	\$80.00	50
TO DISMENTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO TRANSFER TAILGATE MECHANISM	\$100.00	60
TO DISMENTLE & REFIX SEAT, CUSHION UPHOLSTERY	\$150.00	80
TO DISMENTLE & REFIX REAR EXHAUST	\$100.00	60
TO DISMENTLE & REFIX PETROL TANK	11 \$100.00	X
TO SPRAY RUST PROOFING	\$150.00	60
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,080.00	500
TO PUTTY & SPRAY PAINTING	\$1,500.00	800

TOTAL \$13,525.00

7856.4
6285

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5546E

Vehicle Details

Vehicle No.: SKK9409H
Vehicle to be Exported: No
Intended De-registration Date: 22 Jun 2018
Vehicle Make: KIA
Vehicle Model: SORENTO 2.2(8AT) CRDI 2WD S/R
Primary Colour: White
Manufacturing Year: 2018
Engine No.: D4HBJH374100
Chassis No.: KNAPH81BMJ5465077
Maximum Power Output: 147.0 kW (197 bhp)
Open Market Value: \$27,545.00
Original Registration Date: 19 Jun 2018
First Registration Date: 19 Jun 2018
Transfer Count: 0
Actual ARF Paid: \$30,563.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 18 Jun 2028
PARF Rebate Amount: \$22,922.00

Intended COE Rebate Details

COE Expiry Date: 18 Jun 2028
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$37,330.00
COE Rebate Amount: \$37,295.00
Total Rebate Amount: \$60,217.00

The information contained herein is correct as at 22 Jun 2018

OK

**RE: ACCIDENT INVOLVING SKK 9409H AND SLF 2770Z ON 22/06/2018**

Nancy Lam <nancy.lam@fastechauto.com.sg>

Thu 6/27/2019 10:35 AM

To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; jason@fastechauto.com.sg <jason@fastechauto.com.sg>

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Hi Sir,

We do accept your offer as below.

Regards,

Nancy Lam

Fastech Auto Pte Ltd

Tel: 6746 5405

Fax: 6745 8520

From: Asher Sng (LKKAuto) [mailto:AsherSng@lkkauto.com]

Sent: Thursday, June 27, 2019 8:49 AM

To: Nancy Lam <nancy.lam@fastechauto.com.sg>; jason@fastechauto.com.sg

Subject: ACCIDENT INVOLVING SKK 9409H AND SLF 2770Z ON 22/06/2018

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Hi Sir,

We refer to the above matter.

ACCIDENT INVOLVING SKK 9409H AND SLF 2770Z ON 22/06/2018

We propose settlement as follows: -

1. Cost of Repair(w/GST)	\$ 6,687.50
2. Loss of Rental (4days x \$160)	\$ 640.00
3. LTA/GIA search fee	\$ 2.00
TOTAL	<u>\$ 7,329.50</u>

Kindly let us have your acceptance.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Date : 13.07.2018

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

ACCIDENT INVOLVING VEHICLE: SKK9409H AND SLF2770Z ON 22.06.2018

We are the authorized repair workshop for the owner of motor vehicle no: **SKK9409H**, which was involved in the captioned accident with your insured vehicle no: **SLF2770Z**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$	6,687.50
2) Loss Of Use-Rental	\$	1,000.00
3) GIA Search Fee	\$	2.00
	<u>\$</u>	<u>7,689.50</u>

We enclosed herewith the following documents to support the claims:

- | | |
|------------------------------------|----------------------------------|
| a) Final Repair Invoice | b) Vehicle Registration Log Card |
| c) Rental Agreement/Invoice | d) I/C & Driving Licence |
| e) Insurance Certificate | f) GIA Search Result/GIA Report |
| g) Letter of Authorisation, etc... | |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,

Jason Tang (jason@fastechauto.com.sg)

For Kim Chwee Auto Pte Ltd

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S8661301H**

Name: **LIANG FEI**

Birth Date: **22 Mar 1986**

Valid Until: **18 Jan 2018**

002765061A

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S8661301H**

Name: **LIANG FEI**

梁飞

Race: **CHINESE**

Date of birth: **22-03-1986**

Country/Place of birth: **CHINA**

Sex: **M**

S8661301H

Driver

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE: **14 Feb 2014**

Class 3A Motor cars without clutch pedals (Auto) with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight $\leq 2500\text{kg}$

Licence No: **S8661301H**

NP 428A

9470726

S8661301H

Nationality: **CHINESE**

Date of issue: **05-01-2018**

Address: **34 BAYSHORE ROAD
#28-08
SINGAPORE 469978**

KIA AUTO PROTECTOR PRIVATE VEHICLE

The following risk described on this Cover Note is hereby HELD COVERED on the terms and conditions of the policy issued to the Policyholder.

Name of Policyholder : Wang Xiao
Period of Insurance : 1 Jun 2018 to 1 Jun 2019
Engine No. : D4HBJH374100
Chassis No. : KNAPH81BMJ5465077



Vehicle No. : SKK 9409H
Cover Note No. : 1800068253
Endorsement No. :
Issued Date : 08 Jun 2018

ABOUT THE COVER

Make/Model : KIA SORENTO 2.2 A DIESEL
Engine Capacity/Tonnage : 2,199.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)
 Wang Xiao - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre Add: 241 Alexandra Road Singapore 159931 64278800
3. Cycle & Carriage Authorised Service Centre (For windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 8338 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.
 I/We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.

0500710050

C&C FULCO-CORP SALES

22 UBI ROAD 4 FULCO BUILDING

SINGAPORE 408617 ANSP - MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manila

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Chn Ee Liat

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 5546E

Vehicle Details

Vehicle No.: SKK9409H

Vehicle to be Exported: No

Intended De-registration Date: 22 Jun 2018

Vehicle Make: KIA

Vehicle Model: SORENTO 2.2(8AT) CRDI 2WD 5/R

Primary Colour: White

Manufacturing Year: 2018

Engine No.: D4HBJH374100

Chassis No.: KNAPH81BMJ5465077

Maximum Power Output: 147.0 kW (197 bhp)

Open Market Value: \$27,545.00

Original Registration Date: 19 Jun 2018

First Registration Date: 19 Jun 2018

Transfer Count: 0

Actual ARF Paid: \$30,563.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Jun 2028

PARF Rebate Amount: \$22,922.00

Intended COE Rebate Details

COE Expiry Date: 18 Jun 2028

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$37,330.00

COE Rebate Amount: \$37,295.00

Total Rebate Amount: \$60,217.00

The information contained herein is correct as at 22 Jun 2018

OK

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 12 July 2018 9:55 AM
To: 'yewbee40@yahoo.com.sg'; 'susu.p1977@gmail.com'
Subject: ACCIDENT INVOLVING SLF 2770Z(AIG) / SKK 9409H/ OTHERS ON 22/06/2018

13 JULY 2018

Mr Lim Yew Kwee Victor/ Ms Sujanti Pranoto

Dear Sir/Madam,

Our Ref: CC6/AIG18011383/Upb3

ACCIDENT INVOLVING SLF 2770Z(AIG) / SKK 9409H/ OTHERS ON 22/06/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SKK 9409H against your insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

We would like to request a copy of your car video footage as stated in your accident report for our necessary action.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
EMAIL: chewht@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Wang Xiao ("the third party claimant")
of 34 Bayshore Road #28-08 5469976 (address),
owner of SKK 94094 (vehicle no.) hereby authorize
Kim Chwee Auto Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SKK 94094 that was
damaged pursuant to the accident which occurred on 22/6/2018 (date) along
ECP towards City (location)
involving vehicle no/s SLF 2770Z ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 22 day of 06 (month) 20 18 (year)



Signed by "the third party claimant"



Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, Kim Chwee Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd, LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 6,687.50 (repair costs), S\$ 640.00 (loss of use/rental) S\$ 2.00 (search fees) for vehicle no. SKK 9409H that was damaged pursuant to the accident which occurred on 22/6/18 (date) along ECP towards City (location) involving vehicle no/s SLF 2770Z.

This is pursuant to the inspection conducted on 22/06/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Wang Xiao ("third party claimant") of vehicle no. SKK 9409H to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKK 9409H (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 29 day of 06 (month) 20 19 (year)



Cks

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

TAX INVOICE

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

Tax Invoice : 20361

Date: 13.07.2018

Vehicle No: SKK9409H

Make/Model: KIA SORENTO

Chassis/Eng# :

Accident Date: 22.06.2018

Claim No : 0618-20361

:

		Amount
To proceed on lump sum repair	SS	6,250.00

E. & O. E.

Total : S\$ 6,250.00

GST @ 7% : S\$ 437.50

Amount Due : S\$ 6,687.50


for KIM CHWEE AUTO PTE LTD

All Invoices are subjected to GST



Invoice

SKK9409H
WANG XIAO
34 BAYSHORE RD
#28-08
S(469976)

Invoice No : GPLIN0000827
Invoice Date : 30/6/2018
Due Date : 30/6/2018
VHA No : 1122
Referral ID : F001

Description :	Amount
Rental for 4 Day/s @ \$250 per Day	\$1,000

Vehicle No : SLD3824G

Vehicle Description : Toyota Harrier 2.0A

Rental Period : 22/06/2018 to 26/06/2018

Total Amount Payable : \$1,000

GOOD WAY RENT-A-CAR PTE LTD

8 Kaki Bukit Ave 4 #06-04 Premier@Kaki Bukit Singapore 415875
Tel: 6315 8479 H/P: 9833 0807

VHA No: 1122

Invoice No:

Hirer's Vehicle No:

UEN: 201505120D

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULARS

Name: (as in I/C) WANG YIHO

NRIC / FIN No: SP465546E

Address (Res): 34 BAYSHORE RD #2F-05

5149976

Name & Address of Employer:

Occupation: Driving Exp:

Singapore Driving Licence No:

Issue Date: Date of Birth: 6/4/84

Tel: (O) (R) HP:

ADDITIONAL DRIVER'S PARTICULARS

Name: (as in I/C)

NRIC / FIN No:

Address (Res):

Occupation: Driving Exp:

Singapore Driving Licence No:

Issue Date: Date of Birth:

Tel: (O) (R) H/P:

VEHICLE CHECK LIST

INDICATE: D - DENTS A - ACCIDENTS S - SCRATCHES	RIGHT	FRONT	TOP	LEFT

MISSING / FAULTY ACCESSORIES / PARTS

REMARKS:

Vehicle No: SD 35246 Replace Veh No:

Mileage Out: 3000 Mileage Out:

Make & Model: Z. HARRIER 2.0A Auto / Manual

Out : Date 22/6/18 Time: 10:00

HIRE / PERIOD EXPIRY Time:

NON-WAIVER EXCESS-\$ 3000

CHARGES

Daily 4 @ \$ 250 per day \$1000

Weekly @ \$ per week

Monthly @ \$ per month

Hours @ \$ per hour

Extension @ \$

Delivery/Collection Service

SUB-TOTAL \$

PETROL LEVEL

Out E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F

In E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F

Fuel

Traffic / Parking Fines

TOTAL CHARGES \$

Hirer's Signature

Additional Driver's Signature

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment. I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given GOOD WAY RENT-A-CAR PTE LTD in connection with this agreement is true.

*IMPORTANT

- VEHICLE IS STRICTLY PROHIBITED FOR "HIRE FOR REWARDS" USAGE SUCH AS UBER / GRABCAR / GRABSHARE ETC.
- ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY. AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY GOOD WAY RENT-A-CAR PTE LTD.

RETURN OF VEHICLE: THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO GOOD WAY RENT-A-CAR PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
<u>20/06/18</u>	<u>5:08pm</u>	<u>34673</u>			



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-095142

Date of Request: 22/06/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 22/06/2018
Enquiry By Jason Tang Jun Zhong
TP Vehicle No. SLF2770Z
Accident Date 22/06/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLF2770Z	AIG Asia Pacific Insurance Pte. Ltd.	19/08/2017-18/08/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-095142

Date of Request: 22/06/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 22/06/2018
Enquiry By Jason Tang Jun Zhong
TP Vehicle No. SLF2770Z
Accident Date 22/06/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING


















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jun 2018 Edit Reg		22 Jun 2018 00:00 Edit Adj Rpt	S\$6,250.00 Edit Estimates	S\$6,250.00 View Rpt		Pending for Survey Report Cancel Case










































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Lim Yew Kwee Victor, ID: S7142132E								
Main Claimant:	WANG XIAO, ID: S8465546E								
Vehicle Reg. No.:	SKK9409H	Date of Loss:	22/06/2018 09:00 - :59 [3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9082514416SG	Policy/Cover Note No.:	2100479645 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLF2770Z	Policy No. (Claimant):	-						
		Excess:							
Repairer:	Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 03/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (26/06/2018): No Policy Found									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKK9409H (9082514416SG)
[SLF2770Z]
TP
WANG XIAO
Jun 22 2018 9:00AM
[Lim Yew Kwee Victor]
Kim Chwee Auto Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Letters/Correspondences						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	[Draft]	Third Party Express Settlement – Payment Breakdown				Edit	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	23/06/18 09:49	Chassis Number				Load JPG	
2	23/06/18 09:49	Odometer Reading				Load JPG	
3	23/06/18 09:49	General View				Load JPG	
4	23/06/18 09:49	General View				Load JPG	
5	23/06/18 09:49	General View				Load JPG	
6	23/06/18 09:49	General View				Load JPG	
7	23/06/18 09:49	General View				Load JPG	
8	23/06/18 09:49	General View				Load JPG	
9	23/06/18 09:49	General View				Load JPG	
10	23/06/18 09:49	General View				Load JPG	
11	23/06/18 09:49	General View				Load JPG	
12	23/06/18 09:49	General View				Load JPG	
13	23/06/18 09:49	General View				Load JPG	
14	23/06/18 09:49	General View				Load JPG	
15	23/06/18 09:49	General View				Load JPG	
16	23/06/18 09:49	General View				Load JPG	
17	23/06/18 09:49	General View				Load JPG	
18	23/06/18 09:49	General View				Load JPG	
19	23/06/18 09:49	General View				Load JPG	
20	23/06/18 09:49	General View				Load JPG	
21	23/06/18 09:49	General View				Load JPG	
22	23/06/18 09:49	General View				Load JPG	
23	23/06/18 09:49	General View				Load JPG	
24	23/06/18 09:49	General View				Load JPG	
25	23/06/18 09:49	General View				Load JPG	
26	23/06/18 09:49	General View				Load JPG	
27	23/06/18 09:49	General View				Load JPG	
28	23/06/18 09:49	General View				Load JPG	
29	23/06/18 09:49	General View				Load JPG	
30	23/06/18 09:49	General View				Load JPG	
31	23/06/18 09:49	General View				Load JPG	
32	23/06/18 09:49	General View				Load JPG	
33	23/06/18 09:49	General View				Load JPG	
34	23/06/18 09:49	General View				Load JPG	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
36	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
38	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
42	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
43	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
44	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
45	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
46	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
47	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
48	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
49	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
50	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
51	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
52	23/06/18 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
53	23/06/18 09:50	General View	 Load JPG	<input checked="" type="checkbox"/>
54	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	23/06/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/06/18 16:29	TP GIA REPORT	 Load PDF	
2	16/07/19 11:01	WORKSHOP INVOICE	 Load PDF	
3	16/07/19 11:01	AUTHORISATION TO ACT FORM	 Load PDF	
4	16/07/19 11:01	Release Voucher	 Load PDF	
5	16/07/19 11:01	RENTAL RECEIPT	 Load PDF	
6	16/07/19 11:01	GIA SEARCH	 Load PDF	
7	16/07/19 11:01	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/07/18 13:37	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLF2770Z (Insd veh)	Model:	KIA SORENTO 2.2 (A)
	SKK9409H (TP veh)		
Date of Accident:	22/06/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No		
Repair Estimate	:	\$	14,471.75		
Final Repair Cost	:	\$	6,687.50		
Loss of Use	:	\$		4	days at \$0.00 per day
Rental (if any)	:	\$	640.00	4	days
LTA / GIA Search Fee	:	\$	2.00		
Others:	:	\$	0.00		
	:	\$			
Final Settlement Sum	:	\$	7,329.50		

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Kim Chwee Auto Pte Ltd	:	7,329.50
2)		:	
3)		:	

JOANNE LEE KHANG MIN

16 Jul

2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18011383/UEB3Q2
Date: 16/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100479645
Claimant Vehicle No: SKK9409H Insured Vehicle No: SLF2770Z
Date of Loss: 22/06/2018 Nature of Claim: TP Claim No: 9082514416SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKK9409H
Make & Model: KIA SORENTO, 2.2 (A) Engine No: D4HBJH374100
Reg. Date: 19/06/2018 (Man. Year: 2018) Chassis No: KNAPH81BMJ5465077
Colour: White Odometer: 192 km
Engine Capacity: 2199 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18
Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm
Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,035.00	5,996.40	4,038.60	40.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,490.00	1,860.00	1,630.00	46.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,525.00	7,856.40	5,668.60	41.91
Approved Total (Overridden) (S\$)		6,250.00		
(S\$)	13,525.00	6,250.00	7,275.00	53.79
+ GST 7.00/7.00% (S\$)	946.75	437.50	509.25	53.79
Nett Amount (S\$)	14,471.75	6,687.50	7,784.25	53.79
+ Car Rental (4.0 x S\$160.00/day) (S\$)		640.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,329.50		

INSPECTION

Date of Assignment: 22/06/2018
Date Inspected: 22/06/2018 Inspected At: Kim Chwee Auto Pte Ltd (HQ)
1 Kaki Bukit Avenue 6 #01-48,

AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	181.00 F	*181.00 FL
2	1		*TAILGATE	Dented	1,655.00 F	*1,445.00 FL
3	1		*TAILGATE REAR LOGO	Necessary	66.00 F	*66.00 FL
4	1		*TAILGATE SORENTO EMBLEM	Necessary	30.00 F	*30.00 FL
5	1		*TAILGATE C&C LOGO	Necessary	50.00 F	*45.00 FL
6	1		*TAILGATE DYNAMICS EMBLEM	Necessary	320.00 F	*82.00 FL
7	1		*TAILGATE INNER LOCK	Twisted	485.00 F	*485.00 FL
8	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	450.00 F	*450.00 FL
9	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
10	1		*TAILGATE WEATHERSTRIPS	Twisted	292.00 F	*292.00 FL
11	1		*REAR BUMPER	Dented / Deformed	696.00 F	*685.00 FL
12	1		*REAR BUMPER LOWER	Deformed / Torn	650.00 F	*565.00 FL
13	1		*REAR BUMPER CENTRE	Dented	490.00 F	*490.00 FL
14	2		*REAR BUMPER SIDE HOLDERS	Necessary	130.00 F	*130.00 FL
15	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
16	1		*REAR BUMPER TOWIN COVER	Not Necessary	38.00 F	*- FL
17	2		*REAR BUMPER LAMPS	Not Necessary	500.00 F	*- FL
18	1		*REAR BUMPER BEAM	Bent	395.00 F	*366.00 FL
19	1		*REAR END PANEL	Dented	682.00 F	*681.00 FL
20	1		*REAR END PANEL TOP GARNISH	Twisted	420.00 F	*213.00 FL
21	2		*TAILLAMPS	Not Necessary	1,040.00 F	*- FL
22	1		*REAR EXHAUST	Repair	895.00 F	*- FL
23	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
24	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
25	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
26	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
27	1		*REAR LICENSE PLATE HOLDER	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **10,035.00** **6,626.00**
 - List Item Discount on L Items 0.00/10.00% (\$\$) **0.00** **629.60**

Total Parts (\$\$) **10,035.00** **5,996.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
7	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
8	TO SPRAY RUST PROOFING	New	150.00	60.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,080.00	600.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
Gross Labour Cost (S\$)			3,490.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >