## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

MAKE

VEHICLE NO: SHC 8622S

. SHE

· HVIINDAL 340

A24

DATE 21/6/2018 15:25

Qty	Parts Description/ Labour	Type	Unit Price	1	Amount	
	Front Door (RH)			\$	1,403.00	)
	Rear Pour (RH) x report SUB TOTAL  Rear Fee Ser (RH) x report LESS 20%  RH Packer Paul hour? DISCOUNTED TOTAL					
	Rear poor Class tepor SUB TOTAL			\$	1,403.00	)
	Pear Feeder (RH) ~ LESS 20%			\$	280.60	)
	DIS Rocker Paul forth DISCOUNTED TOTAL			\$	1,122.40	)
	Front Door Comfort Logo (RH)			\$	75.00	)
	Rear Door Comfortdelgro & Apps Sticker (RH)			\$	80.00	)
				\$	155.00	)
	Labour Charge			6	300	
	Panel Beating			\$	500.00	7
	Spray Painting Charge			\$	1,000.00	) [
	Tuff Kote			\$	50,00	7
	Transfer of Door			\$	500.00 1,000.00 50.00 120.00	
	TOTAL LABOUR			\$	1,670.00	
	ESTIMATE TOTAL			\$	2,947.40	)
	Kaluz 10kly  1 21/6/18 1530 hs.  2 hys	• To resur • To displa • Parts pr • Third pa	o Consultants hence notify airer of the following: rey before/after spray painting by damaged part(s) during resurvices are subject to confirmation rry survey is on a "Without Prejucal modification(s) is allowed	ey	asis	
	2 673		nentary item(s) must be resurvey ct to final approval from Insuranc	ed <u>and</u> e Com	d npany	
	PIP Betore Part photo	Signatur	edged by Repairer			
	De "	Date:				
	This is an initial estimate based on a visual inspection of the	a a bassa ssal	high. The final repair of	lantu	m will	+