

22/6/2002

ASS. REC. BY:

REF: CS3/AIG18011417/Tl24d3⁵

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

chin lee ying of AIG Date/Time: 22/6/18 @ 11:58am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 9669G

Insured:

SGW 8145J

at Workshop n/s

Ace Autolution

Tel:

6844 1189

of

13 Kaki Bukit Rd 4 # 03-29

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/06/2018

CA / REV / REP. / REV 24 HRS

lup

25/06/2018

H.O.D. Endorsement:

Date/Time:

12:15pm @ 22/6/18

Person Contacted:

Anna

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLL 9669G - X

SGW 8145J - NBA / INCL 7019075/Y

DAA: 04/10/2017

DART

Tanpin

REF: AIG

ASSIGNMENT

From:

Date: 25/6/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SL 9669 G

at Workshop n/s

Ace Auto lution

of 13 Kaki Bukit Road 4 #03-29

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SL 9669 G

Yr Regn:

2010 Out

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Bmw 320i

C.C:

1995

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

102588

T/Ratio: Insured / Std / NI / NA

Eng/No:

WBADV 32000 E491753

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

225 HOK 18.

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

25/6/18 01280

Survey held at

Ace Auto lution

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/7

Submit DAR report.

RECEIVED 23 JUL 2018

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: -

Survey Fee:

Transportation

1) S + RS: \$

2) Photos

3) Others

Report Format: DAR

Lump Sum / I.B.I: (\$

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ Weekend (\$

TOTAL

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE
SGW8145J AND SLL9669G ON 20/06/2018**

From: Chin, Lee-Ying
To: assignments@lkkauto.com, Admin A
Cc: Fong, Andy-SY
Sent: 22/6/2018 11:58:27 AM
Attachments:  20180621172019645.pdf

Hi LKK,

Kindly assist to survey, vehicle is in.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Our Ref : SLL 9669G (Jr)

Your Ref : To be advised

21 June 2018

M/S AIG ASIA PACIFIC INSURANCE PTE. LTD.

BY EMAIL

Dear Sirs,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : TEH GUAN TIONG ALLAN
ACCIDENT INVOLVING SLL 9669G & SGW 8145J ALONG 52 PUNGGOL
WALK B2 CARPARK ON 20 JUNE 2018
PRE-REPAIR SURVEY NOTICE

1. We act for Teh Guan Tiong Allan, the owner of motor vehicle no. SLL 9669G which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SGW 8145J for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	Ace Autolution
Address	13 Kaki Bukit Road 4 #03 - 29 Bartley Biz Centre Singapore 417807
Contact Person	Ms. Anna (6844 1184)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/06/2018 16:55
Date Of Accident	20/06/2018 17:05
Exact Location Of Accident	52 PUNGGOL WALK B2 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL9669G
Insured/Policyholder	
Name Of Registered Owner	TEH GUAN TIONG, ALLAN
NRIC No	S7707420A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96477687
Alternative Phone No	OTHERS-96477687

Vehicle Particulars

Manufacturer	BMW
Model	320I AT ABS D/AB 2WD 2DR GAS/D
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	TEH GUAN TIONG, ALLAN
NRIC No	S7707420A
Date Of Birth	26/03/1977
Occupation	INDOOR
Date Of Driving Pass	07/01/2017
Driving Experience	1 YEAR AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96477687
Fax Number	
Contact Number	OTHERS-96477687
Email Address	NOEMAIL

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the detail of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurer to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulator(s), law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders;

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/IN No.

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLL9669G		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	B.M.W.		
Vehicle Model :	320I AT ABS D/AB 2WD 2DR GAS/D		
Chassis No. :	WBADV32000E491753		
Propellant :	Petrol		
Engine No. :	A334I750N46B20BD		
Engine Capacity :	1995 cc		
Maximum Power Output :	115.0 kW (154 bhp)		
Maximum Laden Weight :	2055 kg		
Unladen Weight :	1625 kg		
Year Of Manufacture :	2010		
Original Registration Date :	22 Oct 2010		
Lifespan Expiry Date :	-		
COE Category :	E - Open Category		
Quota Premium :	\$43,501.00		
COE Expiry Date :	21 Oct 2020		
Road Tax Expiry Date :	21 Oct 2018		
PARF Eligibility Expiry Date :	21 Oct 2020		
Inspection Due Date :	21 Oct 2019		
Intended Transfer Date :	26 Jun 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7420A
Vehicle Details	
Vehicle No.:	SLL9669G
Vehicle to be Exported:	No
Intended De-registration Date:	20 Jul 2018
Vehicle Make:	B.M.W.
Vehicle Model:	320I AT ABS D/AB 2WD 2DR GAS/D
Primary Colour:	Brown
Manufacturing Year:	2010
Engine No.:	A334I750N46B20BD
Chassis No.:	WBADV32000E491753
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$40,939.00
Original Registration Date:	22 Oct 2010
First Registration Date:	22 Oct 2010
Transfer Count:	0
Actual ARF Paid:	\$40,939.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Oct 2020
PARF Rebate Amount:	\$24,563.00
Intended COE Rebate Details	
COE Expiry Date:	21 Oct 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$43,501.00
COE Rebate Amount:	\$9,643.00
Total Rebate Amount:	\$34,206.00

The information contained herein is correct as at 20 Jul 2018

OK

MOTOR CAR (Frt)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish	SCR ✓		
1004	991300	Frt Bumper	DB ✓		
1005	992341	Frt Bumper Clips	NEC ✓		
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille (Lower L/R)	CRA ✓	2	
1014	991301	Frt Bumper Moulding (Upper L/R)	CUT ✓	2	
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp	SCR ✓		
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CRA ✓		
1030	991821	Frt RH Headlamp Assy	CRA ✓		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No: **SL9669 G**

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Headlight Washer cover			
		Headlamp Washer Jet			

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jun 2018 Edit Reg		22 Jun 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TAY KIM SENG PETER, ID: S0079051F		
Main Claimant:	TEH GUAN TIONG, ALLAN, ID: S7707420A		
Vehicle Reg. No.:	SLL9669G	Date of Loss:	20/06/2018 17:00 - :59 [91 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5408598242SG	Policy/Cover Note No.:	2100034711 (Comprehensive) Coverage: 31/07/2017 - 30/07/2018
Vehicle Reg. No. (Insured):	SGW8145J	Policy No. (Claimant):	
		Excess:	
Repairer:	Ace Autolotion Pte Ltd (HQ) 13 Kaki Bukit Road 4 #03-22, Bartley Biz Centre, 417807 Kaki Bukit - Tel: 68441184		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 05/07/2018]		
Claimant's Solicitor:	CHIA S ARUL & LLC - Tel: 67334647		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (27/06/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SLL9669G (5408598242SG)
[SGW8145J]**

TP

TEH GUAN TIONG, ALLAN

Jun 20 2018 5:00PM

[TAY KIM SENG PETER]

Ace Autolution Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/06/18 18:13	General View	Load JPG	
2	26/06/18 18:13	General View	Load JPG	
3	26/06/18 18:13	General View	Load JPG	
4	26/06/18 18:13	General View	Load JPG	
5	26/06/18 18:13	General View	Load JPG	
6	26/06/18 18:13	General View	Load JPG	
7	26/06/18 18:13	General View	Load JPG	
8	26/06/18 18:13	General View	Load JPG	
9	26/06/18 18:13	General View	Load JPG	
10	26/06/18 18:13	General View	Load JPG	
11	26/06/18 18:13	General View	Load JPG	
12	26/06/18 18:13	General View	Load JPG	
13	26/06/18 18:13	General View	Load JPG	
14	26/06/18 18:13	General View	Load JPG	
15	26/06/18 18:13	General View	Load JPG	
16	26/06/18 18:13	General View	Load JPG	
17	26/06/18 18:13	General View	Load JPG	
18	26/06/18 18:13	General View	Load JPG	
19	26/06/18 18:13	General View	Load JPG	
20	26/06/18 18:13	General View	Load JPG	
21	26/06/18 18:13	General View	Load JPG	
22	26/06/18 18:13	General View	Load JPG	
23	26/06/18 18:13	General View	Load JPG	
24	26/06/18 18:13	General View	Load JPG	
25	26/06/18 18:13	General View	Load JPG	
26	26/06/18 18:13	General View	Load JPG	
27	26/06/18 18:13	General View	Load JPG	
28	26/06/18 18:13	General View	Load JPG	
Documentation			1 per page	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/06/18 17:09	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18011417/T1Z4D3S2
Date: 23/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100034711
Claimant Vehicle No : SLL9669G **Insured Vehicle No :** SGW8145J
 Date of Loss: 20/06/2018 Nature of Claim: TP Claim No: 5408598242SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL9669G**
 Make & Model: BMW 320I, 2.0 (A) Engine No: A334I750N46B20BD
 Reg. Date: 22/10/2010 (Man. Year: 2010) Chassis No: WBADV32000E491753
 Colour: Grey Odometer: 102588 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/06/2018
 Date Inspected: 25/06/2018 Inspected At: Ace Autolution Pte Ltd (HQ)
 13 Kaki Bukit Road 4 #03-22, Bartley Biz Centre
 Singapore 417807
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE GARNISH	Scratched	0.00 F	*- F
2	1		*FRT BUMPER	Distorted	0.00 F	*- F
3	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*FRT BUMPER GRILLE (LOWER L/R)	Cracked	0.00 F	*- F
5	2		*FRT BUMPER MOULDING (LOWER L/R)	Cut	0.00 F	*- F
6	1		*FRT RH BUMPER FOG LAMP	Scratched	0.00 F	*- F
7	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
8	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
9	1		*HEADLIGHT WASHER COVER	Missing	0.00 F	*- F
10	1		*HEADLAMP WASHER JET	*Check	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)

0.00

0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >