

INS. CASE OWNER:

CC6, A/G 180 11427, U ja3

LKK: IDAC:

Surveyor:

MARMS

DOI:

ASSIGNMENT

21/6/18

Date / Time:

22/6/18

Registered in Merimen:

22/6/18

Pre-assign / CCU / FTE

SEP 2020



Insured Vehicle No.:

HUA NAN motor p/l

Claim No.:

2100442803

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

Place of Accident:

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Kenny Cheok sui

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

9129 485276L (YES / NO)

Insured Liability: % Final ? Yes / No

Sfm 4804G



INSRS:

WSP:

Tel:

Liability:

RMKS:

Tan Lee
K KIM HIN



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

21/6/18
Jing

Sfm 4804G-x ; SEP 2020-x

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):

Call OI: 207 23-7-18
After call ltr to OI:

Documentation Check List: Handler Typist

| | | |
|----------------------------------|-------------------------------------|--------------------------|
| Notification ltr (if non-pickup) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| After call ltr to OI: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Authorisation To Act: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Release Voucher: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Final Repair Bill: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Car Rental Invoice: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Towing Invoice | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| LTA / GIA: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Medical Bill: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| PIR: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Mandate/Reject Instruction: | <input type="checkbox"/> | <input type="checkbox"/> |
| LOD | <input type="checkbox"/> | <input type="checkbox"/> |
| Payment Breakdown Form: | <input type="checkbox"/> | <input type="checkbox"/> |
| Post-Repair Photos: | <input type="checkbox"/> | <input type="checkbox"/> |
| Others: | <input type="checkbox"/> | <input type="checkbox"/> |

23-7-18 @ 353 PM w/ OI. CONFIRMED ACC. DETAILS. UNDERSTOOD WE ARE DOWN. AGREED & AWARE NCD ISSUE.

7-9-18

PENDING LOD

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: S\$ (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: 28-2-19 Confirm with MARGARET Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: NIL

Repair Cost: S\$ 909.50 100%

Loss of Rental (LOR): S\$ -

Loss of Use (LOU): S\$ 120 (\$ 60 x 2 days)

Loss of Income (LOI): S\$ - (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: S\$ 2

Medical: S\$ =

Disbursement: S\$ = (e.g. Tow/ Independent)

Legal Cost: S\$ =

Total: S\$ 1,031.50 Global Sum S\$: 1,030/-

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: S\$ 1,030.- x Name 1: K KIM HIN AUTO PRE LTD

Payee 2: (Strike if N.A.) S\$ x Name 2: X

Payee 3: (Strike if N.A.) S\$ x Name 3: X

1/3/19

REF: Alt

ASSIGNMENT

From: _____ Date: 25/06/2018

Estimated Cost: _____

OD TP WS TP RES OD RES EVA INV MV

To inspect Vehicle No: SFM 48046

at Workshop n/s: Tan Lim

of: 51 Dehu Lane 10

Insured: SKP 2122B

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SFM 48046 Yr Regn: P of

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CA 1

Make: Toyota corolla Altis c.c. 1598

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 183994 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0537.EE1.06115104

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil SRim / STD A/Rim or

Tyre Size: F: 205/55R16 MIC R: _____

10km

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-------------------------------------|--------------------------|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| N/S | O/S |
| <input type="checkbox"/> | <input type="checkbox"/> |

Bal. or Market Value: 11k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

CA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 1.51 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 28/8/2018

Vehicle IN / OUT: Case log

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front: _____ Rear: _____

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 17/6/18 D.O.I: 25/6/18

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|---|
| 25/6/18 | LTA 8645 confirmed finally by 960 with MR Tan. (only labor) |
| | W/R Kim MIN 1180 |

R (\$1,047.10/55%)

Date/Time, File Pass to? : Prel. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: Site Insp (\$ _____) S+RS (\$ _____)

Interview (\$ _____) Photos

Tech Invs (\$ _____) Other

Weekend (\$ _____) _____

TOTAL _____



AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 30019

Vehicle Insured : SKP 2122 D
Accident Date : 17-Jun-2018

Date : 10-Sep-2018

Our Ref : 180575 (AIG ASIA) / SHUMAN

PAGE : 1

CHAN YEW KEE, DAVID (MR)
Singapore

ESTIMATED COST OF REPAIR FOR TOYOTA COROLLA ALTIS 1.6 A (2008) SFM4804G

| | | | | |
|---|------------|----|--------|--------|
| 1 pc n/s rear bumper side retainer | | 17 | 58.00 | ✓ |
| 5 pcs rear bumper clips | @ S\$ 5.00 | 17 | 25.00 | ✓ |
| 1 pc n/s rear door protector | | 17 | 90.00 | ✓ |
| 1 pc n/s rear door outer chrome moulding | | 17 | 29.00 | ✓ |
| | | | ----- | |
| | | | 202.00 | |
| Less 25% : | | | -50.50 | |
| | | | ----- | |
| | | | | 151.50 |

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

250.00 ✓

To putty and respray on affected
portions.

750.00 600

Total : S\$ 1,151.50

Singapore Dollars One Thousand One Hundred and
Fifty One and Cents Fifty Only

810

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.



陳林峰有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SKP2122B
Date of Accident : 17 June 2018

*not allowed
date
take photo After up
25/6/18
PII # 960
2dy.*

Mr Chan Yew Kee, David

Date : 19 June 2018

*confirmed with
Marcus 25/6/2018*

Estimate To Repair SFM4804G - Toyota COROLLA ALTIS 1.6 AUTO
Chassis No : MR053ZEE106115104

| S/No | Quantity | Description | Amount |
|------|----------|---|------------------------|
| | | <u>LIST ITEMS</u> | |
| 01 | 1 pc | n/s rear door protector <i>R</i> | \$ 75.00 <i>X</i> |
| 02 | 1 pc | n/s rear door protector moulding <i>n1</i> | \$ 27.80 <i>X</i> |
| | | Less 25 % | \$ 102.80 |
| | | | \$ 25.70 |
| | | | \$ 77.10 |
| | | <u>SPECIAL NETT ITEMS</u> | |
| 03 | 1 pc | n/s rear wheel rim <i>n</i> | \$ 400.00 <i>X</i> |
| | | | \$ 400.00 |
| | | <u>LABOUR & MISC. CHARGES</u> | |
| 01 | | To check steering geometry and computer wheel alignment. | \$ 120.00 <i>60</i> |
| 02 | | To transfer of n/s rear wheel tyre, rim and on wheel balancing. | \$ 50.00 |
| 03 | | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. | \$ 450.00 <i>300</i> |
| 04 | | Putty and spray painting of the affected portion. | \$ 800.00 <i>600</i> |
| | | | \$ 1,420.00 <i>960</i> |
| | | Total | \$ 1,897.10 |

LKK Auto Consultants hence notify the Requirer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- The parts supply is on a "Without Prejudice" basis
- No legal endorsement is allowed
- Supplies by third party to be resurveyed and is subject to 20% increase from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 7349A

Vehicle Details

Vehicle No.: SFM4804G
Vehicle to be Exported: No
Intended De-registration Date: 18 Jun 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 AUTO
Primary Colour: Silver
Manufacturing Year: 2008
Engine No.: 3ZZ4786171
Chassis No.: MR053ZEE106115104
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$16,777.00
Original Registration Date: 29 Aug 2008
First Registration Date: 29 Aug 2008
Transfer Count: 0
Actual ARF Paid: \$16,777.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Aug 2018
PARF Rebate Amount: \$8,388.00

Intended COE Rebate Details

COE Expiry Date: 28 Aug 2018
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$13,289.00
COE Rebate Amount: \$257.00
Total Rebate Amount: \$8,645.00

The information contained herein is correct as at 18 Jun 2018

OK



Toyota Corolla Price Range Depreciation 2008 Vehicle Type

Advanced Search

Home - Used Cars - Boeki Auto & Marine - Toyota Corolla Altis 1.6A

Resources

- [Car Buying](#)
- [Car Selling](#)
- [Car Ownership](#)
- [Car Aftermarket](#)
- [On The Move](#)
- [Lifestyle](#)

Toyota Corolla Altis 1.6A

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)



BOEKI AUTO & MARINE



[Add to Shortlist](#) [Add to Compare](#) [Add a Note](#) [Report Error](#) [More Actions](#) [Share](#)

Car Details

| | | |
|----------------------|--|--|
| Price | \$12,688 | |
| Depreciation | - | |
| Reg Date | 28-Aug-2008 (2mths 2days COE left) | |
| Manufactured | 2008 | |
| Mileage | 145,000 km (14.8k /yr) | |
| Transmission | Auto | |
| Engine Cap | 1,598 cc | |
| Road Tax | \$742 /yr | |
| Power | 80.0 kW (107 bhp) View specs of the Toyota Corolla Altis (2008-2013) | |
| Curb Weight | 1,195 kg | |
| Features | - | |
| Accessories | - | |
| Description | Trade In All Available. Interested Please Call For Viewing. Viewing By Appointment Only. | |
| COE | \$12,501 | |
| OMV | \$16,777 | |
| ARF | \$16,777 | |
| Dereg Value | \$8,604 as of today (change) | |
| No. of Owners | 3 | |
| Type of Veh | Mid-Size Sedn | |
| Category | MPV Car | |
| Availability | Available | |

[Add to Shortlist](#) [Add to Compare](#) [Add a Note](#)

Posted on: 23-Jun-2018 | Last Updated on: 23-Jun-2018

Tags: Toyota Corolla, 2008 Toyota Corolla, Toyota, Corolla, used Toyota

Upfront Payment [+ more Financial info](#)

| | | |
|---------------------|------------------|------------------|
| Transfer Fee | \$25 | |
| Down Payment | \$3,806 (change) | Maximum 70% Loan |



Seller Information

| | | |
|--------------------------|--|----------|
| Company | Boeki Auto & Marine • Dealer's pricelist • 109 vehs sold 61 vehs available | |
| Address | 176 Sin Ming Drive #02-15 Search cars nearby this location | |
| Location | Sin Ming Auto Care | |
| Office No | 65549390 | |
| Contact Person(s) | Boeki | 82180500 |

Compare



陳林璋有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel: 68585151 (24 Hours) Fax: 68580877
GST Regn. No.: M2-8922054-2

AIGAsia Insured's Veh No: SKP2122B
Date of Accident: 17 June 2018

*not approved
date
take photo after up
25/6/18
PII to 960
2dy.*

Mr Chan Yew Kee, David

Date: 19 June 2018

*confirmed with
warcus 25/6/2018*

Estimate To Repair SFM4804G - Toyota COROLLAALIS 1.6 AUTO
Chassis No: MR053ZEE106115104

| S/No | Quantity | Description | Amount |
|------|----------|--|------------------------|
| 01 | 1 pc | <u>LIST ITEMS</u> n/s rear door protector <i>R</i> | \$ 75.00 <i>X</i> |
| 02 | 1 pc | n/s rear door protector moulding <i>n1</i> | \$ 27.80 <i>X</i> |
| | | | \$ 102.80 |
| | | Less 25 % | \$ 25.70 |
| | | | \$ 77.10 |
| 03 | 1 pc | <u>SPECIAL NETT ITEMS</u> n/s rear wheel rim <i>n</i> | \$ 400.00 <i>X</i> |
| | | | \$ 400.00 |
| | | <u>LABOUR & MISC. CHARGES</u> | |
| 01 | | To check steering geometry and computer wheel alignment. | \$ 120.00 <i>60</i> |
| 02 | | To transfer of n/s rear wheel tyre, rim and on wheel balancing | \$ 50.00 |
| 03 | | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. | \$ 450.00 <i>300</i> |
| 04 | | Putty and spray painting of the affected portion. | \$ 800.00 <i>600</i> |
| | | | \$ 1,420.00 <i>960</i> |
| | | Total | \$ 1,897.10 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- This parts supply is on a "Without Prejudice" basis
- No single instructions are allowed
- Supplies and services must be resurveyed and is subject to prior approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

- Accident Involving SFM 4804 G and SKP 2122 D on 17 Jun 2018

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 10/9/2018 9:58:48 AM
Attachments:  [GIAreport at Tan Lim.pdf](#)

AIG
KKIMHIN

Hi LKK,

Please assist to handle.

10:36am @ 10/9/18
person @ shuman
vehicle not in

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: service@kkimhin.com.sg [mailto:service@kkimhin.com.sg]
Sent: Monday, September 10, 2018 9:49 AM
To: AIG SGP, Claims-Survey
Cc: sandrakhong@gmail.com; admin1@kkimhin.com.sg; simon@kkimhin.com.sg; survey@kkimhin.com.sg
Subject: Accident Involving SFM 4804 G and SKP 2122 D on 17 Jun 2018

Dear Officer

Enclosed the GIA report of SFM 4804 G who was hit by your insured SKP 2122 D on 17 June 2018.

We understand that the client previously has gone to other workshop and she does not want to repair there anymore.

We will take over the case.

Please kindly appoint surveyor and advise liability. Thank you.

Thanks & Regards
Sandra
6452 7018
K. Kim Hin Auto Pte Ltd

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Monday, 23 July 2018 3:59 PM
To: 'jordan@huanan.com.sg'
Cc: Admin A
Subject: ACCIDENT INVOLVING SKP 2122D AND SFM 4804G ON 17/06/2018

OUR REF: LKK: CC6/AIG18011427/Uja3

HUA NAN MARINE PTE LTD

Policy Holder

Dear Sir,

ACCIDENT INVOLVING SKP 2122D AND SFM 4804G ON 17/06/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Your Ref: SKP2122D
Our Ref : 180575/06

-LOA-

Mr Chan Yew Kee, David
Correspondence Address :
c/o M/s K. Kim Hin Auto Pte Ltd
160 Sin Ming Drive #02-20
Sin Ming AutoCity
Singapore 575722

Date: 29 NOV 2018

AIG Asia Pacific Insurance Pte Ltd
Motor Claims Dept
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Dear Sir/Madam

**ACCIDENT INVOLVING SFM 4804 G AND SKP 2122 D ALONG HOUGANG
AVE 2 TWDS AVE 3 ON 17 JUNE 2018**

I am the owner of the m/vehicle SFM 4804 G which was involved in the above accident.


My vehicle sustained damages as a result of the said accident and I am now claiming against you for the followings:-

| | | |
|---|-----------------|-------------|
| 1. Costs of repairs | | \$ 909.50 |
| 2. Loss of use of vehicle at \$ per day for 3 day(s) | \$80.00 | \$ 240.00 |
| 3. Police documents/Search fees | | \$ 2.00 |
| 4. Surveyor report fee | | \$ - |
| | Total: | \$ 1,151.50 |
| | | ===== |

Please advise whether you are prepared to settle my claim as outlined above. As I have yet to settle my repair bill with my repairers, I hereby authorise my repairers and/or their representatives to negotiate/compromise settlement of above claim on my behalf.

Looking forward to hear from you soon.

Yours faithfully,



encl.

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, K.KIM HIN AUTO PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$1,030.00 (Global Sum) for vehicle no. SFM 4804G that was damaged pursuant to the accident which occurred on 17/06/2018 (date) along HOUGANG AVE 2/ AVE 3 (location) involving vehicle no/s SKP 2122D. This is pursuant to the inspection conducted on 25/06/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHAN YEW KEE DAVID ("the third party claimant") of vehicle no SFM 4804G make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SFM 4804G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 28 (day) of February (month) 2019 (year)



o/k/s

Signed by appointed surveyor



Signed by "the workshop" (with chop)



DUPLICATE

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 23821

Vehicle Insured : SKP 2122 D
Accident Date : 17-Jun-2018

Date : 11-Oct-2018

Our Ref : 180575 (AIG ASIA) / MARGARET

PAGE : 1

CHAN YEW KEE, DAVID (MR)
Singapore

COST OF REPAIR FOR TOYOTA COROLLA ALTIS 1.6 A (2008) SFM4804G
=====

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

250.00

To putty and respray on affected
portions.

600.00

850.00
Add 7% GST : 59.50

Total : S\$ 909.50
=====

Singapore Dollars Nine Hundred and Nine and Cents
Fifty Only



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SFM 4804G

Third Party Insurer Enquiry

Our Ref No: GR-18-138718

Date of Request: 08/09/2018

Your Ref No:

Online Purchase

K Kim Hin Auto Pte Ltd
160 Sin Ming Drive #02-20
Sin Ming AutoCity
Singapore 575722

Dear Sir/Madam,

Enquiry Date 08/09/2018
Enquiry By Sandra Khong Yee Teng
TP Vehicle No. SKP2122D
Accident Date 17/06/2018

Enquiry Result

| TP Vehicle No. | Insurer | Period of Insurance | Insurer Tel. No. |
|----------------|--------------------------------------|-----------------------|------------------|
| SKP2122D | AIG Asia Pacific Insurance Pte. Ltd. | 12/12/2017-11/12/2018 | 65-6419-3000 |

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-138718
Date of Request: 08/09/2018

Your Ref No: Online Purchase

K Kim Hin Auto Pte Ltd
160 Sin Ming Drive #02-20
Sin Ming AutoCity
Singapore 575722

Dear Sir/Madam,

Enquiry Date: 08/09/2018
Enquiry By: Sandra Khong Yee Teng
TP Vehicle No.: SKP2122D
Accident Date: 17/06/2018

| DESCRIPTION | AMOUNT (S\$) |
|----------------------------------|--------------|
| TP Insurer Enquiry | 1.87 |
| GST Amount | 0.13 |
| Total Amount Due (GST Inclusive) | 2.00 |

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 27 Jun 2018 Edit Reg | | 25 Jun 2018 00:00 Edit Adj Rpt | S\$850.00 Edit Estimates | S\$850.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | HUA NAN MARINE PTE LTD , Co. Reg. No.: 2004150612, Tel: +6599999999 | | | | | | | | |
| Main Claimant: | CHAN YEW KEE, DAVID , ID: S0557349A | | | | | | | | |
| Vehicle Reg. No.: | SFM4804G | Date of Loss: | 17/06/2018 00:00 - :59 [117 Months and 19 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 6368850392SG | Policy/Cover Note No.: | 2100492803 (Comprehensive) Coverage: 12/12/2017 - 11/12/2018 | | | | | | |
| Vehicle Reg. No. (Insured): | SKP2122D | Policy No. (Claimant): | 5055218128-05 | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018 | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com | | | | | | | | |
| Claimant's Insurer: | NTUC Income Insurance Co-operative Ltd (HQ) - Tel: | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 03/07/2018] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| • AIG_5G (26/06/2018): No Policy Found | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SFM4804G (6368850392SG)
[SKP2122D]
TP
CHAN YEW KEE, DAVID
Jun 17 2018 12:00AM
[HUA NAN MARINE PTE LTD]
K Kim Hin Auto Pte Ltd

| Upload Documents | | | Upload Photos | | | Compose New Letter | | | Upload Video | | | Upload Audio | | | View View in Browser | |
|--------------------------------|-----------------|---|---------------|--|--|--------------------|--|--|--------------|--|--|--------------|----------|-------------------------------------|---|--|
| Video | | | | | | | | | | | | | | 1 per page | <input checked="" type="checkbox"/> | |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | Thumbnail | Print | | | |
| 1 | 07/09/18 11:11 | Video - Accident VIDEO FROM TP - DIV FROM SLIP ROAD | | | | | | | | | | | Load MP4 | | | |
| Letters/Correspondences | | | | | | | | | | | | | | 1 per page | <input checked="" type="checkbox"/> | |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | Thumbnail | Print | | | |
| 1 | (Draft) | Third Party Express Settlement - Payment Breakdown | | | | | | | | | | | Edit | | | |
| Photos/Images | | | | | | | | | | | | | | 3 per page | <input checked="" type="checkbox"/> | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | Thumbnail | Print | | | |
| 1 | 25/06/18 17:21 | General View | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 2 | 25/06/18 17:21 | General View | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 3 | 25/06/18 17:21 | General View | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 4 | 25/06/18 17:21 | General View | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 5 | 25/06/18 17:21 | General View | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 6 | 25/06/18 17:21 | General View | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 7 | 25/06/18 17:21 | General View | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 8 | 25/06/18 17:21 | General View | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 9 | 25/06/18 17:21 | General View | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 10 | 25/06/18 17:21 | General View | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 11 | 25/06/18 17:21 | General View | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 12 | 25/06/18 17:21 | General View | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 13 | 25/06/18 17:21 | General View | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 14 | 25/06/18 17:21 | General View | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 15 | 25/06/18 17:21 | General View | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 16 | 25/06/18 17:22 | Chassis Number | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| 17 | 25/06/18 17:22 | Odometer Reading | | | | | | | | | | | Load JPG | <input checked="" type="checkbox"/> | | |
| Documentation | | | | | | | | | | | | | | 1 per page | <input checked="" type="checkbox"/> | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | Thumbnail | Print | | | |
| 1 | 25/06/18 19:46 | TP GIA REPORT | | | | | | | | | | | Load PDF | | | |
| 2 | 03/07/18 12:03 | TP GIA REPORT-ADDENDUM | | | | | | | | | | | Load PDF | | | |
| 3 | 10/09/18 15:09 | EMAIL FROM AIG DD 10.09.2018 | | | | | | | | | | | Load PDF | | | |
| 4 | 05/10/18 08:59 | MARKED ESTIMATE | | | | | | | | | | | Load PDF | | | |
| 5 | 04/03/19 10:57 | WORKSHOP INVOICE | | | | | | | | | | | Load PDF | | | |
| 6 | 04/03/19 10:57 | AUTHORISATION TO ACT FORM | | | | | | | | | | | Load PDF | | | |
| 7 | 04/03/19 10:57 | Release Voucher | | | | | | | | | | | Load PDF | | | |
| 8 | 04/03/19 10:57 | GIA SEARCH | | | | | | | | | | | Load PDF | | | |
| 9 | 04/03/19 10:57 | LETTER TO OI | | | | | | | | | | | Load PDF | | | |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | | | | | | | | | | Thumbnail | Print | | | |
| 1 | 27/06/18 11:40 | OI GIA REPORT | | | | | | | | | | | Load PDF | | | |
| 2 | 12/12/18 15:13 | LOD | | | | | | | | | | | Load PDF | | | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|---|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) | | | |
| <div style="border: 1px solid black; height: 40px; width: 100%;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer | | | |
| <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

| | | | |
|-------------------|---------------------|--------|---------------------------------|
| Vehicle No: | SKP2122D (Insd veh) | Model: | TOYOTA COROLLA ALTIS 1.6 (A) |
| | SFM4804G (TP veh) | | |
| Date of Accident: | 17/06/2018 | | |

| | | | |
|---|---|--|------------------------------|
| Global Sum Settlement | : | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| Repair Estimate | : | \$ | 1,232.11 |
| Final Repair Cost | : | \$ | 1,030.00 |
| Loss of Use | : | \$ | 2.00 days at \$60.00 per day |
| Rental (if any) | : | \$ | days |
| LTA / GIA Search Fee | : | \$ | |
| Others: | : | \$ | |
| | : | \$ | |
| Final Settlement Sum (Global Sum) | : | \$ | 1,030.00 |
| Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below) | | | |
| A) For <u>Non GIA Registered Workshop</u> : | | Agreed Liability _____(%) | |
| B) For <u>GIA Registered Workshop</u> : | | BOLA Applicable: Yes / No BOLA Scenario No: | |
| | | __NIL__ | |
| BOLA Liability: _____100____(%) | | Assessed Liability (*): _____(%) | |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply. | | | |
| Remarks _____ | | | |

| Payment Instruction: Payee's Breakdown | | | |
|--|------------------------|---|-------------|
| 1) | K.Kim Hin Auto Pte Ltd | : | \$ 1,030.00 |
| 2) | | : | \$ |
| 3) | | : | \$ |

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

04 Mar
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18011427/UJA3Q2
Date: 04/03/2019

REFERENCE

| | | |
|--|-----------------------------|---------------------------|
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 2100492803 |
| Claimant Vehicle No : SFM4804G | Insured Vehicle No : | SKP2122D |
| Date of Loss: 17/06/2018 | Nature of Claim: | TP Claim No: 6368850392SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SFM4804G | Engine No: | 3ZZ4786171 |
| Make & Model: | TOYOTA COROLLA ALTIS, 1.6 (A) | Chassis No: | MR053ZEE106115104 |
| Reg. Date: | 29/08/2008 (Man. Year: 2008) | Odometer: | 183994 km |
| Colour: | Grey | | |
| Engine Capacity: | 1598 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|------------------|
| Front Tyre Size: | 205/55 R16 | Rear Tyre Size: | 205/55 R16 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Continental 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Continental 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-----------------|-----------------|---------------|--------------|
| Parts | 151.50 | 0.00 | 151.50 | 100.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,000.00 | 850.00 | 150.00 | 15.00 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 1,151.50 | 850.00 | 301.50 | 26.18 |
| + GST 7.00/7.00% (S\$) | 80.61 | 59.50 | 21.11 | 26.19 |
| Nett Amount (S\$) | 1,232.11 | 909.50 | 322.61 | 26.18 |
| + Loss of Use (2.0 x S\$60.00/day) (S\$) | | 120.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 1,031.50 | | |
| Global Sum Settlement (S\$) | | 1,030.00 | | |

INSPECTION

| | | |
|---------------------|--------------------------|--|
| Date of Assignment: | 25/06/2018 | |
| Date Inspected: | 25/06/2018 Inspected At: | K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity Singapore 575722 |

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|-----|-----|----------|--------------------------------------|---------------|---|---------------|-------------|
| 1 | 1 | | *N/S REAR BUMPER SIDE RETAINER | Not Necessary | 58.00 FL | *- FL | |
| 2 | 5 | | *REAR BUMPER CLIPS | Not Necessary | 25.00 FL | *- FL | |
| 3 | 1 | | *N/S REAR DOOR PROTECTOR | Repair | 90.00 FL | *- FL | |
| 4 | 1 | | *N/S REAR DOOR OUTER CHROME MOULDING | Not Necessary | 29.00 FL | *- FL | |
| | | | | | Sub Total (S\$) | 202.00 | 0.00 |
| | | | | | - List Item Discount on L Items 25.00/25.00% (S\$) | 50.50 | 0.00 |
| | | | | | Total Parts (S\$) | 151.50 | 0.00 |

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE ,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW AFFECTED PARTS | New | 250.00 | 250.00 |
| 2 | TO PUTTY AND RESPRAY ON AFFECTED PORTIONS | New | 750.00 | 600.00 |
| Gross Labour Cost (S\$) | | | 1,000.00 | 850.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >