

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: C0446793

Date: 02<sup>nd</sup> July 2018

Our Ref: CS3/AXA17015168/Lsbe2-1

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01 AXA Tower Singapore 068811 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SGE 2615D INSURED VEHICLE: GBB 5698U ACCIDENT DATE: 02/08/2017

We thank you for your instruction on 22/06/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGE 2615D from M/s Par Automotive Consultancy.
- b) Singapore Accident Statement and Police Report of Vehicles SGE 2615D.
- c) Colour damaged vehicle photographs of SGE 2615D.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: SGE 2615D

Make & Model

: Honda Civic 1.8 L A

Year of Registration

: 2006

Chassis Number

: JHMFD16206S205153

**Engine Capacity** 

: 1799 cc

- 2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.