

ASS. REP. BY:

REF CS/FCI18011473 / Krds n2

Special Instruction:

Surveyor

CWS

ASSIGNMENT (Office)

From (Person):

Sithara

of

FCI

Date/Time

25/6/18 @ 9:48am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGV 857X

Insured:

SHC 7831L

at Workshop m/s

Ah lim motor

Tel:

64831244

of

No. 10 AMK Ind. park 2A #01-09

Policy No:

Claim No:

D18004937MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 20/06/2018

26/06/18 @ 1:30pm owner waiting

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement

Date/Time:

10am @ 25/6/18

Person Contacted:

Zila

Vehicle-IN

OUT

| Date/Time | Action/Instruction (✓) Estimate | DOA |
|-----------|--|-----------------|
| | SGV 857X - CC41AXA17023766 / T/pb3 | DOA: 11/12/2017 |
| | SHC 7831L - CS/FCI15008550 / R/bd1 | DOA: 17/05/2015 |
| | Revert thru email. | |
| 2018 | 82787.12 Covered by email (Red. \$1087.60, 28%.) | |

Surveys

REF: FA

ASSIGNMENT

From: _____ Date: **26062018**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. **SGV 857 X**

at Workshop m/s **Ah Lim Motor**

of **Blk 10 AMK Ind Park 2A #**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition) **1:30pm**

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: **8.65k**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **03** days Res.: Yes or No

Lum Sum: **1.81** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Veh No. **SGV 857 X** Yr Regn: **10 / 17**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: **Hyundai Elantra 1.5PI**

Colour: **M. Grey** A/C: Insured / Std / NI / NA

Sp. Reading: **12143** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **KM11D841CMTJ0559884**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: **195/65R15**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Nexen**

| | |
|-----------------------|-----------------------|
| Front | Rear |
| R/Bal. 9 mm | R/Bal. 9 mm |
| L/Bal. 9 mm | L/Bal. 9 mm |
| D.O.A. 20/6/18 | D.O.I. 26/6/18 |

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or **FR N/S**

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-----------------------------|------------------------------|
| 27/6 | Blk pass to Catherine |
| RECEIVED 20 AUG 2018 | |

Date/Time, File Pass to? Preli. Report

1) **typist** Final Report

Date/Time, File Return to? _____

2) _____

Report Format: **1P**

Lump Sum / I.B.I: (\$) **2787.12**

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee: **130**

Transportation: **50**

Photos: **17**

Others: _____

TOTAL: **247**



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004937MFSH

Our Ref: CS/FCI180011473/Krd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGV 857X

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26.06.2018 at the premises of M/s AH LIM MOTOR PTE LTD and have the following to report:-

| | |
|--------------------------|-----------------------|
| Workshop Estimate Amount | : S\$ <u>3,874.72</u> |
| Revised Estimate Amount | : S\$ <u>2,575.04</u> |
| "Check" Items Amount | : S\$ <u>857.28</u> |
| Market Value | : S\$ <u>-</u> |
| LTA Reimbursement Value | : S\$ <u>-</u> |
| Nett Value | : S\$ <u>-</u> |

Description of Damage:

The vehicle sustained damages at o/s front n/s portion.



Yours faithfully
KENNETH KONG
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

| | | |
|---------------------------|---|-------------------------------------|
| Date | 22-06-2018 | Our Ref No. D18004937MFSH |
| Accident Date | 20-06-2018 | Claim Type. Third Party |
| Insured Vehicle | SHC7831L | Third Party Vehicle. SGV857X |
| Survey Location | NO. 10 ANG MO KIO IND PARK 2A #01-09 AMK AUTOPOINT | |
| Contact Person. | ZILA | |
| Contact No. | 64831244/ 64831244 | Fax No. 64836170 |
| Survey Type | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: | |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD | |
| Contact Person | NA | Fax No. 68416315 |
| Contact Number. | NA | |

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

| | | |
|--------------------------|----------------------|--------------------------------|
| Cc : Workshop | AH LIM MOTOR COMPANY | Attention. NIL |
| Cc : TP Solicitor | NA | TP Solicitor Fax No. NA |
| Officer Incharge | SITHARA | |

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241697)



PRI Documents



Close



PRI Header Details

| | | | | | |
|--------------------------|--|--|--|---------------------------------|--------------|
| Claim No | D18004937MFSH | Policy No | D-18088937MFSH | Claimant S.No & Name | 1 & AH LIM M |
| Workshop Name | AH LIM MOTOR COMPANY (Contact Person : ZILA) | Survey Location & Contact Details | NO. 10 ANG MO KIO IND PARK 2A #01-09 AMK AUTOPC Mobile: 64831244 , Phone: 64831244 , Fax: 64836171 EmailId: ZILA@AHLIMMOTOR.COM.SG | | |
| Our Surveyor | LKK AUTO CONSULTANTS PTE LTD | Instructions To Surveyor | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM | | |
| Insured Name | CITYCAB PTE LTD | Insured Vehicle No | SHC7831L | TP Vehicle No | SGV857X |
| PRI Recieved Date | 22-06-2018 09:40:25 PM | Surveyor Appointed Date | 25-06-2018 09:47:51 AM | Surveyor Accept Date | 25-06-2018 1 |

Survey Report Upload

| | | | | | |
|------------------------------------|----------------------|-----------------------------|------------|--------------------------------|--|
| Surveyor Inspection Date *: | <input type="text"/> | Surveyor Report Date | 25-06-2018 | Upload Survey Report *: | <input type="button" value="Choose File"/> |
|------------------------------------|----------------------|-----------------------------|------------|--------------------------------|--|

Vehicle Particulars

| | | | | | |
|------------------|---|-----------------------|--|----------------|--|
| Make | <input type="text" value="Please Select Make"/> | Model | <input type="text" value="Please Select Model"/> | Year | <input type="text" value="Select Year"/> |
| Chasis No | <input type="text"/> | Engine No | <input type="text"/> | Mileage | <input type="text"/> |
| Color | <input type="text"/> | Cubic Capacity | <input type="text"/> | | |

Multiple Documents Upload

| | |
|--|---------------|
| <input type="button" value="Upload Multiple Documents"/> | |
| File Name | Action |

Surveyor Job Remarks

| | | |
|----------------|----------------------|-------------------------------------|
| Remarks | <input type="text"/> | <input type="button" value="Save"/> |
|----------------|----------------------|-------------------------------------|

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3099G

Vehicle Details

Vehicle No.: SGV857X
Vehicle to be Exported: No
Intended De-registration Date: 21 Jun 2018
Vehicle Make: HYUNDAI
Vehicle Model: ELANTRA AD 1.6 GLS AT
Primary Colour: Silver
Manufacturing Year: 2017
Engine No.: G4FGHU795820
Chassis No.: KMHD841CMJU559884
Maximum Power Output: 93.8 kW (125 bhp)
Open Market Value: \$12,032.00
Original Registration Date: 27 Oct 2017
First Registration Date: 27 Oct 2017
Transfer Count: 0
Actual ARF Paid: \$12,032.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Oct 2027
PARF Rebate Amount: \$9,024.00

Intended COE Rebate Details

COE Expiry Date: 26 Oct 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$42,902.00
COE Rebate Amount: \$40,099.00
Total Rebate Amount: \$49,123.00

The information contained herein is correct as at 21 Jun 2018

OK

Sketch Plan Pg. 3

AXA INSURANCE PTE LTD
 8 Shenton Way, #24-01
 AXA Tower, Singapore 068811
 Customer Service Centre #B1-01
 Tel:(65)63387288 Fax:(65)63382522
 Website:www.axa.com.sg
 GST Registration Number: 199903512M
 customer.service@axa.com.sg



Private Cars COMP
 POLICY SCHEDULE
 NEW BUSINESS
 Original

| | | |
|--|--|--------------------------------------|
| POLICY INFORMATION | | Policy No. : VFA/P2026133 |
| Source | : (01) 08260 KOMOCO TRADING P/L (HY) | |
| Insured | : CHEW YONG ALEX | |
| Address | : BLK 299C COMPASSVALE STREET #04-124 SINGAPORE 543299 | |
| Business/Profession | : PROFESSIONAL Carrying on or engaged in the business or profession last declared and no other for the purpose of this insurance. | |
| Period of Insurance | : From 27/10/2017 To 26/10/2018 (Both Dates Inclusive) | |
| Any subsequent period for which the Insured shall pay and the Company shall agree to accept a renewal premium. | | |
| PREMIUM | | |
| Premium After 50.00% NCD | : SGD 809.60 | |
| Safe Driver Disc 8.00% | : SGD 64.77 | |
| NCD Protector | : SGD 59.59 | |
| GST 7.00% | : SGD 56.31 | |
| Annual Premium | : SGD 860.73 | |
| Total Payable | : SGD 860.73 | |
| RISK DETAILS THE MOTOR VEHICLE | | |
| Type Of Cover | : Comprehensive | |
| Regn No. | : SGV857X | |
| Type Of Use | : Private Car | |
| Make/Model | : HYUNDAI ELANTRA AD 1.6 GLS AT | |
| Year of Manufacture | 2017 | Seating Capacity (excl. Driver) : 04 |
| Body Type | : SALOON | Engine C.C. : 1591 |
| Engine No. | : G4FGHU795820 | Chassis No. : KMHD841CMJU559884 |
| Insured's Estimated Market Value | : Market Value At The Time Of Loss (including Accessories and Spare Parts) | |
| Limitations as to Use : As specified in Certificate of Insurance | | |
| <u>Extra Coverage(Premium Breakdown)</u> | <u>Limits (SGD)</u> | <u>Premium (SGD)</u> |
| NCD Protector | | 59.59 |
| Basic Own Damage Excess | : SGD | |
| <u>Named Drivers</u> | | |
| 1 CHEW YONG ALEX | | |
| 2 CAROLINE QUEK MAY PEI | | |

Sketch Plan Pg. 4

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7813099G




Name
CHEW YONG, ALEX
(ZHOU YONG)
周 勇

Race
CHINESE

Date of birth 11-05-1978 Sex M

Country of birth
SINGAPORE

S7813099G

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S7813099G



CHEW YONG, ALEX (ZHOU YONG, ALEX)

Exp. Date 11 May 1978

Issue Date 18 Feb 2003

000210788H

93259320.

D/C
No injury.
No video.
Lifex

Caroline female
Tiffany female
Ian male

4210245



NRIC No S7813099G



Date of issue
15-05-2008

Address
APT BLK 299C COMPASSVALE STREET
#04-124
SINGAPORE 543299

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

| Class | Description | PASS DATE |
|---------|--|-------------|
| Class 3 | Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms | 12 Mar 1996 |

NP 428A

Licence No: S7813099G



Sketch Plan Pg. 5



Date: 2010/06/18

To: Owner of Vehicle Number: SGV 857X

The following has been advised to you via your workshop, Ah Lim Motor Company through their staff, Zila / Eileen / Mui Hong.

Please tick the applicable box if you had been advice on the content as seen below:

You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

You had been advised by the workshop on the liability and merits of the case accordingly.

You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.

There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.

There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.

The estimated waiting time for the spare parts to arrive is _____ . The estimated arrival time does not include the repair period.

You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.

For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.

For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using *any combination* of genuine original parts and/or original equipment manufacturer (OEM) parts.

You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.

For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.

Others claim trust party.

Signed and acknowledge by:

[Signature]

Name and signature of policyholder/authorised driver

mtc
Name and signature of workshop personnel including company stamp



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHEW YONG ALEX (ZHOU YONG)
 BLK 299C COMPASSVALE STREET
 #04-124
 SINGAPORE 543299

Estimate No: MC0913206
Date: 22 Jun 2018
Policy No: P2026133
Veh Reg No: SGV857X
Make/Model: HYUNDAI ELANTRA
 AD 1.6 GLS

ATTN:

Your Ref No: SGV857X
 Claim Type: Third Party — 1st cap
 Accident Date: 20/06/2018
 TP Veh Reg No: SHC7831L

LKIC
 1:30pm

NOT Authorized
 1.B.1
 Resurvey B4 painting
 3 days

Estimate Repair Cost to Vehicle No :SGV857X

| Description | Quantity | List Price | Amount |
|--|----------|-----------------------------|--------------------|
| | | <u>SS</u> | <u>SS</u> |
| SPARE PARTS | | | |
| 1 FRONT GRILLE ASSY | 1 PC | <i>nd/wt</i> 460.20 | ✓ |
| 2 FRONT GRILLE CLIPS | 6 PC | <i>m</i> 12.00 | ✓ |
| 3 HEADLAMP LH | 1 PC | <i>ca</i> 1,198.80 | ✓ |
| 4 FRONT BUMPER | 1 PC | <i>cm</i> 474.40 | ✓ |
| 5 FRONT BUMPER SIDE RETAINER LH & RH | 2 PC | <i>n/d</i> 56.00 | 4 28 |
| 6 FRONT BUMPER CLIPS | 15 PC | <i>m</i> 30.00 | ✓ |
| 7 FRONT BUMPER REINFORCEMENT | 1 PC | <i>R</i> 695.80 | ✗ |
| 8 FRONT BUMPER SPONGE | 1 PC | <i>su</i> 110.70 | ✗ |
| 9 FOGLAMP LH | 1 PC | 265.10 | ✓ |
| 10 FOGLAMP COVER LH | 1 PC | <i>cm</i> 115.40 | ✓ |
| | | 3,418.40 | |
| | Less 20% | 683.68 | 2,734.72 |
| LABOUR | | | |
| 11 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING. | 1 PC | 40.00 | 200 |
| 12 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. | 1 PC | 500.00 | 3000 |
| 13 TO SPRAY FRONT BONNET,FRONT BUMPER,FRONT FENDER LH. | 1 PC | 600.00 | 4000 |
| | | 1,140.00 | 1,140.00 |
| | | Total | SS 3,874.72 |
| | | Add GST @ 7% | 271.23 |
| | | Total Amount Payable | SS 4,145.95 |

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND ONE HUNDRED FORTY FIVE AND CENTS NINETY FIVE ONLY

Please arrange this vehicle to be surveyed as soon as possible
 Thank You

LKK Auto Consultants hence notify the Receiver of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|-----------------------------|---|
| FIRST CAPITAL INSURANCE LTD | | Ref : CS/FCI18011473/Krd3n2 | |
| 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 | | Date : 21-08-2018 |  |
| | | Code : FCI2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SHC 7831L | Veh. Inspected | SGV 857X |
| Policy No. | D-18088937MFSH | Coverage (\$) | 0.00 |
| Claim No. | D18004937MFSH | Excess (\$) | 0.00 |
| Assign From | SITHARA | Assign Date | 25/06/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | HYUNDAI ELANTRA (A) | c.c | 1591 |
| Engine No. | HIDDEN | Year of Reg. | 2017 |
| Chassis No. | KMHD841CMJU559884 | Colour | METALLIC GREY |
| Odometer | 12143 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 195/65 R15 | NEXEN | 9 mm |
| L/H Front Tyre | 195/65 R15 | NEXEN | 9 mm |
| R/H Rear Tyre | 195/65 R15 | NEXEN | 9 mm |
| L/H Rear Tyre | 195/65 R15 | NEXEN | 9 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 20/06/2018 | Inspection Date | 26/06/2018 |
| Survey held at | AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047 | | |
| 5a. Remarks | | | |
| A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 3 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGV 857X

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|----------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | FRONT GRILLE ASSY | DENTED / CUT | 460.20 | 460.20 |
| 6 | FRONT GRILLE CLIPS | NECESSARY | 12.00 | 12.00 |
| 1 | HEADLAMP LH | CUT | 1,198.80 | 1,198.80 |
| 1 | FRONT BUMPER | CRACKED | 474.40 | 474.40 |
| 2 | FRONT BUMPER SIDE RETAINER LH & RH | N/S DISTORTED | 56.00 | 28.00 |
| 15 | FRONT BUMPER CLIPS | NECESSARY | 30.00 | 30.00 |
| 1 | FRONT BUMPER REINFORCEMENT | TO REPAIR SEE LABOUR | 695.80 | - |
| 1 | FRONT BUMPER SPONGE | SERVICEABLE | 110.70 | - |
| 1 | FOGLAMP LH | MTG BENT | 265.10 | 265.10 |
| 1 | FOGLAMP COVER LH | CRACKED | 115.40 | 115.40 |
| | LESS 20% DISCOUNT | | -683.68 | -516.78 |
| | | | 2,734.72 | 2,067.12 |
| LABOUR | | | | |
| | TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING. | | 40.00 | 20.00 |
| | TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT. | | 500.00 | 300.00 |
| | TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH. | | 600.00 | 400.00 |
| | | | 1,140.00 | 720.00 |
| GRAND TOTAL | | | 3,874.72 | 2,787.12 |
| RECOMMENDED COST OF REPAIRS | | | | 2,787.12 |

Report Ref No. CS/FCI18011473/Krd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.