

ASS. REC. BY:

REF:

CS3 | LCR18011474 | T124d302

Instruction: ✓

Surveyor
Maimun

Taufik

ASSIGNMENT (Office)

From (Person):

chin lee ying

of

LCR

Date/Time:

25/6/18 @ 9:33am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGM 7111 R

Insured:

SLG 5429 K

at Workshop m/s

Verve Motorclinic

Tel:

9159 5951

of NO. 25 Kaki Bkt Rd 4 # 03-39 Synergy

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/06/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time: 10:15am @ 25/6/18

Person Contacted:

Mr. Jaron

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SGM 7111 R - X
	SLG 5429 K - 03 / LCR17022943 / Spb392 DUA: 30/11/2017
26/6/18	Dismantled

Tanjan

REF: AIG

ASSIGNMENT

From: Date: 25/06/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGM711R.
at Workshop m/s: Verve Motorclinic
of: No. 25 Kaki Bkt Rd 4 #03-39
Insured: synergy

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh: Mr. Juran @ 91595951

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ups

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

*Battery weak -

31/7/18 Submit DAR Report.

MV 30K - 31K lulu, 26/7/18

Repair Days 10

Veh No: SGM711R Yr Regn: 2009 June.

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic Type-R C.C: 1998

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: — T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FD2600357

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I.

25/6/18 E3pm

Survey held at: Verve Motorclinic

Des. of Damages: (Ft) (Rear) O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1) S+R: SI

2) Photos

3) Others

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.F. (\$

180

20

200

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE
SLG5429K AND SGM7111R ON DOA 22/6/2018**

From: Chin, Lee-Ying
To: assignments@lkkauto.com, Admin A
Cc: Fong, Andy-SY
Sent: 25/6/2018 9:33:42 AM
Attachments:  180622-Info of SGM7111R.PDF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Yvonne [mailto:yvonne@ealc.com.sg]
Sent: Friday, June 22, 2018 4:01 PM
To: Chan, Yoke Shi
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina
Subject: PRI AIG Insured SLG5429K [EAL.2018.5739.MK.ya -SGM7111R]

Our ref : 2018.5739.MK.ya -**SGM7111R**
Your ref : **SLG5429K**

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

AIG Asia Pacific Insurance Pte Ltd
No. 78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s AIG Asia Pacific Insurance Pte Ltd
Vehicle **SGM7111R** inspected as follows by Name:

Before repair	Parts removed	After repair
<hr/>	<hr/>	<hr/>
Signature	Signature	Signature
Date/ Time:	Date/ Time:	Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE

CLAIMANT: RAMESH S/O RENEANATHAN

ACCIDENT INVOLVING SGM7111R & SLG5429K & SLT776Y ON 22 JUNE 2018 ALONG KPE TUNNEL AT ABOUT 0942 HOURS

We refer to the above matter wherein we are instructed to act for **RAMESH S/O RENEANATHAN**, the owner of vehicle no. **SGM7111R**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **SGM7111R** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Verve Motorclinic Pte Ltd
No. 25 Kaki Bukit Road 4,
#03-39 Synergy@KB,
Singapore 417800
Tel: 91595951 (Mr Jaron)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9299H
Vehicle Details	
Vehicle No.:	SGM7111R
Vehicle to be Exported:	No
Intended De-registration Date:	26 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC TYPE-R 2.0 M
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	K20A5840414
Chassis No.:	FD21600357
Maximum Power Output:	165.0 kW (221 bhp)
Open Market Value:	\$31,550.00
Original Registration Date:	23 Jun 2009
First Registration Date:	23 Jun 2009
Transfer Count:	0
Actual ARF Paid:	\$31,550.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jun 2019
PARF Rebate Amount:	\$15,775.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jun 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$10,046.00
COE Rebate Amount:	\$909.00
Total Rebate Amount:	\$16,684.00

The information contained herein is correct as at 26 Jun 2018

OK

Dep 23,880/yr
1990/m-th

MV 30K - 31K

lin
26/7/18

MSME18080703 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 22/06/2018 16:14
 SUBMITTED BY: Farida Wen

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/06/2018 16:14
Date Of Accident	22/06/2018 09:40
Exact Location Of Accident	KPE TUNNEL.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGM7111R
Insured/Policyholder	
Name Of Registered Owner	RAMESH S/O REGANATHAN
NRIC No	S7809299H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93886898
Alternative Phone No	OFFICE-93886898

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01009316
Cover Note Number	

Driver

Name of Driver	RAMESH S/O REGANATHAN
NRIC No	S7809299H
Date Of Birth	10/04/1978
Occupation	INDOOR
Date Of Driving Pass	14/09/2005
Driving Experience	12 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93886898
Fax Number	
Contact Number	OFFICE-93886898
Email Address	NOEMAIL

Address	BLK 916 HOUGANG AVE 9 #13-08
Postcode	530916
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO POLICE REPORT NO.T/20180622/7008.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG5429K
Vehicle Make/Model/Colour	TOYOTA ALTIS
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	PANG NIXON
NRIC/Passport Number	S7206098I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLT776Y
Vehicle Make/Model/Colour	HONDA CIVIC
Details Of Properties	VEHICLE C
Vehicle Category	PRIVATE CAR
Name of Driver	WONG CHEN FATT
NRIC/Passport Number	S7940036Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	RAMESH S/O RENGANTHAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SGM7111R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

22/6/18 3.10pm
Witnessed by Reporting Centre Personnel

Sketch Plan



Accident Sketch Plan Pg. 1

Circumstances of the Accident

REFER TO POLICE REPORT NO T/20180622/1008

Large empty area for drawing the accident sketch.

Declaration

We declare the foregoing particulars are true in every respect.

[Handwritten Signature]

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Insurance Co.	Compo	Date Of Accident	22, 06, 18
Vehicle NO.	SGM 7111R		
<input type="checkbox"/> Reporting Only <input type="checkbox"/> Own Damage Claim <input checked="" type="checkbox"/> Third Party Claim			
Verve Motorworks2			

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180622/7008

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180622/7008

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/06/2018 14:28		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: RAMESH S/O RENGANATHAN			Address: APT BLK 916 HOUGANG AVENUE 9 #13-08 SINGAPORE 530916		
ID Type / ID No.: NRIC NO / S7809299H			Contact No.: Home/Office: Mobile: 93886898		
Nationality: SINGAPORE CITIZEN			Email: ramren78@gmail.com		
Sex: Male	Age: 40	Date of Birth: 10/04/1978	Type of Informant: Vehicle Owner		
Race: Indian			Language: English		Institution / School Name:
Occupation: Financial consultant			Driving Licence Information: Class: 3		Date of Expiry: 31/12/2028

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 22/06/2018 09:42	Type of Location: Straight Road
Location: KALLANG PAYA LEBAR EXPRESSWAY KPE tunnel towards MCE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGM7111R	Car	HONDA	Civic Type R	Blue	Seriously Damaged	0
SLG5429K	Car	TOYOTA	Altis	Silver	Seriously Damaged	1
SLT776Y	Car	HONDA	Civic	Silver	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180622/7008

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20180622/7008

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGM7111R	TENET SOMPO INSURANCE PTE. LTD.	D17MTPV0100931 6	23/06/2017	23/06/2018

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Vehicle Owner			
Name	RAMESH S/O RENGANATHAN	ID No.	S7809299H
Related Vehicle	SGM7111R (Car)	Contact No.	93886898
Hospital/Clinic	PARKWAY EAST HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: 31/12/2028
Date Treatment	22/06/2018	Date Discharge	22/06/2018
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Driver			
Name	Ramesh S/O Renganathan	ID No.	S7809299H
Related Vehicle	SGM7111R (Car)	Contact No.	93886898
Hospital/Clinic	PARKWAY EAST HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: 31/12/2028
Date Treatment	22/06/2018	Date Discharge	22/06/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

Whilst coming to a complete stop due to traffic condition, suddenly vehicle bearing no.SLG5429K collided onto my rear portion. The impact then surged my vehicle forward to collide onto vehicle bearing no. SLT776Y. Its a 3 car chain collision.

Accident Sketch Plan Pg. 1

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20180622/7008

3 of 3

Report No. T/20180622/7008

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TP1B /
KASMAWATI BTE SAMIAN
Contact No.: 65476179

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
22/06/2018 14:28

Classification Of Case:

- A New Chapter - Skoda Singapore
- Laos dam collapse - hundreds dead
- Summer Transfer Windows for 2018/2019 Season

Honda Price Range Depreciation 2009 Vehicle Type

Advanced Search

Home » Used Cars » Monster Motors Pte Ltd » Honda Civic Type R 2.0M 3DR

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Tyres



Singtel

BROADBAND ONLINE SALE 4 DAYS ONLY!

Sign up now

T&Cs apply.

Honda Civic Type R 2.0M 3DR

Overview Financial Accessories Similar Research Photos Map

PREMIUM AD



Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$34,888	
Depreciation	\$23,880 /yr	View models with similar depreciation
Reg Date	20-May-2009 (9mths 23days COE left)	
Manufactured	2008	
Mileage	84,500 km (9.2k /yr)	
Transmission	Manual	
Engine Cap	1,998 cc	
Road Tax	\$1,210 /yr	
Power	148.0 kW (198 bhp)	View specs of the Honda Civic Type-R (2007-2010)
Curb Weight	1,345 kg	
Features	18 Inch Alloy Wheels Electronic Stability Program Limited Slip Differential Radio Compact Disc Player Side Airbags.	
Accessories	View To Know More.	
Description	Regularly Serviced And Well Maintained With Minimum Mods. Always Parked In Sheltered Area Trade In And High Loans Available. Call/Whatsapp Now To Arrange An Appointment For Viewing.	
COE	\$7,789	
OMV	\$30,911	
ARF	\$30,911	
Dereg Value	\$16,089 as of today (change)	
No. of Owners	3	
Type of Veh	Sports Car	
Category	PARF Car, Premium Ad Car, Low Mileage Car	
Availability	Available	PREMIUM AD

Add to Shortlist Add to Compare Add a Note

Posted on: 21-May-2018 | Last Updated on: 18-Jul-2018

Tags: Honda Civic, 2009 Honda Civic, Honda Civic, Used Honda



Seller Information

Company	Monster Motors Pte Ltd » dealer's pricelist » 140 vehs sold 183 vehs available	
Address	453 Tagore Industrial Avenue #01-02 Search cars nearby this location	
Location	Sindo Industrial Estate	
Website	www.monstermotors.com.sg	
Office No	69090035	
Contact Person(s)	Althan 92718770 Alex Lim 92207602 Enzo 97598881 Austin 87512137	

Upfront Payment

» more Financial info

Transfer Fee \$25



Compare [1]

**Honda Civic 1.8A VTI-S****\$23,000****\$13,110 /yr****22-Apr-2009****1,799 cc****159,000 km****Sedan****Available**

1.8L 16 Valves I-VTEC Engine, Accident Free And In Good Condition. All Wear And Tear Replaced. Drive Till End With No Worries. Many Accessories To Come Along, Why Wait? Call/SMS To Arrange A Viewing N...

PREMIUM AD

Posted: 31-May-2018 Tags: 2009 Honda Civic, Honda Civic, Honda, Civic, Used Honda

**Honda Civic Type R 2.0M 3DR****\$34,888****\$23,880 /yr****20-May-2009****1,998 cc****84,500 km****Sports****Available**

Regularly Serviced And Well Maintained With Minimum Mods. Always Parked In Sheltered Area Trade In And High Loans Available. Call/Whatsapp Now To Arrange An Appointment For Viewing.

PREMIUM AD

Monster Motors Pte Ltd

Posted: 21-May-2018 Tags: 2009 Honda Civic, Honda Civic, Honda, Civic, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view [Expired ads](#)

« Back (1 2) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Honda, Honda Singapore, used Honda Singapore, used Honda, used vehicles Singapore or even buy used Honda Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

MV 30K - 31K

Min
26/7/18

Compare [1]

Select used cars to **Compare** or **Add to Alert**



Honda Civic Type R
2.0M 3DR
20-May-2009

To compare cars,
select from the
search results.

To compare cars,
select from the
search results.

To compare cars,
select from the
search results.

Shortlist [1]

Add to Shortlist

Compare Now

Clear All

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DIS	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	SCR	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	6
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NS	KRA	✓
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	CUT	✓	1
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	BR	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	BR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	DD	✓	
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel	DD	✓	
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	✓	
1171	991328	Bootlid Emblem	NEC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH	CRA	✓	
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	CUT	✓	
1178	990377	Bootlid Rubber	CUT	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SGM 7111R

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	DD	R	X
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel	DD	R	
1221	993431	Rear LH Fender Inner Trim	CUT	✓	
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield	TN	✓	
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille	NS	BR	✓
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

MOTOR CAR (Frt)

Front Portion

Vehicle No: **SGM 711R**

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	CRA ✓		
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	CRA ✓		
1005	992341	Frt Bumper Clips	NEC ✓	6	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	DSE ✓	2	
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	CRA ✓		
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem	CAT ✓		
1023	991799	Frt Grille Chrome Moulding	SCR ✓		
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	BR ✓		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	SCR R X		
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items:

Accessories:

26/7/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jun 2018 Edit Reg		25 Jun 2018 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

LCRF Pte Ltd, Co. Reg. No.: NA

Main Claimant:

RAMESH S/O REGANATHAN, ID: S7809299H

Vehicle Reg. No.:

SGM7111R

Claim Type:

TP / 2815475640SG

Vehicle Reg. No. (Insured):

SLG5429K

Repairer:

Verve Autoclinic (HQ) No. 25 Kaki Bukit Road 4, #03-39 Synergy@KB, 417800 Kaki Bukit - Tel: 91595951

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tee, Chee-Wah] Chee-Wah.Tee@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 05/07/2018]

Date of Loss:

22/06/2018 09:00 - :59
[107 Months and 30 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

0999994766

Policy No. (Claimant):

Excess:

[Created by adjuster]

View All

Compose Case Mail

ASSOCIATED MAIL RECEIVED

- AIG_SG (27/06/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On



















































Done?



































No results.

Claim Documents

***SGM7111R (2815475640SG)**
[SLG5429K]
TP
RAMESH S/O REGANATHAN
Jun 22 2018 9:00AM
[LCRF Pte Ltd]
Verve Autoclinic

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images												3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print
1	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
2	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
3	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
4	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
5	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
6	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
7	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
8	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
9	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
10	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
11	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
12	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
13	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
14	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
15	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
16	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
17	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
18	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
19	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
20	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
21	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
22	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
23	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
24	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
25	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
26	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
27	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
28	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
29	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
30	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
31	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
32	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
33	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
34	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
35	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
36	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>
37	26/06/18 14:02	General View											Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	26/06/18 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/06/18 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/06/18 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/06/18 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
42	26/06/18 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
43	26/06/18 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
44	26/06/18 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/06/18 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
46	26/06/18 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
47	26/06/18 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
48	26/06/18 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
49	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
92	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
93	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
94	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
95	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
96	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
97	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
98	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
99	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
100	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
101	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
102	30/07/18 14:59	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
103	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
104	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
105	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
106	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
107	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
108	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
109	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
110	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
111	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
112	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
113	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
114	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
115	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
116	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
117	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
118	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
119	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
120	30/07/18 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/06/18 17:05	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/LCR18011474/T1Z4D3E2

Date: 31/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994766
Claimant Vehicle No : SGM7111R **Insured Vehicle No :** SLG5429K
 Date of Loss: 22/06/2018 Nature of Claim: TP Claim No: 2815475640SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGM7111R**
 Make & Model: HONDA CIVIC, 2.0 TYPE-R (M) Engine No: K20A5840414
 Reg. Date: 23/06/2009 (Man. Year: 2008) Chassis No: FD21600357
 Colour: Blue Odometer: 0 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/06/2018
 Date Inspected: 25/06/2018 Inspected At: Verve Autoclinic (HQ)
 No. 25 Kaki Bukit Road 4, #03-39
 Synergy@KB
 Singapore 417800
 Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Scratched	0.00 F	*- F
3	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER N/S	Cracked	0.00 F	*- F
5	1		*REVERSE SENSOR	Cut	0.00 F	*- F
6	1		*REAR END PANEL	Dented	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Broken	0.00 F	*- F
8	1		*REAR LH TAILLAMP	Broken	0.00 F	*- F
9	1		*REAR LH TAILLAMP PANEL	Dented	0.00 F	*- F
10	1		*REAR RH TAILLAMP PANEL	Dented	0.00 F	*- F
11	1		*BOOTLID	Dented	0.00 F	*- F
12	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*BOOTLID LAMP LH	Cracked	0.00 F	*- F
14	1		*BOOTLID LOCK	Cut	0.00 F	*- F
15	1		*BOOTLID RUBBER	Cut	0.00 F	*- F
16	1		*REAR LH FENDER	Repair	0.00 F	*- F
17	1		*REAR LH FENDER INNER PANEL	Repair	0.00 F	*- F
18	1		*REAR LH FENDER INNER TRIM	Cut	0.00 F	*- F
19	1		*REAR LH FENDER INNER SHIELD	Torn	0.00 F	*- F
20	1		*REAR FENDER AIR GRILLE N/S	Broken	0.00 F	*- F
21	1		*FRT NUMBER PLATE	Cracked	0.00 F	*- F
22	1		*FRT BUMPER	Cracked	0.00 F	*- F
23	6		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
24	2		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
25	1		*FRT BUMPER GRILLE	Cracked	0.00 F	*- F
26	1		*FRT GRILLE EMBLEM	Cut	0.00 F	*- F
27	1		*FRT GRILLE MOULDING	Scratched	0.00 F	*- F
28	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
29	1		*FRT LH FENDER	Repair	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >