

22/03/2002

ASS. REC. BY:

REF:

CS/GAI18011497/Ksd30

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Rachel Tan

of

GAI

Date/Time:

25/6/18 @ 2.21pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SJH 1533L

Insured:

GBG 1084R

at Workshop m/s

Wega Engineering

Tel:

6452 1493/8491 7768

of

Blk 176, Sin Ming Drive # 04-16

Policy No.:

Claim No.:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/06/2018

CA / REV / REP. / REV 24 HRS

'up'

26/06/2018

H.O.D. Endorsement:

Date/Time:

3.06pm @ 25/6/18

Person Contacted:

Mr. Leong

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJH 1533L-X

GBG 1084R-CC4/AXA/7015332/Uua3q2

D.O.A.: 05/08/2017

27/06/18 @ 17:09 p.m. revised PA to Rachel via email.

83601.84 email Confirmed

REF: GAI

## ASSIGNMENT

From:

Date:

26/6/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.:

SJH 1533L

at Workshop n/s

of 81K 176, Sin Ming Drive #04-16

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

1.21 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJH 1533L Yr Regn: 03 / 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Hammer

C.C.

1986

Colour:

n. P. white

A/C:

Insured / Std / NI / NA

Sp. Reading

31047

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZSU60

0077048

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225 / 65R17

R:

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

1916118

D.O.I.

2616118

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/6 File pass to Carman

25/10/18 Confirmed P/P \$ 3,601.84 @ 4 days with Kenneth.  
( \$ 7,023.16 Red - 66% )

RECEIVED 25 OCT 2018

Date/Time, File Pass to?

25/10/18

1)

Typist

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

350

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

350

Report Format :

Lump Sum / I.B.I. (\$ 3,601.84 P/P)

## Nivitha (LKK Auto)

---

**From:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Sent:** Monday, 25 June 2018 2:21 PM  
**To:** wega claim  
**Cc:** Leong Chee kwong; LKK Assignments  
**Subject:** RE: Accident Between SJH1533L & GBG1084R (GA) on 14/06/2018  
**Attachments:** SJH1533L VS GBG1084R.PDF

Without prejudice

Dear Sir

We spoke this morning, and will be sending LKK to conduct survey on a without prejudice basis. Our driver has not reported accident. Please also send us your client's GIA report for reference.

Dear LKK

Please accept assignment. Attached estimates for your reference.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

**From:** wega claim <wegaclaim@gmail.com>  
**Sent:** Monday, June 25, 2018 1:19 PM  
**To:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Cc:** Leong Chee kwong <cheekwongwega@gmail.com>  
**Subject:** [External] Accident Between SJH1533L & GBG1084R on 14/06/2018

Dear Sir/Mdm,

Accident Between SJH1533L & GBG1084R on 14/06/2018

Please kindly help to arrange surveyor , Kindly refer to the attachment.

--

Thanks & Regards,  
Claim Advisor  
Wega Engineering Pte Ltd  
Tel: 64521493  
Hp: 98332798/98267051

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

25th JUNE 2018

Great American insurance Company  
3 Temasek Avenue , #16-01 Centennial Tower Singapore 039190

Attention : Motor Vehicle Claim Department

Dear Sir / Mdm,

Third Party Claim

We are currently assisting SJH1533L to make accident claims

Against vehicle number GBG1084R which eventuated on 14/06/2018  
This vehicle is insured by Great American Insurance


We seek your co-operation to get the vehicle surveyed by your  
Accredited surveyors.

Vehicle is quartered at our workshop, Wega Engineering.

Once arrangement is being made, please do notify us to let us have the  
Ample time to get things arranged for the surveyor.

Your Faithfully,

Wega Engineering Pte Ltd



Leong Chee Kwong  
Claims Advisor  
Mobile No: 84917768

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Wednesday, 27 June 2018 5:09 PM  
**To:** 'Tan, Rachel'  
**Cc:** sur@lkkauto.com; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM  
**Subject:** RE: Accident Between SJH1533L & GBG1084R (GA) on 14/06/2018  
**Attachments:** SJH 1533L - Preli Advise.pdf

Dear Rachel,

Enclosed herewith preliminary advice of SJH 1533L.

Kindly provide us the claim reference no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Monday, 25 June 2018 3:10 PM  
**To:** 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; ASSIGNMENTS@LKKAUTO.COM  
**Cc:** sur@lkkauto.com  
**Subject:** RE: Accident Between SJH1533L & GBG1084R (GA) on 14/06/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]  
**Sent:** Monday, 25 June 2018 2:21 PM  
**To:** wega claim <[wegaclaim@gmail.com](mailto:wegaclaim@gmail.com)>  
**Cc:** Leong Chee kwong <[cheekwongwega@gmail.com](mailto:cheekwongwega@gmail.com)>; LKK Assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** RE: Accident Between SJH1533L & GBG1084R (GA) on 14/06/2018

Without prejudice

Dear Sir

We spoke this morning, and will be sending LKK to conduct survey on a without prejudice basis. Our driver has not reported accident. Please also send us your client's GIA report for reference.

Dear LKK

Please accept assignment. Attached estimates for your reference.

Regards  
Rachel Tan  
Executive, Motor Claims, Great American Insurance Company  
Tel: 6804 7846

**From:** wega claim <wegaclaim@gmail.com>  
**Sent:** Monday, June 25, 2018 1:19 PM  
**To:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Cc:** Leong Chee kwong <cheekwongwega@gmail.com>  
**Subject:** [External] Accident Between SJH1533L & GBG1084R on 14/06/2018

Dear Sir/Mdm,

Accident Between SJH1533L & GBG1084R on 14/06/2018

Please kindly help to arrange surveyor , Kindly refer to the attachment.

--

Thanks & Regards,  
Claim Advisor  
Wega Engineering Pte Ltd  
Tel: 64521493  
Hp: 98332798/98267051

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 27 June 2018

Our Ref: CS/GAI18011497/Ksd3

The Motor Claims Department  
GREAT AMERICAN INSURANCE COMPANY

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. SJH 1533L .**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26/06/2018 at the premises of M/s Wega Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,625.00</u> .
Revised Estimate Amount	: S\$ <u>3,925.50</u> .
"Check" Items Amount	: S\$ <u>1,188.75</u> .
Market Value	: S\$ <u>                    </u> .
LTA Reimbursement Value	: S\$ <u>                    </u> .
Nett Value	: S\$ <u>                    </u> .

**Description of Damage:**

The vehicle sustained damages at the rear portion.



**Comments/ Present Status:**

Damages Consistent.

Repair days: 4 Days

Yours faithfully,  
Kenneth Kong  
Automotive Assessor



Our Ref: MT/CA/OD/078

15 Jun 2018

GOH SIEM CHU  
52 LORONG G TELOK KURAU  
#02-04 PRESTIGE RESIDENCE  
SINGAPORE 426235

Dear Sir/Madam

**ONLINE MOTOR ACCIDENT REPORT FOR SJH1533L ON 14 JUN 2018**

We would like to inform you that we have received the Motor Accident Report submitted by you or your driver.

A copy of the form is enclosed. Please review and let us know within 5 working days if the information is not correct.

We wish to remind you that this report is accepted based on the understanding that you are not submitting any claim on your policy or against the other party.

If you have any queries, please contact our Customer Service Officers at 6430 7948 or email us at [motor@income.com.sg](mailto:motor@income.com.sg).

Yours sincerely



Goh Peng Hong  
Manager  
Motor Insurance





# SINGAPORE POLICE FORCE



T/20180625/7013

1 of 3

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20180625/7013

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 25/06/2018 16:39	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

**Informant's Particulars**

Name of Informant: GOH SIEM CHU		Address: 52 LORONG G TELOK KURAU #02-04 SINGAPORE 426235	
ID Type / ID No.: NRIC NO / S7784499F		Contact No.: Home/Office:	Mobile: 81124699
Nationality: SINGAPORE CITIZEN		Email: danielle_goh@yahoo.com	
Sex: Female	Age: 40	Date of Birth: 18/12/1977	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Company director		Driving Licence Information: Class: 2B,3	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 14/06/2018 17:06	Type of Location: Straight Road
Location:  SIMS AVENUE  ALONG SIMS AVENUE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJH1533L		TOYOTA	HARRIER ELEGANCE 2.0 CVT	White		0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJH1533L	NTUC Income Insurance Co-Operative Limited	5090849492-01	09/05/2018	08/05/2019



**SINGAPORE  
POLICE FORCE**



T/20180625/7013

2 of 3

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20180625/7013

**CONTINUATION OF REPORT**

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	GOH SIEM CHU	ID No.	S7784499F
Related Vehicle	SJH1533L	Contact No.	81124699
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

My car was passing the traffic light and stop while waiting for front car moving. The back vehicle trying to pass the amber light with no intention of stop (break) and hit at my rear car.

I had file a first police, but now the driver had not file any report, and no contactable. I couldn't proceed with insurance claim and car repair.



**SINGAPORE  
POLICE FORCE**



T/20180625/7013

3 of 3

Report No. T/20180625/7013

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPIB /  
ESTHER CHONG  
Contact No.: 65476368

Authentication Stamp  
NP168

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
25/06/2018 16:39

Classification Of Case:

Report Reference No.: MTAR000003209  
Entry Date/Time: 15 Jun 2018 02:55 PM  
Completion Date/Time: 15 Jun 2018 03:26 PM

## MOTOR ACCIDENT REPORT

### General

- I am the owner of the vehicle Yes
- I am the driver at the time of accident Yes

### Brief Description of Accident

Date of Accident	14 Jun 2018	Time of Accident	05:06 PM
Location of Accident	Along Silms Avenue		
Weather Condition	Clear	Road Surface	Dry
Type of Accident	Collision - Head to Rear		
Was the accident reported to the police?	Yes		
Name of the Police station	Online	Police Report No.	N/A
Number of Passengers (Including Driver)	1		
Any foreign vehicle involved in this accident?	No		
Any other vehicle or property damaged?	No		
Anybody injured in this accident?	No		
Do you have any video recording as evidence?	Yes		

### Details of Policyholder / Insured Vehicle

Vehicle No.	SJH1533L	Is this a company vehicle	No
Name of Owner	goh siem chu		
NRIC No./ Company Reg No.	S****499F		
Tel (Mobile)	81124699	Email	danielle_goh@yahoo.com
Address	52 LORONG G TELOK KURAU #02-04 PRESTIGE RESIDENCE SINGAPORE 426235		

### Details of Driver

Name of Driver	goh siem chu		
NRIC No.	S****499F		
Date of Birth	18 Dec	Sex	Female
Occupation	Indoor	Pass Date of Driving License	24 Feb 2005
Tel (Mobile)	81124699	Email	danielle_goh@yahoo.com
Address	52 LORONG G TELOK KURAU #02-04 PRESTIGE RESIDENCE SINGAPORE 426235		

# WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref:

Great American insurance Company

3 Temasek Avenue , #16-01 Centennial Tower Singapore 039190

Date : 25/6/2018

Vehicle No : SJH1533L  
Chassis No : ZSU6000077048  
Make/Model : TOYOTA HARRIER ELEGANCE 2.0 CVT  
Year : 2016

*Not Authorised  
Resurvey 6 days  
\$3601.84 4 days*

S/N	Qty	Description	Unit Price	Amount
-----	-----	-------------	------------	--------

## Estimate Cost Of Repair

1	1pc	REAR TAIL GATE ASSY
2	1pc	TAILGATE LOCK
3	1pc	TAILGATE LOCK COVER
4	1pc	TAIL GATE DOOR WEATHERSTRIP
5	1pc	TAIL GATE BOARD ASSY
6	1pc	NAME PLATE ( HARRIER )
7	1pc	EMBLEM REAR
8	1pc	CAMERA ASSY REVERSE
9	1pc	REAR BUMPER
10	1pc	REAR BUMPER ABSORBER
11	1pc	REVERSE SENSOR
12	1pc	REAR END PANAL
13	1pc	REAR END PANAL COVER
14	1pc	REAR BUMPER LOWER COVER
15	1pc	NUMBER PLATE SET

<i>Rt</i>	\$ 1,590.00	\$ 1,590.00	<i>✓</i>
<i>nr</i>	\$ 360.00	\$ 360.00	<i>✓</i>
<i>Del</i>	\$ 49.00	\$ 49.00	<i>✓</i>
<i>Sm</i>	\$ 328.00	\$ 328.00	<i>✓</i>
<i>Sm</i>	\$ 690.00	\$ 690.00	<i>✓</i>
<i>nr</i>	\$ 75.00	\$ 75.00	<i>✓</i>
<i>Sm</i>	\$ 55.00	\$ 55.00	<i>✓</i>
<i>Sm</i>	\$ 1,185.00	\$ 1,185.00	<i>✓</i>
<i>Del/Rt</i>	\$ 1,460.00	\$ 1,460.00	<i>✓</i>
<i>Sm</i>	\$ 93.00	\$ 93.00	<i>✓</i>
<i>Sm</i>	\$ 220.00	\$ 220.00	<i>✓</i>
<i>nr</i>	\$ 670.00	\$ 670.00	<i>✓</i>
<i>nr</i>	\$ 400.00	\$ 400.00	<i>✓</i>
<i>Del/Rt</i>	\$ 420.00	\$ 420.00	<i>✓</i>
<i>Sm</i>	\$ 60.00	\$ 60.00	<i>✓</i>

*1028.45*

*258*

## Labour Charges

1	To check wiring & system function	\$ 100.00	<i>201</i>
2	To apply rust proofing on affected area	\$ 150.00	<i>301</i>
3	To transfer rear tail gate mechanism	\$ 120.00	<i>801</i>
4	To remove & refix rear windscreen	\$ 200.00	<i>1201</i>
5	To replace sundry parts	\$ 100.00	<i>✓</i>
6	To replace , repair & knocking accident rear portion rear bumper , rear tailgate , rear bumper lower cover and rear end panal	\$ 1,300.00	<i>5001</i>
7	To respray rear bumper , rear tail gate & rear end panal	\$ 1,000.00	<i>5001</i>

\$ 10,625.00

Wega Engineering Pte Ltd

Authorised Signature

Leong Chee Kwong

Mobile No: 84917768

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18011497/Ksd3e2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 22-11-2018		
		Code : GAI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBG 1084R	Veh. Inspected	SJH 1533L	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBG1084R	Excess (\$)	0.00	
Assign From	RACHEL TAN	Assign Date	25/06/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HARRIER (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZSU600077048	Colour	METALLIC PEARL WHITE	
Odometer	31047	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	DUNLOP	8 mm	
L/H Front Tyre	225/65 R17	DUNLOP	8 mm	
R/H Rear Tyre	225/65 R17	DUNLOP	8 mm	
L/H Rear Tyre	225/65 R17	DUNLOP	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/06/2018	Inspection Date	26/06/2018	
Survey held at	WEGA ENGINEERING PTE LTD BLK 176 SIN MING DRIVE #04-16 SIN MING AUTOCARE . SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 1533L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR TAIL GATE ASSY	BENT	1,590.00	1,590.00
1	TAILGATE LOCK	TO REPAIR SEE LABOUR	360.00	-
1	TAILGATE LOCK COVER	DENTED	49.00	49.00
1	TAIL GATE DOOR WEATHERSTRIP	SERVICEABLE	328.00	-
1	TAIL GATE BOARD ASSY	SERVICEABLE	690.00	-
1	NAME PLATE (HARRIER)	NECESSARY	75.00	75.00
1	EMBLEM REAR	SERVICEABLE	55.00	-
1	CAMERA ASSY REVERSE	SERVICEABLE	1,185.00	-
1	REAR BUMPER	BUCKLED / DENTED	1,460.00	1,028.45
1	REAR BUMPER ABSORBER	SERVICEABLE	93.00	-
1	REVERSE SENSOR	SERVICEABLE	220.00	-
1	REAR END PANAL	TO REPAIR SEE LABOUR	670.00	-
1	REAR END PANAL COVER	SERVICEABLE	400.00	-
1	REAR BUMPER LOWER COVER	DENTED / CUT	420.00	420.00
1	SET NUMBER PLATE	SERVICEABLE	60.00	-
	LESS 25% DISCOUNT		-	-790.61
			7,655.00	2,371.84
<b><u>LABOUR</u></b>				
	TO CHECK WIRING & SYSTEM FUNCTION.		100.00	20.00
	TO APPLY RUST PROOFING ON AFFECTED AREA.		150.00	30.00
	TO TRANSFER REAR TAIL GATE MECHANISM.		120.00	60.00
	TO REMOVE & REFIX REAR WINDSCREEN.		200.00	120.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO REPLACE, REPAIR & KNOCKING ACCIDENT REAR PORTION REAR BUMPER, REAR TAILGATE, REAR BUMPER LOWER COVER AND REAR END PANAL. INCLUSIVE OF THE REPAIR OF TAILGATE LOCK AND REAR END PANAL.		1,300.00	500.00

Report Ref No. CS/GAI18011497/Ksd3e2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY REAR BUMPER, REAR TAIL GATE & REAR END PANAL.		1,000.00	500.00
			2,970.00	1,230.00
GRAND TOTAL			10,625.00	3,601.84
RECOMMENDED COST OF REPAIRS				3,601.84

Report Ref No. CS/GAI18011497/Ksd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.