

ASS. REC. BY:

REF:

CS/ III 180 11509 / Dg d3 / n2

Special Instruction:

Surveyor:

From (Person):

Gabriel Wee

ASSIGNMENT (Office)

of

III

Date/Time:

25/6/18 @ 3:35pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 7032G

Insured:

SHD 3174X

at Workshop m/s

S three Automotive

Tel:

6284 1542

of

Blk 8, Sin Ming Ind. Est #01-64

Policy No:

MCOM0015

Claim No:

MCT18060 449

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/06/2018

CA / REV / REP. / REV 24 HRS

1up

26/06/2018

H.O.D. Endorsement:

Date/Time:

4pm @ 25/6/18

Person Contacted:

Michelle

Vehicle:

IN

OUT

Date/Time

Action/Instruction (X) Estimate

YP 7032G - X

SHD 3174X - NS/INC/7024 232 / K/rbn2

DOA: 21/12/2017

26/6/18 @ 11:40am : jay said can arrange other surveyor to go down.

REF:

ASSIGNMENT

Firm: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured _____


Excess: _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No. YP 7032G Yr Began July 2017

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Tow Truck

Make: Isuzu NPR75 CC 5193

Colour: Yellow A/C Insured / Std / NI / NA

Co. Reading: 71597 T/Radio: Insured / Std / NI / NA

Eng/No: 4HK1574573

C/No: JAANPR75KH7100746

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/85 R16

R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bridgestone

Front

Rear

R/Bal: 5 mm R/Bal: 5/5 mm

L/Bal: 5 mm L/Bal: 5/5 mm

D.O.A: 15/06/2018 D.O.I: 26/06/2018

Survey held at 3 Three Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Bunt y o/s Body y o/s Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TIL SHD 3174X

check company registration number

18/10/18 Jinnah 4/3 4550/- with 7 days of reg
 (Red \$ 11458.45, 7.2%)

date of accident 15/06/2018

Date/Time, File Pass to?



: Preli. Report

18/10/18



: Final Report

Date/Time, File Return to?

Days Of Repair: 7

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

3:

Add Fee:



Site Insp: \$



Interview: \$



Tech Insp: \$



Workhand: \$

Report Format:

MER-TP

Lump Sum / L.P. \$

4550

450
10

460

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 25 June 2018 3:35 PM
To: Sim Teo Koon; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Sundari Nagarajan - III
Subject: FW: PRE-REPAIR INSPECTION FOR VEHICLE NO. YP7032G (Accident involving YP7032G and SHD3174X on 16.06.2018)
Attachments: shd3174x_20180625114316.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle YP7032G and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]
Sent: 25 June, 2018 2:43 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: 'S Three Automotive' <admin@sthreeautomotive.com.sg>
Subject: FW: PRE-REPAIR INSPECTION FOR VEHICLE NO. YP7032G (Accident involving YP7032G and SHD3174X on 16.06.2018)

Dear Sir,

We refer to your letter.

Our client is agreeable to appoint **Xing Guo Qiang (LKK Auto Consultants Pte Ltd)** as a single joint expert.

Please be informed that our client's motor vehicle is available for inspection at the under-stated workshop: -

S THREE AUTOMOTIVE RECOVERY PTE LTD

Blk 8 Sin Ming Industrial Estate #01-64/66,

Singapore 575643

Tel: 6284 1542; Fax: 6487 5315

Regards,

Sim Teo Koon
JusEquity Law Corporation
171 Chin Swee Road #02-06, CES Centre
Singapore 169877
Tel: 6506 6488 / 6536 9339
Fax: 6536 5368
E-mail: tk_sim@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]
Sent: Monday, June 25, 2018 11:55 AM
To: JUSEQ <juseq@singnet.com.sg>
Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. YP7032G (Accident involving YP7032G and SHD3174X on 16.06.2018)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.
India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



JusEquity Law Corporation

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

171 Chin Swee Road #02-08, CES Centre, Singapore 169877

Telephone (65) 6536 9339, (65) 6253 1812, (65) 6397 2008, (65) 6533 2327

Fax : (65) 6253 0120 (Conveyancing) , (65) 6536 5368 (Litigation)

Email : juseq@singnet.com.sg

website : www.juseq.com.sg

Our Ref: JEQ/180516/0618/ S3 (zl)

Your Ref: SHD3174X

25 June 2018

COMFORT TRANSPORTATION PTE LTD

383 Sin Ming Drive

GAS BUILDING

Singapore 575717

By Post Only



INDIA INTERNATIONAL INSURANCE PTE LTD

Singapore

By Fax: 6224 4174 Only

Dear Sir

ACCIDENT INVOLVING YP7032G & SHD3174X ON 16.06.2018

We act for the owner of vehicle no. YP7032G.

We hereby notify you of a road traffic accident on 16 June 2018 at about 1020 hrs, at TPE – PIE involving our client's vehicle and vehicle registration no. SHD3174X driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Encl

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/06/2018 16:31
Date Of Accident	15/06/2018 10:20
Exact Location Of Accident	TPE TWD PIE (57KM MARK)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP7032G
Insured/Policyholder	
Name Of Registered Owner	SUPERSONIC MAINTENANCE SERVICES PTE LTD
Co Reg No	198901352W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93831954

Vehicle Particulars

Manufacturer	ISUZU
Model	TOW TRUCK
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2017-V0101804-VCV
Cover Note Number	

Driver

Name of Driver	SOMASUNDARAM BALAMURUGAN
NRIC No	G7642116T
Date Of Birth	02/05/1986
Occupation	OUTDOOR
Date Of Driving Pass	21/04/2016
Driving Experience	2 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-93831954
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address NO ADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLIDED INTO PARKED VEHICLE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLANS

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD3174X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforsaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:




18 JUN 2018

Sketch Plan Pg. 2

Date of accident: _____ Time: _____ Location: _____
 Veh A: _____ Veh B: _____ No of pax: _____ Weather: Clear/dry Rain/Wet

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident happened at PLE TPE toward PLE.
 There was a vehicle breakdown (veh. 'X') on TPE.
 My vehicle was providing 'safety cover' for the
 breakdown vehicle. Suddenly veh. taxi No 870 3174 X
 hit on to the right rear ^{side} portion of my vehicle.

☐ Claim OD/TP at Falcon-Air ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks : Please forward a copy of my efile accident report to :

My workshop :
 Email address :
 & myself :
 Email address :

Note : Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:



Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name: *[Signature]*
 NRIC/FIN No.:



18 JUN 2018

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Statutory Board
Owner ID:	0027D
Vehicle Details	
Vehicle No.:	YP7032G
Vehicle to be Exported:	No
Intended De-registration Date:	27 Jun 2018
Vehicle Make:	ISUZU
Vehicle Model:	NPR75UK5W
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4HK1574573
Chassis No.:	JAANPR75KH7100746
Maximum Power Output:	-
Open Market Value:	\$44,479.00
Original Registration Date:	24 Jul 2017
First Registration Date:	24 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$2,224.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$40,212.00
COE Rebate Amount:	\$36,472.00
Total Rebate Amount:	\$36,472.00

The information contained herein is correct as at 27 Jun 2018

OK

0% 25% 50% 75% 100%

Register New Vehicle (Acknowledgement)

Vehicle Particulars

Vehicle No.	YP7032G		
Vehicle Type	B76 - Goods (Open) Recovery Vehicle	Vehicle Scheme	Normal
Vehicle Attachment 1	No Attachment		
Vehicle Attachment 2	-	Vehicle Attachment 3	-
Vehicle Make	ISUZU	Vehicle Model	NPR75UK5W
Chassis No.	JAANPR75KH7100746	Engine No.	4HK1574573
Motor No.	-	Trailer Chassis No.	-
Propellant	Diesel	Passenger Capacity	6
Engine Capacity	5193 cc	Power Rating	-
Maximum Power Output -			
Unladen Weight	4700 kg	Maximum Laden Weight	7900 kg
Primary Colour	White	Secondary Colour	-
First Registration Date	24 Jul 2017	Original Registration Date	24 Jul 2017
Manufacturing Year	2016	Open Market Value	\$44 479 00
PARF Eligibility	No	Minimum PARF Benefit	\$0 00
No. of Transfers	0	Additional Registration Fee Rate	5 00%
Actual ARF Paid	\$2 224 00		

Owner Particulars

Owner Name	LAND TRANSPORT AUTHORITY
Owner ID Type	Statutory Board
Owner ID	T08GB0027D
Registered Address Type	Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.	1
Registered Street Name	HAMPSHIRE ROAD
Registered Unit No.	-
Registered Building Name	-
Registered Postal Code	219428
COE No. / Expiry Date	2017080105000116H / 23 Jul 2027
COE Bid Category	C - Goods Vehicle & Bus
QP Paid	\$40,212 00

Transaction Details

Business Transaction Ref No.	20170724151215633879
Business Transaction Date	24 Jul 2017
Business Transaction Time	15:12:15

0% 25% 50% 75% 100%

Register New Vehicle (Confirmation)**Owner Particulars**

Owner ID: T08GB0027D
 Owner Name: LAND TRANSPORT AUTHORITY
 Home Telephone No.: -
 Email Address: -
 Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
 Registered Block/House No.: -
 Registered Street Name: HAMPSHIRE ROAD
 Registered Unit No.: -
 Registered Building Name: -
 Registered Postal Code: 219428
 TCOE No.: 2017080105000116H / 14 Oct 2017 / \$40,212.00
 PARF/COE Rebate No.: -

Handphone No.: -
 Office Telephone No.: -
 Fax No.: -

Vehicle Particulars

Vehicle Type	B76 - Goods (Open) Recovery Vehicle	Vehicle Scheme	Normal
Vehicle Attachment 1	No Attachment		
Vehicle Attachment 2	-	Vehicle Attachment 3	-
Vehicle Make	ISUZU	Vehicle Model	NPR75UK5W
Propellant	Diesel	Passenger Capacity	6
Engine Capacity	5193 cc	Power Rating	-
Maximum Power Output	-		
No. Of Axles	2	Front/Rear Tyre Information	215/85R16 / 215/85/R16(D)
Unladen Weight	4700 kg	Maximum Laden Weight	7900 kg
Emission Standard Code	1005 (Euro V)	CO2 Emission	-
Primary Colour	White	Secondary Colour	-
Manufacturing Year	2016		
First Registration Date	24 Jul 2017	Original Registration Date	24 Jul 2017
Chassis No.	JAANPR75KH7100746	Engine No.	4HK1574573
Motor No.	-	Trailer Chassis No.	-
Insurance Company	O03 - GREAT EASTERN GENERAL INSURANCE LIMITED	Insurance Cover Note No.	2017/07/0027
Open Market Value	\$44,479.00	Actual ARF Paid	\$2,224.00

New Registration & Road Tax Fees

Total COE Rebate Amount: \$0.00
 Total PARF Rebate Amount: \$0.00

TO :
ATTN : **MOTOR CLAIM DEPT.**

T/P VEH. NO : **SHD3174X**

ESTIMATE REPORT 1st QUOTATION

JOB NO : _____

OWNER'S PARTICULAR

NAME : **SUPERSONIC MAINTENANCE SERVICES PTE LTD**
ADDRESS : _____

CONTACT : **93831954**

VEHICLE NO **YP7032G** TRANS.
MAKE / MODEL : **ISUZU LORRY**
OWNER'S INSURER **GREAT EASTERN INSURANCE**
JOB-CODE : **TP** S/A : **MICHELLE**

CHASSIS NO :
ENGINE NO :

ACCIDENT DATE : **15-Jun-18**

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR. DISP	REV. PRICE
1 TAILLAMP ASSY RH <i>HH</i>	1.00	450.00	15.00	382.50	Y	✓
2 REAR MUD GUARD RH <i>Cnt</i>	1.00	520.00	15.00	442.00	Y	✓
3 REAR MUD GUARD LOWER RUBBER - ISUZU <i>HH</i>	1.00	180.00	15.00	153.00	Y	X
4 FRONT SIDE LAMP RH <i>Cnt</i>	1.00	189.00	15.00	160.65	Y	✓
5 SIDE GUARD RH <i>Cnt Front</i>	1.00	140.00	15.00	119.00	Y	✓
6 SIDE WHEEL GUARD RH <i>Cnt Front</i>	1.00	298.00	15.00	253.30	Y	✓
7 REAR WHEEL BEARING INNER RH <i>HH</i>	1.00	450.00	15.00	382.50	Y	X
8 REAR WHEEL BEARING OUTER RH <i>X Dim</i>	1.00	450.00	15.00	382.50	Y	2 ✓
9 REAR SHAFT WHEEL RH <i>HH</i>	1.00	2280.00	15.00	1938.00	Y	X
10 REAR SPRING BRACKET (FRONT) RH <i>HH</i>	1.00	650.00	15.00	552.50	Y	X
11 REAR SPRING BRACKET (REAR) RH <i>HH</i>	1.00	650.00	15.00	552.50	Y	X
TOTAL (PARTS) :		6257.00		5318.45		

1597.00
1357.45

SPECIAL NETT ITEM

1 REAR CABIN TAILLAMP PANEL RH <i>repr</i>	1.00	680.00	0.00	680.00	Y	X
2 REAR SIDE REFLECTOR STICKER RH <i>hkc</i>	1.00	360.00	0.00	360.00	Y	✓
3 REAR REFLECTOR STICKER (RED) <i>hkc</i>	1.00	180.00	0.00	180.00	Y	✓
4 REAR DOOR REFLECTOR STICKER RH <i>Cnt</i>	1.00	360.00	0.00	360.00	Y	✓
5 REAR DOOR LTA STICKER <i>hkc</i>	1.00	280.00	0.00	280.00	Y	✓
6 FRONT DOOR EMAS RECOVERY STICKER <i>hkc</i>	1.00	280.00	0.00	280.00	Y	✓
7 REAR MUD GUARD BRACKET RH <i>repr</i>	1.00	180.00	0.00	180.00	Y	X
8 REAR RIM RH <i>hkc</i>	1.00	680.00	0.00	680.00	Y	✓
9 REAR TYRES RH <i>SVC</i>	1.00	380.00	0.00	380.00	Y	X
10 REAR NO PLATE <i>hkc</i>	1.00	50.00	0.00	50.00	Y	X
11 SIDE CABIN DOOR ALUMINIUM W/LOCK HANDLE ASSY <i>broken</i>	1.00	2800.00	0.00	2800.00	Y	✓
TOTAL (PARTS) :		6230.00		6230.00		

2440.00

3001-

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	1.00	900.00	0.00	900.00	Y	700/-
2	SPRAY PAINTING ON ACCIDENT AREA	1.00	1600.00	0.00	1600.00	Y	1000/-
3	R&R CRANE TO SERVICE TO LIFT UP & DOWN	1.00	480.00	0.00	480.00	Y	N/A
4	R&R REAR SPRING SUSPENSION RH	1.00	380.00	0.00	380.00	Y	N/A
5	CHECK & REPAIR WIRING SYSTEM	1.00	80.00	0.00	80.00	Y	30/-
6	RESpray TUFF KOTE ON AFFECTED AREA	1.00	120.00	0.00	120.00	Y	80/-
7	R&R REAR AXLE SPRING & LONG SHAFT TO ASSIST REPAIR	1.00	900.00	0.00	900.00	Y	80/-

1890.00

TOTAL (LABOUR):

4460.00

4460.00

5687.45

TOTAL PARTS & LABOUR

16947.00

16008.45

4154550/-

26/06/2016 @ 1500h

Not done

2/15mm 7 days

Ryan

LKK Auto

97237799

EXCESS: S\$

NO. OF DAY:

RE-SURVEY: BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM

S\$

DATE OF SURVEY: / /

SURVEY BY:

CONTACT NO:

NOTE: LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENTARY REPAIRS REQUIRED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FAX NO:

Photo of new and old Side cabin.
Photo after repair.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III18011509/DQD3N2

Date: 19/10/2018

REFERENCE

Handling India International Insurance Pte Ltd Policy No: MCOM0015
 Insurer:
 Claimant YP7032G Insured Vehicle No: SHD3174X
 Vehicle No:
 Date of Loss: 15/06/2018 Nature of Claim: TP Claim No: MCT18060449

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP7032G Engine No: 4HK1574573
 Make & Model: ISUZU NPR75UK5W, 5.2 D (M) Chassis No: JAANPR75KH7100746
 Reg. Date: 24/07/2017 (Man. Year: 2016) Odometer: 71597 km
 Colour: Yellow
 Engine Capacity: 5193 cc
 Market Value/New Car Price: N/A
 Price:
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/85R16 Rear Tyre Size: 215/85R16 (D)
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5/5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,548.45	3,797.45	7,751.00	67.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,460.00	1,890.00	2,570.00	57.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,008.45	5,687.45	10,321.00	64.47
Approved Total (Overridden) (S\$)		4,550.00		
(S\$)	16,008.45	4,550.00	11,458.45	71.58
+ GST 7.00/7.00% (S\$)	1,120.59	318.50	802.09	71.58
Nett Amount (S\$)	17,129.04	4,868.50	12,260.54	71.58

INSPECTION

Date of Assignment: 25/06/2018

Date Inspected: 26/06/2018 Inspected At:

S Three Automotive Recovery Pte Ltd
 (HQ)
 Blk 8 Sin Ming Industrial Estate, #01-
 64/66 Sector C
 Singapore 575643

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Oct 2018)	
Parts:	N/A	ISUZU NPR75UK5W 5.2 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP7032G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP ASSY RH	Not Necessary	450.00 FL	*- FL
2	1		*REAR MUD GUARD RH	Cut	520.00 FL	*520.00 FL
3	1		*REAR MUD GUARD LOWER RUBBER-ISUZU	Not Necessary	180.00 FL	*- FL
4	1		*FRONT SIDE LAMP RH	Cut	189.00 FL	*189.00 FL
5	1		*SIDE GUARD RH FRONT	Cut	140.00 FL	*140.00 FL
6	1		*SIDE WHEEL GUARD RH FRONT	Cut	298.00 FL	*298.00 FL
7	1		*REAR WHEEL BEARING INNER RH	Not Necessary	450.00 FL	*- FL
8	1		*REAR WHEEL BEARING OUTER RH	Damaged	450.00 FL	*450.00 FL
9	1		*REAR SHAFT WHEEL RH	Not Necessary	2,280.00 FL	*- FL
10	1		*REAR SPRING BRACKET (FRONT) RH	Not Necessary	650.00 FL	*- FL
11	1		*REAR SPRING BRACKET (REAR) RH	Not Necessary	650.00 FL	*- FL
12	1		*REAR CABIN TAILLAMP PANEL RH	Repair	680.00 FS	*- FS
13	1		*REAR SIDE REFLECTOR STICKER RH	Necessary	360.00 FS	*360.00 FS
14	1		*REAR REFLECTOR STICKER (RED)	Necessary	180.00 FS	*180.00 FS
15	1		*REAR DOOR REFLECTOR STICKER RH	Cut	360.00 FS	*360.00 FS
16	1		*REAR DOOR LTA STICKER	Necessary	280.00 FS	*280.00 FS
17	1		*FRONT DOOR EMAS RECOVERY STICKER	Necessary	280.00 FS	*280.00 FS
18	1		*REAR MUD GUARD BRACKET RH	Repair	180.00 FS	*- FS
19	1		*REAR RIM RH	Bent	680.00 FS	*680.00 FS
20	1		*REAR TYRES RH	Serviceable	380.00 FS	*- FS
21	1		*REAR NO PLATE	Not Necessary	50.00 FS	*- FS
22	1		*SIDE CABIN DOOR ALUMINIUM W/LOCK HANDLE ASSY	Broken	2,800.00 FS	*300.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	12,487.00	4,037.00
- List Item Discount on L Items 15.00/15.00% (S\$)	938.55	239.55
Total Parts (S\$)	11,548.45	3,797.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	New	900.00	700.00
2	SPRAY PAINTING ON ACCIDENT AREA	New	1,600.00	1,000.00
3	R&R CRANE TO SERVICE TO LIFT UP & DOWN	New	480.00	-
4	R&R REAR SPRING SUSPENSION RH	New	380.00	-
5	CHECK & REPAIR WIRING SYSTEM	New	80.00	30.00
6	RESPRAY TUFF KOTE ON AFFECTED AREA	New	120.00	80.00
7	R&R REAR AXLE SPRING & LONG SHAFT TO ASSIST REPAIR	New	900.00	80.00
Gross Labour Cost (S\$)			4,460.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >