

ASS. REC. BY:

REF:

CS/LPC18011531/Tivd30

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Ong Li Li

of

LPC

Date/Time:

25/6/18 @ 4:40pm

Estimated Cost:

Bill to:

OD

TP/WS/TP RES/OD RES/EVA/INV/MV7CS

To Inspect Vehicle No:

SGY 9819G

Insured:

at Workshop m/s

Woon Meng

Tel:

6316 1131

of

50 Bkt Batok St. 23 # 01-06

Policy No:

Z17VP05015221

Claim No:

17/18/18/VP05/020700

Sum Insured:

Excess:

TBA 0

Make of Veh:

(Client's Record)

D.O.A

25/06/2018

CA / (REV) /

REP. / REV 24 HRS

26/06/2018

H.O.D. Endorsement:

Date/Time:

5:19pm @ 25/6/18

Person Contacted:

Mst Heng

Vehicle (IN) OUT

Date/Time

Action/Instruction

(✓)

Estimate

SGY 9819G-X

27/6/18

Revert via merimen

27/6/18

Recd approved \$ 5657.35 from Chew Beng Kee via merimen

28/6/18

Informed ms Heng c/A on part by part excess 0 via email

26/7/18

Final fig \$ 4331.90 confirmed by email (Red 4039.60, 4890)

Tung Ma

REF: LPC

ASSIGNMENT

From: Date: 26/6/2018

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. SGY 9819 G

at Workshop n/s Woon Meng

of 50 Bukit Batok St. 23 # 01-06

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

thru

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S

Bal. or Market Value:

\$82K.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No. SGY 9819 G

Yr Regn: 2015 / 2T

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota wish

CC:

1798

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading:

65281

T/Radio: Insured / Std / NI / NA

Eng/No.

C/No:

STDG920W 505002783

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

145/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fallen

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

26/6/1501750

Survey held at:

Woon Meng BBS.

Des. of Damages: ☒ Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 26 JUL 2018

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2) 26/7 - typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Merimen

Lump Sum / I.B.L: (\$

4331.90

Survey Fee:

Transportation

) S + RS: \$

) Photos

) Others

TOTAL

160 x 20% = 32

32 + 160 =

160 + 32 = 192

50

50

78

370 + 10

380

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jun 2018 Sendback Est	26 Jun 2018 11:31 \$8,230.05	26 Jun 2018 11:41 Edit Adj Rpt		Last:IA 27 Jun 2018 13:24		Pending for Survey Report Cancel Case
	28 Jun 2018 13:26 Sendback Est	28 Jun 2018 13:27 \$141.45	28 Jun 2018 13:27 Assign			Combine Suppl.	New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: LEE KING CHYE , ID: S7521484G, Tel: +6596468965, Email: lee_kc7475@yahoo.com	
Vehicle Reg. No.: SGY9819G	Date of Loss: 25/06/2018 09:00 - :59 [32 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type: OD / 17/18/18/VP05/020700	Policy/Cover Note No.: Z17VP05015221 (Comprehensive)
Vehicle Reg. No. (TP): ET9933J	Policy No. (TP):
	Excess: S\$0.00
Repairer: Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131	
Handling Insurer: Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Ong Li Li - 62799254]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 05/07/2018]	
Driver/Custodian: LEE KING CHYE (42 / Male), NRIC: S7521484G, Tel: +6596468965	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- LONPAC_HQ (27/06/2018): Alert - Adj Mandate Approved (S\$5957.35) - SGY9819G - Claim Handler: Ong Li Li

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 28 June 2018 8:08 AM
To: 'Woon Meng'
Cc: SUR
Subject: SGY 9819G-DOA: 25/6/2018 (LONPAC OD)

Dear Ms Heng,

As instructed by our client , please proceed to repair the insured vehicle **SGY 9819G on part by part (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SGY9819G (17/18/18/VP05/020700)
[ET9933J]

OD
Jun 25 2018 9:00AM
[LEE KING CHYE]
Woon Meng Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Lonpac Insurance Bhd (HQ) (LONPAC_HQ), sent on 27/06/2018 18:07 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5957.35) - SGY9819G - Claim Handler: Ong Li Li

Approved:5957.35.

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAUTO)

From: Admin-D (LKKAUTO)
Sent: Thursday, 28 June 2018 8:56 AM
To: 'ONG LI LI'; SUR
Cc: 'MT_Claim_SG'; assignments
Subject: RE: OD claim SGY9819G Our Ref: 17/18/18/VP05/020700

Dear Li Li,

Thank you for your email.

Dear Veron,

FYNA. Our Ref: CS/LPC18011531/T1vd3

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]
Sent: Thursday, 28 June, 2018 8:43 AM
To: Nivitha (LKK Auto) <admin-d@lkkauto.com>; assignments@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>; sur@lkkauto.com
Subject: RE: OD claim SGY9819G Our Ref: 17/18/18/VP05/020700

Dear Nivitha

Please proceed to authorise OD repairs as per your surveyor's adjustment if the damages are consistent & within repair limit.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Tuesday, 26 June, 2018 2:13 PM
To: ONG LI LI; assignments@lkkauto.com
Cc: MT_Claim_SG; sur@lkkauto.com
Subject: RE: OD claim SGY9819G Our Ref: 17/18/18/VP05/020700

*Dear Li Li,

We have arranged for survey today.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]

Sent: Tuesday, 26 June 2018 2:11 PM

To: Nivitha (LKK Auto) <admin-d@lkkauto.com>; assignments@lkkauto.com

Cc: MT_Claim_SG <mt_claim@lonpac.com>; sur@lkkauto.com

Subject: RE: OD claim SGY9819G Our Ref: 17/18/18/VP05/020700

Hi Nivitha

Have the surveyor surveyed the vehicle?

Please expedite on this case as Insured urgently requires the vehicle to be repaired.

Thank you.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]

Sent: Monday, 25 June, 2018 5:22 PM

To: ONG LI LI; assignments@lkkauto.com

Cc: MT_Claim_SG; sur@lkkauto.com

Subject: RE: OD claim SGY9819G Our Ref: To be advised

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]

Sent: Monday, 25 June 2018 4:40 PM

To: assignments@lkkauto.com; 'SUR' (sur@lkkauto.com) <sur@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>; woonmeng@singnet.com.sg

Subject: OD claim SGY9819G Our Ref: To be advised

Dear LKK

Please arrange OD survey at Woon Meng Motor Pte Ltd – Bukit Batok.

Case will be uploaded to Merimen once the workshop has the parts' price.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 25 June 2018 4:40 PM
To: assignments@lkkauto.com; 'SUR' (sur@lkkauto.com)
Cc: MT_Claim_SG; woonmeng@singnet.com.sg
Subject: OD claim SGY9819G Our Ref: To be advised
Attachments: SGY9819G 250618.PDF

Dear LKK

Please arrange OD survey at Woon Meng Motor Pte Ltd – Bukit Batok.

Case will be uploaded to Merimen once the workshop has the parts' price.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Lompac Insurance Bhd 300 Beach Road #17-04/07 The Concourse Singapore 199555	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Ong Li Li	Date: 27 Jun 2018
<u>Preliminary Advice</u>	

Vehicle No	: SGY9819G	Accident Date	: 25/06/2018
Make	: TOYOTA WISH	Policy No.	: Z17VP05015221
Assignment Date	: 26/06/2018	Excess	: S\$0.00
Date of Inspection	: 26/06/2018	Est. Duration of Repair	: 6.00
Inspection At	: WOON MENG MOTOR PTE LTD (BUKIT BATOK) 50 BUKIT BATOK STREET 23,, #01-06 MIDVIEW BUILDING SINGAPORE 659578		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,230.05
Revised Amount	:S\$	3,592.45
Check Items (Estimated)	:S\$	2,364.90
Total	:S\$	5,957.35
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	63,753.00
Salvage Value	:S\$	
Margin for Repair	:S\$	18,247.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1484G
Vehicle Details	
Vehicle No.:	SGY9819G
Vehicle to be Exported:	No
Intended De-registration Date:	25 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Beige
Manufacturing Year:	2015
Engine No.:	2ZR1593355
Chassis No.:	JTDGG20W50J002783
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$23,454.00
Original Registration Date:	02 Oct 2015
First Registration Date:	02 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$24,836.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Oct 2025
PARF Rebate Amount:	\$18,627.00
Intended COE Rebate Details	
COE Expiry Date:	01 Oct 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$62,101.00
COE Rebate Amount:	\$45,126.00
Total Rebate Amount:	\$63,753.00

The information contained herein is correct as at 25 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/06/2018 13:23
Date Of Accident	25/06/2018 09:30
Exact Location Of Accident	BKE TOWARDS PIE (TUAS)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGY9819G
Insured/Policyholder	
Name Of Registered Owner	LEE KING CHYE
NRIC No	S7521484G
Email Address	LEE_KC7475@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96468965
Alternative Phone No	OFFICE-96468965

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z17VP05015221
Cover Note Number	

Driver

Name of Driver	LEE KING CHYE
NRIC No	S7521484G
Date Of Birth	22/07/1975
Occupation	INDOOR
Date Of Driving Pass	09/12/1998
Driving Experience	19 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96468965
Fax Number	
Contact Number	OFFICE-96468965
Email Address	LEE_KC7475@YAHOO.COM

Address	28B JALAN LEMPENG # 12-19
Postcode	178809
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	DIFFERENT FORMAT
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	ET9933J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	FBB6032J
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At around 0900hrs to 0930hrs, I was driving from BKE towards PIE Tuas. Because it was raining, the road is slippery. Biker 'C' skidded and fell at the bend. Car 'B' immediately emergency brake and could have hit biker C. I also emergency brake, but my car hit car 'B' rear. My car front was damaged by the hard metal of car 'B' mercedes car. The rear of mercedes car B was only slight dent and a bit crack only. Car 'B' mercedes car could have hit biker C. Car B driver said there is some scratches in front. Both of us confirmed there was no injury. We helped Biker 'C' to get up from his fall and assisted his bike to the shoulder. Car 'B' rear was slightly dented and no injury of the car B driver and his passenger. I took some pictures of the slight dented rear of car B and there are no damages on other parts of his car apart some chipped off and no injuries from car 'B' and biker 'C' who fell off on his own and biker was also not injured and all of us drive & ride off from the scene. No traffic report made as no injury. Car B has no major damage except rear slight dent and chipped off.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 25/6/18
1230hr

Driver's Signature
(If driver is not the policyholder)
Date & Time: 25/6/18
1230hr

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 25/6/18 1230hr

Driver's Signature

(If driver is not the policyholder)

Date & Time: 25/6/18 1230hr

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Please note that you might be able to submit an Own Damage Claim under own policy within 14 days.

() Claim Own Damage () Claim TP () Reporting Only () Claim OD/TP at other workshop

Workshop Name: _____

Woon Meng Motor Pte Ltd (Co.Reg.No.200603678M)

50 Bukit Batok Street 23., #01-06 Midview Building

Singapore 659578

Tel: 6316 1131 Fax: 6316 7050 Email: woonmeng@singnet.com.sg

INSURER: **Lonpac Insurance Bhd (HQ)****PARTICULARS OF CLAIM**

Claim Type: OD (OWN DAMAGE)
 Policy No: Z17VP05015221
 Vehicle Reg. No.: **SGY9819G**
 Driver Age/Info: 42 / MALE
 TP Injury Involved? NO
 Insured/Claimant: LEE KING CHYE
 Driver: LEE KING CHYE

Ref. No:
 Date of Loss: 25/06/2018
 Driveable?
 Party At Fault: UNKNOWN
 Third Party Involved? YES
 Contact No: +6596468965

Make/Model: TOYOTA WISH, 1.8 CVT (A)
 Vehicle Colour: BROWN
 Engine No: 2ZR1593355
 Odometer: 60289 KM

Vehicle Reg. Date: 02/10/2015
 Chassis No: JTDGG20W50J002783

Paint Type:
 Total Loss? **NO**
 Est. Duration of Repair (day) 10

Tanjin 97495749
26/6/18 01730
Not Authorise
Ex: to be advise

Description of Accident/Loss: REFER TO SKETCH PLAN.
 Present Location: WOON MENG MOTOR PTE LTD (BUKIT BATOK)

Surv @ 1kl auto.com
Wimpsum.
Resulting after repair.
5-6 days.

COST OF CLAIMS

	Amount
Parts	5,735.05
Miscellaneous Items	65.00
Labour	1,330.00
Paintwork Labour	1,100.00
Towing	0.00
	8,230.05

Gross Total (S\$) 8,230.05**+ GST 7.00% (S\$) 576.10****Nett Amount (S\$) 8,806.15****This claim is handled by: HENG SEW SOW**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT	30.00
2	1	FRONT NUMBER PLATE	35.00
Sub Total (S\$)			65.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO PUTTY & SPRAY PAINTING	New	1,100.00
<u>Labour Items</u>			
2	TO REMOVE, REPLACE, REPAIR & REPLACE FRONT DAMAGED PARTS.	New	1,000.00
3	TO R & R FRONT RADIATOR	New	120.00
4	TO R & R AIR CON SYSTEM. TOP UP AIR CON GAS.	New	150.00
5	TO R & R WIRING.	New	60.00
Gross Labour Cost (S\$)			2,430.00

Woon Meng Motor Pte Ltd/SGY9819G/26/06/2018 11:31. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

INSURER:

Lonpac Insurance Bhd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z17VP05015221	Date of Loss:	25/06/2018
Vehicle Reg. No.:	SGY9819G	Driveable?	
Driver Age/Info:	42 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LEE KING CHYE	Contact No:	+6596468965
Driver:	LEE KING CHYE		

Make/Model:	TOYOTA WISH, 1.8 CVT (A)	Vehicle Reg. Date:	02/10/2015
Vehicle Colour:	BROWN	Chassis No:	JTDGG20W50J002783
Engine No:	2ZR1593355		
Odometer:	60289 KM		

Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		

Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	WOON MENG MOTOR PTE LTD (BUKIT BATOK)		

Tayfer 97495749
26/6/18 C1730
Not Authorise
Ex: to be advise
Sur @ lkk auto.com
humpson.
Ready after repair.
5-6 days

COST OF CLAIMS

	Amount
Parts	5,735.05
Miscellaneous Items	65.00
Labour	1,330.00
Paintwork Labour	1,100.00
Towing	0.00
Gross Total (\$\$)	8,230.05
+ GST 7.00% (\$\$)	576.10
Nett Amount (\$\$)	8,806.15

This claim is handled by: HENG SEW SOW

Generated using LKK Auto Consultants Inc. Estimation & Adjusting System

LKK Auto Consultants Inc. hereby notifies the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Jun 2018)
 Parts: M1-MPV TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: Woon Meng Motor Pte Ltd/SGY9819G/26/06/2018 11:31

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.


Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	250.00 F
2	2		*FRONT BUMPER RETAINER	0.00	0.00	76.00 F
3	2		*FRONT BUMPER LOWER SIDE GRILLE	0.00	0.00	70.00 F
4	2		*FRONT BUMPER FOG LAMP	0.00	0.00	560.00 F
5	2		*FRONT BUMPER FOG LAMP GRILLE	0.00	0.00	76.00 F
6	1		*FRONT BUMPER REFORCEMENT	0.00	0.00	110.00 F
7	1		*FRONT BUMPER SPONGE	0.00	0.00	75.00 F
8	1		*FRONT CENTER GRILLE	0.00	0.00	175.00 F
9	10		*CLIPS	0.00	0.00	15.00 F
10	2		*FRONT HEADLAMP	0.00	0.00	960.00 F
11	2		*UNDER ENGINE COVER	0.00	0.00	120.00 F
12	1		*FRONT SUPPORT PANEL	0.00	0.00	520.00 F
13	1		*FRONT SUPPORT TOP GARNISH	0.00	0.00	50.00 F
14	1		*FRONT RADIATOR	0.00	0.00	580.00 F
15	1		*AIR CON CONDENSOR	0.00	0.00	180.00 F
16	1		*AIR CON FAN MOTOR	0.00	0.00	220.00 F
17	1		*AIR CON FAN BLADE	0.00	0.00	65.00 F
18	1		*RAD FAN MOTOR	0.00	0.00	240.00 F
19	1		*RAD FAN COWLING	0.00	0.00	120.00 F
20	1		*RAD FAN BLADE	0.00	0.00	75.00 F
21	1		*FRONT BONNET	0.00	0.00	280.00 F
22	2		*FRONT BONNET HINGE	0.00	0.00	84.00 F
23	1		*FRONT BONNET LOCK	0.00	0.00	48.00 F
24	1		*EMBLEM	0.00	0.00	38.00 F

F=Franchise part.

Sub Total (\$\$) 4,987.00
 + Margin on L,N Items 15.00% (\$\$) 748.05
 Total Parts (\$\$) 5,735.05

Woon Meng Motor Pte Ltd/SGY9819G/26/06/2018 11:31. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Estimates on Miscellaneous Items

No	Particulars	Amount
<u>Miscellaneous Items</u>		
1	COOLANT	nnx ? 30.00
2	FRONT NUMBER PLATE	bt 35.00
Sub Total (S\$)		65.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO PUTTY & SPRAY PAINTING	New	4700 1,100.00
<u>Labour Items</u>			
2	TO REMOVE, REPLACE, REPAIR & REPLACE FRONT DAMAGED PARTS.	New	700 1,000.00
3	TO R & R FRONT RADIATOR	New	nnx ? 120.00
4	TO R & R AIR CON SYSTEM. TOP UP AIR CON GAS.	New	100 150.00
5	TO R & R WIRING.	New	30 60.00
Gross Labour Cost (S\$)			2,430.00

Woon Meng Motor Pte Ltd/SGY9819G/26/06/2018 11:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*FRONT BONNET HINGE ✓
 *FRONT BONNET LOCK ✓
 *EMBLEM ✓

0.00 ✓ 0.00 net 38.00 F

Sub Total (S\$) 4,987.00
 + Margin on L,N Items 15.00% (S\$) 748.05
 Total Parts (S\$) 5,735.05

Woon Meng Motor Pte Ltd/SGY9819G/26/06/2018 11:31. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

1 base panel - 48 BT -
 2 spare tank - 75 de ✓
 1000g

Woon Meng Motor Pte Ltd (Co.Reg.No:200603678M)

50 Bukit Batok Street 23,, #01-06 Midview Building

Singapore 659578

Tel: 6316 1131 Fax: 6316 7050 Email: woonmeng@singnet.com.sg

(SUPPLEMENTARY)**INSURER: Lonpac Insurance Bhd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z17VP05015221	Date of Loss:	25/06/2018
Vehicle Reg. No.:	SGY9819G	Driveable?	
Driver Age/Info:	42 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LEE KING CHYE	Contact No:	+6596468965
Driver:	LEE KING CHYE		

Make/Model:	TOYOTA WISH, 1.8 CVT (A)	Vehicle Reg. Date:	02/10/2015
Vehicle Colour:	BROWN		
Engine No:	2ZR1593355	Chassis No:	JTDGG20W50J002783
Odometer:	60289 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Description of Accident/Loss	REFER TO SKETCH PLAN.
Present Location:	WOON MENG MOTOR PTE LTD (BUKIT BATOK)

COST OF CLAIMS

	Amount
Parts	141.45
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	141.45
+ GST 7.00% (S\$)	9.90
Nett Amount (S\$)	151.35
+ Previous Estimates (S\$)	8,806.15
Claim Total (S\$)	8,957.50

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Jun 2018)**Parts:** M1-MPV TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Woon Meng Motor Pte Ltd/SGY9819G/28/06/2018 13:27**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BASE PANEL bt	0.00	0.00	*48.00 F
2	1		*SPARE TANK de	0.00	0.00	*75.00 F
F=Franchise part.						
Sub Total (S\$)						123.00
+ Margin on L,N Items 15.00% (S\$)						18.45
Total Parts (S\$)						141.45

Woon Meng Motor Pte Ltd/SGY9819G/28/06/2018 13:27. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Woon Meng Motor Pte Ltd/SGY9819G/28/06/2018 13:27. Not valid without Reference section.

Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 26 July 2018 12:18 PM
To: 'Heng Sew Sow'
Cc: SUR
Subject: RE: SGY9819G

Dear Ms Heng,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Heng Sew Sow <woonmeng@singnet.com.sg>
Sent: Thursday, 26 July 2018 11:32 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SGY9819G

Dear Veron

Accept your offer \$4331.90

Best Regards,
Heng Sew Sow (Ms)
Woon Meng Motor Pte Ltd
Tel: 6316 1131/51
Fax: 6316 7050

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Thursday, 26 July 2018 10:11 AM
To: Heng Sew Sow <woonmeng@singnet.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SGY9819G

Dear Ms Heng,

Finalize amount \$4331.90 @ 5 working days.

Kindly confirm.

Best Regards,

Veron Chen | Case Handler

'LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Heng Sew Sow <woonmeng@singnet.com.sg>

Sent: Wednesday, 25 July 2018 5:20 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: SGY9819G

Best Regards,
Heng Sew Sow (Ms)
Woon Meng Motor Pte Ltd
Tel: 6316 1131/51
Fax: 6316 7050

From: Heng Sew Sow <woonmeng@singnet.com.sg>

Sent: Wednesday, 25 July 2018 11:42 AM

To: 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>

Cc: 'SUR' <sur@lkkauto.com>

Subject: SGY9819G

Best Regards,
Heng Sew Sow (Ms)
Woon Meng Motor Pte Ltd
Tel: 6316 1131/51
Fax: 6316 7050

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed
Main	25 Jun 2018 Sendback Est	26 Jun 2018 11:31 S\$8,230.05	26 Jun 2018 11:41 Edit Adj Rpt	S\$4,331.90 Edit Estimates	S\$4,331.90 View Rpt	Pending for Survey Report Cancel Case
Supp #1	28 Jun 2018 13:26	28 Jun 2018 13:27 S\$141.45	28 Jun 2018 13:27			(Combined) Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	LEE KING CHYE, ID: S7521484G, Tel: +6596468965, Email: lee_kc7475@yahoo.com			
Vehicle Reg. No.:	SGY9819G	Date of Loss:	25/06/2018 09:00 - :59 [32 Months and 23 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / 17/18/18/VP05/020700	Policy/Cover Note No.:	Z17VP05015221 (Comprehensive)	
Vehicle Reg. No. (TP):	ET9933J	Policy No. (TP):		
		Excess:	S\$0.00	
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131			
Handling Insurer:	Lompac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Ong Li Li - 62799254]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 05/07/2018]			
Driver/Custodian:	LEE KING CHYE (42 / Male), NRIC: S7521484G, Tel: +6596468965			

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- LONPAC_HQ (26/07/2018): Re: SGY 9819G-SUPPLEMENTARY
- LONPAC_HQ (27/06/2018): Alert - Adj Mandate Approved (S\$5957.35) - SGY9819G - Claim Handler: Ong Li Li

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGY9819G (17/18/18/VP05/020700)

[ET9933J]














































OD




Jun 25 2018 9:00AM

[LEE KING CHYE]

Woon Meng Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Letters/Correspondences									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Lonpac Insurance Bhd (HQ)								Thumbnail	Print	
1	26/06/18 13:38	Letter template to inf Insd TP claim							1	Load HTM		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)								Thumbnail	Print	
1	26/06/18 11:31	Repairer Estimates							1	Load HTM		
2	28/06/18 13:27	Repairer Estimates Suppl. #1							1	Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	27/06/18 13:24	Adjuster Immediate Advice							1	Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
2	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
3	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
4	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
5	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
6	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
7	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
8	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
9	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
10	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
11	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
12	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
13	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
14	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
15	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
16	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
17	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
18	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
19	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
20	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
21	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
22	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
23	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
24	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
25	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
26	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
27	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
28	28/06/18 11:42	General View							1	Load JPG	<input checked="" type="checkbox"/>	
29	28/06/18 11:42	General View							1	Load JPG		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lonpac Insurance Bhd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
30	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
31	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
32	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
33	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
34	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
35	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
36	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
37	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
38	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
39	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
40	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
41	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
42	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
43	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
44	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
45	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
46	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
47	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
48	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
49	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
50	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
51	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
52	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
53	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
54	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
55	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
56	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
57	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
58	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
59	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
60	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
61	28/06/18 11:42	General View	 Load JPG	<input checked="" type="checkbox"/>
62	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	28/06/18 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
		Lonpac Insurance Bhd (HQ)		
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/06/18 13:25	MARK ESTIMATE	 Load PDF	
2	26/07/18 12:29	SUPPLEMENTARY	 Load PDF	
3	06/08/18 15:57	Supplementary	 Load PDF	

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)	Thumbnail	Print
1	25/06/18 16:28	Accident Statement	 Load HTM	
2	26/06/18 16:42	Addendum Sheet	 Load TIF	
3	26/06/18 16:44	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)	Thumbnail	Print
1	25/06/18 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	25/06/18 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	25/06/18 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	25/06/18 13:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	25/06/18 13:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	25/06/18 13:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	25/06/18 13:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	25/06/18 13:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)	Thumbnail	Print
1	25/06/18 13:46	Driver's Driving License/ NRIC	 Load TIF	
2	26/06/18 16:44	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC18011531/T1VD3E2

Date: 06/08/2018

REFERENCE

Insured/Claimant: LEE KING CHYE Policy No: Z17VP05015221
Date of Loss: 25/06/2018 Nature of Claim: OD Claim No: 17/18/18/VP05/020700

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGY9819G**
Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR1593355
Reg. Date: 02/10/2015 (Man. Year: 2015) Chassis No: JTDGG20W50J002783
Colour: Gold Odometer: 60289 km
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$82,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,876.50	2,766.90	3,109.60	52.92
Miscellaneous Items	65.00	35.00	30.00	46.15
Labour	1,330.00	830.00	500.00	37.59
Paintwork Labour	1,100.00	700.00	400.00	36.36
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,371.50	4,331.90	4,039.60	48.25
+ GST 7.00/7.00% (S\$)	586.00	303.23	282.77	48.25
Nett Amount (S\$)	8,957.50	4,635.13	4,322.37	48.25

INSPECTION

Date of Assignment: 26/06/2018 Present Location: Woon Meng Motor Pte Ltd (Bukit Batok)
Date Inspected: 26/06/2018 Inspected At: 50 Bukit Batok Street 23,, #01-06 Midview Building
Singapore 659578
Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2018)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGY9819G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER (WCP)	Cracked	250.00 F	*250.00 F
2	2	*FRONT BUMPER RETAINER (WCP)	Necessary	76.00 F	*76.00 F
3	2	*FRONT BUMPER LOWER SIDE GRILLE (WCP)	Not Necessary	70.00 F	*- F
4	2	*FRONT BUMPER FOG LAMP (WCP)	Not Necessary	560.00 F	*- F
5	2	*FRONT BUMPER FOG LAMP GRILLE (WCP)	Not Necessary	76.00 F	*- F
6	1	*FRONT BUMPER REINFORCEMENT (WCP)	Bent	110.00 F	*110.00 F
7	1	*FRONT BUMPER SPONGE (WCP)	Cracked	75.00 F	*75.00 F
8	1	*FRONT CENTER GRILLE (WCP)	Cracked	175.00 F	*175.00 F
9	10	*CLIPS (WCP)	Necessary	15.00 F	*15.00 F
10	1	*FRONT HEADLAMP (WCP)	N/S Not Necessary / O/SCracked	960.00 F	*480.00 F
11	2	*UNDER ENGINE COVER (WCP)	Not Necessary	120.00 F	*- F
12	1	*FRONT SUPPORT PANEL (WCP)	Bent	520.00 F	*520.00 F
13	1	*FRONT SUPPORT TOP GARNISH (WCP)	Not Necessary	50.00 F	*- F
14	1	*FRONT RADIATOR (WCP)	Not Necessary	580.00 F	*- F
15	1	*AIR CON CONDENSOR (WCP)	Bent	180.00 F	*180.00 F
16	1	*AIR CON FAN MOTOR (WCP)	Not Necessary	220.00 F	*- F
17	1	*AIR CON FAN BLADE (WCP)	Not Necessary	65.00 F	*- F
18	1	*RAD FAN MOTOR (WCP)	Not Necessary	240.00 F	*- F
19	1	*RAD FAN COWLING (WCP)	Not Necessary	120.00 F	*- F
20	1	*RAD FAN BLADE (WCP)	Not Necessary	75.00 F	*- F
21	1	*FRONT BONNET (WCP)	Bent	280.00 F	*280.00 F
22	2	*FRONT BONNET HINGE (WCP)	Bent	84.00 F	*84.00 F
23	1	*FRONT BONNET LOCK (WCP)	Repair	48.00 F	*- F
24	1		Necessary	38.00 F	*38.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*EMBLEM (WCP)			
Supplementary #1						
25	1		*BASE PANEL (WCP)	Bent	48.00 F	*48.00 F
26	1		*SPARE TANK (WCP)	Deformed	75.00 F	*75.00 F
F=Franchise part.						
					Sub Total (S\$)	5,110.00 2,406.00
					+ Margin on L,N Items 15.00/15.00% (S\$)	766.50 360.90
					Total Parts (S\$)	5,876.50 2,766.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	COOLANT (NOT NECESSARY)	30.00	0.00
2	1	FRONT NUMBER PLATE (BENT)	35.00	35.00
Sub Total (S\$)			65.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO PUTTY & SPRAY PAINTING	New	1,100.00	700.00
Labour Items				
2	TO REMOVE, REPLACE, REPAIR & REPLACE FRONT DAMAGED PARTS.	New	1,000.00	700.00
3	TO R & R FRONT RADIATOR	New	120.00	0.00
4	TO R & R AIR CON SYSTEM. TOP UP AIR CON GAS.	New	150.00	100.00
5	TO R & R WIRING.	New	60.00	30.00
Gross Labour Cost (S\$)			2,430.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >