

22/03/2002

SS. REC. BY:

REF:

CS3/MSG18011574/Gzadben

General Instruction:

Surveyor:

Meimen

ASSIGNMENT (Office)

From (Person):

Catherine thin

of

MSG

Date/Time:

26/06/18 09:45am

Estimated Cost:

Bill to:

OD-TP-WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBG 4789X

Insured:

SKQ 9966J

at Workshop m/s

Ong Motor Trading

Tel:

8380 2233

of

No. 464 Macpherson Road

Policy No:

B277 83538SMP

Claim No:

562029

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/06/2018

CA / REV / REP. / REV 24 HRS

lup

27/06/2018

H.O.D. Endorsement:

Date/Time:

11:04am @ 26/6/18

Person Contacted:

jacky

Vehicle

IN/OUT

Date/Time

Action/Instruction (X) Estimate

FBG 4789X - X

SKQ 9966J - X

(08/11/13) wef

ASS. REC. BY:

REF:

MSIG

ASSIGNMENT

From:

Date: 27/6/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBG 4789 X

at Workshop m/s

Ong Motor Trading
No. 464 Macpherson Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Jueky @ 8380 2233

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBG 4789 X

Yr Regn:

2012, Jul

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha

c.c.

153

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

89689

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim, or

Tyre Size:

F:

100/70-17

R:

140/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

IRC (FA)

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

27-06-18

Survey held at

w/s

5:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$4000 - \$5000

29/6/18 Submit PRS report.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

120

Transportation:

S + RS, SI

Photos

Others

10

TOTAL

130

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jun 2018		26 Jun 2018 09:45 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LAU KAY HOE, ID: S0213444F, Tel: +6596923401, Email: LAUKAYHOE@YAHOO.COM		
Main Claimant:	KUAN JIN TAT, ID: S9616299E		
Vehicle Reg. No.:	FBG4789X	Date of Loss:	20/06/2018 10:00 - :59 [70 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 562029	Policy/Cover Note No.:	B27783538SMP (Comprehensive) Coverage: 30/09/2017 - 29/09/2018
Vehicle Reg. No. (Insured):	SKQ9966J	Policy No. (Claimant):	
		Excess:	S\$750.00
Repairer:	Ong Motor Trading (MACPHERSON RD) No. 464 Macpherson Road, 368182 Macpherson - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/06/2018]		
Driver/Custodian (Insured):	LAU KAY HOE (68 / Male), NRIC: S0213444F, Tel: +6596923401		
Adj Asg. Remarks:	on WP. Liability unclear. TP reject SJE - assign LKK Auto Consultants Pte Ltd. Contact: Mr Jacky Siah (8380 2233)		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18011574/Gz4d3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 26-06-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKQ 9966J	Veh. Inspected	FBG 4789X
Policy No.	B27783538SMP	Coverage (\$)	0.00
Claim No.	562029	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	26/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/06/2018	Inspection Date	27/06/2018
Survey held at	ONG MOTOR TRADING NO. 464 MACPHERSON ROAD SINGAPORE 368182		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBG4789X		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	FZ16ST		
Chassis No. :	ME145S094C2005536		
Propellant :	Petrol		
Engine No. :	45S9005550		
Engine Capacity :	153 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	330 kg		
Unladen Weight :	141 kg		
Year Of Manufacture :	2012		
Original Registration Date :	30 Jul 2012		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$1,859.00		
COE Expiry Date :	29 Jul 2022		
Road Tax Expiry Date :	29 Jul 2018		
Inspection Due Date :	29 Jul 2018		
Intended Transfer Date :	29 Jun 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 29 Jul 2018. You may renew the road tax from 30 Apr 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 29 Jul 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 30 Jul 2018 to 29 Jan 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	32.00	-	32.00
Total Amount Payable :			57.00
Amount Payable (From 30 Jul 2018 to 29 Jul 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	64.00	-	64.00
Total Amount Payable :			89.00

You may print this page for reference.

[OK](#)
[Print](#)




























...CLAIM SUBFOLDER...(Pending for Survey Report)












CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jun 2018		26 Jun 2018 09:45 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LAU KAY HOE , ID: S0213444F, Tel: +6596923401, Email: LAUKAYHOE@YAHOO.COM									
Main Claimant: KUAN JIN TAT , ID: S9616299E									
Vehicle Reg. No.: FBG4789X		Date of Loss: 20/06/2018 10:00 - :59 [70 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 562029		Policy/Cover Note No.: B27783538SMP (Comprehensive) Coverage: 30/09/2017 - 29/09/2018							
Vehicle Reg. No. (Insured): SKQ9966J		Policy No. (Claimant):							
		Excess: S\$750.00							
Repairer: Ong Motor Trading (MACPHERSON RD) No. 464 Macpherson Road, 368182 Macpherson - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 27/06/2018]									
Driver/Custodian (Insured): LAU KAY HOE (68 / Male), NRIC: S0213444F, Tel: +6596923401									
Adj Asg. Remarks: on WP. Liability unclear. TP reject SJE - assign LKK Auto Consultants Pte Ltd. Contact: Mr Jacky Siah (8380 2233)									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBG4789X (562029)**
[SKQ9966J]
TP
KUAN JIN TAT
Jun 20 2018 10:00AM
[LAU KAY HOE]
Ong Motor Trading

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page	<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	25/06/18 16:46	Accident Statement Addm. #2 From:OD - Reg. No: SKQ9966J, Claimant: LAU KAY HOE					 Load HTM		
Photos/Images							3 per page	<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
2	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
3	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
4	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
5	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
6	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
7	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
8	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
9	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
10	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
11	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
12	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
13	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
14	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
15	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
16	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
17	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
18	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
19	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
20	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
21	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
22	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
23	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
24	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
25	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
26	29/06/18 15:44	General View					 Load JPG	<input checked="" type="checkbox"/>	
27	29/06/18 15:44	General View					Load JPG	<input checked="" type="checkbox"/>	
28	29/06/18 15:44	General View					Load JPG	<input checked="" type="checkbox"/>	
29	29/06/18 15:44	General View					Load JPG	<input checked="" type="checkbox"/>	
30	29/06/18 15:44	General View					Load JPG	<input checked="" type="checkbox"/>	
31	29/06/18 15:44	General View					Load JPG	<input checked="" type="checkbox"/>	
32	29/06/18 15:44	General View					Load JPG	<input checked="" type="checkbox"/>	
33	29/06/18 15:44	General View					Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	29/06/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
35	29/06/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
36	29/06/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
37	29/06/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
38	29/06/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
39	29/06/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/06/18 16:47	FBG4789X E-FILE REPORT	 Load PDF	
2	25/06/18 16:47	TP PRI Request	 Load PDF	
3	25/06/18 16:48	TP PRI Request email	 Load PDF	
4	25/06/18 16:51	TP reject SJE - assign LKK	 Load PDF	
5	25/06/18 17:04	Workshop name from lawyer	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18011574/GZ4D3E2

Date: 02/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B27783538SMP

Claimant Vehicle No : FBG4789X

Insured Vehicle No : SKQ9966J

Date of Loss: 20/06/2018

Nature of Claim: TP

Claim No: 562029

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBG4789X**

Make & Model: YAMAHA FZ16ST, 153cc (M)

Reg. Date: 30/07/2012 (Man. Year: 2012)

Colour: Red

Engine Capacity: 153 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 45S9005550

Chassis No: ME145S094C2005536

Odometer: 89689 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/70-17

Rear Tyre Size:

140/70-17

Front Left Side: IRC 4 mm

Rear Left Side:

Michelin 4 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/06/2018

Date Inspected: 27/06/2018 Inspected At:

Ong Motor Trading (MACPHERSON RD)

No. 464 Macpherson Road

Singapore 368182

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 02 Jul 2018)

Parts: N/A YAMAHA FZ16ST 153cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBG4789X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >