



# EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG. NO. : 53105453E

Vehicle Number : SLX 6598J  
 Vehicle Model : HONDA VEZEL  
 Accident Date : 19.06.2018  
 Original Reg Date : 04.04.2018

Date : 26.06.2018  
 Chassis : RU31262280  
 TP Ins. : AXA

## ESTIMATE

1	1 pc	Front Bumper	900	972.50	✓ client
2	2 pcs	Front Bumper Side Retainers	1 pc (42.00)	84.00	? LH X 200 RH X 200 D13
3	1 set	Front Bumper Clips		50.00	✓ all
4	1 pc	Front Bumper Reinforcement	400	462.50	? DD
5	1 pc	Front Bumper Lower Grille		230.00	✓ best
6	1 pc	Front Bumper Fog Lamp RH		395.00	X m
7	1 pc	Front Bumper Fog Lamps Cover RH		75.00	X m
8	1 pc	Front Bumper Lower Skirt	500	695.00	✓ sockets
9	1 pc	Front Grille		345.10	✓ sockets
10	1 pc	Front Grille Top Support Garnish		132.00	? X 200
11	1 pc	Front Grille Top Outer Cover		486.00	✓ screws
12	1 pc	Front Grille Badge		60.00	✓ all
13	1 set	Front Grille Clips		30.00	✓ all
14	1 pc	Headlamps (HID) RH		1,859.80	? ✓ CRK
15	1 pc	Headlamps Bottom Retainers		46.20	? ✓ CRK
16	1 set	Headlamps Clips		25.00	X m
				4949.10	5,948.10
				Less 20%	1,189.62
					4,758.48
					3959.28

## Special Nett

1	1 pc	Front No. Plate w/cover	hu	70.00	30
---	------	-------------------------	----	-------	----

## Labour charge

Panel Beating	800.00	400
Spray painting	800.00	400
Check Wiring	40.00	20
Anti rust	70.00	40
	<b>\$ 6,538.48</b>	860

NA2 LK  
 27/6/18 1730  
 3-4 days

PARTS 4949.10  
 LESS 20% 989.82  
 S/NETT \$ 30.00  
 LABOUR \$ 860.00

Page 1 of 1 LESS LIS 20% 53879.42

L/S TOTAL \$3850.00 / 3 REPAIR DAYS

# EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG. NO. : 53105453E

Vehicle Number : SLX 6598J  
 Vehicle Model : HONDA VEZEL  
 Accident Date : 19.06.2018  
 Original Reg Date : 04.04.2018

Date : 26.06.2018  
 Chassis : RU31262280  
 TP Ins. AXA

## ESTIMATE

1	1 pc	Front Bumper		972.50	✓ clear
2	2 pcs	Front Bumper Side Retainers	42.00	84.00	?
3	1 set	Front Bumper Clips		50.00	✓ all
4	1 pc	Front Bumper Reinforcement		462.50	?
5	1 pc	Front Bumper Lower Grille		230.00	✓ best
6	1 pc	Front Bumper Fog Lamp RH		395.00	X m
7	1 pc	Front Bumper Fog Lamps Cover RH		75.00	X m
8	1 pc	Front Bumper Lower Skirt		695.00	✓ sockets
9	1 pc	Front Grille		345.10	✓ sockets
10	1 pc	Front Grille Top Support Garnish		132.00	?
11	1 pc	Front Grille Top Outer Cover		486.00	✓ scratches
12	1 pc	Front Grille Badge		60.00	✓ all
13	1 set	Front Grille Clips		30.00	✓ all
14	1 pc	Headlamps (HID) RH		1,859.80	?
15	1 pc	Headlamps Bottom Retainers		46.20	?
16	1 set	Headlamps Clips		25.00	X m
				5,948.10	
				Less 20%	1,189.62
					4,758.48

## Special Nett

1	1 pc	Front No. Plate w/cover		70.00	30
---	------	-------------------------	--	-------	----

## Labour charge

Panel Beating		800.00	400
Spray painting		800.00	400
Check Wiring		40.00	20
Anti rust		70.00	40
		<b>\$ 6,538.48</b>	

NA2 LK  
 27/6/18 1730  
 3-4 days

⏪ **Re:S8M00LGW- Seek Mandate approval**

Type

🗉 Question

Message

Hi Pls proceed as per IA-VO

Reply

# EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autotrade@gmail.com

COMPANY REGISTRATION NO: 53105453E

## Letter of Demand

M/S INFINITE PARK

AXA INSURANCE (S) PTE LTD  
MOTOR CLAIMS DEPARTMENT  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811

Ref No. 19/PI00006/1971TP

Date 30/01/2019

WITHOUT PREJUDICE

Date of Accident	19/06/2018
Our Vehicle Number	SLX 6598J
Model	HONDA VEZEL
Your Insured	SLJ 6919R

Lump Sum Repair Cost (Recommended by LKK Naz)	\$	3,850.00
GIA Fee	\$	29.00
Loss of Use/Rental (3 days @ \$120.00/day)	\$	360.00

Total Amount : \$ 4,239.00

Singapore Dollars : Four thousand Two Hundred and Thirty-Nine only.

A handwritten signature in blue ink is written over a circular stamp. The stamp contains the text "EM-1 AUTO TRADE" around the perimeter and "SINGAPORE" at the bottom. The signature is a stylized, cursive script.



18 July 2018

**NG MEI LENG AMELIA (HUANG MEILING AMELIA)**  
BLK 101 AH HOOD ROAD, #22-03,  
Singapore 320101,

Dear Sir/ Mdm

**OUR REF : CC4/ASM18011575/Nwa3**  
**YOUR REF : SLJ 6919R**

**ACCIDENT INVOLVING SLJ 6919R & SLX 6598J ALONG ORCHARD CINELISURE  
C/P ON 19/06/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **Em-1 Auto Trade** acting on behalf of the owner of SLX 6598J against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to [Vivianlau@lkkauto.com](mailto:Vivianlau@lkkauto.com) within 7 days if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us 6841 8625 or email us at [Vivianlau@lkkauto.com](mailto:Vivianlau@lkkauto.com)

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vivian Lau  
Case Handler  
DID: 6841 8625  
FAX: 6741 4108  
EMAIL: [Vivianlau@lkkauto.com](mailto:Vivianlau@lkkauto.com)

c.c. *AXA Insurance Pte Ltd*  
*(Motor Claims Dept)*

**LETTER OF AUTHORISATION**

ACCIDENT INVOLVING (any vehicle) SLX 6598J and SLJ 6919R,  
ON 19/6/2018 ALONG Orchard Building Open Space Carpark LOT

I, Infinite Park, NRIC No. / Company Reg. No.  
53202080D of (address) \_\_\_\_\_

Postal Code \_\_\_\_\_, the registered owner (or authorised agent) of motor vehicle registration number  
SLX 6598J hereby authorise your workshop EM-1 Auto Trade (Company/GST REG.No. :

531054536) Blk 8 #01-68 Sector C Sin Ming Industrial Estate Singapore 575643 to :-

1. Begin or commence repairs to my/our motor vehicle;
2. Start or initiate third party claims for damages incurred by me against third party(ies) responsible for the accident.
3. To instruct EM-1 Auto Trade on my/our behalf to negotiate a settlement with the third party and/or his insurers as you deem fit.
4. To appoint vehicle surveyor on my/our behalf to determine reasonable costs of repair and period of repair.
5. To act on my/our behalf for any documents mailed to EM-1 Auto Trade by the third party and/or his insurers for the claim of my vehicle, if I am not contactable.

I am prepared to attend at my/our solicitors' office or to attend Court in connection with my/our claim, if necessary, I shall give my full co-operation and support for the claim for cost of repair and loss of use and shall keep you informed of any correspondences and/or summons that I may receive due to this action before agreeing to pay up or receive any monies due to this claim.

I authorise you to claim for the period of loss of use as specified by the motor surveyor or such shorter period due to accelerated work. I further authorise you to accelerate the repair period with overtime work and additional resource, I will pay you a reasonable amount to reflect the additional period of time to shorten.

I agree to keep you informed of any document(s), including cheques, mailed to me by third party and/or his insurers before taking any action. I also will not bank in any cheques issued by third party insurance and/or his insurers without the approval of EM-1 Auto Trade, and should I get approval from EM-1 Auto Trade to bank in the said cheques, I agree to pay EM-1 Auto Trade the full settlement amount as stated on the cheques within 5 working days.

Should my/our claim be partly successful or unsuccessful or cannot be proceeded with and/or if any judgement or settlement is not honoured or satisfied by third party, I/We:

1. Agree to pay you the sum of monies (as agreed) or as certified by the surveyor appointed, being the costs of repairs, survey fees and/or any other expenses reasonably incurred by you on my/our behalf. You may use the recovered amount from my claim for loss of us to partially offset the difference.
2. Agree to pay you such increased cost for additional resources and overtime work to shorten the period of repair.
3. Will pay for any shortfall that may result in the settlement amount.

In the event that EM-1 Auto Trade or the Repairer is compelled to enforce this undertaking, I/We agree that I/we shall pay on a full indemnity basis, the legal costs incurred by EM-1 Auto Trade or the Repairer.

Signature: [Signature]

Company Stamp:  
(if applicable)



Name: Wong Soon Peng  
NRIC No: S77772572  
Contact No: 97779257  
Date: 19/6/2018



### AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	BLJ 8919R (Insd veh)	Model: Honda Vezel 1.5 X
	BLX 899R2 (TP veh)	
Date of Accident/ Time:	19/06/2019	

Repair Estimate	: \$	6,538.48
Final Repair Cost	: \$	3,860.00
Loss of Use	: \$	180.00 5 days at \$ 60.00 per day
Rental (if any)	: \$	days at \$ per day
LTA / GIA Search Fee	: \$	20.00
Others:	: \$	
Final Settlement Sum (GLOBAL SUM)	: \$	4,000.00
Payee Name : Em-1 Auto Trade		
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)		
A)	For Non GIA Registered Workshop:	Agreed Liability: 100 (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks:		


**NOTE:**

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTEFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are *not received within 7 days* of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

  Signature of workshop representative / Workshop stamp Name of Representative: <u>Cheng Hlee Joo</u> Date: <u>9/5/19</u>  Signature of AXA's surveyor/representative: Name of AXA's surveyor /Representative: Date: <u>13/5/2019</u>	 Signature of Witness / Workshop stamp (if applicable) Name of Witness: <u>Karen Cheong</u> Date: <u>9/5/19</u>
--	--

# EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autotrade@gmail.com

COMPANY REGISTRATION NO: 53105453E

---

M/S INFINITE PARK

AXA INSURANCE (S) PTE LTD  
MOTOR CLAIMS DEPARTMENT  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811

RefNo. 19/P100006/1971TP

Date 30/01/2019

WITHOUT PREJUDICE

Date of Accident	19/06/2018
Our Vehicle Number	SLX 6598J
Model	HONDA VEZEL
Your Insured	SLJ 6919R

Lump Sum Repair Cost (Recommended by LKK Naz)	\$	3,850.00
---	----	----------

A handwritten signature in black ink is written over a circular stamp. The stamp contains the text "SINGAPORE" at the top and "EM-1 AUTO TRADE" at the bottom, with a central emblem.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-096352

Date of Request: 25/06/2018

Your Ref No:

WALK IN BOEY

EM1 AUTO PTE LTD  
BLK 8 #01-68 SIN MING INDUSTRIAL ESTATE SECTOR C  
SINGAPORE 575643

Dear Sir/Madam,

Date of Accident: 19/06/2018

Vehicle No: SLX6598J

Place of Accident: ORCHARD BUILDING OPEN SPACE CARPARK LOT

Involving Vehicle No: SLJ8919R

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SLJ8919R	ORCHARD BUILDING OPEN SPACE CARPARK LOT	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

GIRO  Cash  Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-096350

Date of Request: 25/06/2018

Your Ref No: WALK IN BOEY

EM1 AUTO PTE LTD  
BLK 8 #01-68 SIN MING INDUSTRIAL ESTATE SECTOR C  
SINGAPORE 575643

Dear Sir/Madam,

Your Vehicle No: SLX6598J  
Date of Accident: 19/06/2018  
Place of Accident: ORCHARD BUILDING  
Involving Vehicle No: SLJ6919R

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

GIRO  Cash  Cheque

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SLJ 6919R ✓ (Insd veh)	Model:	HONDA VEZEL HYBRID ✓
	SLX 6598J ✓ (TP veh)		
Date of Accident:	19/06/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	6,538.48
Final Repair Cost	:	\$	3,850.00
Loss of Use	:	\$	180.00 3days at \$60.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	29.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum (Global Sum)	:	\$	4,000.00

Is Third Party Workshop GIA Registered?  YES  NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability 100 (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks  
\_\_\_\_\_

<b>Payment Instruction: Payee's Breakdown</b>			
1)	EM-1 AUTO TRADE	:	\$ 4,000.00

\_\_\_\_\_  
JOANNE LEE KHANG MIN  
LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
28/05/2019  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18011575/Nwa3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:VALE OH

Date : 28-05-2019



Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLJ 6919R	Veh. Inspected	SLX 6598J
Policy No.	VPA/P2033274	Coverage (\$)	0.00
Claim No.	S8M00LGW	Excess (\$)	0.00
Assign From		Assign Date	26/06/2018

## 2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL HYBRID	c.c	0
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	RU31262280	Colour	RED
Odometer	7750	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	DUNLOP	6 mm
L/H Front Tyre	215/55 R17	DUNLOP	6 mm
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.
---

## 5. General Information

Accident Date	19/06/2018	Inspection Date	27/06/2018
Survey held at	EM-1 AUTO TRADE BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 6598J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER (CONSISTENT)	DEFORMED	972.50	900.00
2	FRONT BUMPER SIDE RETAINERS @\$42.00 (CONSISTENT)	N/S SERVICEABLE / O/S DISTORTED	84.00	42.00
1	SET FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	DENTED	462.50	400.00
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	BENT	230.00	230.00
1	FRONT BUMPER FOG LAMP RH (CONSISTENT)	NOT NECESSARY	395.00	-
1	FRONT BUMPER FOG LAMPS COVER RH (CONSISTENT)	NOT NECESSARY	75.00	-
1	FRONT BUMPER LOWER SKIRT (CONSISTENT)	SCRATCHED	695.00	500.00
1	FRONT GRILLE (CONSISTENT)	SCRATCHED	345.10	345.10
1	FRONT GRILLE TOP SUPPORT GARNISH (CONSISTENT)	SERVICEABLE	132.00	-
1	FRONT GRILLE TOP OUTER COVER (CONSISTENT)	SCRATCHED	486.00	486.00
1	FRONT GRILLE BADGE (CONSISTENT)	NECESSARY	60.00	60.00
1	SET FRONT GRILLE CLIPS (CONSISTENT)	NECESSARY	30.00	30.00
1	HEADLAMPS (HID) RH (CONSISTENT)	CRACKED	1,859.80	1,859.80
1	HEADLAMPS BOTTOM RETAINERS (CONSISTENT)	CRACKED	46.20	46.20
1	SET HEADLAMPS CLIPS (CONSISTENT)	NOT NECESSARY	25.00	-
	LESS 20% DISCOUNT		-1,189.62	-989.82
			<b>4,758.48</b>	<b>3,959.28</b>
<b>SPECIAL NETT ITEMS</b>				
1	FRONT NO.PLATE W/COVER (CONSISTENT) (SN)	NECESSARY	70.00	30.00
			70.00	30.00
<b>LABOUR</b>				
	PANEL BEATING.		800.00	400.00
	SPRAY PAINTING.		800.00	400.00
	CHECK WIRING.		40.00	20.00
	ANTI RUST.		70.00	40.00
			<b>1,710.00</b>	<b>860.00</b>
<b>GRAND TOTAL</b>			<b>6,538.48</b>	<b>4,849.28</b>

Report Ref No. CC4/ASM18011575/Nwa3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,850.00
---	--	--	----------

Report Ref No. CC4/ASM18011575/Nwa3q2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim: S8M00LQW  
 Reference: CGU/ASM18011575/Nw6302  
 Loss Date: 19 June 2018  
 Report Date: 21 Jun 2018 9:20:00 AM  
 Request Date: 27 September 2018  
 Due Date:  
 Vendor Name: LKK AUTO CONSULTANTS PTE LTD (TP)  
 Type of Loss: Third Party Vehicle Damage  
 Services: Pending verification - Direct Settlement

**Actions**

Next Step: [Wait for Approve Invoice](#)

[Add Events](#)

**Vehicle Information**

Incident Vehicle Registration #: SLX6598J  
 Make: TPVD HONDA  
 Model: VEZEL RED  
 Service Address:  
 ...

**Primary Contact/Insured**

NG MEI LENG AMELIA (HUANG MEILING AMELIA)  
 BLK 101 AH HOOD ROAD, #22-03, 320101, Singapore  
 84680018  
 NGAM9999@HOTMAIL.COM

**Claim Handler**

OH Vale  
 6568804897  
 vale.oh@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type:

[Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (3).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	30 May 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Payment Breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 May 2019
 LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 May 2019
 LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 May 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 May 2019
 DS FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	30 May 2019
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	30 May 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	30 May 2019
 LETTER TO CH.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	30 May 2019
 MARKED ESTIMATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 After paint Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 LOD.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 LKK Inspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 LKK Reinspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 SLX 6596J - IA.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	12 July 2018
TP SLX659BJ TP-GIA.PDF	Reports & Statement	GIA Report	KUMAR Shalendra	26 June 2018
TP EMAIL FROM WORKSHOP.msg	Forms / Claim Documents	Others	KUMAR Shalendra	26 June 2018
OO GIA REPORT OF SLJ6/919R (IKSQ).PDF	Reports & Statement	GIA Report	KADRI Mubeen	21 June 2018
P2033274_NE_00001_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	CH Vale	21 June 2018
P2033274_CI_00001_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	CH Vale	21 June 2018