

22/03/2002

ASS. REC. BY:

REF: CS/AIG18011585/Tltd302 Special Instruction:

Surveyor:

Munim

ASSIGNMENT (Office)

From (Person):

Phan Yoke Shi

of

AIG

Date/Time:

26/6/2018 @ 9:27

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FX8140D

Insured:

SLT 7568K

at Workshop m/s

New Union Company

Tel:

6784 9488

of

Blk 9004, Tampines St. 93 # 01-106

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/06/2018

CA / REV / REP. / REV 24 HRS

lup

27/06/2018

H.O.D. Endorsement:

Date/Time:

9:52am @ 26/6/18

Person Contacted:

Mr. Teo

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

FX8140D - NA / MSG18011279 / K4

DOA: 11/06/2018

SLT 7568K - NA / MSG18011279 / K4

DOA: 11/06/2018

REF: --- **AIG**

**ASSIGNMENT**

COE 2024 Feb.

From: \_\_\_\_\_ Date: --- --- 3

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lup

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **FX 81421**

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: **Honda Phantom** c.c. **197**

Colour: **Black** A/C: Insured / Std / NI / NA

Sp. Reading: **23448** T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: **TA 200E 0020219.**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **80/90 R17**

R: **130/90 R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front		Rear	
R/Bal. <b>5</b> mm		R/Bal. <b>5</b> mm	
L/Bal. mm		L/Bal. mm	
D.O.A.		D.O.I. <b>24/6/18 @ 1745</b>	

Survey held at **New Union**

Des. of Damages Frnt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<b>No 917</b>
	<b>\$3500 - \$4500 6 days.</b>
	<b>1/5/2300, 5 days confirm with Mr Yo</b>
	<b>(Red: 205A, 40%b)</b>

RECEIVED 04 SEP 2018

Date/Time, File Pass to?

1) **819 Tuplet**

Date/Time, File Return to?

2)

Report Format: **TP**

Lump Sum / I.B.E. (\$) **93007**

☐ : Preli. Report

☒ : Final Report

Days Of Repair: **6**

Resurvey No. of Trip: **2**

Add Fee:

- ☐ : Site Insp (\$)
- ☐ : Interview (\$)
- ☐ : Tech. Invs (\$)
- ☐ : Weekend (\$)

Survey Fee: **250**

Transportation:

) S + RS: SI

) Photos

) Others

**20**

**270**

TOTAL

- Pre repair inspection request - FX8140D VS SLT7568K (OI) DOA 11/06/2018

From: Chan, Yoke Shi  
To: ASSIGNMENTS@LKKAUTO.COM, Admin-a@lkkauto.com  
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Supramaniam, Darshene, Mithoosingh, Aashweenjeetkaur, A  
Sent: 26/6/2018 9:27:22 AM  
Attachments:  SKMBT\_C364e18062511510.pdf

---

Hi,

Please refer to the enclosed request from **Cheonghoh Law**.

Claim no : 2379271017SG003  
Case Owner : JOANE BOYOGAN

If you have any queries/concerns, please let us know.  
*Kindly assist to assign Mohamad Taufik as Single Joint Expert as requested.*

Thank you.

Regards,

Yoke Shi @ Ashley  
AIG  
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto  
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)  
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia  
Tel +6 03 2719 6000 | Ext 1012102

[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com) | [www.aig.com](http://www.aig.com)

---

**From:** Cheonghoh Law [mailto:mail@cheonghoh.sg]  
**Sent:** Tuesday, June 26, 2018 8:55 AM  
**To:** Chan, Yoke Shi  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina  
**Subject:** Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLT7568K AND FX8140D ON 11/06/2018

Dear Yoke Shi,

confirm nominating Mohamad Taufik as SJE.

Thanks & regards  
Catherine  
CHEONGHOH LAW CORPORATION  
Blk 53 Chin Swee Road #03-05  
Singapore 160053  
T: 6337 8700 | F: 6337 3700 | E: [mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)

On 26 Jun 2018, at 8:32 AM, Chan, Yoke Shi <[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com)> wrote:

Dear Catherine,

Please confirm that you are nominating Mohamad Taufik named in the list of surveyors to conduct the pre-repair survey and appointed as the "Single Joint Expert".  
Thank you.

Regards,

Yoke Shi @ Ashley  
AIG  
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto  
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)  
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia  
Tel +6 03 2719 6000 | Ext 1012102

[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com) | [www.aig.com](http://www.aig.com)

---

**From:** Cheonghoh Law [mailto:mail@cheonghoh.sg]  
**Sent:** Monday, June 25, 2018 5:58 PM  
**To:** Chan, Yoke Shi  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene;

Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina

**Subject:** Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLT7568K AND FX8140D ON 11/06/2018

Dear Sirs,

We refer to the above matter and to your email of even date.

Our client hereby nominate Mohamad Taufik of LKK Auto Consultants Pte Ltd named in paragraph 2 of your said email to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please contact our client's workshop, New Union Company, Blk 9004 Tampines Street 93 #01-106 Singapore 528838 to conduct the survey of FBJ 5842 C (Bike in).

Contact Person : Mr B T Yeo  
Telephone : 6784 9488

Kindly proceed to do the needful.

Thanks & regards  
Catherine  
CHEONGHOH LAW CORPORATION  
Blk 53 Chin Swee Road #03-05  
Singapore 160053  
T: 6337 8700 | F: 6337 3700 | E: [mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)

On 25 Jun 2018, at 12:20 PM, Chan, Yoke Shi <[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com)> wrote:

Without Prejudice

Your Reference : LCH.lg/TNU-80570.18  
Our Reference : 2379271017SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motorsurveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG  
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto  
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)  
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia  
Tel +6 03 2719 6000 | Ext 1012102

[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com) | [www.aig.com](http://www.aig.com)

---

**From:** Cheonghoh Law [<mailto:mail@cheonghoh.sg>]  
**Sent:** Monday, June 25, 2018 11:59 AM  
**To:** Supramaniam, Darshene  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene; Chin, Lee-Ying  
**Subject:** Re: PRS for FX 8140 D involving vehicle SLT 7568 K on 11 June 2018 along Cantonment Road (Oref: LCH.Ig/TNU-80570.18)

Dear Sirs,

We append below our letter of PRS and await your urgent reply.

Thanks & regards  
Catherine  
CHEONGHOH LAW CORPORATION  
Blk 53 Chin Swee Road #03-05  
Singapore 160053  
T: 6337 8700 | F: 6337 3700 | E: [mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)

Begin forwarded message:

**From:** [c364@cheonghoh.sg](mailto:c364@cheonghoh.sg)  
**Subject:** Message from KMBT\_C364e  
**Date:** 25 June 2018 at 11:51:55 AM SGT  
**To:** [mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)  
**Reply-To:** [c364@cheonghoh.sg](mailto:c364@cheonghoh.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

<SKMBT\_C364e18062511510.pdf>

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/06/2018 14:55
Date Of Accident	11/06/2018 20:00
Exact Location Of Accident	CANTONMENT ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FX8140D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MOHAMED SHAFI
NRIC No	S6872175Z
Email Address	MDNIYAS98@GMAIL.COM
Mobile Phone No	(LOCAL) +65-84546451
Alternative Phone No	OTHERS-84546451

### Vehicle Particulars

Manufacturer	HONDA
Model	PHANTOM 200M
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	
Cover Note Number	72081610

### Driver

Name of Driver	MOHAMED SHAFI
NRIC No	S6872175Z
Date Of Birth	21/03/1968
Occupation	INDOOR
Date Of Driving Pass	22/03/2017
Driving Experience	1 YEAR AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84546451
Fax Number	
Contact Number	OTHERS-84546451
Email Address	MDNIYAS98@GMAIL.COM

Address	BLK 54 CHAI CHEE STREET #11-853
Postcode	460054
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 CHAI CHEE DRIVE , POSTCODE: 469045 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2448999 - FAX NO: 62446558
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE POLICE REPORT : T/20180612/2183

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT7568K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	MOHAMED SHAFI
Approximate Age	
Injuries Sustain	SLIGHT
Injured person in which vehicle?	FX8140D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2

## SKETCH PLAN

A-FX8140D

B-SLT7568K





## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Pls Refer to the Police Report  
T/20180612/2183

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

 21/6/2018  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Police Report



**SINGAPORE  
POLICE FORCE**



T/20180612/2183

Police Station Of Origin:  
Bedok South N.P.C  
20 Chai Chee Drive SINGAPORE 469045  
Tel No: 1800-2448999

1 of 3

Report No. T/20180612/2183

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/06/2018 23:20	Vide Report No.: T/20180612/2182	Station Diary No.: 51
--	-------------------------------------	--------------------------

## Informant's Particulars

Name of Informant: MOHAMED SHAFI			Address: APT BLK 54 CHAI CHEE STREET #11-853 SINGAPORE 460054	
ID Type / ID No.: NRIC NO / S6872175Z			Contact No.: Home/Office:	Mobile: 84546451
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 50	Date of Birth: 21/03/1968	Type of Informant: Rider	
Race: Indian			Language: English	Institution / School Name:
Occupation: SALESMAN			Driving Licence Information: Class: 2B	
			Date of Expiry:	

## General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 11/06/2018 20:00	Type of Location: Turn
Location: Along Road 1 CANTONMENT ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance; Yes

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FX8140D	Motorcycle	HONDA	PHANTOM 200M	Grey	Slightly Damaged	0
SLT7568K	Car	TOYOTA		White		0

## Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FX8140D	MSIG INSURANCE (SINGAPORE) PTE. LTD.	72081610	29/03/2018	28/03/2019

## Police Report



**SINGAPORE  
POLICE FORCE**



T/20180612/2183

Police Station Of Origin:  
Bedok South N.P.C  
20 Chai Chee Drive SINGAPORE 469045  
Tel No: 1800-2448999

2 of 3

Report No. T/20180612/2183

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	MOHAMED SHAFI	ID No.	S6872175Z
Related Vehicle	FX8140D (Motorcycle)	Contact No.	84546451
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	11/06/2018	Date Discharge	11/06/2018
No. of Days granted Medical Leave	07	Degree of Injury	Slight

**Brief Details.**

On 11/06/2018 about 8pm, I was driving along Cantonment Road. I was at the right turn to CTE. I was turning to CTE suddenly one car from the opposite left direction drive forward and knocked onto my motorcycle. Ambulance and Traffic Police came. I was conveyed by the Ambulance to SGH. I was discharged on 11/06/2018. There are abrasion on my right side elbow and my neck swollen. I wish to state that there was a vehicle SLD6912R nearby and he helped me out.

Police Report



**SINGAPORE  
POLICE FORCE**



T/20180612/2183

Police Station Of Origin:  
Bedok South N.P.C  
20 Chai Chee Drive SINGAPORE 469045  
Tel No: 1800-2448999

3 of 3

Report No. T/20180612/2183

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
G /  
Staff Sgt CHIN YONG PEI, DESMOND

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / GIT /  
Staff Sgt MOHAMED SUFIAN BIN SUDIN  
Contact No.: 65476367

Authentication Stamp  
NP168

Signature Of Informant:

Date/Time:  
12/06/2018 23:20

Classification Of Case:

# New Union Company

Pg  
1

GST Reg No. M90370043N

9004 Tampines Street 93 #01-106  
Singapore 528838P: 67849488  
F: 67847588

Email: numotor@singnet.com

Attn: To Whom Concern

Phone:

Quotation No. #03\_08\_2018\_I

Address: -

Fax:

Quote Date: 04-08-18

Email:

Quotation For: Bike Repair - FX8140D

Item #	Description	Qty	Unit Price(\$)	Discount	Price
1	Fork Set Assy <i>bt ✓</i>	1	450.00		\$ 450.00
2	Handle Bar <i>bt ✓</i>	1	135.00		\$ 135.00
3	Mirror <i>bw ✓</i>	2	45.00		\$ 90.00
4	Signal Lamp, Front LHS & RHS <i>new ✓</i>	2	35.00		\$ 70.00
5	Headlamp Assy <i>new ✓</i>	1	125.00		\$ 125.00
6	Front Fender <i>cut ✓</i>	1	150.00		\$ 150.00
7	Front Rim Shaft <i>x nu</i>	1	45.00		\$ 45.00
8	Steering Corn Bearing <i>new ✓</i>	1	135.00		\$ 135.00
9	Head Lamp Stay Bracket <i>bt ✓</i>	1	125.00		\$ 125.00
10	Brake Lever <i>cut ✓</i>	1	29.00		\$ 29.00
11	Clutch Lever <i>x nu</i>	1	29.00		\$ 29.00
12	Balancer <i>cut ✓</i>	2	40.00		\$ 80.00
13	Front Disc Brake <i>x nu</i>	1	145.00		\$ 145.00
14	Carrier Box <i>cut ✓</i>	1	150.00		\$ 150.00
15	Box Racking <i>bt ✓</i>	1	125.00		\$ 125.00
16	No. plate - Front <i>x nu</i>	1	20.00		\$ 20.00
17	Tank <i>dd ✓</i>	1	485		\$ 485.00 <i>485</i>
18	Tank Logo <i>new ✓</i>	2	35.00		\$ 70.00
19	Mirror Bracket Holder <i>bt ✓</i>	1	45.00		\$ 45.00
20	FootRest Bracket, RHS <i>cut ✓</i>	1	95.00		\$ 95.00
21	Spray Paint <i>200</i>	1	380.00		\$ 380.00
22	Front Wheel Bearing <i>x nu</i>	2	45.00		\$ 90.00
23	Chasiss Repair <i>150</i>	1	250.00		\$ 250.00
24	Handle grip <i>cut ✓</i>	1	25.00		\$ 25.00
25	Rim Press <i>60</i>	1	120.00		\$ 120.00
26	Motor Oil <i>x nu</i>	2	30.00		\$ 60.00
27	Handle Bar Bracket <i>bt ✓</i>	1	115.00		\$ 115.00
28	Fork Oil <i>new ✓</i>	1	15.00		\$ 15.00

...Contd next pg

Sub-Total \$ 3,268.00 *3653*

Tax Rate Cont...Next Pg

GST

Other

Deposit Received

Customer Signature

Make all checks payable to New Union Company.



# New Union Company

Pg  
2

GST Reg No. M90370043N

9004 Tampines Street 93 #01-106  
Singapore 528838

P: 67849488  
F: 67847588

Email: numotor@singnet.com

Attn: To Whom Concern

Phone:

Quotation No. #03\_08\_2018\_1

Address: -

Fax:

Quote Date: 04-08-18

Email:

Quotation For: Bike Repair - FX8140D

Item #	Description	Qty	Unit Price	Discount	Price
29	Fork Holder <i>bt</i>	1	\$ 121.00		\$ 121.00
30	Side Stand <i>x nn</i>	1	65.00		\$ 65.00
31	Engine Oil Seal <i>x nn</i>	1	25.00		\$ 25.00
32	Full Overhaul Gasket Set <i>x nn</i>	1	95.00		\$ 95.00
33	Brake Pump Master Cylinder <i>x nn</i>	1	150.00		\$ 150.00
34	Labor charges <i>250</i>	1	350.00		\$ 350.00
35					
36		<i>Parts</i>	<i>2480</i>		
37	<i>Taxi 9749549</i>	<i>10%</i>	<i>2232</i>		
38	<i>5 days</i>	<i>Labor</i>	<i>660</i>		
39	<i>Lumpsum, Repair after repair</i>		<i>2892</i>		
40	<i>sur @ 1000000</i>	<i>1/5</i>	<i>2300</i>		
41			<i>5 days</i>		
42					
43					
44					
45					
46					
47					
48					
49					
50					
51					
52					
53					

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Sub-Total b/f GST	\$ 4,074.00
Tax Rate	7.00%
GST	285.18
Other	-
Deposit Received	
<b>Total with GST</b>	<b>\$ 4,359.18</b>

Customer Signature

Make all checks payable to New Union Company.

4459

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2018 <a href="#">Edit Reg</a>		26 Jun 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$2,300.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,300.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:

LCRF Pte Ltd, Co. Reg. No.: 201624597K

Main Claimant:

-

Vehicle Reg. No.:

FX8140D

Claim Type:

TP / 2379271017SG

Vehicle Reg. No. (Insured):

SLT7568K

Repairster:

New Union Company (HQ) BLK 9004 TAMPINES STREET 93 #01-106, 528838 Tampines - Tel:

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 09/07/2018]

Claimant's Solicitor:

CHEONGHOH LAW CORPORATION - Tel: 63378700

Date of Loss:

11/06/2018 00:00 - :59  
[171 Months and 2 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

0999994758 (Comprehensive)

Policy No. (Claimant):

Excess:

**ASSOCIATED MAIL RECEIVED**

[View All](#)
[Compose Case Mail](#)

- AIG\_SG (29/06/2018): Request To Upload TP GIA Report

**ALL ASSOCIATED TASKS**

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





















































## Claim Documents

**\*FX8140D (2379271017SG)**  
**[SLT7568K]**  
**TP**

**Jun 11 2018 12:00AM**  
**[LCRF Pte Ltd]**  
**New Union Company**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
2	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
3	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
4	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
5	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
6	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
7	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
8	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
9	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
10	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
11	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
12	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
13	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
14	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
15	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
16	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
17	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
18	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
19	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
20	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
21	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
22	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
23	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
24	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
25	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
26	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
27	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
28	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
29	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
30	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
31	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
32	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
33	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
34	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
35	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
36	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			
37	03/09/18 16:54	General View														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	03/09/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/09/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/09/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/09/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/09/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/09/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/09/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/09/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	03/09/18 17:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	03/09/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	03/09/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	03/09/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	03/09/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	03/09/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	03/09/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	03/09/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	03/09/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	03/09/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	03/09/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	03/09/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	03/09/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	03/09/18 17:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
89	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
90	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
91	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
92	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
93	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
94	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
95	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
96	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
97	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
98	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
99	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
100	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
101	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
102	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
103	03/09/18 17:18	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/06/18 14:03	OI GIA REPORT	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18011585/T1TD3E2

Date: 08/10/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994758

Claimant Vehicle No : FX8140D

Insured Vehicle No : SLT7568K

Date of Loss: 11/06/2018

Nature of Claim:

TP

Claim No: 2379271017SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FX8140D**

Make &amp; Model: HONDA PHANTOM, 149cc (M)

Engine No: TA200E0020219

Reg. Date: 09/03/2004 (Man. Year: 2003)

Chassis No: TA2000020219

Colour: Black

Odometer: 23448 km

Engine Capacity: 197 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 80/90 R17

Rear Tyre Size:

130/90 R15

Front Left Side: Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,359.00	2,371.50	987.50	29.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	660.00	440.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>4,459.00</b>	<b>3,031.50</b>	<b>1,427.50</b>	<b>32.01</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,300.00</b>		
<b>(\$\$)</b>	4,459.00	2,300.00	2,159.00	48.42
<b>+ GST 7.00/7.00% (\$\$)</b>	312.13	161.00	151.13	48.42
<b>Nett Amount (\$\$)</b>	<b>4,771.13</b>	<b>2,461.00</b>	<b>2,310.13</b>	<b>48.42</b>

### INSPECTION

Date of Assignment: 26/06/2018

Date Inspected: 27/06/2018 Inspected At:

New Union Company (HQ)

BLK 9004 TAMPINES STREET 93 #01-106

Singapore 528838

Estimated Period of Repair: 6.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FORK SET ASSY	Bent	450.00 F	*450.00 FL
2	1		*HANDLE BAR	Bent	135.00 F	*135.00 FL
3	2		*MIRROR	Broken	90.00 F	*90.00 FL
4	2		*SIGNAL LAMP, FRONT LHS & RHS	Cracked	70.00 F	*70.00 FL
5	1		*HEADLAMP ASSY	Cracked	125.00 F	*125.00 FL
6	1		*FRONT FENDER	Cut	150.00 F	*150.00 FL
7	1		*FRONT RIM SHAFT	Not Necessary	45.00 F	*- FL
8	1		*STEERING CORN BEARING	Necessary	135.00 F	*135.00 FL
9	1		*HEAD LAMP STAY BRACKET	Bent	125.00 F	*125.00 FL
10	1		*BRAKE LEVER	Cut	29.00 F	*29.00 FL
11	1		*CLUTCH LEVER	Not Necessary	29.00 F	*- FL
12	2		*BALANCER	Cut	80.00 F	*80.00 FL
13	1		*FRONT DISC BRAKE	Not Necessary	145.00 F	*- FL
14	1		*CARRIER BOX	Cut	150.00 F	*150.00 FL
15	1		*BOX RACKING	Bent	125.00 F	*125.00 FL
16	1		*NO. PLATE - FRONT	Not Necessary	20.00 F	*- FL
17	1		*TANK	Dented	485.00 F	*485.00 FL
18	2		*TANK LOGO	Necessary	70.00 F	*70.00 FL
19	1		*MIRROR BRACKET HOLDER	Bent	45.00 F	*45.00 FL
20	1		*FOOTREST BRACKET, RHS	Cut	95.00 F	*95.00 FL
21	2		*FRONT WHEEL BEARING	Not Necessary	90.00 F	*- FL
22	1		*HANDLE GRIP	Cut	25.00 F	*25.00 FL
23	2		*MOTOR OIL	Not Necessary	60.00 F	*- FL
24	1		*HANDLE BAR BRACKET	Bent	115.00 F	*115.00 FL
25	1		*FORK OIL	Necessary	15.00 F	*15.00 FL
26	1		*FORK HOLDER	Bent	121.00 F	*121.00 FL
27	1		*SIDE STAND	Not Necessary	65.00 F	*- FL
28	1		*ENGINE OIL SEAL	Not Necessary	25.00 F	*- FL
29	1		*SET FULL OVERHAUL GASKET	Not Necessary	95.00 F	*- FL
30	1		*BRAKE PUMP MASTER CYCLINDER	Not Necessary	150.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,359.00</b>	<b>2,635.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>263.50</b>
<b>Total Parts (\$\$)</b>	<b>3,359.00</b>	<b>2,371.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAY PAINT	New	380.00	200.00
2	CHASSIS REPAIR	New	250.00	150.00
3	RIM PRESS	New	120.00	60.00
4	LABOR CHARGES	New	350.00	250.00
Gross Labour Cost (S\$)			<b>1,100.00</b>	<b>660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >