

ASS. REC. BY:

REF: CS/FCI18011593/R19d3n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

cws  
From (Person): May Chua

of FCI

Date/Time: 25/6/18 @ 5.20pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGN 6736P

Insured: SHA 1500S

at Workshop n/s: Chem's Customcraft

Tel: 6272 5429

of Blk 1010, Bkt Merah Lane 3 # 01-105

Policy No: D-18088936 MFSH

Claim No: D18004698 MFSH

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A: 09/06/2018

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time: 10:09am @ 26/6/18 Person Contacted: Sharon

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGN 6736P - X
	SHA 1500S - CS/FCI16013861 / M/qh 3e2 DOA: 20/07/2016
12/7/18 @ 4.12pm	REVISED to May Chua by email.
17/06/18 @ 11.47am	Confirmed with Sharon US to 1700, 3 days. (Red to 723-90, 30%)

Signature: Ramu

REF: \_\_\_\_\_

4236  
CoE XPIRY: 2021 / NOV

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SGN 6736P  
 at Workshop m/s: CHARN'S CUSTOMCRAFT  
 of: 1010, BURNETT MCRASH #01-105, FCI  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition) 1pm - 3pm  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

N/S	O/S

Veh No: SGN 6736P Yr Regn: 2006 / NOV  
 Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: TOYOTA WLSH 1.8 A c.c. 1794  
 Colour: MARON A/C: Insured / Std / NI / NA  
 Sp. Reading: 88570 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: ZNE100332743  
 Gen. Cond: Good /  Fair / Poor / Burnt  
 Steering:  order / Jammed / Leaked / Burnt or  
 Brake:  order / Jammed / Leaked / Burnt or  
 Mod: Nil /  SKM / STD A/Rim or  
 Tyre Size: F: 205/55R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or CONTINENTAL  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 09/06/18 D.O.I. 10/07/18  
 Survey held at CHARN'S CUSTOMCRAFT  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
6/3 FRT  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
RECEIVED 17 OCT 2018	

Date/Time File Pass to?  : Preli. Report  
 : Final Report  
 1) 17/10 12:15  
 Date/Time File Return to?  
 2) \_\_\_\_\_  
 Report Format : TP  
 Lump Sum / I.B.F. (\$) 1700

Days Of Repair: 3  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Invs (\$)  
 : Weekend (\$)

Survey Fee:	110
Transportation:	50
____ S+RS ____ SI	
Photos	20
Others	
<b>TOTAL</b>	<b>180</b>



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004698MFSH

Date: 12 July 2018

Our Ref: CS/FCI18011593/R1qd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SGN 6736P.**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/07/2018 at the premises of M/s CHARN'S CUSTOMCRAFT and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 2,423.90</u>
Revised Estimate Amount	: <u>S\$ 2,113.90</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Yours faithfully

Rasul  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	12-06-2018	<b>Our Ref No.</b> D18004698MFSH
<b>Accident Date</b>	09-06-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA1500S	<b>Third Party Vehicle.</b> SGN6736P
<b>Survey Location</b>	BLK 1010 BUKIT MERAH LANE 3 #01-105	
<b>Contact Person.</b>	SHARON LEE	
<b>Contact No.</b>	62725429/ 0	<b>Fax No.</b> 62736676
<b>Survey Type</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	CHARN'S CUSTOMCRAFT	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	MAY CHUA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241396)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18004698MFSH	<b>Policy No</b>	D-18088936MFSH	<b>Claimant S.No &amp; Name</b>	1 & CHARN'S
<b>Workshop Name</b>	CHARN'S CUSTOMCRAFT (Contact Person : SHARON LEE)	<b>Survey Location &amp; Contact Details</b>	BLK 1010 BUKIT MERAH LANE 3 #01-105 <b>Mobile:</b> 0 , <b>Phone:</b> 62725429 , <b>Fax:</b> 62736676 <b>EmailId:</b> CHARN@SINGNET.COM.SG		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHA1500S	<b>TP Vehicle No</b>	SGN6736P
<b>PRI Recieved Date</b>	25-06-2018 05:44:24 PM	<b>Surveyor Appointed Date</b>	25-06-2018 05:19:35 PM	<b>Surveyor Accept Date</b>	26-06-2018 1

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	26-06-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
<b>File Name</b>	<b>Action</b>

## Surveyor Job Remarks

<b>Remarks</b>	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 12 July 2018 4:12 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18004698MFSH/1  
**Attachments:** CSFCI18011593R1qd3.pdf

Dear May,

Enclosed herewith preliminary advice of SGN 6736P.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 26 June 2018 10:12 AM  
**To:** 'Claim Workflow System' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D18004698MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Monday, 25 June 2018 5:20 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [MAYCHUA@MSFIRSTCAPITAL.COM.SG](mailto:MAYCHUA@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18004698MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4236C
Vehicle Details	
Vehicle No.:	SGN6736P
Vehicle to be Exported:	Yes
Intended De-registration Date:	30 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	1ZZ2727543
Chassis No.:	ZNE100332743
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,007.00
Original Registration Date:	24 Nov 2006
First Registration Date:	24 Nov 2006
Transfer Count:	0
Actual ARF Paid:	\$17,309.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Nov 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$28,027.00
COE Rebate Amount:	\$19,042.00
<b>Total Rebate Amount:</b>	<b>\$19,042.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 22 Jun 2018

OK



AXA Insurance Pte Ltd  
 ☎ 1800 880 4888 (Within Singapore)  
 (65) 4880 4888 (International)  
 ☎ (65) 6880 4740  
 ✉ customer.care@axa.com.sg  
 🌐 www.axa.com.sg

NG GUEK ENG  
 BLK 51 TELOK BLANGAH DRIVE  
 #12-124  
 SINGAPORE 100051

**Renewal**

Date  
**02/11/2017**

your servicing distributor  
**VITESSE SOLUTIONS / 04060**

your servicing distributor contact  
**65533468**

**Policy Schedule**  
 Your SmartDrive Comprehensive Private MPV APW

**Your policy snapshot**

<b>Policyholder name</b>	NG GUEK ENG	<b>Policy number</b>	VA1 / GA073715
<b>Cover</b>	Comprehensive	<b>FIN / NRIC</b>	S1664236C
<b>Period of Insurance</b>	from 24/11/2017 to 23/11/2018 (both dates inclusive)		

**Premium breakdown**

Gross Premium after 50% NCD	SGD 894.65
Total Discounts	- SGD 0.01
7% GST	SGD 62.62
<b>Final Premium</b>	<b>SGD 957.26</b>

**Your benefits highlights**

(refer to Policy Wording for full terms and conditions)

**SmartDrive Comprehensive Private MPV APW Benefits**

- 24/7 Towing & Transportation in Singapore or Overseas
- Guaranteed Repairs for twelve (12) Months
- Loss or Damage
- Legal Liability
- Loss of Personal Effects in Singapore up to \$3,000
- Daily Transport Allowance of \$50 for a maximum of five (5) days
- Double Personal Accidental Benefit for Young and Old Passengers
- Car Accessories up to \$2,500
- Medical and dental expenses up to \$500 per person for either you as the driver or your authorised driver and a passenger
- Waiver of Named Young or Inexperienced Driver Excess
- Basic Own Damage Excess Reduction for AXA Premium Workshop
- Personal accident benefit of up to \$30,000 for you or one of your named drivers while driving and \$20,000 per passenger
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess

**Additional Benefits**

- No Claim Discount Protector

**Vehicle details**

<b>Make &amp; Model of Vehicle</b>	TOYOTA WISH 1.8	<b>Year of manufacture</b>	2006
<b>Vehicle registration number</b>	SGN6736P	<b>Type of Use</b>	Private use
<b>Body type</b>	MPV	<b>Engine capacity (c.c.)</b>	1794
<b>Seating capacity (excl driver)</b>	6	<b>Engine number</b>	1ZZ2727543
<b>Off-Peak car</b>	No	<b>Chassis number</b>	ZNE100332743

Insured's Estimated Market Value  
 Limitation to use  
 Finance Loan Company

Market Value at the time of Loss (including accessories and spare parts)  
 As per Certificate of Insurance  
 OCBC BANK LIMITED

AXA Insurance Pte Ltd (199903512M)  
 8 Silenton Way, #24-01, AXA Tower,  
 Singapore 068811  
 Customer Centre, #B1.01

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S8804547E**

Name: **LIN WEIGUO, EUGENE**

Birth Date: **13 Feb 1988**

Issue Date: **26 Jul 2008**

001631538A



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S8804547E**

Name: **LIN WEIGUO, EUGENE**

**林伟国**

Race: **CHINESE**

Date of Birth: **13-02-1988** Sex: **M**

Country of Birth: **SINGAPORE**

S8804547E




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S1664236C**

Name: **NG GUEK ENG**

**黄丽英**

Race: **CHINESE**

Date of Birth: **21-12-1964** Sex: **F**

Country of Birth: **SINGAPORE**

S1664236C




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver, and other motor vehicles < 2500kg 26 Jul 2008

NP 428A

Licence No: **S8804547E**

3312740

Barcode

NRIC No. **S8804547E**

Blood Group: **O+** Date of issue: **20-02-2003**

Address: **APT BLK 51 TELOK BLANGAH DRIVE #12-124 SINGAPORE 100051**




0889519


Barcode

NRIC No. **S1664236C**

Blood Group: **O+** Date of issue: **13-04-1993**

Address: **APT BLK 51 TELOK BLANGAH DRIVE #12-124 SINGAPORE 100051**

NRIC No: **S1664236C** Date: **14-07-2000** No: **8820141**





# 創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

AXA/FC (SHA15009) ...  
DOA: 09/06/2018@2000

MS FIRST CAPITAL INSURANCE PTE LTD

22/06/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM  
ESTIMATE COST OF REPAIR FOR VEHICLE NO:  
SGN 6736 P - TOYOTA WISH 1.8 A  
CHASSIS NO: ZNE100332743 (2006)

1 pc	Front headlamp LH	\$ 980.00	SCA ✓
1 pc	Front fender LH	\$ 865.20	PH ✓
		\$ 1,845.20	
	LESS 25%	\$ 461.30	
		\$ 1,383.90	
	Check wiring function	\$ 40.00	30
	Remove/reinstall/replace the necessary parts: jacking, panel beating, repair and straighten front headlamp panel LH and front fender LH.	\$ 350.00	300
	Putty and respray front headlamp panel, front bonnet, front fender LH and front bumper.	\$ 650.00	400
		\$ 2,423.90	
	ADD 7% GST	\$ 169.67	
		\$ 2,593.57	

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damage / part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

12/7/18  
Resue  
HP 900 10068  
3 days  
4s  
10/07/18 PM10  
Resue after repair



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18011593/R1qd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-10-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1500S	Veh. Inspected	SGN 6736P	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18004698MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	25/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH 1.8 A	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	ZNE100332743	Colour	MAROON	
Odometer	88570	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm	
L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm	
R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm	
L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/06/2018	Inspection Date	10/07/2018	
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGN 6736P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	FRONT HEADLAMP LH	SCRATCHED	980.00	980.00
1	FRONT FENDER LH	BENT	865.20	865.20
	LESS 25% DISCOUNT		-461.30	-461.30
			1,383.90	1,383.90
	<b>LABOUR</b>			
	CHECK WIRING FUNCTION.		40.00	30.00
	REMOVE/REINSTALL/REPLACE THE NECESSARY PARTS, JACKING, PANEL BEATING, REPAIR AND STRAIGHTEN FRONT HEADLAMP PANEL LH AND FRONT FENDER LH.		350.00	300.00
	PUTTY AND RESPRAY FRONT HEADLAMP PANEL, FRONT BONNET, FRONT FENDER LH AND FRONT BUMPER.		650.00	400.00
			1,040.00	730.00
	<b>GRAND TOTAL</b>		<b>2,423.90</b>	<b>2,113.90</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,700.00</b>

Report Ref No. CS/FCI18011593/R1qd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.