



Your Ref: AEMD/105/009/2017/161 (PD)

Date: 02<sup>nd</sup> July 2018

Our Ref: CS1/SPF18011597/K1rbs2

**M/s Automotive Engineering & MGT Division**

Accident Claim Section  
(Singapore Police Force)  
1 Mount Pleasant Road  
Blk 8 Old Police Academy  
Singapore 298333  
(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
SHB 8984C INSURED VEHICLE: QX 581L ACCIDENT DATE: 03/12/2017**

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHB 8984C from M/s KM Auto Assessors Pte. Ltd.
- b) Colour damaged vehicle photographs of SHB 8984C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SHB 8984C  
Make & Model : Kia Optima 1.7 Taxi Auto  
Year of Registration : 2014  
Chassis Number : KNAGM414ME5455540

2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.