

REC. BY:

REF:

CS/SPF18011602 / TIT best

Special Instruction:

Surveyor

Tawhiah

ASSIGNMENT (Office)

From (Person):

Abdul Rahman

of

SPF

Date/Time:

26062018

Estimated Cost:

Bill to:

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 6960X

Insured:

AX 532D

at Workshop m/s

Motor Image

Tel:

of

25 Leng Kie Rd

Policy No:

Claim No:

AEMD/105/009/2018/080

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18062018

(Client's Record)

04072018 @ 10am owner waiting

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

26062018 1:15pm

Person Contacted:

Jeff

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLX 6960X - X
	AX 532D - X
	Submit Preli report
	liability not clear, & still under investigation

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 04/07/2018

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX G960X  
at Workshop m/s Motor Image  
of 25 Leng Kee Rd

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

10 am @ owner waiting

Make of Veh: \_\_\_\_\_

Jeff

(Policy Condition)

N/S	O/S
	X

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (w/p)

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLX G960X Yr Regn: 2018, April.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru Forestar c.c

Colour: Black. A/C: Insured / Std / NI / NA

Sp. Reading: 7255 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JP1535RC5-34106703

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_ R: 275 / 60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 4/7/18 @ 1045

Survey held at Motor Image Leng Kee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

RECEIVED 27 AUG 2018

Date/Time, File Pass to?

: Preli. Report  
 : Final Report

1) 27/8 Typist  
Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip: —

Survey Fee:

280

Transportation:

\_\_\_\_ S + RS, \_\_\_\_ SI

Photos

Others

TOTAL

280

Report Format: TP

Lump Sum / I.B.I: (\$ \_\_\_\_\_ )

Add Fee:  : Site Insp (\$ \_\_\_\_\_ )  
 : Interview (\$ \_\_\_\_\_ )  
 : Tech. Invs (\$ \_\_\_\_\_ )  
 : Weekend (\$ \_\_\_\_\_ )



# SINGAPORE POLICE FORCE

SPF Accidents Claims Section  
Automotive Engg & Mgmt Div  
Police Logistics Department  
No. 1 Mount Pleasant Road  
Block 8 Old Police Academy  
#02-12 Singapore 298333

Your Ref : SLX6960X

Our Ref : AEMD/105/009/2018/080

Date : 26 June 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd  
Paya Ubi Industrial Park  
51 Ubi Avenue 1 #01/02-25  
Singapore 408933

Via Fax Only: 62564315

Dear Sir,

**RTA ON 19 JUNE 2018 INVOLVING GOVT VEHICLE QX532D AND OTHER VEHICLE SLX6960X**

We refer to the above matter.

- 2 Please arrange for a Pre- Repair Inspection of vehicle no. **SLX6960X** at **M/s Motor Image Enterprises Pte Ltd** of **25 Leng Kee Road, Singapore 159097.**
- 3 Estimates were provided by the workshop.
- 4 Thank you.

Yours faithfully,

Abdul Rahman  
Accident Claims Officer  
for ASST DIRECTOR



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref : CS/SPF18011602/T1tb

ACCIDENT CLAIM SECTION  
(SINGAPORE POLICE FORCE)  
1 MOUNT PLEASANT ROAD  
BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 26-06-2018



Code : SPF

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 532D	Veh. Inspected	SLX 6960X
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/080	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	26/06/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

## 5. General Information

Accident Date	19/06/2018	Inspection Date	
Survey held at	25 LENG KEE ROAD		
Repairer	MOTOR IMAGE ENTERPRISES PTE LTD		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## Denise Tay (LKKAuto)

---

**From:** Jeff Teh /MIE-LK Svc <t00335s@tanchong.org>  
**Sent:** Friday, 24 August 2018 1:53 PM  
**To:** Denise Tay (LKKAuto)  
**Cc:** 'Daniel Jude'; 'Sayedinah'; Dennis Leong /MIE-LK Svc  
**Subject:** RE: SLX 6960X / DOA: 19/06/2018

Dear Denise,

For this case liability not clear yet and still under investigating by traffic police, once the vehicle ready for finalize will update you.

Thanks

Best Regards,

**Jeff Teh**

---

Service Advisor  
Motor Image Enterprises Pte Ltd  
25 Leng Kee Road  
Singapore 159097  
DID:(65)6703 8631  
HP:(65)9073 2232  
FAX:(65)6479 1137  
Email:tengchuen@motorimage.net



**SUBARU TECNICA  
INTERNATIONAL**

---

**From:** Dennis Leong [mailto:dennisleong@motorimage.net]  
**Sent:** Friday, 24 August 2018 1:47 PM  
**To:** Jeff Teh <tengchuen@motorimage.net>  
**Cc:** Daniel Jude <danieljude@motorimage.net>; Sayedinah <sayedinah@motorimage.net>  
**Subject:** FW: SLX 6960X / DOA: 19/06/2018

Hi Jeff,

Kindly follow up.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/06/2018 11:21
Date Of Accident	18/06/2018 13:15
Exact Location Of Accident	COMMONWEALTH DRIVE/DIRECTION OF TANGLIN HALT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX6960X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WONG TAT KAI
NRIC No	S1289595Z
Email Address	TATKAIWONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97433789
Alternative Phone No	OTHERS-97433789

### Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 I-L (SJ) (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800034819
Cover Note Number	

### Driver

Name of Driver	WONG TAT KAI
NRIC No	S1289595Z
Date Of Birth	26/07/1958
Occupation	INDOOR
Date Of Driving Pass	23/01/1980
Driving Experience	38 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97433789
Fax Number	
Contact Number	OTHERS-97433789
EMail Address	TATKAIWONG@GMAIL.COM

Address	257 ARCADIA ROAD #06-03
Postcode	1128
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ALEXANDRA NPP
Police Station Address	<b>ROAD:</b> BLK 46 TANGLIN HAIT RD #01-328 , <b>POSTCODE:</b> 140462 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> - <b>FAX NO:</b>
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Refer Sketch Plan & police report

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX532D
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	SGT KELVIN
NRIC/Passport Number	
Contact Number	64719999
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

Nô. Of Passenger (Including Driver)

2

Passenger 1

NAME: : YIP XUANYU

GENDER: : MALE

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO :  
REFERENCE : INS/IC/LHI/034/2018  
DATE : 19-JUN-2018

S()  
TEL :  
FAX :

OWNER'S NAME : WONG TAT KAI  
ADDRESS : 257 ARCADIA ROAD  
#06-03  
S(289851)  
TELEPHONE NO : 97433789

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 180034819  
VEHICLE NO : SLX6960X  
MODEL CODE : SJ5EK7C  
MODEL/YEAR : FORESTER 2.0I-L AWD CVT  
ENGINE NO : FB20YD1248B  
CHASSIS NO : JF1SJ5KC5JG106703  
MILEAGE : 1 KM  
DATE IN : 19/06/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : JEFF TEH TENG CHUEN  
ACCIDENT DATE : 19/06/2018

Print Date : 19/06/2018  
Print Time : 12:05:10

Tanpin 97495749-  
'WP'  
4/7/18 @1045

Resurvey before paint  
Sur@lkkauto.com  
03 days

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLX6960X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	TO SUPPLY AND REPLACE REAR BUMPER ASSY AND REAR EXHAUST COVER	1680.00	560
2	ZZ/002	TO RESPRAY REAR BUMPER ASSY	880.00	440
3	ZZ/003	TO REMOVE AND CHECK REVERSE SENSOR CONDITION	60.00	40
4	ZZ/004	SUNDRIES	50.00	20
TOTAL LABOUR CHARGES			2670.00	

3377.04

MOTORIMAGE ENTERPRISES PTE. LTD.  
 25 LENG KEE ROAD  
 SINGAPORE\*159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLX6960X

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	BUMPER FACE REAR FORESTER IL	57704SG012	540.00	dl ✓		
2	BRKT SD R RH	(1) 57707SG080	14.40	?		
3	BRKT SD R LH	57707SG090	14.40	?		
4	BEAM COMPL R EU	57711SG0219P	288.00	?		
5	COVER BMPR R (EXHAUST)	57731SG060	14.40	cut ✓		
SUB TOTAL			871.20	0.00	0.00	0.00
LESS DISCOUNT ( NETT-20 %)			174.24	0.00	0.00	0.00
GRAND TOTAL			696.96	0.00	0.00	0.00
OVERALL TOTAL			696.96			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

6- Cover hook R

57731SG060NN

12.60 cut ✓

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLX6960X  
-----

TOTAL LABOUR CHARGES	2670.00
TOTAL SPARE PARTS CHARGES	696.96
	-----
GRAND TOTAL	3366.96 *
	-----

\* All charges do not include GST.

SURVEYOR'S PARTICULARS  
-----

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18011602/T1tbe2	
ACCIDENT CLAIM SECTION(SINGAPORE POLICE FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date : 28-08-2018	
ATTN : ABDUL RAHMAN		Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 532D	Veh. Inspected	SLX 6960X
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/080	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	26/06/2018
2. Vehicle Particulars & Condition			
Make & Model	SUBARU FORESTER	c.c	0
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JF1SJ5KC5JG106703	Colour	BLACK
Odometer	7255	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/60 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/60 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/06/2018	Inspection Date	04/07/2018
Survey held at	25 LENG KEE ROAD		
Repairer	MOTOR IMAGE ENTERPRISES PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 6960X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	BUMPER FACE REAR FORESTER IL (N)	DEFORMED	540.00	540.00
1	BRKT SD R RH (N)	* CHECK	14.40	-
1	BRKT SD R LH (N)	* CHECK	14.40	-
1	BEAM COMPL R EU (N)	* CHECK	288.00	-
1	COVER BMPR R (EXHAUST) (N)	CUT	14.40	14.40
1	COVER HOOK R (N)	CUT	12.60	12.60
	LESS 20% DISCOUNT		-176.76	-113.40
			707.04	453.60
	<b>SPECIAL NETT ITEMS</b>			
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			50.00	20.00
	<b>LABOUR</b>			
	TO SUPPLY AND REPLACE REAR BUMPER ASSY AND REAR EXHAUST COVER.		1,680.00	560.00
	TO RESPRAY REAR BUMPER ASSY.		880.00	440.00
	TO REMOVE AND CHECK REVERSE SENSOR CONDITION.		60.00	40.00
			2,620.00	1,040.00
	<b>GRAND TOTAL</b>		<b>3,377.04</b>	<b>1,513.60</b>
	<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$253.44 NETT)</b>			<b>1,513.60</b>

Report Ref No. CS/SPF18011602/T1tbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.