

INSURANCE CASE OWNER: Stally | CC4 ASM 1616 Umbh | LKIC IDAC

Surveyor: Marius | DOI: ASSIGNMENT 26/6/18 | Date / Time: 26/6/18

Pre-assign / CCU / FTE: S42 7551K | Registered in Merimen: _____



Insured Vehicle No.: _____
 Name of Insured: YUSMAN Bin ABD MUDJID
 Insured Tel No.: _____ HP: 92223247
 Excess Sec II :SS _____ D.O.A.: 26/2/14
 Is driver the owner? (YES / NO) Nature of Accident: _____

Claim No.: S3M 00686 / 52763
 Policy No.: AR-4959+1
 Make / Model: MTSUBLMI
 Place of Accident: Oppo Lp of BIE 256 Bishan ST 22

If NO, Driver Name / Age: _____ | OI GIA REPORT: YES / NO | TP GIA REPORT: YES / NO
 Driver Tel No.: _____ | (V/L) YES / NO | Insured Liability: % Final? Yes / No

YP 6A67K → Get the 2 Tampines

	INSRS: _____ WSP: _____ Tel: _____ Liability: _____ RMKS: _____						
--	---	--	---	--	---	--	---

Date/Time	STAGE	DATE / PIC
<u>27/6/18</u> <u>VIVIAN</u>	Non-Reporting Ir (1st) Non-Reporting Ir (2nd) Non-Reporting Ir (Final) Notification Ir (if non-pickup) Call OI After call Ir to OI	
<u>8/5/19</u>	Documentation Check List: Handler Typist	
<u>28/5/19</u>	Notification Ir (if non-pickup) After call Ir to OI Authorisation To Act	
<u>29/5/19</u>	Release Voucher Final Repair Bill Car Rental Invoice Towing Invoice LTA / GIA Medical Bill PIR Mandate/Reject Instruction LOD Payment Breakdown Form Post-Repair Photos Others	

*Gmail claim

Pending AXIA instruction

email from AXIA to reject claim

email to workshop reject claim

Reject Case

By: VIVIAN

Approved by: [Signature]

Date: 10-06-19

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: \$S _____ (_____ days) Reduction: % _____ Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call

Final Liability: % _____ (Agreed / Assessed) BOLA S/N No.: _____ IF NO or B 28, Ass. Liu

Repair Cost: \$S _____

Loss of Rental (LOR): \$S _____ (_____ days)

Loss of Use (LOU): \$S _____ (_____ x _____ days)

Loss of Income (LOI): \$S _____ (_____ x _____ days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: \$S _____

Medical: \$S _____

Disbursement: \$S _____ (e.g. Tow/Independent)

Legal Cost: \$S _____

Total \$S _____ **Global Sum \$S:** _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S _____ Name 1: _____

Payee 2 (Strike if N.A.): \$S _____ Name 2: _____

Payee 3 (Strike if N.A.): \$S _____ Name 3: _____

COPY SENT

ENTERED 10 JUN 2019

1) Claim Status: Normal/Reject/Private Settle

2) Report Format: AGIA

3) Survey fee: \$350.00

AXA

ASSIGNMENT

From _____ Date: _____
 Estimated Cost: _____
 QD: TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: 1/P 6967R
 at Workshop m/s: Sofex Transport
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 80k
 IDAC Accident Report: 2 Consistent? : Yes or No
 CA / PR Seen: 2 Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: 1.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 1/P 6967R Yr Regn: 7 17
 Type: M.Car / M.Cycle / Bus / Lor / Taxi / Prime Mova: /
 Truck / Trailer or (M)
 Make: ISUZU NMR85 cc 2999
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 561 KM T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JAA NMR85HH7100793
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: R / S/Rim / STD A/Rim or
 Tyre Size: F: 195/80 R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 mm Rear: 6/6 mm
 R/Bal: _____ mm R/Bal: _____ mm
 L/Bal: 6 mm L/Bal: 6/6 mm
 D.O.A: 28/12/17 D.O.I: 26/6/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>26/6/18</u>	<u>P/P # 800 Summary</u>

(ed. \$1960.00 7.1)

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Date/Time, File Return to? _____
 2) _____
 Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____ \$ + RS _____ \$
 Photos _____
 Others _____
 TOTAL _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18011616/Uwb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 26-06-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGZ 7551K	Veh. Inspected	YP 6967R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/12/2017	Inspection Date	
Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

PLEASE ARRANGE TO SURVEY
VEHICLE AT 22 TAMPINES ST 92 (S
528876)

Jimmy Goh Ki
CLAIM DEPARTMENT
DID : 66547618
FAX :

Date : 21/06/2018
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTHCVE000096 Accident Date : 28/12/2017
Vehicle No : YP-6967-R Make & Model : ISUZU NMR85UH5A 3.0 Y (M) EURO 5
Excess : 0.00 Add Excess : 0.00

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>Special Nett Item</u>			
1	SIDE GATE LH <i>2 X</i>	RESTORE	
9	SIDE GATE HINGE LH <i>2 X</i>	RESTORE	
1	FLAT BED FRAME <i>2 X</i>	RESTORE	
1	REAR MUDGUARD LH <i>2 X</i>		550.00
1	SIDE GATE ADVERTISEMENT STICKER LH <i>142 d/c X</i>		380.00
	Sub Total		930.00
<u>Labour & Misc</u>			
	LABOUR TO FACILITATE REPAIR		700.00
	TO REMOVE & INSTALL REAR MUDGUARD LH		100.00
			} <i>400</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To dispose damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party estimate is on a "Without Prejudice" basis
- No illegal deductions is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date : 21/06/2018
 To : AXA INSURANCE PTE LTD
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : D17MTHCVE000096 Accident Date : 28/12/2017
 Vehicle No : YP-6967-R Make & Model : ISUZU NMR85UH5A 3.0 Y (M) EURO 5
ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	TO REMOVE & INSTALL SIDE GATE ALUMINIUM CHECKER PLATE LH	200.00	X
1	TO RUST PROOF AFFECTED AREA	80.00	X
	TO SPRAY PAINT ON AFFECTED AREAS	750.00	400
	Sub Total	1830.00	

2,760.00

Remarks:

not submit

SUB TOTAL
GST 7.0 % 193.20
TOTAL 2,953.20

Surveyor's name: *marcus LKH*

Principal's name: ETHOZ Group Ltd

Survey Date & Time: *26/6/18 @*

p/p \$800
2 dy.
take photos after repair

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4531H
Vehicle Details	
Vehicle No.:	YP6967R
Vehicle to be Exported:	No
Intended De-registration Date:	27 Jun 2018
Vehicle Make:	ISUZU
Vehicle Model:	NMR85UH5A
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	4JJ13A1869
Chassis No.:	JAANMR85HH7100793
Maximum Power Output:	-
Open Market Value:	\$28,320.00
Original Registration Date:	24 Jul 2017
First Registration Date:	24 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$1,416.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$14,070.00
COE Rebate Amount:	\$12,761.00
Total Rebate Amount:	\$12,761.00

The information contained herein is correct as at 27 Jun 2018

OK

◀ Service Request Details

Claim

S7M0068G

Reference

None ✎

Loss Date

December 28, 2017

Request Date

June 26, 2018

Due Date

July 3, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

26/06/2018 @ 11:55am

Jimmy veh in.

Ethoz (Kampines)

Meruis.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

YP6967R

Make

TPVD ISUZU

Model

NMR85UH5A 3.0 Y (M) EURO

Service Address

...

Primary Contact/Insured

ABD MADJID YUSMAN BIN
535 WOODLANDS DRIVE 14, 730535, Singapore
92223297
GHOST_RYDER27@HOTMAIL.COM

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

- Messages
 - Invoices
 - History
 - Documents
 - Assessment
 - Metrics
 - Notes
-

New Message

TYPE



SENT

6/26/18 11:39 AM

FROM

NG Stacey

SUBJECT

proceed ds

BODY



Letter of Demand

Your Ref : SGZ - 7551 - K
Our Ref : OCR/28122017/TP-9864
Date : 06/07/2018

AXA INSURANCE PTE LTD
8 SHENTON WAY #27-01
AXA TOWER
Singapore - 068811

Attn : Motor Claim Department

Subject : ACCIDENT INVOLVING VEHICLE NUM : YP -6967-R, SGZ7551K ON 28/12/2017
AT CAR PARK ENTRANCE TO BLK 258 BISHAN ST 22

Dear Sir / Madam,

We would like to append our losses as follows :-

	AMOUNT (\$)
1. Repair Cost	856.00
2. Loss Of Use (2 days)	240.00
3. Miscellaneous - GIA fee	2.00

TOTAL 1,098.00

Enclosed : Copies of Repair Cost Invoice, GIA search invoice & GIA Report for your perusal and kind attention.

Kindly look into the matter and revert to us as soon as possible.

Thank you,

Yours faithfully,

Ashley Nguyen

CLAIM DEPARTMENT

DID : 66547920

FAX : 6654 - 7540

EMAIL : ashley.nguyen@ethozgroup.com

TAX INVOICE

GROUND INSTRUMENTATION & ENGINEERING PTE. LTD.
62 UBI ROAD 1
#01-32 OXLEY BIZHUB 2
SINGAPORE - 408734

Tax Invoice : WS 1807/OFM0306
Invoice Date : 06-Jul-2018
Ref. No. : 17121370
GST No. : M2-0057587-3

Page 1

VEHICLE NO. : YP -6967-R

MAKE & MODEL : ISUZU NMR85UH5A 3.0 Y (M) EURO 5

ACCIDENT DATE : 28/12/2017

Description	Qty	Unit Price(S\$)	Amount (S\$)
BEING REPAIR COST FOR THE ABOVE VEHICLE			800.00
7 % GST			56.00

Total (S\$) 856.00

E & O.E

CHEQUE SHOULD BE CROSSED AND MADE PAYABLE TO ETHOZ GROUP LTD

No receipt will be issued.

Computer generated document! no signature required.

CONTACT : ASHLEY NGUYEN
DID : 66547920
Main : 63198000
Fax :

PLEASE DETACH AND ENCLOSED WITH PAYMENT

Customer's Copy

Please do not staple. Please write your Invoice No. on the back of your cheque.

Customer Name : GROUND INSTRUMENTATION & ENGINEERING PTE. LTD.
Reference. No. : 17121370
Tax Invoice : WS 1807/OFM0306
Invoice Date : 06-Jul-2018
Invoice Amount : S\$ 856.00
Payment Due Date : 06-Jul-2018
Cheque No. : _____

ETHOZ GROUP LTD
30 BUKIT BATOK CRESCENT
SINGAPORE 658075





**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-094715
Date of Request: 21/06/2018

Your Ref No: Online Purchase

ETHOZ Protect Pte Ltd
30 Bukit Batok Crescent
Singapore 658075

Dear Sir/Madam,

Enquiry Date: 21/06/2018
Enquiry By: JACKSON TEO Ban Chye
TP Vehicle No.: SGZ7551K
Accident Date: 28/12/2017

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SGZ7551K	AXA Insurance Pte Ltd	16/11/2017-15/11/2018	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-094715
Date of Request: 21/06/2018

Your Ref No: Online Purchase

ETHOZ Protect Pte Ltd
30 Bukit Batok Crescent
Singapore 658075

Dear Sir/Madam,

Enquiry Date: 21/06/2018
Enquiry By: JACKSON TEO Ban Chye
TP Vehicle No.: SGZ7551K
Accident Date: 28/12/2017

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Wednesday, 29 May, 2019 4:47 PM
To: Joyce Choo
Cc: Admin A; Hsiao Tong (LKKAuto)
Subject: RE: Reminder: Your ref: SGZ7551K Our ref: YP6967R
Attachments: Sketch Plan.pdf

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/Madam,

Accident involving Vehicle YP 6967R & SGZ 7551K ON 28/12/2017

We refer to the above matter

Our insured driver has reiterated that the accident was caused due to the entire negligence of your client. base on damaged photos of both vehicles, YP6967R damaged right rear portion, SGZ7551K damaged at rear fender RH and tail lamp RH If Insured was stationery at the time of accident and TP going straight, the damaged of TP should be at front rear portion, that's not at rear right as per photos.

We attached herewith our insured's accident report for your perusal.

Under such circumstances, we have our principal's instruction to deny liability of your client's claim.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vivian Lau (LKKAuto)
Sent: Friday, 17 May, 2019 11:14 AM
To: Joyce Choo <Joyce.Choo@ethozgroup.com>; Shu Pei (LKKAuto) <shupeil@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Reminder: Your ref: SGZ7551K Our ref: YP6967R

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Joyce,

We refer to the above matter.

Please be informed that we are pending our principal further instruction

We will get back to you for an update/offer in due course

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joyce Choo [<mailto:Joyce.Cho@ethozgroup.com>]

Sent: Friday, 17 May, 2019 10:56 AM

To: Shu Pei (LKKAuto) <shupe@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Subject: Reminder: Your ref: SGZ7551K Our ref: YP6967R

Dear Sir/Madam,

Accident involving YP6967R & SGZ7551K on 28/12/2017.

Please refer to the above matter.

Is there any outcome for this case? Our client is chasing us for the result.

Kindly revert as soon as possible.

We await your favorable reply.

Best regards,
Joyce Choo

Claims Settlement



ETHOZ GROUP LTD

22 Tampines Street 92 Singapore 528876

DID: 6654 7920 | Fax: 6654 7540

Website: www.ethozgroup.com



Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

⏪ **Re:RE: Liab**

Type

🗨 Question

Message

Please proceed to reject

Reply

◀ Re:RE: Liab

Type

📍 Question

Message

Please proceed to reject

Reply



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18011616/Uwb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:STACEY

Date : 19-06-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGZ 7551K	Veh. Inspected	YP 6967R
Policy No.	GA049596/1	Coverage (\$)	0.00
Claim No.	S7M0068G	Excess (\$)	0.00
Assign From		Assign Date	26/06/2018

2. Vehicle Particulars & Condition

Make & Model	ISUZU NMR85 (M)	c.c	2999
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JAANMR85HH7100793	Colour	WHITE
Odometer	56145	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/85 R16	BRIDGESTONE	6 mm
L/H Front Tyre	195/85 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	195/85 R16 (D)	BRIDGESTONE	6/6 mm
L/H Rear Tyre	195/85 R16 (D)	BRIDGESTONE	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/12/2017	Inspection Date	26/06/2018
Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 6967R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SIDE GATE LH (SN) (CONSISTENT) (NPA)	TO REPAIR SEE LABOUR	-	-
9	SIDE GATE HINGE LH (SN) (CONSISTENT) (NPA)	TO REPAIR SEE LABOUR	-	-
1	FLAT BED FRAME (SN) (CONSISTENT) (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR MUDGUARD LH (SN)(CONSISTENT)	TO REPAIR SEE LABOUR	550.00	-
1	SIDE GATE ADVERTISEMENT STICKER LH (SN) (CUT)	NOT CONSISTENT WITH THE IMPACT	380.00	-
			930.00	-
LABOUR				
	LABOUR TO FACILITATE REPAIR.INCLUSIVE O THE REPAIR OF SIDE GATE LH,SIDE GATE HINGE LH, FLAT BED FRAME AND REAR MUDGUARD LH.)		700.00	400.00
	TO REMOVE & INSTALL REAR MUDGUARD LH . }		100.00	-
	TO REMOVE & INSTALL SIDE GATE ALUMINIUM CHECKER PLATE LH.	NOT NECESSARY	200.00	-
	TO RUST RPOOF AFFECTED AREA.	NOT NECESSARY	80.00	-
	TO SPRAY PAINT ON AFFECTED AREAS.		750.00	400.00
			1,830.00	800.00
GRAND TOTAL			2,760.00	800.00
RECOMMENDED COST OF REPAIRS				800.00

Report Ref No. CC4/ASM18011616/Uwb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.