

Surveyor

DOI:

Date / Time:

Registered in Meripen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 4/3/2020

Confirm with: Swan

Email

Call

Final Liability:

%

FD

(Agreed/Assessed) BOLA S/N No. 1111

If NO or B 28, Ass. Lia:

Repair Cost: \$2400

S\$ 1200.00

Loss of Rental (LOR):

S\$ -

(

days)

Loss of Use (LOU): \$320

S\$ 160.00

(\$ 80 x 4 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search:

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost:

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: PIR

3) Survey fee: \$450

Total:

S\$ 1362.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 1362.00

Name 1:

Lin's Brother Auto Engineering Workshop

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

REF: LPC

ASSIGNMENT

2004

From: Date: 26/06/2018

Estimated Cost:

OO: TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

YL 63482

at Workshop no:

Liu's Brother

of: No-1, Kaki Bukit Ave 6 # 01-01

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

6800

IDAC Accident Report:

Consistent? Yes or No

CVA / PR Seen:

Consistent? Yes or No

Est. Repair:

3

days

Res.:

Yes or No

Lump Sum

200

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

(up)

7/3/2019

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

1/L 63482

Yr Regs:

304

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Primo Mover /

Truck / Trailer or (M/

Make:

m.t center

CC 3908

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading:

635990

T/Radio: Insured / Std / NI / NA

Eng/No:

FE639EA 45404

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

7.00 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

Rear

R/Bal:

6

mm

R/Bal:

6/6

mm

L/Bal:

6

mm

L/Bal:

6/6

mm

D.O.A.

2/6/18

D.O.I.

2/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MS Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L7A 3479

U/S # 24W (Red) # 2943.90 / STN

Date/Time: File Paid In:

☐

Preli. Report

To:

☐

Final Report

Date/Time: File Return In:

By:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) Site Insp. (\$

) Interview (\$

) Tech. Insp (\$

) Weekend (\$

Report Format:

Lump Sum / I.B.F. (\$

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

TOTAL

PARF/COE Rebate Enquiry

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

1196N

Vehicle Details

Vehicle No.:

YL6348Z

Vehicle to be Exported:

No

Intended De-registration Date:

23 Jun 2018

Vehicle Make:

MITSUBISHI

Vehicle Model:

FE639E6SRDE

Primary Colour:

White

Manufacturing Year:

2003

Engine No.:

4D34J68683

Chassis No.:

FE639EA45404

Maximum Power Output:

\$25,568.00

Open Market Value:

08 Mar 2004

Original Registration Date:

08 Mar 2004

First Registration Date:

1

Transfer Count:

\$1,279.00

Actual ARF Paid:

No

Intended PARF Rebate Details

PARF Eligibility:

-

PARF Eligibility Expiry Date:

\$0.00

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

07 Mar 2019

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

5

PQP Paid:

\$25,158.00

COE Rebate Amount:

\$3,523.00

Total Rebate Amount:

\$3,523.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 23 Jun 2018

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 1196N

Vehicle Details

Vehicle No.: YL6348Z

Vehicle to be Exported: No

Intended De-registration Date: 26 Jun 2018

Vehicle Make: MITSUBISHI

Vehicle Model: FE639E6SRDE

Primary Colour: White

Manufacturing Year: 2003

Engine No.: 4D34J68683

Chassis No.: FE639EA45404

Maximum Power Output: -

Open Market Value: \$25,568.00

Original Registration Date: 08 Mar 2004

First Registration Date: 08 Mar 2004

Transfer Count: 1

Actual ARF Paid: \$1,279.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 07 Mar 2019

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$25,158.00

COE Rebate Amount: \$3,479.00

Total Rebate Amount: \$3,479.00**Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 26 Jun 2018

OK

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53197911, Tel: 6741-1730 / 731, Fax: 6744-5746, Email: liushro@gmail.com

Invoice/Ref No: YL6348Z180602

Estimate

Customer

Name: Lompac Insurance Berhad

Date: 23-06-18

Address: Motor Claims Department

Vehicle No: YL6348Z

100 Beach Road #19-00

Model/Make: Mitsubishi

Shaw Tower

Singapore 060428

FE639EA45404

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bumper <i>Dis/cn 1645.32</i>	\$ 1,929.80	X
2	Bumper Bracket <i>1</i>	\$ 375.00	X
3	Bumper Clip 1 set <i>1</i>	\$ 48.00	SN ✓
4	HeadLamp <i>cn</i>	\$ 1,041.20	✓
5	Signal Lamp <i>cn</i>	\$ 324.30	✓
6	Side Lamp <i>11</i>	\$ 250.20	X
7	Step Panel <i>11 cn</i>	\$ 334.00	✓
8	Step Panel Garnish <i>n/s Du 256</i>	\$ 182.40	✓
	To check all wiring & electrical component for proper function	\$ 50.00	- 20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 420.00	- 300
	To putty & spray painting & including touch up paint on accident affected	\$ 380.00	- X

Total Parts & Labour of estimate for damaged vehicle

\$ 5,343.90

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

*Not Authorised**3527.22
2645.41**1/5 @ 2400/-
26/6/18**Wheeler After up*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before any spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



**GENERAL INSURANCE ASSOCIATION
OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-095670

Date of Request: 23/06/2018

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 23/06/2018

Enquiry By Susan Low Siew Yian

TP Vehicle No. SGP5630G

Accident Date 02/06/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SGP5630G	Lonpac Insurance Bhd	19/12/2017-18/12/2018	+65 62507388

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL INSURANCE ASSOCIATION
OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-095670

Date of Request: 23/06/2018

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 23/06/2018

Enquiry By: Susan Low Siew Yian

TP Vehicle No: SGP5630G

Accident Date: 02/06/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SGP5630G	Lonpac Insurance Bhd	19/12/2017-18/12/2018	+65 62507388

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 25 June 2018 3:52 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG; Susan Low
Subject: FW: Re: RE: Request for 3rd party claims survey YL6348Z Claims against SGP5630G Our Ref: 17/18/18/VP05/020649

Our Ref : 17/18/18/VP05/020649

Dear Nivitha,

Kindly note the request from the third party and proceed to conduct a third party survey.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 190555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Susan Low [mailto:liusbro@ymail.com]
Sent: Monday, 25 June, 2018 3:31 PM
To: GERALD POH WEE BIN; ERIC WOO JUN KIAT
Subject: Fw: Re: RE: Request for 3rd party claims survey YL6348Z Claims against SGP5630G Our Ref: 17/18/18/VP05/020649

----- Forwarded message -----

From: Susan Low <liusbro@ymail.com>
To: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Monday, 25 June 2018 03:27:00 PM
Subject: Re: RE: Request for 3rd party claims survey YL6348Z Claims against SGP5630G Our Ref: 17/18/18/VP05/020649

We did like to chose as follow:

Marcus Chua

Thank.

Best Regards,

Susan Low
M/s Liu's Brother Auto Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67411730 Fax: 67445746

On Monday, 25 June 2018 12:41:47 PM, ERIC WOO JUN KIAT <ericwoo@lonpac.com> wrote:

1:22pm @ 25/6/2018
person @ Susan
vehicle in
amway on 26/6/2018

Dear Susan,

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please refer to attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. We will select one of the listed motor surveyors.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: Susan Low [<mailto:liusbro@ymail.com>]

Sent: Saturday, 23 June, 2018 2:05 PM

To: MT_Claim_SG

Subject: Request for 3rd party claims survey YL6348Z Claims against SGP5630G

Accident on 02/06/2018 Along AYE (Tuas) Before Alexandra Road Exit
Involving YL6348Z and SGP5630G

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop, located at Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regard!

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 6741 1730
Fax: 6744 5746

Date of Survey:-

Name of Authorise Surveyor:-

Surveyor Email:

Remark :-

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 5 July, 2018 10:16 AM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: FW: Re: RE: Request for 3rd party claims survey YL6348Z Claims against SGP5630G Our Ref: 17/18/18/VP05/020649
Attachments: 28062018115736.pdf

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Re send

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: GERALD POH WEE BIN
Sent: Thursday, 28 June, 2018 12:03 PM
To: 'Mei Kwan (LKKAUTO)'
Cc: 'mt_claim@lonpac.com'; 'Hsiao Tong (LKKAUTO)'
Subject: RE: Re: RE: Request for 3rd party claims survey YL6348Z Claims against SGP5630G Our Ref: 17/18/18/VP05/020649

Dear Mei Kwan,

Attached a copy of insured's GIA report for your attention.

Kindly assess liability before direct settlement as our insured is claiming against the third party.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [<mailto:Meikwan@lkkauto.com>]
Sent: Thursday, 28 June, 2018 11:25 AM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; ONG LI LI; Hsiao Tong (LKKAUTO); Vic (LKKAUTO); Admin A
Subject: RE: Re: RE: Request for 3rd party claims survey YL6348Z Claims against SGP5630G Our Ref: 17/18/18/VP05/020649

EQI ref: 17/18/18/VP05/020649

Our Ref : 17/18/18/VP05/020649

Dear Nivitha,

Kindly note the request from the third party and proceed to conduct a pre-repair survey.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Susan Low [<mailto:liusbro@ymail.com>]

Sent: Monday, 25 June, 2018 3:31 PM

To: GERALD POH WEE BIN; ERIC WOO JUN KIAT

Subject: Fw: Re: RE: Request for 3rd party claims survey YL6348Z Claims against SGP5630G Our Ref: 17/18/18/VP05/020649

----- Forwarded message -----

From: Susan Low <liusbro@ymail.com>

To: ERIC WOO JUN KIAT <ericwoo@lonpac.com>

Sent: Monday, 25 June 2018 03:27:00 PM

Subject: Re: RE: Request for 3rd party claims survey YL6348Z Claims against SGP5630G Our Ref: 17/18/18/VP05/020649

We did like to chose as follow:

Marcus Chua

Thank.

Best Regards,

Susan Low

M/s Liu's Brother Auto Workshop

No. 1 Kaki Bukit Avenue 6 #01-01

AutoBay @ Kaki Bukit

Singapore 417883

Tel: 67411730 Fax: 67445746

On Monday, 25 June 2018 12:41:47 PM, ERIC WOO JUN KIAT <ericwoo@lonpac.com> wrote:

Dear Susan,

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 6741 1730
Fax: 6744 5746

Date of Survey:- _____

Name of Authorise Surveyor:- _____

Surveyor Email: _____

Remark :- _____

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 9 July 2018 8:30 AM
To: 'Susan Low'
Subject: Your Ref: YL 6348Z *Our Ref: CC4/LPC18011622/Upa3 [ACCIDENT INVOLVING SGP 5630G(LONPAC) AND YL 6348Z ON 02/06/2018]

Your Ref: **YL 6348Z** Without Prejudice
Our Ref: CC4/LPC18011622/Upa3

Dear Sirs/Madam,


ACCIDENT INVOLVING SGP 5630G(LONPAC) AND YL 6348Z ON 02/06/2018

We refer to the above matter.

Please be informed that liability is unclear. Kindly refer to our insured accident report below for your easy reference.

Kindly let us have evidences (ie: video footage/ scene photos / PIR) for our consideration.

Appreciate and early reply.

SKETCH PLAN	
 <p>A = SGP 5630G (Insd) B = YL 6348Z (TP)</p>	
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	
Please refer to police report	

Brief Details.

On 02/06/2018 at about 1330hrs, I was driving my vehicle bearing registration plate number SGP5630G on the 3rd lane of a 3 lane road. After I had drove pass the merging lane of Lower Delta Road onto AYE, I then noticed a lorry which was travelling on the 2nd lane bearing registration plate number YL 6348Z was travelling at a fast speed. Suddenly, I felt my vehicle jerked and vehicle had started to spin, the vehicle only stopped when it had collided onto the road diverter at the middle of the road. my vehicle had stopped on the first lane facing the on coming traffic. No one was injured at the point of accident. There was a Police Car which was travelling behind had stopped and assisted until the Traffic police Came.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18011622/Uda3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555		Date : 12-03-2020	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SGP 5630G	Veh. Inspected
			YL 6348Z
	Policy No.	Z17VP05016294	Coverage (\$)
			0.00
	Claim No.	17/18/18/VP05/020649	Excess (\$)
			0.00
	Assign From	GERALD	Assign Date
			25/06/2018
2. Vehicle Particulars & Condition			
	Make & Model	MITSUBISHI CANTER (M)	
		c.c	3908
	Engine No.	HIDDEN	
		Year of Reg.	2004
	Chassis No.	FE639EA45404	
		Colour	WHITE
	Odometer	635990	
		Steering	IN ORDER
	Brakes	IN ORDER	
		Modification	NIL
	General	GOOD	
3. Conditions of Tyres			
		Size	Make
			Balance
	R/H Front Tyre	7.00 R16	TRIANGLE
			6 mm
	L/H Front Tyre	7.00 R16	TRIANGLE
			6 mm
	R/H Rear Tyre	7.00 R16 (D)	TRIANGLE
			6/6 mm
	L/H Rear Tyre	7.00 R16 (D)	TRIANGLE
			6/6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.		
	DAMAGES SEE DETAILS.		
5. General Information			
	Accident Date	02/06/2018	Inspection Date
			26/06/2018
	Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP	
		1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT	
		SINGAPORE	
		417883	
5a. Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.		
	B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YL 6348Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DISTORTED / CRACKED	1,929.80	1,645.32
1	FRONT BUMPER BRACKET	TO REPAIR SEE LABOUR	375.00	-
1	FRONT HEADLAMP	CRACKED	1,041.20	1,041.20
1	FRONT SIGNAL LAMP	CRACKED	324.30	324.30
1	FRONT SIDE LAMP	NOT NECESSARY	259.20	-
1	FRONT STEP PANEL N/S	CRACKED	334.00	334.00
1	FRONT STEP PANEL GARNISH N/S	DISTORTED	182.40	182.40
	LESS 25% DISCOUNT		-	-881.81
			4,445.90	2,645.41
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	48.00	48.00
			48.00	48.00
LABOUR				
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION .		50.00	20.00
	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKET .		420.00	300.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED.	NOT NECESSARY	380.00	-
			850.00	320.00
GRAND TOTAL			5,343.90	3,013.41
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CC4/LPC18011622/Uda3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.