

22/03/2002

ASS. REC. BY:

REF: CS/CTL18011634/Kgber

Special Instruction:

Surveyor: Kenneth  
Mofima

ASSIGNMENT (Office)

From (Person): Jowyn Tay of CTL Date/Time: 26062018 4:28pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PA 7302M Insured: PC 6823Y

at Workshop m/s Comfort Delgro Tel: 6383 8115

of 205 Braddell Rd

Policy No: DMB16N1768511700 Claim No: SNM18D0310402

Sum Insured: Excess:

Make of Veh: D.O.A. 21062018  
(Client's Record)

CA / REV / REP. / REV 24 HRS wpi 27062018 H.O.D. Endorsement:

Date/Time: 26062018 4:50pm Person Contacted: William Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	PA 7302M - NS / INC 11007505 / H/Plt PC 6823Y - x DA: 21042011
25/01/19 @ 9:27am	checked with Mr Ngo, they already convert to OD claim
25/01/19	submit Preli. report.

08/11/13 wef

ASS. REC. BY:

REF: CTI

ASSIGNMENT

From: Date: 27/06/2018

Estimated Cost:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PA 7302M

at Workshop m/s Comfort Delgro

of 205 Briddell Road

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up) 12'22

Date: Person Contacted: Npo

97442989 Vehicle: IN / OUT

Veh No: PA 7302M Yr Regn: 12, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: King Long c.c. 6700

Colour: Multi Colour A/C: Insured / Std / NI / NA

Sp. Reading: 850389 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: LKURIG-S E17B 103129

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Pir 1100 R22.5

Aedus

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 66 mm

L/Bal. 7 mm

L/Bal. 66 mm

D.O.A. 21/8/18

D.O.I. 27/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/6 File pass to Cothane

RECEIVED 25 JAN 2019

Date/Time, File Pass to?

[X] Preli. Report

11/25/11

[ ] Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ )

Days Of Repair:

Resurvey No. of Trip:

Add Fee: [ ] Site Insp (\$ ) [ ] Interview (\$ ) [ ] Tech. Invs (\$ ) [ ] Weekend (\$ )

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

220
220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jun 2018		26 Jun 2018 16:28 Assign				<b>New Assignment</b> Cancel Case

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	CHANG CHEN PTE LTD, Co. Reg. No.: 201530624M		
Main Claimant:	COMFORTDELGRO BUS PTE LTD, Co. Reg. No.: 199607256W		
Vehicle Reg. No.:	PA7302M	Date of Loss:	21/06/2018 07:00 - :59
Claim Type:	TP / SNM18D03104C02	Policy/Cover Note No.:	DMB1SN1768511700 (Comprehensive)
Vehicle Reg. No. (Insured):	PC6823Y	Policy No. (Claimant):	5085550657-02
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road, 579701 Toa Payoh - Tel: 63837168 /63837118		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/07/2018]		
Driver/Custodian (Insured):	LIM KIAN SENG (38 / Male), NRIC: S8009809Z, Tel: +6597938065		
Adj Asg. Remarks:	EST \$4256, CASE WITH SJE.		

**ASSOCIATED MAIL RECEIVED**

There are no mail for this case.

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TP Vehicle No. : PA7302M  
 Make & Model : KING LONG XMQ6119K  
 Year of Manufacture : 2007  
 Chassis No. : LKLR1GSE17B103129  
 Ins Company : NTUC VS CHINA Engine No. : \_\_\_\_\_  
 Excess : \_\_\_\_\_ Policy No. : \_\_\_\_\_  
 Date of Accident : 6/21/2018 Time of Accident : 0730

Suggested Days of Repair : \_\_\_\_\_ In-house Vehicle Assessor  
 Case Owner : \_\_\_\_\_  
 Signature : \_\_\_\_\_

**Repair Estimates**

<b>Parts (a) Cost / List Price Items</b>	<b>\$</b>	<b>-</b>
Plus/Less 10%	<b>\$</b>	<b>-</b>
<b>Total of Cost / List</b>	<b>\$</b>	<b>-</b>
<b>(b) Nett Price Items</b>	<b>\$</b>	<b>-</b>
Less		
<b>Total of Nett Item</b>		
<b>(c) Special Nett Items</b>	<b>\$</b>	<b>806.00</b>
<b>Total Parts Cost (Appendix A)</b>	<b>\$</b>	<b>806.00</b>
<b>Labour (Appendix B)</b>	<b>\$</b>	<b>3,450.00</b>
<b>Total Repair Cost</b>	<b>\$</b>	<b>4,256.00</b>

Contact No  
**Fr Counter Operation**  
 63837466 – Patrick  
 63837730 - Brenda  
 63837890 – Rohani  
[braddell\\_cr@sparkcarecar.com](mailto:braddell_cr@sparkcarecar.com)

**Back-end Operation**  
 63837656 - Ngo  
 63837362 - Andrew  
 63838115 - William  
[braddell\\_operation@sparkcarcar.com](mailto:braddell_operation@sparkcarcar.com)

*NOT Authorized  
Resurvey After Repair*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
 Company : CKK  
 Survey conducted on : 27/6/18 at \_\_\_\_\_

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.  
 (b) Recommended Days of Repair : 07 day(s)  
 (c) Resurvey : Required / ~~Not Required~~  
 (d) Excess : \$ \_\_\_\_\_  
 (e) Signature of surveyor : Le Date: 27/6/18

**Spark Car Care**  
**ComfortDelGro Engineering Pte Ltd**  
 205 Braddell Road S (579701)  
 Tel: 63837168 / 63837466 Fax:62815767

**Spare Parts**

Vehicle No : PA7302M Case Owner : 0

Make & Model : KING LONG XMQ6119K Year Manufacture : 2007

Chassis No : LKLR1GSE17B103129 Engine No : 0

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	FRT WINDSCREEN GLASS <i>CM</i>	1					✓
2	SEALANT	8			<i>NE</i>	\$ 320.00	✓
3	INNER SEAL	1			<i>NE</i>	\$ 160.00	✓
4	LH WIND MIRROR ASSY	1			<i>CM</i>		✓
5	LH HEADLAMP	1					?
6	LH HEADLAMP OUTER GARNISH	1			<i>RM</i>		✓
7	ERP BRACKET	1			<i>NE</i>	\$ 26.00	✓
8	STICKER 'AZ'	1			<i>NE</i>	\$ 300.00	<i>20052</i>
9	0	1					
10	0	1					
11	0	1					
12	0						
13	0						
14	0						
15	0						
16	0						
17	0						
18	0						
19	0						
20	0						
21	0						
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29		0					
30		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/06/2018 10:46
Date Of Accident	21/06/2018 07:30
Exact Location Of Accident	WOODLANDS SQUARE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PA7302M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORTDELGRO BUS PTE LTD
Co Reg No	199607256W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91435662

### Vehicle Particulars

Manufacturer	KING LONG
Model	XMQ6119K

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5085550657-02
Cover Note Number	

### Driver

Name of Driver	ASMAWI BIN ASMAULLAH
NRIC No	S1699656D
Date Of Birth	06/06/1965
Occupation	OUTDOOR
Date Of Driving Pass	23/12/1988
Driving Experience	29 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91435662
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 603 WOODLANDS DRIVE 42#01-23  
 Postcode 730603  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 15

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes,Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes,against whom?

**Circumstances of Accident**

REFER TO STATEMENT

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number PC6823Y  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category BUS  
 Name of Driver LIM KIAN MENG  
 NRIC/Passport Number S8009809Z  
 Contact Number 97938065  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



A - PA7302M  
B - PC6823Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving towards to Woodlands Square to turn left, Before turning I stopped my vehicle at yellow box. A Bus PC6823Y suddenly <sup>turn right and</sup> hit my left side and damage my windscreen and side mirror.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S1699656D  
 Name: ASMAWI BIN ASMAULLAH  
 Birth Date: 06 Jun 1965  
 Issue Date: 29 Nov 2014

002371438D



REPUBLIC OF SINGAPORE  
 IDENTITY CARD NO. S1699656D

Name: ASMAWI BIN ASMAULLAH

Race: MALAY  
 Date of Birth: 06-06-1965 Sex: M  
 Country of Birth: SINGAPORE



Land Transport Authority

VOCATIONAL LICENCE

Licence No: S1699656D  
 Name: ASMAWI BIN ASMAULLAH  
 Issue Date: 27/6/2011

Please visit [www.lta.gov.sg](http://www.lta.gov.sg) to check the status of this vocational licence



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	EFFECTIVE DATE
Class 2B	Motorcycles <= 200 cc	12 Aug 1988
Class 2A	Motorcycles between 201 cc and 400 cc	12 Aug 1988
Class 3	Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg	29 Nov 1984
Class 4	*Motor vehicles which are constructed to carry load or passengers and the unladen weight > 2500kg *Motor vehicles which are not constructed to carry load and the unladen weight < 7250kg	23 Dec 1988
Class 5	Motor vehicles not constructed to carry any load and the unladen weight > 7250kg	30 Apr 1990

Licence No: S1699656D

NP 428A

2514875

NRIC No: S1699656D

Blood Group: A+ Date of Issue: 29-10-1994

Address: 1PT BLK 803 WOODLANDS DRIVE 42 #01-23 SINGAPORE 730803

NRIC No: S1699656D Date: 02-01-2003 No: 4067311



This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
02	TAXI VL	21/07/2004
03	BUS VL	16/11/1990

Barcode



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5085550657-02 Cover : Comprehensive

- |   |                             |
|---|-----------------------------|
| 1. Index mark and Registration Number of Vehicle  | : PA7302M                   |
| Chassis Number  | : LKLR1GSE17B103129         |
| 2. Name of Policyholder   | : COMFORTDELGRO BUS PTE LTD |
| 3. Effective Date of Insurance  | : 01 Jun 2018               |
| 4. Expiry Date of Insurance   | : 31 May 2019               |
| 5. Persons or Classes of Persons entitled to drive*   |                             |
| (a) The Policyholder.   |                             |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission.   |                             |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. |                             |
| 6. Limitations as to Use*   |                             |
| (a) Use for the carriage of passengers in connection with the Policyholder's business.  |                             |
| (b) Limited to carry 45 passengers  |                             |

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

GEOGRAPHICAL LIMIT	: WITHIN THE REPUBLIC OF SINGAPORE ONLY
EXCESS (SECTION I)	: S\$1,500
EXCESS (SECTION II)	: S\$1,500
WINDSCREEN EXCESS	: S\$500
INSURE WITH COE	: YES
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : COMFORTDELGRO INSURANCE BROKERS P/L (00000690698)  
 Date of Issue : 01 Jun 2018 14:56 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

[Back to OneMotoring](#)

## Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	PA7302M		
Vehicle Type :	Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus		
Vehicle Attachment 1 :	Air-Conditioned		
Vehicle Scheme :	Public Service Vehicle (Others)		
Vehicle Make :	KING LONG		
Vehicle Model :	XMQ6119K		
Chassis No. :	LKLR1GSE17B103129		
Propellant :	Diesel		
Engine No. :	21785251		
Engine Capacity :	6700 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	15500 kg		
Unladen Weight :	11020 kg		
Year Of Manufacture :	2007		
Original Registration Date :	31 Dec 2007		
Lifespan Expiry Date :	30 Dec 2027		
COE Category :	C - Goods Vehicle & Bus		
PQP Paid :	\$25,536.00		
COE Expiry Date :	30 Dec 2022		
Road Tax Expiry Date :	30 Jun 2018		
Inspection Due Date :	30 Jun 2018		
Intended Transfer Date :	26 Jun 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 30 Jun 2018. You may renew the road tax from 01 Apr 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 30 Jun 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
<b>Amount Payable (From 01 Jul 2018 to 31 Dec 2018)</b>			
	<b>Amount Before GST</b>	<b>GST Amount</b>	<b>Amount After GST</b>
	<b>(S\$)</b>	<b>(S\$)</b>	<b>(S\$)</b>
Transfer Fee :	25.00	-	25.00
<b>Sub Total :</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment) :	0.00	-	0.00
<b>Total Amount Payable :</b>			<b>25.00</b>
<b>Message</b>			
This vehicle has a road tax Over Payment of \$467.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.			

You may print this page for reference.

OK

Print

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Jun 2018		26 Jun 2018 16:28 <a href="#">Edit Adj Rpt</a>	<b>S\$3,166.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,166.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>CHANG CHEN PTE LTD</b> , Co. Reg. No.: 201530624M								
Main Claimant:	<b>COMFORTDELGRO BUS PTE LTD</b> , Co. Reg. No.: 199607256W								
Vehicle Reg. No.:	<b>PA7302M</b>	Date of Loss:	21/06/2018 07:00 - :59 [125 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D03104C02</b>	Policy/Cover Note No.:	DMB1SN1768511700 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>PC6823Y</b>	Policy No. (Claimant):	5085550657-02						
		Excess:	S\$0.00						
Repairer:	<b>ComfortDelGro Engineering Pte Ltd (Braddell)</b> 205 Braddell Road, 579701 Toa Payoh - Tel: 63837168 /63837118								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Jowyn Tay</b> - 6389 6174]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 05/07/2018]								
Driver/Custodian (Insured):	LIM KIAN SENG (38 / Male), NRIC: S8009809Z, Tel: +6597938065								
Adj Asg. Remarks:	EST \$4256, CASE WITH SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

### Claim Documents

**\*PA7302M (SNM18D03104C02)**  
**[PC6823Y]**  
**TP**  
**COMFORTDELGRO BUS PTE LTD**  
**Jun 21 2018 7:00AM**  
**[CHANG CHEN PTE LTD]**  
**ComfortDelGro Engineering Pte Ltd**

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print		
1	21/06/18 15:59	<b>Accident Statement</b>		 Load HTM	<input checked="" type="checkbox"/>		
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print		
1	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
2	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
3	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
4	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
5	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
6	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
7	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
8	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
9	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
10	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
11	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
12	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
13	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
14	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
15	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
16	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
17	21/06/18 15:32	<b>Accident Photo</b> [Linked Accident Report Documents]		 Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	25/01/19 09:35	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
2	25/01/19 09:35	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
3	25/01/19 09:35	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
4	25/01/19 09:35	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
5	25/01/19 09:35	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
6	25/01/19 09:35	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
7	25/01/19 09:35	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
8	25/01/19 09:35	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
9	25/01/19 09:35	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
10	25/01/19 09:35	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
11	25/01/19 09:35	<b>Odometer Reading</b>	Load JPG	<input checked="" type="checkbox"/>
12	25/01/19 09:35	<b>Chassis Number</b>	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	21/06/18 15:58	<b>Sketch Plan</b> <small>[Linked Accident Report Documents]</small>	Load TIF	

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/06/18 16:27	<b>REPAIR EST WITH TP GIA</b>	Load PDF	
2	26/06/18 16:27	<b>OI GIA</b>	Load PDF	
3	02/01/19 18:17	<b>INSURED'S TP CLAIM SUCCESSFUL</b>	Load PDF	

### Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	21/06/18 15:59	<b>Accident Statement</b>	Load HTM	
2	20/07/18 17:44	<b>Addendum Sheet</b>	Load TIF	
3	20/07/18 17:46	<b>Accident Statement Addm. #1</b>	Load HTM	
4	23/07/18 10:35	<b>Addendum Sheet</b>	Load TIF	
5	23/07/18 10:37	<b>Accident Statement Addm. #2</b>	Load HTM	
6	31/07/18 09:31	<b>Addendum Sheet</b>	Load TIF	
7	31/07/18 09:31	<b>Accident Statement Addm. #3</b>	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
2	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
3	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
4	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
5	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
6	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
7	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
8	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
9	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
10	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
11	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
12	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
13	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
14	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
15	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
16	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
17	21/06/18 15:32	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	21/06/18 15:58	<b>Sketch Plan</b>	Load TIF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**



**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI18011634/KQBE2  
**Date:** 25/01/2019

#### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN1768511700
Claimant Vehicle No :	PA7302M	Insured Vehicle No :	PC6823Y
Date of Loss:	21/06/2018	Nature of Claim:	TP
		Claim No:	SNM18D03104C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA7302M	Engine No:	21785251
Make & Model:	KING LONG XMQ6119K, 6.7 (A)	Chassis No:	LKLR1GSE17B103129
Reg. Date:	31/12/2007 (Man. Year: 2007)	Odometer:	850389 km
Colour:	Multi-colour		
Engine Capacity:	6700 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	1100 R22.5	Rear Tyre Size:	1100 R22.5 (D)
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Achilles 6/6 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Achilles 6/6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	806.00	706.00	100.00	12.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,450.00	2,460.00	990.00	28.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,256.00</b>	<b>3,166.00</b>	<b>1,090.00</b>	<b>25.61</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>297.92</b>	<b>221.62</b>	<b>76.30</b>	<b>25.61</b>
<b>Nett Amount (S\$)</b>	<b>4,553.92</b>	<b>3,387.62</b>	<b>1,166.30</b>	<b>25.61</b>

#### INSPECTION

Date of Assignment:	26/06/2018	
Date Inspected:	27/06/2018 Inspected At:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	7.0 days	

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)  
(EXCLUDE CHECK ITEMS S\$ NETT)

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 25 Jan 2019)	
<b>Parts:</b>	N/A	KING LONG XMQ6119K 6.7 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PA7302M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT WINDSCREEN GLASS (NPA)	Cracked	0.00 FS	*- FS
2	1		*SEALANT	Necessary	320.00 FS	*320.00 FS
3	1		*INNER SEAL	Necessary	160.00 FS	*160.00 FS
4	1		*LH WIND MIRROR ASSY (NPA)	Cracked	0.00 FS	*- FS
5	1		*LH HEADLAMP (NPA)	* Check	0.00 FS	*- FS
6	1		*LH HEADLAMP OUTER GARNISH (NPA)	Bent	0.00 FS	*- FS
7	1		*ERP BRACKET	Necessary	26.00 FS	*26.00 FS
8	1		*STICKER AZ	Necessary	300.00 FS	*200.00 FS
<b>Total Parts (S\$)</b>					<b>806.00</b>	<b>706.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND RENEW FRT WINDSCREEN GLASS	New	800.00	680.00
2	TO KNOCK, STRAIGHTEN AND RENEW ACCIDENT SUCH AS LH WIND MIRROR ASSY, LH HEADLAMP, LH HEADLAMP OUTER GARNISH, FRT BODY PANEL, FRT WINDSCREEN PILLAR LH AND ETC	New	1,500.00	960.00
3	TO PUTTY AND RESPRAY ACCIDENT AREA SUCH AS, LH WING MIRROR ASSY, FRT BODY PANEL, LH HEADLAMP OUT GARNISH, FRT BUMPER, LH WINDSCREEN PILLAR AND ETC	New	1,100.00	800.00
4	TO CHECK WIRING AND LIGHTING	New	50.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>3,450.00</b>	<b>2,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >