

ASS. REC. BY:

REF: CS/FCI 18011645/Tivd327 Special Instruction:

Surveyor  
WLS

## ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

26/6/18 @ 2:39pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 8298A

Insured:

SHD 4598A

at Workshop m/s

Tanaka Automotive

Tel:

9838 5899

of

3rd Park Crescent / Tucson Park

Policy No:

Claim No:

DISCO 4309MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/05/2018

CA / REV / REP. / REV 24 HRS

Lup

27/6/18

H.O.D. Endorsement:

Date/Time:

3:17pm @ 27/6/18

Person Contacted:

Cheryl

Vehicle: IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

XD 8298A - X

SHD 4598A - NS/INC 17007492/H/vbn2

DOA: 11/04/2017

28/6/18

Email preli revised to FCI

5/7/18

LS \$ 3200 Confirmed by email (Real 2052.25, 39%)

Signature: *[Signature]*

REF:


FCI

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR. Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **XD 8298A** Yr Regn: **2013 Nov**  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: **UD Trucks** C.C. **10837**  
 Colour: **white** A/C: Insured / Std / NI / NA  
 Sp. Reading: **15/170** T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **GK B5E 00102**  
 Gen. Cond: **Good** / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: **295/80R 22.5**  
 R: **295/80R 22.5**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Firemax**

Front **7** mm Rear **7** mm  
 R/Bal. **7** mm L/Bal. **7** mm

D.O.A. \_\_\_\_\_ D.O.I. **27/6/18**

Survey held at **Tanaka Automotive**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

**Frt N/S**

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 05 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Fjnal Report

Date/Time, File Return to?

2) **slr - typist**

Report Format : **cws**

Lump Sum / I.B.I. (\$) **3200/-**

Days Of Repair: **4**

Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

**180**

**50**

**50**

**34**

**274**

**MOTOR SURVEY ASSIGNMENT**

Date	30-05-2018	Our Ref No. D18004309MFSH
Accident Date	27-05-2018	Claim Type. Third Party
Insured Vehicle	SHD4598A	Third Party Vehicle. XD8298A
Survey Location	3 TECH PARK CRESCENT TUAS TECH PARK	
Contact Person.	CHERYL YUAN	
Contact No.	98385899/ 98385899	Fax No. 68636477
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	TANALA AUTOMOTIVE CONSULTANCY	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Thursday, 28 June 2018 2:21 PM  
**To:** 'Claim Workflow System'  
**Cc:** EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18004309MFSH/1, XD 8298A  
**Attachments:** XD 8298A PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle XD 8298A  
Date of survey: 27/6/2018  
Number of days :4 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 26 June 2018 3:19 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18004309MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 26 June 2018 2:39 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [EILEENLEE@MSFIRSTCAPITAL.COM.SG](mailto:EILEENLEE@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18004309MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18004309MFSH

Our ref: CS/FCI18011645/T1vd3

Date: 28/6/2018

The Motor Claims Department  
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. XD 8298A**


We thank you for your instruction on 26/6/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/6/2018 at the premises of M/s TANALA AUTOMOTIVE CONSULTANCY and have the following to report:-

Workshop Estimate Amount	: S\$4,552.25
Revised Estimate Amount	: S\$2,990.81
"Check" Items Amount	: S\$450.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the front n/s portion.



**Comments/Present Status:**

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH  
M.MATAI, AMSAE-A  
Automobile Assessor

### Vehicle Details

Vehicle No.:	XD8298A
Vehicle Type:	B36 - Goods (Open) Prime Mover
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	UD TRUCKS
Vehicle Model:	GKB5ELDHNT ESCOT V
Chassis No.:	GKB5E00162
Propellant:	Diesel
Engine No.:	GH11715808
Engine Capacity:	10837 cc
Maximum Power Output:	-
Maximum Laden Weight:	55000 kg
Unladen Weight:	6760 kg
Year Of Manufacture:	2013
Original Registration Date:	21 Nov 2013
Lifespan Expiry Date:	20 Nov 2033

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/05/2018 09:58
Date Of Accident	27/05/2018 15:40
Exact Location Of Accident	GEYLANG RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD8298A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	C & P LEASING PTE LTD
Co Reg No	199000050G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68853213

### Vehicle Particulars

Manufacturer	UD TRUCKS
Model	QUON GK-10.8 D GKB5ELDHNT (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V01475/VC/R05
Cover Note Number	

### Driver

Name of Driver	MUHAMMAD RAZIS BIN MOHD SAN
NRIC No	S8741248B
Date Of Birth	17/12/1987
Occupation	OUTDOOR
Date Of Driving Pass	06/11/2017
Driving Experience	0 YEAR AND 6 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-93913145
Fax Number	
Contact Number	
Email Address	NOEMAIL

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Tanala Automotive Consultancy

My Mail Box 883230

Singapore 919191

ROB: 53240124K

### C&P Leasing Pte Ltd

41 Pandan Road  
Singapore 609283

Attn: Motor Claims Department

Estimate No : ES2018/0099

Date : 27/06/2018

Vehicle No : XD8298A

Make/Model : UD GKB5E

Date of Accident : 27/05/2018

S/N	Description	Qty	Unit Amount	Amount
<u>List Items</u>				
1	Front bumper, LH 2352	1	166.20	bt ✓ 166.20 1166.20
2	Bumper corner, LH	1	185.20	de ✓ 185.20
3	Headlamp, LH 2218.40	1	1,656.20	ant ✓ 1,656.20
4	Signal lamp, LH	1	165.20	one ✓ 165.20
5	Side lamp, LH	1	268.50	nn X 268.50
6	Corner panel, lower garnish LH	1	195.50	nn X 195.50
7	Step, LH	1	452.10	dd ✓ 452.10
8	Reflector, LH	1	65.20	wt ✓ 65.20
9	Step garnish, LH 287.10	1	368.20	ana ✓ 368.20
10	Fender lower, LH	1	695.20	Ry ✓ 695.20
				4,217.50
			Less: 30%	(1,265.25)
				<u>2,952.25</u>

1 Tyre rim cover (Nett)

1

450.00

450.00 mis ✓

### Labour

To panel beat/repair LH body

To dismantle/replace above-mentioned parts

To spray painting on repaired areas

450.00

400 500.00  
1,150.00

Days of Repair: 5 days @ S\$200/day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL

4,552.25

Cheryl

Tanala Automotive Consultancy

Tanala 97497744  
WP  
27/6/18 @ 1430  
Lump sum  
Resurvey after repair - 28/6/18  
Hobbs  
sur@lkkauto.com

## Tanala Automotive Consultancy

My Mail Box 883230  
Singapore 919191  
ROB: 53240124K

### C&P Leasing Pte Ltd

41 Pandan Road  
Singapore 609283

Attn: Motor Claims Department

Estimate No : ES2018/0099  
Date : 27/06/2018  
Vehicle No : XD8298A  
Make/Model : UD GKB5E  
Date of Accident : 27/05/2018

S/N	Description	Qty	Unit Amount	Amount
<u>List Items</u>				
1	Front bumper, LH	1	1,166.20	1,166.20
2	Bumper corner, LH	1	185.20	185.20
3	Headlamp, LH	1	1,656.20	1,656.20
4	Signal lamp, LH	1	165.20	165.20
5	Side lamp, LH	1	268.50	268.50
6	Corner panel, lower garnish LH	1	195.50	195.50
7	Step, LH	1	452.10	452.10
8	Reflector, LH	1	65.20	65.20
9	Step garnish, LH	1	368.20	368.20
10	Fender lower, LH	1	695.20	695.20
				5,217.50
Less: 30%				(1,565.25)
				<b>3,652.25</b>
1	Tyre rim cover (Nett)	1	450.00	<b>450.00</b>
<u>Labour</u>				
To panel beat/repair LH body				650.00
To dismantle/replace above-mentioned parts				
To spray painting on repaired areas				500.00
				<b>1,150.00</b>

Days of Repair: 5 days @ S\$200/day

---

TOTAL	<b>5,252.25</b>
-------	-----------------

---

*Cheryl*

---

Tanala Automotive Consultancy

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Thursday, 5 July 2018 2:55 PM  
**To:** 'Tanala'  
**Cc:** SUR  
**Subject:** RE: Accident involving XD8298A and SHD4598A (MS FCIL) on 27 May 2018

Dear Fanny,

Noted with thanks.

**Final invoice and all supporting documents sent over to First Capital Ins Ltd.**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Tanala [mailto:tanala.motoring@gmail.com]  
**Sent:** Thursday, 5 July 2018 2:27 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** Re: Accident involving XD8298A and SHD4598A (MS FCIL) on 27 May 2018

Dear Veron,

We confirmed L/S @ \$3,200/- and 4 working days.

Regards,  
Fanny

On Thu, Jul 5, 2018 at 11:45 AM, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Fanny,

WITHOUT PREJUDICE

Offer Lump Sum \$3200/ @ 4 working days.

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Tanala [<mailto:tanala.motoring@gmail.com>]

**Sent:** Tuesday, 3 July 2018 3:35 PM

**To:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** Re: Accident involving XD8298A and SHD4598A (MS FCIL) on 27 May 2018

Dear Taufikh,

Kindly discard the previous quotation due to typo error for the amount of front bumper.

Attached revised quotation of XD8298A for your attention, please.

Regards,

Fanny

On Mon, Jul 2, 2018 at 2:36 PM, Tanala <[tanala.motoring@gmail.com](mailto:tanala.motoring@gmail.com)> wrote:

Dear Taufikh,

Please find attached after repair photos for your attention.

Regards,


Fanny

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18011645/T1vd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-07-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 4598A	Veh. Inspected	XD 8298A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004309MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	26/06/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	UD TRUCKS	c.c	10837	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	GKB5E00162	Colour	WHITE	
Odometer	151170	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	FIREMAX	7 mm	
L/H Front Tyre	295/80 R22.5	FIREMAX	7 mm	
R/H Rear Tyre	295/80 R22.5	FIREMAX	7 mm	
L/H Rear Tyre	295/80 R22.5	FIREMAX	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	27/05/2018	Inspection Date	27/06/2018	
Survey held at	3 TECH PARK CRESCENT TUAS TECH PARK			
Repairer	TANALA AUTOMOTIVE CONSULTANCY			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 8298A**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER, LH	BENT	1,166.20	1,166.20
1	BUMPER CORNER, LH	DEFORMED	185.20	185.20
1	HEADLAMP, LH	CUT	1,656.20	1,656.20
1	SIGNAL LAMP, LH	CRACKED	165.20	165.20
1	SIDE LAMP, LH	NOT NECESSARY	268.50	-
1	CORNER PANEL, LOWER GARNISH LH	NOT NECESSARY	195.50	-
1	STEP, LH	DENTED	452.10	452.10
1	REFLECTOR, LH	CUT	65.20	65.20
1	STEP GARNISH, LH	CRACKED	368.20	287.10
1	FENDER LOWER, LH	TO REPAIR SEE LABOUR	695.20	-
	LESS 30% DISCOUNT		-1,565.25	-1,193.16
			3,652.25	2,784.04
<b><u>SPECIAL NETT ITEMS</u></b>				
1	TYRE RIM COVER (SN)	MISSING	450.00	450.00
			450.00	450.00
<b><u>LABOUR</u></b>				
	TO PANEL BEAT / REPAIR LH BODY. TO DISMANTLE / REPLACE ABOVE - MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF FENDER LOWER, LH.		650.00	450.00
	TO SPRAY PAINTING ON REPAIRED AREAS.		500.00	400.00
			1,150.00	850.00
<b>GRAND TOTAL</b>			<b>5,252.25</b>	<b>4,084.04</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,200.00</b>

Report Ref No. CS/FCI18011645/T1vd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.