

ASS. REQ. BY: NAZ REF: CS3/MSG18008809/Lsb-1 ^{ev}

Surveyor: Mehmen ASSIGNMENT (Office)

Person (Person): Irene Tan of MSIG Date/Time: 26062018

Estimated Cost: BH10

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MY / CS

To inspect Vehicle No: SJ4 2535G Insured: SKP 2662L

at Workshop on: Alpha Car Services Tel: 6509 8258

of Kaki Bukit Ave 6 Blkc # 01-59

Policy No: 80438269 QMY Claim No: 558290/IT

Sum Insured: _____ Excess: _____

Make of Veh: _____

(Client's Record) DOA 12/05/2018

CA / REV / REC / REV 24 HRS 16/5/18 @ 64 1pm

Date/Time: 3:35pm @ 15/5/18 Person Contacted: cai ling Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate	Do Not Finalize
	<u>SJ4 2535G - X</u>	
	<u>SKP 2662L - X</u>	

17/5/18 Dismantled
 (\$3,824.10 Red - 61%)
 5 days 2400h
 2800h
 10/7/18

RECEIVED 11 JUL 2018

25% let me know

nett value:

less than
 one year to scrap

ASSIGNMENT

From:

Date: 16/5/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJU 2535G

at Workshop m/s

Alpha Car Services

of

Kaki Bukit Ave 6 Blk C # 01-59

insured

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Before 1pm

Make of Veh:

cai ling @ 6509 8258

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS (w/p)

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No

SJU 2535G

Yr Regn:

NOV 2009

Type:

M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

VOLVO C30

Colour:

GREY

A/C

Insured / Std / NI / NA

Sp. Reading

101,039

T/Radio

Insured / Std / NI / NA

Eng/No:

C/No:

YVIMK43BA2175704

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45 R17

R:

11

BS / PUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

12/05/18

D.O.I.

16/05/18

Survey held at

Alpha Car Services

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision

* Repair Estimate : S\$ 3500 - 4500

* 3 days

RECEIVED 16 MAY 2018

Date/Time: File Pass to:

☐

Prell. Report

1)

☐

Final Report

Date/Time: File Return to:

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

1 - 5 - 10 - 15

Phone

Other

TOTAL

120

50

10

10

10

10

190

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

ANNEX A

REPAIR DETAILS

Recommended Parts


No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Rear bumper assy	warped/dented	\$ 1,298.00	\$ 1,298.00
2	1	Rear bumper retainer	bent/necessary	\$ 166.00	\$ 166.00
3	1	Rear bumper reflector	bent/warped	\$ 186.00	\$ 186.00
4	1	Rear bumper 'C30' emblem	necessary	\$ 108.00	\$ 108.00
5	1	Rear bumper '2.0' emblem	necessary	\$ 103.00	\$ 103.00
6	1	Rear bumper reinforcement	bent/dented	\$ 374.00	\$ 374.00
7	1	Rear tailgate 'volvo' emblem	necessary	\$ 156.00	\$ 156.00
8	1	Rear left taillamp	cut/bent	\$ 866.00	\$ 866.00
9	1	Rear right side protector	warped	\$ 195.00	\$ 195.00
10	1	Rear air duct ventilator	cracked	\$ 197.00	\$ 197.00
				\$ 3,649.00	\$ 3,649.00
Less 10%				\$ 364.90	\$ 364.90
				\$ 3,284.10	\$ 3,284.10

Special Nett Items

1	10	Rear bumper clips	necessary	\$ 50.00	\$ 50.00
2	6	Rear left side protector clips	necessary	\$ 10.00	\$ 10.00
3	2	Rear bumper reverse sensor	malfunction	\$ 250.00	\$ 250.00
4	1	Rear no plate with garnish	necessary	\$ 80.00	\$ 80.00
				\$ 390.00	\$ 390.00

Total Parts

\$ 3,674.10 \$ 3,674.10



ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount	
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 900.00	\$ 800.00	500
2	To putty and spray painting rear portion.	\$ 900.00	\$ 800.00	500
3	To check rear lighting and wiring.	\$ 50.00	\$ 30.00	20
4	To remove and install rear tailgate lock mechanism.	\$ 80.00	\$ 60.00	40
5	To remove and install rear inner trim and inner garnish to facilitate the repair.	\$ 140.00	\$ 120.00	80
6	To apply anti rust proofing to rear affected area.	\$ 120.00	\$ 100.00	60
7	To remove and install rear bumper reverse sensor.	\$ 80.00	\$ 60.00	40
8	To repair, straighten and align rear left fender assy.	\$ 180.00	\$ 150.00	100
9	Towing service.	\$ 100.00	\$ 80.00	60
Total labour :		\$ 2,550.00	\$ 2,200.00	

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 3,674.10	\$ 3,674.10
Total labour :	\$ 2,550.00	\$ 2,200.00
Total repair cost :	\$ 6,224.10	\$ 5,874.10

Adjusted Repair Cost (Lump Sum Repair)

\$ 4,700.00



5 days

Catherine Chong (LKK Auto)

From: Irene Tan <irene_tan@sg.msig-asia.com>
Sent: Monday, 25 June, 2018 6:38 PM
To: Veron Chen (LKKAuto); Shiau Chan (LKKAuto); Catherine Chong (LKK Auto); assignments
Subject: Please prepare and upload paper survey report on SJU2535G; Our claim no.: 558290/IT

Importance: High

Good evening Veron,

We refer to your PRI report dated 23.5.18.

Please prepare and upload paper survey report asap.

Best Regards

Irene Tan
Senior Executive, Claims Services (Motor)
Direct line +65 6594 2541 | Direct fax +65 6225 7402 | irene_tan@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 May 2018		15 May 2018 15:14 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		TOH EE-WEN LISSA, ID: S7635847H							
Main Claimant:		CHAN WENG SUNG JOHN, ID: S8011757D							
Vehicle Reg. No.:		SJU2535G	Date of Loss:	12/05/2018 18:00 - :59 [101 Months and 17 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / 558290	Policy/Cover Note No.:	80438269QMY (Comprehensive) Coverage: 27/07/2017 - 26/07/2018					
Vehicle Reg. No. (Insured):		SKP2662L	Policy No. (Claimant):						
		Excess:	S\$600.00						
Repairer:		Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 27/06/2018]							
Adj Asg. Remarks:		SURVEY DISAGREE ON SJE - ASSIGN LKK AUTO CONSULTANTS PTE LTD OI NOT REPORTED CONTACT: CAI LING (6509 8258)/ AH YAP (9807 3304)/ AH HWA (9136 8884)							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (25/06/2018): Report Send Back Alerts - SJU2535G (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

CROSSBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.6006.2018.AC-PD

Your Ref: SKP2662L
558290

TO: TOH EE-WEN LISSA
361 Bukit Timah Road
#04-01 The Legend
Singapore 259725

cc: MSIG Insurance (Singapore) Pte Ltd
(Motor Claims Dept)
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581

Dear Sirs

CHAN WENG SUNG, JOHN
68B Thomson Road
Singapore 307587

We are instructed by the abovenamed to claim damages against you in connection with an accident on 12 May 2018 at about 18:00 hours along Essex Road involving our client's vehicle no. SJU2535G and vehicle registration number SKP2662L driven by you at the material time.

We are instructed that the accident was caused by the negligence of you in the driving, management and control of vehicle registration number SKP2662L.

As a result of the accident, our client's vehicle registration number SJU2535G was damaged and our client has been put to loss and expense, particulars of which are as follows:-

A	Damages		
a.	Cost of Repairs	\$	4,700.00
b.	Vehicle Rental (6 days x \$180.00 per day)	\$	1,080.00
c.	Loss of Use (12 days x \$120.00 per day) (inclusive of 3 Sundays and 2 days Pre-Repair Inspection Notice and 1 Vesak Public Holiday)	\$	1,440.00
B	Disbursements		
a.	Insurance Enquiry Fees	\$	7.45
b.	Third Party Insurer Enquiry	\$	2.00
c.	GIA Report	\$	29.00
d.	Survey Report	\$	584.00
C	LEGAL COSTS (AT THIS STAGE)	\$	749.00
		\$	8,591.45

CONFIDENTIALITY CAUTION

THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CROSSBORDERS LLC

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

BY CERTIFICATE OF
POSTING

WITHOUT PREJUDICE

BY PDX

WITHOUT PREJUDICE

EA ✓
1. Upload ✓
2. MLI \$2
Weng
25/6/18

We enclose herewith copies of the following documents in support of our client's claim:-

- a) GIA Report lodged by our client (SJU2535G) with sketch plan together with photographs of our client's vehicle no. SJU2535G;
- b) GIA Report lodged by you (SKP2662L) with sketch plan;
- c) Result of Third Party Insurer Enquiry on your vehicle registration no. SKP2662L;
- d) Result of Insurance Enquiry on your vehicle registration no. SKP2662L;
- e) Vehicle Rental Invoice and Agreement from Carz Rental Pte Ltd;
- f) Proformer Invoice from Alpha Car Services Pte Ltd;
- g) Vehicle Assessment Report & Invoice from Sincere Appraiser Services Pte Ltd;
- h) Forty Four (44) colour photographs depicting the damage to our client's motor vehicle no. SJU2535G;
- i) Certificate of Insurance of our client's vehicle no. SJU2535G; and
- j) Vehicle Owner Particulars of our client's vehicle no. SJU2535G.


We have on 15 May 2018 notified your insurers MSIG Insurance (Singapore) Pte Ltd of the accident and pre-repair inspection of our client's vehicle was carried out by your insurer.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter **within 14 days** of your receipt of this letter, failing which our clients will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our clients arising out of the accident, you are required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents **within 8 weeks** of your receipt of this letter.

Yours faithfully


Kuldip Singh

Email: corene@crossbordersllc.com (secretary)

encs

cc: SJU2535G

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/05/2018 17:25
Date Of Accident	12/05/2018 18:00
Exact Location Of Accident	ESSEX ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU2535G
Insured/Policyholder	
Name Of Registered Owner	CHAN WENG SUNG, JOHN
NRIC No	S8011757D
Email Address	JOHNCHANWS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96929533
Alternative Phone No	OFFICE-96929533

Vehicle Particulars

Manufacturer	VOLVO
Model	C30
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P27255983DMA
Cover Note Number	

Driver

Name of Driver	CHAN WENG SUNG, JOHN
NRIC No	S8011757D
Date Of Birth	23/04/1980
Occupation	INDOOR
Date Of Driving Pass	25/08/2000
Driving Experience	17 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96929533
Fax Number	
Contact Number	OFFICE-96929533
EMail Address	JOHNCHANWS@GMAIL.COM

Address	68B THOMSON ROAD
Postcode	307587
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKP2662L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LISSA TOH
NRIC/Passport Number	S7635847H
Contact Number	90388081
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY CAR WAS PARK STATIONARY AT
BACK ALLEY OF EBBEX ROAD WITH NO ONE
INSIDE THE CAR.

WHEN I CAME BACK TO MY CAR ON
13th MAY 2018 AT 5:30PM. I FOUND
OUT THAT MY REAR LEFT BUMPER
WAS DAMAGED. THERE WAS A MARK
LEFT BY THE DRIVER ON MY
WINDSCREEN.

DECLARATION

I/We declare the foregoing particulars are true in every respect

[Signature]
Police Officer's Signature
Date & Time

[Signature]
Witness's Signature
If driver is not the sole suspect
Date & Time

[Signature]
Reporting Officer's Signature
Name
Rank/Post



Alpha Car Services Pte Ltd

ALPHA

Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, Singapore 417883

Tel: 6509 8258 Email: alphacarservices@hotmail.com

ROC No. 201717633Z

Chan Weng Sung, John

(S8011757D)

C/O. BLK C Kaki Bukit Avenue 6

#01-59 Autobay @ Kaki Bukit

Singapore 417883

PROFORMER INVOICE

Date: 28/05/2018

Vehicle No: SJU 2535G

Make/Model: VOLVO C30 2.0

Chassis/Engine No: B4204S3171992

Acc. Date: 12/05/2018

Claim No.: 1805-0119IC (SJU2535G) CROSS.

Ref Policy No.: P27255983DMA

Amount S\$

Inclusive of Supplying Parts and labour,
Panel beating and spray painting

Repairs Costs

4,700.00

4,700.00

SGD FOUR THOUSAND AND SEVEN HUNDRED ONLY

ALPHA CAR SERVICES PTE LTD

ALPHA CAR SERVICES PTE LTD

UEN: 201717633Z

Blk C, Kaki Bukit Ave 6 #01-59

Kaki Bukit Autobay, Singapore 417883

Tel: 6509 8258

Email: alphacarservices@hotmail.com

ALPHA

CARZ RENTAL PTE. LTD.

1 Kaki Bukit Avenue 6, #02-47 Autobay, Singapore 417883

Tel: (65) 6509 5521 Fax: (65) 6509 5523

Co. Reg. No.: 201312119K

INVOICE
3532

Messrs: ALPHA CAR SERVICES PTE LTD

CHAN WENG SUNG JOHN

S8011777D

SJU 2535G

Date : 22/5/2018

QTY.	DESCRIPTIONS	AMOUNT
1	Veh. No. : SJF 3297R Model : TOYOTA CAMRY Date Out : 15/05/2018 Date In : 21/05/2018 S\$/ day : \$ 180.00 Agreement : 3532	1,080.00
TOTAL AMOUNT		1,080.00

E. & O.E.

* Please make all payments within 7 days.

* All service and repairing are in good order & conditions.



Customer Sign & Chop

CARZ RENTAL PTE. LTD.

CARZ RENTAL PTE. LTD.

1 Kaki Bukit Avenue 6, #02-47 Autobay,
Singapore 417883
Tel: (65) 6509 5521 Fax: (65) 6509 5523

Alpha: SJU2356

VEHICLE RENTAL AGREEMENT

ROC NO: 201312119K

RANO: 3532

Hirer Particulars - ALPHA CAR SERVICES PTE LTD		Veh. No. SJF3297R Replace veh. No. SJU2356	
Name	UEN: 201717833Z	Make / Model	TOYOTA CAMRY
Address	Blk C, Kaki Bukit Ave 6 #01-59	Date/Time Out	15/5/18 1210HR
	Kaki Bukit Autobay, Singapore 417883	Date/Time In	21/5/18 1515HR
NRIC/Passport	Email: alphacarservices@hotmail.com	Estimated Date/Time Return	
Tel (O)		Rental charges -	
Fax		Hours	@
Authorised Driver's Particulars -		Days	@
Name	Chan Weng Sung, John	Weeks	@
Address	68B Thomson Road, S 307187	Months	@
C/Passport	S8011737D	Nationality	S'porean
Date of Birth	23/4/1980	Occupation	
D/Licence No.	S8011737D	Mobile	
Expiry Date		Tel (O)	96924533
Country of Issue	S'pore	Tel (H)	
(A) - ACCIDENTS (D) - DENTS (S) - SCRATCHES		Optional Charges -	
		Delivery	@
		Collection	@
		Sub-Total	
		Add 7% GST	
(A) Estimated Total Rental			
Extension -			
Extension Rental		X	
Surcharge (Malaysia)		X	
P.A.I.		X	
Others -		X	
Misc :			
Cash/Nets/Cheque/VISA/MC Card No:			
Sub-Total			
Add 7% GST			
(B) Extension/others Total			
(A) + (B) Grand Total Rental Charges			
Less Prepayment			
Balance Due			
Deposit		Deposit Refunded	
Amount			
Remarks:		Received by	
The hirer hereby read and understood all terms and conditions stated on this page and overleaf :			
IMPORTANT NOTE: 1. Only persons aged 24 and above or below 65 with 2 years or more driving experience, authorized, licensed and signing this agreement may drive the vehicle. 2. In case of accident, the Hirer shall report to rental office immediately. If there is any bodily injury, a police report must be made within 24 hours. 3. Vehicle is strictly for SINGAPORE USE ONLY, and may not be driven out of Singapore without prior consent of Carz Rental Pte. Ltd. 4. Unauthorised drivers, drivers who did not fulfill the above requirement are liable for the full cost & other losses suffered by Carz Rental Pte. Ltd. should the vehicle is damaged or stolen.		CARZ RENTAL PTE. LTD. 1 Kaki Bukit Avenue 6, #02-47 Autobay Singapore 417883 Tel: (65) 6509 5521 Fax: (65) 6509 5523 Co. Reg. No: 201312119K Hirer Signature/Co's Stamp/Date	



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-073435

Date of Request: 15/05/2018

Your Ref No: Online Purchase

CROSSBORDERS LLC
133 New Bridge Road #23-03/04/05
Chinatown Point
Singapore 059413

Dear Sir/Madam,

Enquiry Date 15/05/2018
Enquiry By Tang Hui Ting
TP Vehicle No. SKP2662L
Accident Date 12/05/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKP2662L	MSIG Insurance (Singapore) Pte. Ltd.	27/07/2017-26/07/2018	+65 6827 7888

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

> Back to OneMotoring

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 15 May 2018 / 09:21:04

Receipt Date/Time : 15 May 2018 / 09:21:04

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180515-000307

Previous Receipt No. :

S/N Item Description/
Business Transaction Reference
No.

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SKP2662L
As at 12 May 2018/18:00:00

Insurance Co: MSIG INSURANCE (SINGAPORE) PTE LTD

1 Insurance Enquiry - SKP2662L
Enquiry Fee
20180515091928585262

7.00	0.49	7.49
------	------	------

Sub-Total

7.00	0.49	7.49
------	------	------

Total Before Rounding

7.00	0.49	7.49
------	------	------

Rounding Difference

0.04

Total Amount Payable

7.45

Paid By

xxxxxxxxxxxx0682

Credit Card:
Visa/MasterCard

7.45

Total

7.45

Cash Change

0.00

Tendered Amount

7.45

Excess Refundable Amount

0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



SINCERE APPRAISAL SERVICES PTE LTD Co.Reg no: 201800639R
60 Paya Lebar Road #07-41 Paya Lebar Square Singapore 409051
Tel : 6636 4628 Fax : 6636 4638 E-mail : sincereappraisal@gmail.com

INVOICE

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413

Invoice No: 250518-269
Our ref: 269/TP/2018
Date: 25/5/2018

Claim Type: Third Party	Date of Loss: 12/5/2018
Vehicle Reg No: SJU2535G	Claimant: Chan Weng Sung, John
Vehicle Make/Model: Volvo C30 2.0L AT	
Description	Amount (S\$)
1. Professional Fee (including Transport, 44 Photographs and Miscellaneous charges)	584
Total	584
Singapore Dollar: Five hundred and eighty four dollars only.	

Cheques should be crossed A/C PAYEE and made payable to Sincere Appraisal Services Pte Ltd



Sincere Appraisal Services Pte Ltd



SINCERE

APPRAISAL SERVICES PTE LTD

VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 269/TP/2018

Date: 25/5/2018

REFERENCE

Date of loss: 12/5/2018
Claimant: Chan Weng Sung, John

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU2535G	Make &	Volvo
Reg date:	25/11/2009	Model	C30 2.0L AT
Colour:	Silver	Engine No:	B4204S3171992
Type:	Motor Car	Chassis No:	YV1MK434BA2175704
Type of Claims:	Third Party	Odometer No:	101039km
		Engine Cap:	1999cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY (STATIC ONLY)

General Condition: Good	Steering: Good	Engine Modification: Nil
Paint work: Good	Handbrake: Good	Pre-accident
	Footbrake: Good	Damage: Nil

CONDITION OF TYRES

Front Left Size: Dunlop 225/45R17 70%	Front Right Size: Dunlop 225/45R17 70%
Rear Left Size: Dunlop 225/45R17 70%	Rear Right Size: Dunlop 225/45R17 70%

The above percentages represent the remaining life of the tyre threads

COST OF REPAIRS

	Repairer S\$	Adjuster S\$
Parts	S 3,674.10	S 3,674.10
Labour	S 2,550.00	S 2,200.00
Calculated Cost (S\$):	<u>S 6,224.10</u>	<u>S 5,874.10</u>

Recommended Lump Sum Repair Cost (S\$): \$ 4,700.00

Date of Assignment: 15/5/2018
Date Inspected: 15/5/2018
Est. repair Period: 12 days


Inspected At: Alpha Car Services Pte Ltd
Blk C, #01-59
Kaki Bukit Autobay
Singapore 417883

SINCERE APPRAISAL SERVICES PTE LTD Co.Reg no: 201800639R

60 Paya Lebar Road #07-41 Paya Lebar Square Singapore 409051

Tel: 6636 4628 Fax: 6636 4638 E-mail: sincereappraisal@gmail.com

POINT OF IMPACT



BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle along Essex Road.

GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are at the left hand rear portion.

SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$6,224.10. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$4,700.00.

We have not authorised the repair. Under normal circumstances, estimated **12** working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Dave Chang
Automotive Appraiser
AUTO. ENG, CAE, CGI
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended De-registration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Singapore NRIC

1757D

SJU2535G

Yes

14 Jun 2018

VOLVO

C30 2.0L AT ABD D/AB 2WD 3DR

Silver

2009

B4204S3171992

YV1MK434BA2175704

107.0 kW (143 bhp)

\$30,514.00

25 Nov 2009

25 Nov 2009

1

\$30,514.00

Yes

24 Nov 2019

\$16,782.00

24 Nov 2019

E - Open Category

10

\$18,267.00

\$2,600.00

\$19,382.00

Bal = 1 yr 6-4 mths.

M.V. \$27,000 - \$28,000

15,257

The information contained herein is correct as at 14 Jun 2018

OK

DOA: 12/05/18

...CLAIM SUBFOLDER...(Pending for Survey Report)




























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 May 2018		15 May 2018 15:14 Edit Adj Rpt	S\$2,400.00 Edit Estimates	S\$2,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TOH EE-WEN LISSA, ID: S7635847H								
Main Claimant:	CHAN WENG SUNG JOHN, ID: S8011757D								
Vehicle Reg. No.:	SJU2535G	Date of Loss:	12/05/2018 18:00 - :59 [101 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 558290	Policy/Cover Note No.:	80438269QMY (Comprehensive) Coverage: 27/07/2017 - 26/07/2018						
Vehicle Reg. No. (Insured):	SKP2662L	Policy No. (Claimant):							
		Excess:	S\$600.00						
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 27/06/2018]								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK AUTO CONSULTANTS PTE LTD OI NOT REPORTED CONTACT: CAI LING (6509 8258)/ AH YAP (9807 3304)/ AH HWA (9136 8884)								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (25/06/2018): Report Send Back Alerts - SJU2535G (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJU2535G (558290)**
[SKP2662L]
TP
CHAN WENG SUNG JOHN
May 12 2018 6:00PM
[TOH EE-WEN LISSA]
Alpha Car Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/05/18 18:32	Accident Statement From: SC - Reg. No: SKP2662L, Claimant: TOH EE-WEN LISSA	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
2	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
3	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
4	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
5	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
6	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
7	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
8	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
9	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
10	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
11	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
12	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
13	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
14	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
15	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
16	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
17	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
18	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
19	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
20	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
21	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
22	17/05/18 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
23	17/05/18 17:16	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
24	17/05/18 17:16	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
25	17/05/18 17:16	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
26	17/05/18 17:16	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
27	17/05/18 17:16	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
28	17/05/18 17:16	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
29	17/05/18 17:16	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
30	17/05/18 17:16	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
31	17/05/18 17:16	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
32	17/05/18 17:16	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
33	17/05/18 17:16	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	30/05/18 09:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	30/05/18 09:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	30/05/18 09:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	30/05/18 09:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	30/05/18 09:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	30/05/18 09:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	30/05/18 09:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/05/18 11:22	PRI - CROSSBORDERS LLC	 Load PDF	
2	15/05/18 11:27	SURVEY DISAGREE ON SJE - ASSIGN AIS	 Load PDF	
3	15/05/18 18:32	SJU2535G E-FILE REPORT From: SC - Reg. No: SKP2662L, Claimant: TOH EE-WEN LISSA	 Load PDF	
4	25/06/18 15:28	LOD with supporting Documents	 Load PDF	
5	25/06/18 15:28	Survey report & Photos	 Load PDF	
6	25/06/18 18:39	our instruction to LKK to prepare paper survey report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/07/18 12:17	PRS Invoice	 Load PDF	
2	13/07/18 12:22	PHOTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18008809/LSBE2-1

Date: 13/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80438269QMY

Claimant Vehicle No : SJU2535G

Insured Vehicle No : SKP2662L

Date of Loss: 12/05/2018

Nature of Claim: TP

Claim No: 558290

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU2535G

Make & Model: VOLVO C30, 2.0 (A)

Reg. Date: 25/11/2009 (Man. Year: 2009)

Colour: Grey

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: B4204S3171992

Chassis No: YV1MK434BA2175704

Odometer: 101039 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Dunlop 7 mm

Rear Left Side: Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,674.10	2,208.50	1,465.60	39.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	1,400.00	1,150.00	45.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,224.10	3,608.50	2,615.60	42.02
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	6,224.10	2,400.00	3,824.10	61.44

INSPECTION

Date of Assignment: 15/05/2018

Date Inspected: 16/05/2018 Inspected At:

Alpha Car Services Pte Ltd (HQ)
BLK C KAKI BUKIT AVE 6 #01-59
AUTOBAY@KB
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2018)
Parts: M1-COUPE	VOLVO C30 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJU2535G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Warped / Dented	1,298.00 FL	*1,298.00 FL
2	1		*REAR BUMPER RETAINER	Bent / Necessary	166.00 FL	*166.00 FL
3	1		*REAR BUMPER REFLECTOR	Serviceable	186.00 FL	*- FL
4	1		*REAR BUMPER C30 EMBLEM	Necessary	108.00 FL	*108.00 FL
5	1		*REAR BUMPER 2.0 EMBLEM	Necessary	103.00 FL	*103.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Repair	374.00 FL	*- FL
7	1		*REAR TAILGATE VOLVO EMBLEM	Not Necessary	156.00 FL	*- FL
8	1		*REAR LEFT TAILLAMP	Cut / Bent	866.00 FL	*490.00 FL
9	1		*REAR RIGHT SIDE PROTECTOR	Serviceable	195.00 FL	*- FL
10	1		*REAR AIR DUCT VENTILATOR	Not Necessary	197.00 FL	*- FL
11	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
12	1		*REAR LEFT SIDE PROTECTOR CLIPS (6PCS)	Necessary	10.00 FS	*10.00 FS
13	2		*REAR BUMPER REVERSE SENSOR	Malfunction	250.00 FS	*200.00 FS
14	1		*REAR NO PLATE WITH GARNISH	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,039.00	2,425.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	364.90	216.50
Total Parts (\$\$)	3,674.10	2,208.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	900.00	500.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	900.00	500.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	20.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	40.00
5	TO REMOVE AND INSTALL REAR INNER TRIM AND INNER GARNISH TO FACILITATE THE REPAIR	New	140.00	80.00
6	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	120.00	60.00
7	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	40.00
8	TO REPAIR, STRAIGHTEN AND ALIGN REAR LEFT FENDER ASSY	New	180.00	100.00
9	TOWING SERVICE	New	100.00	60.00
Gross Labour Cost (\$\$)			2,550.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >