

ASS. REC. BY:

REF: CS3/11618011690/G24d3ek

Special Instruction:

Surveyor:

Maimun

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Chin lee Ying

of

AIG

Date/Time:

27/6/2018 @ 10:52am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SJN 8995J

Insured:

SLJ 5649B

at Workshop no/s

Green Star Spray Painting

Tel:

65463092

of

81k 3011, Bedok North Ave 4 #01-2004

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

26/06/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time: 211pm @ 27/6/18

Person Contacted:

Jenny

Vehicle: IN / OUT

Date/Time

Action/Instruction (X) Estimate

SJN 8995J - X

SLJ 5649B - X

28/6/18

Dismantled

6/7/18

After Repair

INSURANCE
SURVEILLANCE

YKS
XAL

REF: ALG

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop n/s Green Star
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____


(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$24K.
IDAC Accident Rpt.: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 6 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: SJN8995J Yr Regn: 03 Mar 2009
Type: ☒ M/Cas / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota wish cc 1794
Colour: Grey A/C Insured / Std / NI / NA
Sp. Reading: 91436 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JTDER12WX03001965
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: ☒ Inter / Jammed / Leaked / Burnt or
Brake: ☒ Inter / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD ☒ A/Rim or
Tyre Size: F: 195/65 R15
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
☒ TOYO / YOKO or

Front: _____ Rear: _____
R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A. _____ D.O.I. 27-06-18
Survey held at: w/s 4:20pm
Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>07/18</u>	<u>Submit DAR report</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation _____

) \$ + RS \$ _____

) Photos _____

) Others _____

TOTAL

<u>180</u>
<u>20</u>
<u>200</u>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18011690/Gz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 27-06-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLJ 5649B	Veh. Inspected	SJN 8995J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	27/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/06/2018	Inspection Date	27/06/2018
Survey held at	GREEN STAR SPRAY PAINTING BLK 3011 BEDOK NORTH AVE 4 #01-2004 BEDOK INDUSTRIAL PARK E SINGAPORE 489977		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE
SLJ5649B AND SJN8995J ON 26/06/2018**

From: Chin, Lee-Ying
To: assignments@lkkauto.com, Admin A
Cc: Fong, Andy-SY
Sent: Wednesday, 27 June, 2018 10:52:30 AM
Attachments:  Fax2F49.tif  FaxC1CF.TIF

Hi LKK,

Kindly assist to survey, vehicle is in.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Attn : Motor Claims Department

26/06/2018

To : Defendant's Insurers AIGa Asia Pacific Insurance Pte Ltd.
Address BY FAX & POST

Dear Sir

We are instructed by (name of claimant) to notify you of a road traffic accident on (date) at about (time) at (place of accident which must be sufficiently detailed to establish location) involving our client's vehicle registration number (SSN 84453) and vehicle registration number (SLX 5644B. insured by you at the material time. A copy of the Singapore Accident Statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Green- Star Spray Painting
Blk 3011 Bedok North Ave 4
01 - 2004 Bedok Ind Park E
Singapore 484477

Tel : 6546 3092
Fax : 6545 2066
Email : Sales @ greentorep.com.

Cc 1. Defendant's name
Address

2. Other Defendant and his insurers

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/06/2018 14:21
Date Of Accident	26/06/2018 12:45
Exact Location Of Accident	X-JUNCTION OF LOYANG AVE/LOYANG WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN8995J
Insured/Policyholder	
Name Of Registered Owner	SEAH KIM ENG
NRIC No	S1495417A
Email Address	BANJISG@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96618476
Alternative Phone No	OTHERS-96618476

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P60270202DMV
Cover Note Number	

Driver

Name of Driver	SEAH KIM ENG
NRIC No	S1495417A
Date Of Birth	12/08/1961
Occupation	OUTDOOR
Date Of Driving Pass	22/09/1986
Driving Experience	31 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96618476
Fax Number	
Contact Number	OTHERS-96618476
Email Address	BANJISG@YAHOO.COM.SG

Address	BLK 101 SIMEI STREET 1 #05-902
Postcode	1852
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ5649B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KWOK CHEE KONG
NRIC/Passport Number	S7220991E
Contact Number	97422272
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


E. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

26/6/18
 2:14 PM


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

A - SJN 8995J
B - SLJ 5649B

A - SIN 8995J
B - SLJ 5649B

WHILE STOPPING AT ~~THE~~ TRAFFIC LIGHT ALONG LOYANG
AVENUE JUNCTION OFF ~~LOH~~ LOYANG WAY MY CAR
WAS HIT AT THE BACK ^{BY} ~~BACK~~ A CAR NO. PLATE
SLJ5649B

WHILE STOPPING AT THE TRAFFIC LIGHT ALONG LOYANG
AVENUE JUNCTION OFF ~~LE~~ LOYANG WAY & MY CAR
WAS HIT AT THE BACK ^{BY} A CAR NO. PLATE
SLJ5649B

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 3

REPUBLIC OF SINGAPORE DRIVING LICENCE

License No: S1495417A

Name: SEAH KIM ENG

Date of Birth: 12 Aug 1961

Issue Date: 08 Jul 2003

Barcode: 9006371906



REPUBLIC OF SINGAPORE

IDENTITY CARD NO: S1495417A

Name: SEAH KIM ENG

Race: 余金英

CHINESE

Date of Birth: 12-08-1961

Sex: M

Country of Birth: SINGAPORE




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class	Description	Valid Until
Class 1	Motor cars not exceeding 3500 kg with not more than 7 passengers, exclusive of the driver; and motor tractors/vehicles not exceeding 2000 kg	31 Dec 1999
Class 4	Heavy motor cars and motor tractors not exceeding 3500 kg	30 Mar 2002
Class 6	Motor vehicles not exceeding 3500 kg and not exceeding 12 seats	08 Jul 2003

NP 428A

License No: S1495417A

Barcode: 9006371906

Barcode: 9006371906

License No: S1495417A

Address: APT BLK 101 SIMEX STREET 1
#05-900
SINGAPORE 1852

Valid Until: 04-11-1993



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5417A
Vehicle Details	
Vehicle No.:	SJN8995J
Vehicle to be Exported:	No
Intended De-registration Date:	28 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 AUTO
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	1ZZ3229294
Chassis No.:	JTDER12WX03001965
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,803.00
Original Registration Date:	03 Mar 2009
First Registration Date:	03 Mar 2009
Transfer Count:	0
Actual ARF Paid:	\$18,803.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Mar 2019
PARF Rebate Amount:	\$9,401.00
Intended COE Rebate Details	
COE Expiry Date:	02 Mar 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$689.00
COE Rebate Amount:	\$46.00
Total Rebate Amount:	\$9,447.00

The information contained herein is correct as at 28 Jun 2018

Dep 23,330 /yr

OK

MV 22K - 23K @ 9/2/18

7 mths 20 days COE left

MOTORCAR (Rear)

Rear Portion

Vehicle No: SIN 8995J

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	BT	✓	
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish	BT	✓	
1140	993632	Rear Number Plate Lamp		2	
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	BT	✓	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector		2	
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	CUT	✓	
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	CRA	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp		2	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRA	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel	DD	✓	
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	NEC	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish	BT	✓	
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC	✓	
1196	994607	Tailgate Glass Sealant	NEC	✓	
1197	994629	Tailgate Lock	BR	✓	
1198	994651	Tailgate Rubber	CUT	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board	CRA	✓	

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish	BR	✓	
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: 16

Assessor: Gino Diany

12/1/2018

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0991E
Vehicle Details	
Vehicle No.:	SLJ5649B
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jul 2018
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	HRA2301481A
Chassis No.:	SJNFEAJ11U1707683
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,689.00
Original Registration Date:	16 Dec 2016
First Registration Date:	16 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$13,689.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Dec 2026
PARF Rebate Amount:	\$10,266.00
Intended COE Rebate Details	
COE Expiry Date:	15 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,000.00
COE Rebate Amount:	\$26,124.00
Total Rebate Amount:	\$36,390.00

The information contained herein is correct as at 11 Jul 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jun 2018 Edit Reg		27 Jun 2018 00:00 Edit Adj Rpt	\$40.00 Edit Estimates	\$40.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	KWOK CHEE KONG, ID: 57220991E		
Main Claimant:	SEAH KIM ENG, ID: 51495417A		
Vehicle Reg. No.:	SJN8995J	Date of Loss:	26/06/2018 12:00 - :59 [111 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3729663307SG	Policy/Cover Note No.:	2100493587
Vehicle Reg. No. (Insured):	SLJ56498	Policy No. (Claimant):	
		Excess:	
Repairer:	Green Star Spray Painting Garage (Bedok) Blk3011 Bedok North Ave4, #01-2004/2006 Bedok Ind. Park E, 489977 Bedok - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijie.Wui@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/07/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)




































- AIG_SG (29/06/2018): Request To Upload TP GIA Report









































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJN8995J (3729663307SG)
[SLJ5649B]
TP
SEAH KIM ENG
Jun 26 2018 12:00PM
[KWOK CHEE KONG]
Green Star Spray Painting Garage

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
2	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
3	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
4	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
5	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
6	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
7	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
8	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
9	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
10	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
11	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
12	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
13	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
14	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
15	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
16	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
17	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
18	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
19	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
20	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
21	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
22	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
23	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
24	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
25	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
26	29/06/18 15:20	General View														Load JPG	<input checked="" type="checkbox"/>	
27	29/06/18 15:21	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
28	29/06/18 15:21	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
29	29/06/18 15:21	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
30	29/06/18 15:21	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
31	29/06/18 15:21	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
32	29/06/18 15:21	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
33	29/06/18 15:21	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
34	29/06/18 15:21	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
35	29/06/18 15:21	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
36	29/06/18 15:21	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
37	29/06/18 15:21	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	29/06/18 15:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	12/07/18 16:05	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/06/18 12:57	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18011690/GZ4D3E2

Date: 13/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100493587
 Claimant Vehicle No: SJN8995J Insured Vehicle No: SLJ5649B
 Date of Loss: 26/06/2018 Nature of Claim: TP Claim No: 3729663307SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJN8995J
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ3229294
 Reg. Date: 03/03/2009 (Man. Year: 2009) Chassis No: JTDER12WX03001965
 Colour: Grey Odometer: 91436 km
 Engine Capacity: 1794 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/06/2018
 Date Inspected: 27/06/2018 Inspected At: Green Star Spray Painting Garage (Bedok)
 Blk3011 Bedok North Ave4, #01-
 2004/2006 Bedok Ind. Park E
 Singapore 489977
 Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	2		*REAR NUMBER PLATE LAMP	* Check	0.00 F	*- F
3	1		*REAR BUMPER	Dented	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
6	2		*REAR BUMPER REFLECTOR	* Check	0.00 F	*- F
7	1		*REVERSE SENSOR	Cut	0.00 F	*- F
8	1		*REAR END PANEL	Dented	0.00 F	*- F
9	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
10	1		*REAR LH TAILLAMP	* Check	0.00 F	*- F
11	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
12	1		*REAR RH TAILLAMP PANEL	Repair	0.00 F	*- F
13	1		*TAILGATE	Dented	0.00 F	*- F
14	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
15	1		*TAILGATE GARNISH	Bent	0.00 F	*- F
16	1		*TAILGATE WIPER MOTOR	* Check	0.00 F	*- F
17	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
18	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
19	1		*TAILGATE LOCK	Broken	0.00 F	*- F
20	1		*TAILGATE RUBBER	Cut	0.00 F	*- F
21	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F
22	1		*REAR LH FENDER INNER GARNISH	Broken	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >