

INSURANCE

INS. CASE OWNER:

CC 4/FWD1801 1704, 11/11/18

LKK:

IDAC:

Surveyor:

WH1016

DOI:

ASSIGNMENT

27/6/18

Date / Time:

27/6/18

Registered in Merimen:

27/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

FBG 12715

Name of Insured:

Flon Tan RM 111

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

27/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

1201800008786

Policy No.:

PWMI 10A-0001298

Make / Model:

YAMAHA

Place of Accident:

ALEXANDRA RD

If NO. Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SPB 11895



INSRS:

WSP:

Tel:

Liability:

RMKS:

SOC

11/11/18



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

27/10/18
Asker

SPB 11895-4 PHOTODUPLICATION

13-11-18 THE PAGE TO TYPST TO PREPARE REPORT.

RECEIVED 1 DEC 2018

STAGE

DATE / PIC

Non-Reporting Itr (1st):
Non-Reporting Itr (2nd):
Non-Reporting Itr (Final):
Notification Itr (if non-pickup):
Call OI:
After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)		
After call Itr to OI		
Authorisation To Act:		
Release Voucher:		
Final Repair Bill		
Car Rental Invoice:		
Towing Invoice		
LTA / GIA:		
Medical Bill:		
PIR		
Mandate/Reject Instruction:		
LOD		
Payment Breakdown Form:		
Post-Repair Photos:		
Others:		

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost: 46 \$5550.00

(3 days) Reduction: 42 %

Confirm by: GKS

FINAL SETTLEMENT

Date/Time: 11-12-18

Confirm with (Ring)

Email ☒ Call ☐

Final Liability: % 80

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost: \$5550.00

DI REAR BENCH 12

Loss of Rental (LOR): \$5 -

(3 days)

Loss of Use (LOU): \$5 120.00

(560 x 3 days)

Loss of Income (LOI): \$5 -

(5 x 3 days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search \$52.00

Medical: \$5 -

Disbursement: \$5 -

(e.g. Tow/ Independent)

Legal Cost: \$5 -

Total: \$5672.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 11-12-18

Confirm with: (Ring)

Email ☒ Call ☐

Payee 1: \$5672.00

Name 1: SOC LEON MOTOR VIDEOS

Payee 2: (Strike if N.A.) \$5

Name 2:

Payee 3: (Strike if N.A.) \$5

Name 3:

COPY SENT

1) Claim status: Normal/Reject/Private Settle
2) Report Format: 12
3) Survey fee: 500

REF: FWD

ASSIGNMENT

Pinish Date: 27/06/18

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop no/s:

1 Kaki Bukit Ave 6 Bldg # 01-91

Insured:

Policy No:

Claims No:

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

Q/A / FR Seen:

Consistent? : Yes or No

Est. Repair:

2

days

Res:

Yes or No

Lump Sum:

2

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

1up

LTA 24763

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SKB11895 Yr Reg: 9 11

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

Hyundai Elantra 15-9/

Colour:

Brown

A/C: Insured / Std / NI / NA

Spr. Roofing:

174825

T/Ratio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHD H 41 CMCU 270964

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55-216

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

7

mm

R/Bal:

7

mm

L/Bal:

7

mm

L/Bal:

7

mm

D.O.A:

7/6/18

D.O.I:

27/6/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time:

Action / Instruction:

45: +550 (RED: +400.30 42%)

Date/Time, File Pass to:

☐

: Preli. Report

If:

☐

: Final Report

Date/Time, File Return to:

3:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + R. R

I Phone:

I Other:

Report Format:

Lump Sum / L.B.E (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CC4/FWD18011704/Ueb3

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 27-06-2018



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBG 1271S	Veh. Inspected	SKB 1189S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/06/2018	Inspection Date	27/06/2018
Survey held at	SOC LEON MOTOR WORKS 1 KAKI BUKIT AVE 6 BLK D #01-91 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE

速 良 摩 哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 20663900K

修理汽車貨車兼
打嗎甲燒杆噴漆
代理保險：車禍
賠償及買賣汽車

MR CHEW YOONG KEONG

DATE: 26/06/2018

DOA: 07/06/2018

ESTIMATE REPAIR FOR VEHICLE NO. SKB 1189 S (HYUNDAI ELANTRA)

	Description	List Price
1 pc	Rear bumper <i>De / warped</i>	\$ 446.40
2 pcs	Bumper side retainer @ \$532.00 <i>11</i>	\$ 64.00 <i>X</i>
10 pcs	Bumper clips @ \$55.50 <i>11</i>	\$ 55.00
		\$ 565.40
	Less : 20%	\$ (113.08)
		\$ 452.32
	Special Nett Items	
	Labour charges for knocking & replacing parts	\$ 200.00 <i>100</i>
	Spraypainting	\$ 300.00 <i>200</i>
	TOTAL :	\$ 952.32

701.4
401.2
71.12
560.81

LKS Auto Parts hereby notify the Receiver of the following:

- The receiver before after spray painting
- 2nd class (scratched parts) during recovery
- Parts prices are subject to confirmation
- This quote is given on a "Without Prejudice" basis
- No legal responsibility is assumed
- Supplementary damages are not covered and belong to the relevant insurance company

Acknowledged by Receiver
Signature:
Date:

W. f. Adhoni
27/6/18
After repair
2 day
1/5 # 550/-

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE

速 良 摩 哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒奸噴漆
代理保險：車禍
賠償及買賣汽車

MR CHEW YOONG KEONG

DATE: 26/06/2018

DOA : 07/06/2018

ESTIMATE REPAIR FOR VEHICLE NO. SKB 1189 S (HYUNDAI ELANTRA)

	Description	List Price
1 pc	Rear bumper <i>De / warped</i>	\$ 446.40
2 pcs	Bumper side retainer @S\$32.00 <i>11</i>	\$ 64.00
10 pcs	Bumper clips @S\$5.50 <i>10</i>	\$ 55.00
		\$ 565.40
	Less : 20%	\$ (113.08)
		\$ 452.32

Special Nett Items

Labour charges for knocking & replacing parts.	\$ 200.00
Spraypainting	\$ 300.00
TOTAL :	\$ 952.32

W. f. Alford
27/6/18

27/6/18
After repair
2dy.

L/S

LKS Auto Insurance hence notify the Repaired of the following:

- Full survey before repair spray painting
- To include damaged parts during survey
- Parts prices are linked to confirmation
- Third party survey is on a "Without Prejudice" basis
- Rep. work modification is allowed
- Supplementary details must be reviewed and
- Is sent to LKS Auto Insurance Company

Acknowledged by Repaired
Signature:
Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	2387A

Vehicle Details

Vehicle No.:	SKB1189S
Vehicle to be Exported:	No
Intended De-registration Date:	27 Jun 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Brown
Manufacturing Year:	2011
Engine No.:	G4FGBU331479
Chassis No.:	KMHDH41CMCU270964
Maximum Power Output:	95.6 kW (128 bhp)
Open Market Value:	\$13,578.00
Original Registration Date:	21 Sep 2011
First Registration Date:	21 Sep 2011
Transfer Count:	1
Actual ARF Paid:	\$13,578.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Sep 2021
PARF Rebate Amount:	\$8,825.00

Intended COE Rebate Details

COE Expiry Date:	20 Sep 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$49,301.00
COE Rebate Amount:	\$15,938.00
Total Rebate Amount:	\$24,763.00

The information contained herein is correct as at 27 Jun 2018

OK

Nivitha (LKK Auto)

From:

Sent:

To:

motorclaims.sg@fwd.com

Tuesday, 26 June 2018 1:08 PM

AsherSng@lkkauto.com; sur@lkkauto.com; assignments@lkkauto.com; admin-

a@lkkauto.com; admin-d@lkkauto.com

FW: Accident involving SKB1189S & FBG1271S on 07/06/2018

PDF_20180626_0001.pdf; PDF_20180626_0002.pdf

Subject:

Attachments:

Hi LKK team,

Please refer to the email below and liaise with TP repairer for survey arrangement.

Attached is the repair estimate & TP GIA report.

Please create the case in Merimen. Our insured has yet reported the accident to us.

Thank you.

Kind Regards

Josey Loh

Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E josey.loh@fwd.com

W fwd.com.sg



Endowment Plan

Get the biggest guaranteed return for a 3 year plan available online.

Limited time offer!



2.02% p.a.

fwd.com.sg

SAVE NOW

From: slmoi [mailto:slmoi@singnet.com.sg]

Sent: Tuesday, 26 June, 2018 12:39 PM

To: Motor Claims SG - SG Common

Subject: Accident involving SKB1189S & FBG1271S on 07/06/2018

Hi,

Please find attached repair estimate and accident report and arrange for survey at your earliest conven

Thanks & Regards,

Irene Leong

SOC LEON MOTOR WORKS

REPAIRING OF
MOTOR VEHICLES.
PANEL BEATING.
WELDING, SPRAYING.
INSURANCE AGENT.
CLAIMS
DEALING IN 2ND
HAND VEHICLE.

速 良 摩 哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒杆噴漆
代理保險：車禍
賠償及買賣汽車

25 July 2018

FWD Singapore Pte Ltd
6 Temasek Boulevard #18-01
Suntec Tower Four
Singapore 038986

Dear Sir/Madam,

**RE: ACCIDENT ON 07/06/2018 ALONG ALEXANDRA RD & DEPOT RD INVOLVING
YOUR INSURED'S VEHICLE FBG 1271 S AND OUR CLIENT'S VEHICLE SKB 1189 S**

We are assisting our client, Mr Chew Yoong Keong, the owner of vehicle no. SKB 1189 S in the above matter.

Please note that the above accident was caused by the driver of vehicle no. FBG 1271 S which was insured with you at the time of accident. As a result of the accident, our client's vehicle has suffered damages and was put to loss and expenses as follows:


- | | |
|---|------------|
| 1) Repair cost | S\$ 550.00 |
| 2) Loss of use for
2 days @S\$70 per day | 140.00 |
| 3) Search fee | 2.00 |

TOTAL	<u>S\$ 692.00</u>
-------	-------------------

We enclosed herewith all relevant documents for your perusal.

Hope to receive your reply soonest possible.

Yours faithfully


SOC LEON MOTOR WORKS

Encl. Final repair bill/Letter of Authority
Cert of Insurance
Accident Statement/Search letter

TO WHOM IT MAY CONCERN

LETTER OF AUTHORITY

Accident on 7/6/18 at Intersection between Alexandra Rd & Depot Rd involving SKB 1189S & FBG 1271S

I/We, Chew Young Keong
NRIC No. S6932387A of 14 Thomson Heights (S) 574842

owner of Motor Vehicle
Registration No. SKB 1189S insured by MSIG Insurance
under Policy No. D29025397 CMY do hereby
authorise M/S. SOC LEON MOTOR WORKS, 1 Kaki Bukit Ave 6 Blk D 01-91, Singapore
417883 as my/our authorised representative to write, negotiate & settle claim on
my/our behalf in my/our claim against the owner/or driver of Motor Vehicle
Registration No. FBG 1271S in respect of the abovementioned accident.

I/We also hereby authorise that the agreed settlement sum be made in favour of my/our
representative, M/S. SOC LEON MOTOR WORKS and that the said payment be
forwarded to them as full and final discharge of my/our claim.

I/We hereby exonerate the FWD Singapore Pte Ltd
and/or their insured and/or driver of
Vehicle No. FBG 1271S from any liability after payment of
any claim to my/our authorised representative M/S. SOC LEON MOTOR WORKS.

Dated: 27-June 2018

Signature X Pam
(Co's Stamp if necessary)

RELEASE

Claim Reference:	1201800008186
Surveyor's Reference:	CC4/FWD18011704/Ueb3
TP Reference:	SKB 11895

We, SOC LEON MOTOR WORKS ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle SKB 11895 ("Vehicle") to accept the sum of \$672.00, being the amount claimed for \$550.00 (repair costs), \$120.00 (loss of ~~rental~~/use), \$ - (loss of income), \$2.00 (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on 07/06/2018 (date of accident) at / along INTERSECTION BETWEEN ALEXANDRA RD & DEPOT RD (location) involving vehicle no/s. SKB 11895 and FBG 12715.

This is pursuant to the inspection conducted on 27/06/2018 (date) at the Workshop.


We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of FBG 12715 be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them. .

Dated this ____ day of _____ 2018

CLAIMANT



[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"

12 DEC 2018



CKS

[FWD's appointed surveyor with Co. Stamp]

For and on behalf of FWD Singapore Pte. Ltd.

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE

速 良 摩 哆
SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒杆噴漆
代理保險：車禍
賠償及買賣汽車

MR CHEW YOONG KEONG

DATE: 25/07/2018

DOA: 07/06/2018

INVOICE NO : 8028

REPAIR COST FOR VEHICLE NO. SKB 1189 S (HYUNDAI ELANTRA)

LUMP SUM AT COST OF REPAIRS \$ 550.00

速 良 摩 哆
SOC LEON MOTOR WORKS

.....
Authorized Signature



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-090815
Date of Request: 13/06/2018

Your Ref No: Online Purchase

Soc Leon Motor Works
1 Kaki Bukit Ave 6, #01-91
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 13/06/2018
Enquiry By IRENE LEONG SUM PHENG
TP Vehicle No. FBG1271S
Accident Date 07/06/2018

SKB 1189 S

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
FBG1271S	FWD Singapore Pte. Ltd.	11/10/2017-10/10/2018	6727 5700

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-090815

Date of Request: 13/06/2018

Your Ref No: Online Purchase

Soc Leon Motor Works
1 Kaki Bukit Ave 6, #01-91
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 13/06/2018
Enquiry By IRENE LEONG SUM PHENG
TP Vehicle No. FBG1271S
Accident Date 07/06/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jun 2018 Edit Reg		27 Jun 2018 00:00 Edit Adj Rpt	S\$550.00 Edit Estimates	S\$550.00 View Rpt		Pending for Survey Report Cancel Case



Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Fion Tan Rui Lin , ID: S9217087Z								
Main Claimant:	CHEW YOONG KEONG , ID: S6932387A								
Vehicle Reg. No.:	SKB1189S	Date of Loss:	07/06/2018 17:00 - :59 [80 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201800008186	Policy/Cover Note No.:	PNMC2017-00001298 (Comprehensive)						
Vehicle Reg. No. (Insured):	FBG1271S	Policy No. (Claimant):	D29025397QMY						
		Excess:							
Repairer:	Soc Leon Motor Works (Kaki Bukit) 1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 7858								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 06/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• FWD_SG (03/12/2018): Alert - Adj Mandate Approved (S\$672.00) - SKB1189S - Claim Handler: Clara Li Zi ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKB1189S (1201800008186)**
[FBG1271S]

TP
CHEW YOONG KEONG
Jun 7 2018 5:00PM
[Fion Tan Rui Lin]
Soc Leon Motor Works

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/06/18 13:40	Adjuster Immediate Advice	Load HTML	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/11/18 15:36	General View	Load JPG	<input checked="" type="checkbox"/>
2	27/11/18 15:36	General View	Load JPG	<input checked="" type="checkbox"/>
3	27/11/18 15:36	General View	Load JPG	<input checked="" type="checkbox"/>
4	27/11/18 15:36	General View	Load JPG	<input checked="" type="checkbox"/>
5	27/11/18 15:36	General View	Load JPG	<input checked="" type="checkbox"/>
6	27/11/18 15:36	General View	Load JPG	<input checked="" type="checkbox"/>
7	27/11/18 15:36	General View	Load JPG	<input checked="" type="checkbox"/>
8	27/11/18 15:36	General View	Load JPG	<input checked="" type="checkbox"/>
9	27/11/18 15:36	General View	Load JPG	<input checked="" type="checkbox"/>
10	27/11/18 15:36	General View	Load JPG	<input checked="" type="checkbox"/>
11	27/11/18 15:36	General View	Load JPG	<input checked="" type="checkbox"/>
12	27/11/18 15:36	General View	Load JPG	<input checked="" type="checkbox"/>
13	27/11/18 15:36	General View	Load JPG	<input checked="" type="checkbox"/>
14	27/11/18 15:36	General View	Load JPG	<input checked="" type="checkbox"/>
15	27/11/18 15:36	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
16	27/11/18 15:36	General View	Load JPG	<input checked="" type="checkbox"/>
17	27/11/18 15:36	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
18	27/11/18 15:37	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	27/11/18 15:37	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	27/11/18 15:37	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/06/18 15:12	EMAIL FROM FWD DD 26062018	Load PDF	
2	27/06/18 15:12	TP ESTIMATE	Load PDF	
3	27/06/18 15:12	TP GIA REPORT	Load PDF	
4	28/06/18 17:49	TP ESTIMATE- MARKED	Load PDF	
5	23/07/18 11:11	FWD SENT REMINDER TO INSURED DD 23072018	Load PDF	
6	23/11/18 08:09	WORKSHOP INVOICE	Load PDF	
7	23/11/18 08:09	GIA SEARCH	Load PDF	
8	23/11/18 08:09	LOD	Load PDF	
9	14/12/18 10:28	Release Voucher	Load PDF	

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
10	14/12/18 10:28	LKK Auto Consultants Pte Ltd (HQ)			
		AUTHORISATION TO ACT FORM		Load PDF	
No	Finalized On			Thumbnail	Print
1	26/10/18 17:49	FWD Singapore Pte. Ltd. (HQ)			
		OI GIA Report		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	FBG1271S (Insd veh)	Model:	HYUNDAI ELANTRA 1.6 (A)
	SKB1189S (TP veh)		
Date of Accident:	07/06/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$		952.32
Final Repair Cost	:	\$		550.00
Loss of Use	:	\$		120.00
				2.00 days at \$60.00 per day
Rental (if any)	:	\$		0.00
				days
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		672.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Soc Leon Motor Works	:	672.00
2)		:	
3)		:	

JOANNE LEE KHANG MIN

14 Dec
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18011704/UEB3Q2

Date: 14/12/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2017-00001298

Claimant Vehicle No : SKB1189S **Insured Vehicle No :** FBG1271S

Date of Loss: 07/06/2018 Nature of Claim: TP Claim No: 1201800008186

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKB1189S**
 Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGBU331479
 Reg. Date: 21/09/2011 (Man. Year: 2011) Chassis No: KMHDH41CMCU270964
 Colour: Brown Odometer: 174825 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	452.32	401.12	51.20	11.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	300.00	200.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	952.32	701.12	251.20	26.38
Approved Total (Overridden) (S\$)		550.00		
Nett Amount (S\$)	952.32	550.00	402.32	42.25
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		672.00		

INSPECTION

Date of Assignment: 27/06/2018

Date Inspected: 27/06/2018 Inspected At:

Soc Leon Motor Works (Kaki Bukit)
 1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki
 Bukit
 Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2018)
Parts: 143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB1189S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Warped	446.40 FL	*446.40 FL
2	2		*BUMPER SIDE RETAINER	Not Necessary	84.00 FL	*- FL
3	10		*BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
					Sub Total (S\$)	565.40
					- List Item Discount on L Items 20.00/20.00% (S\$)	113.08
					Total Parts (S\$)	452.32

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR KNOCKING & REPLACING PARTS	New	200.00	100.00
2	SPRAYPAINTING	New	300.00	200.00
Gross Labour Cost (S\$)			500.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >