

Surveyor

Marcus

ASSIGNMENT (Office)

From Person

Kelvyn Ngian

of

GAP

Date/Time

27/6/18 11am

Estimated Cost

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No

SJU 3010Y

Insured

SKG 8477M

at Workshop m/s

Focus Auto

Tel:

6886 9097

of

No.1, Kaki Bukit Ave 6 #02-50

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/06/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time

12:30pm 27/6/18

Person Contacted:

Ms. Sin

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SJU 3010Y - CC4/ICR 17021894/Uwa 3s2

DOA: 11/11/2017

SKG 8477M-x

05/11/17
ASS. REC BY: M. J. ...

REF:

GA-1

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
CD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: STU 3010Y
at Workshop n/s: focus
of: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 22k
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 7 days Res: Yes or No
Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP: / 24 HRS

LTA 121P2

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time / Action / Instruction
23/7/18 costumed bol 1yrs 5mth net 4 98%
1/5 \$6900 with n/s wong
Clad. 6608.20, 48%

RECEIVED 24 JUL 2018

Date/Time, File Pass to? ☐ : Preli. Report

24/7 Typist ☒ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$) 6900/-

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee

Transportation:

Photos

Others

TOTAL

350

Veh No: STU 3010Y Yr Regn: 24/11/09
Type: CA / M.Cycle / Bus / Van / Lorry / Taxi / Prime Move.
Truck / Trailer or CA
Make: Toyota wish ope 1797
Colour: Red A/C: Insured / Std / NI / NA
Sp. Reading: PO 250 T/Radin: Insured / Std / NI / NA
Eng/No: _____
C/No: 26E200010466
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/65-R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or nexen
Front 6 mm Rear 6 mm
R/Bal. 6 mm L/Bal. 6 mm
D.O.A. 23/6/18 D.O.I. 27/6/18
Survey held at: _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Catherine Chong (LKK Auto)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Wednesday, 27 June, 2018 11:00 AM
To: SUR; Catherine Chong (LKK Auto)
Subject: RE: Re: RE: ACCIDENT INVOLVING SJU 3010 Y & SKG 8477 M ON 23/06/18 ALONG PIE TOWARDS CHANGI, NEAR TOH GUAN RD EXIT AT ABOUT 1520 HOUR
Attachments: SJU3010Y.PDF; SKG8477M.pdf

Hi team,

Please do TP survey

Thanks
Kelvyna

From: Focus Auto <focus.autopteltd@yahoo.com.sg>
Sent: Tuesday, June 26, 2018 5:41 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: [External] Re: RE: ACCIDENT INVOLVING SJU 3010 Y & SKG 8477 M ON 23/06/18 ALONG PIE TOWARDS CHANGI, NEAR TOH GUAN RD EXIT AT ABOUT 1520 HOUR

Without Prejudice

Dear Kelvyna,

Thank for reply

We choose as follow below

5) LKK Auto Consultants

Thank You

Best Regards
Ms Sin/Ms Laura

Focus Auto Pte Ltd

No. 1 Kaki Bukit Avenue 6

#02-50 AutoBay Singapore 417883

Tel: 6886 9097 Fax: 6481 9095

From: Focus Auto <focus.autopteltd@yahoo.com.sg>

Sent: Monday, June 25, 2018 5:50 PM

To: General Claims <GeneralClaims@sg.gaiq.com>

Subject: [External] ACCIDENT INVOLVING SJU 3010 Y & SKG 8477 M ON 23/06/18 ALONG PIE TOWARDS CHANGI, NEAR TOH GUAN RD EXIT AT ABOUT 1520 HOUR

Dear Officer-In-Charge,

Please send a list of surveyor name to arrange the surveyor down our workshop regarding as below.

We are instructed by our client to notify you of a road traffic accident on 23/06/18 at about 1520 hours along PIE TOWARDS CHANGI, NEAR TOH GUAN RD EXIT involving our client's SJU 3010 Y and SKG 8477M driven by your insured or your insured's authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop : FOCUS AUTO PTE LTD

Address: No.1 Kaki Bukit Ave 6
AutoBay #02-50
Singapore 417883

Telephone no. : 6886 9097

Best Regards,
Ms Sin

Focus Auto Pte Ltd

No. 1 Kaki Bukit Avenue 6

#02-50 AutoBay Singapore 417883

Tel: 6886 9097 Fax: 6481 9095

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2354Z

Vehicle Details

Vehicle No.: SJU3010Y
Vehicle to be Exported: No
Intended De-registration Date: 25 Jun 2018
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8X A
Primary Colour: Red
Manufacturing Year: 2009
Engine No.: 2ZR0430063
Chassis No.: ZGE200010466
Maximum Power Output: 106.0 kW (142 bhp)
Open Market Value: \$21,562.00
Original Registration Date: 26 Nov 2009
First Registration Date: 26 Nov 2009
Transfer Count: 1
Actual ARF Paid: \$21,562.00

OPC Cash Rebate Details

OPC Cash Rebate Eligibility: No
OPC Cash Rebate Eligibility Expiry Date: -
OPC Cash Rebate Amount: -

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Nov 2019
PARF Rebate Amount: \$11,859.00

Intended COE Rebate Details

COE Expiry Date: 25 Nov 2019
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$2,830.00
COE Rebate Amount: \$324.00
Total Rebate Amount: \$12,183.00

The information contained herein is correct as at 25 Jun 2018

OK

Sharing
&
Serving

COME VOLUNTEER WITH US!

If you are 40 years old and above and are able to spend half a day every month to contribute your talents and skills in many meaningful ways, we want you!



toyota wish opc

Price Range

Depreciation

Year Reg

Vehicle Type



Submit

Advanced Search

Home » Used Cars » YS Auto Pte Ltd » Toyota Wish 2.0A (OPC)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Trim your debts and enjoy
interest rate
from as low
as 4.70% p.a.
(EIR: 8.48% p.a.)
Maybank Debt Consolidation Plan

FIND OUT MORE

Terms and Conditions apply.



Maybank

Compare

Toyota Wish 2.0A (OPC)

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price [Share](#) **\$26,800**

Depreciation [Email](#) **\$10,740 /yr**

OPC Scheme Revised OPC scheme (use full day on Sat)

Reg Date 17-Dec-2009
(1yr 5mths 19days COE left)

Manufactured 2009**Mileage** -**Transmission** Auto**Engine Cap** 1,987 cc**Road Tax** \$698 /yr

Power 106.0 kW (142 bhp)
[View specs of the Toyota Wish \(2009-2018\)](#)

Curb Weight 1,380 kg

Features 2.0L 16 Valves Dual VVT-i DOHC Engine, CVT Automatic With Steptronic, Digital Climate Aircon Controls, ABS, SRS Airbags, Knockdown Rear Seats.

Accessories Leather Seats, Sports Rims, Original Touch Screen DVD Player, Reverse Camera And Sensors, Retractable Side Mirrors, Solar Film, Fog Lights.

Description One Owner, Low Depreciation, Original Paint/Accident Free. Agent Unit, Facelift Version, Cheapest In Market, Well Maintained. Great Leather Interior, Spacious Inner Cabin, Most Popular MPV Seen On The Road. Smooth Transmission, Quiet Undercarriage. Conversion Fee To Normal Car Is \$3,164. This Will Be One Of The Best Unit In Town. Flexible Finance Package Available, Grab Owner Are Welcome.

COE \$1,002**OMV** \$22,003**ARF** \$22,003**Dereg Value** \$12,249 as of today (change)**No. of Owners** 1**Type of Veh** MPV**Category** OPC Car, PARF Car**Availability** Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 13-Jun-2018 | Last Updated on: 22-Jun-2018

Tags: Toyota Wish, 2009 Toyota Wish, Toyota, Wish, Used Toyota



Seller Information

Company YS Auto Pte Ltd
* dealer's pricelist
* 38 vehs sold | 33 vehs available

Address 210 Turf Club Road Lot C2
[Search cars nearby this location](#)

Location Car Mall @ The Grandstand

Office No 64669792

Contact Person(s) Mr Teo 97433225
Steven 96791011
Mr Ng Julian 96791611
Vicky 82469627

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2354Z

Vehicle Details

Vehicle No.: SJU3010Y
Vehicle to be Exported: No
Intended De-registration Date: 27 Jun 2018
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8X A
Primary Colour: Red
Manufacturing Year: 2009
Engine No.: 2ZR0430063
Chassis No.: ZGE200010466
Maximum Power Output: 106.0 kW (142 bhp)
Open Market Value: \$21,562.00
Original Registration Date: 26 Nov 2009
First Registration Date: 26 Nov 2009
Transfer Count: 1
Actual ARF Paid: \$21,562.00 10781

OPC Cash Rebate Details

OPC Cash Rebate Eligibility: No
OPC Cash Rebate Eligibility Expiry Date: -
OPC Cash Rebate Amount: -

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Nov 2019
PARF Rebate Amount: \$11,859.00

Intended COE Rebate Details

COE Expiry Date: 25 Nov 2019
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$2,830.00
COE Rebate Amount: \$323.00
Total Rebate Amount: \$12,182.00

The information contained herein is correct as at 27 Jun 2018

MSME18081940 / SME Motor Pte Ltd - Koko Bukit
 ENTRY DATE & TIME: 25/06/2018 17:54
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 25/06/2018 17:54
 Date Of Accident 23/06/2018 15:20
 Exact Location Of Accident PIE TWDS CHANGI NEAR TOH GUAN RD EXIT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJU3010Y
Insured/Policyholder
 Name Of Registered Owner IRWAN BIN ISNIN
 NRIC No S7832354Z
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-92397895
 Alternative Phone No OFFICE-92397895

Vehicle Particulars

Manufacturer TOYOTA
 Model WISH
 Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number GA073485
 Cover Note Number

Driver

Name of Driver IRWAN BIN ISNIN
 NRIC No S7832354Z
 Date Of Birth 29/10/1978
 Occupation INDOOR
 Date Of Driving Pass 01/03/2005
 Driving Experience 13 YEARS AND 3 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-92397895
 Fax Number
 Contact Number OFFICE-92397895
 EMail Address NOEMAIL

Address 1 JURONG EAST ST 32 #04-02
 Postcode 609477
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 5

Passenger 1
 NAME: : IRSALINA BINTE IRWAN
 GENDER: : FEMALE

Passenger 2
 NAME: : NORWANI BINTE SHEDEK
 GENDER: : FEMALE

Passenger 3
 NAME: : HARITH DANISH BIN IRWAN
 GENDER: : MALE

Passenger 4
 NAME: : HAZIQ DANIAL BIN RIWAN
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name JURONG WEST NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-2689999 - FAX NO: 62672438
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT: T/20180623/2158.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKG8477M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

VEHICLE B

PRIVATE CAR

TEO LIAP HUAT

98455311

DETAILS OF INJURED PERSON 1

Name

HARITH DANISH BIN IRWAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJU3010Y

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

HAZIQ DANIAL BIN RIWAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJU3010Y

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 3

Name

IRWAN BIN ISNIN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJU3010Y

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 4

Name

IRSALINA BTE IRWAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJU3010Y

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 5

Name	NORWANI BINTE SHEDEK
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJU3010Y
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan #2 Pg. 1

SKETCH PLAN

PIE
toward
Chang
NaurToh
Guah Exit



veh A: SJU3010Y

veh B: SKG 8477M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report No. T/20180623/2158

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

25/6/16 4.20pm
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

LETTER OF UNDERTAKING

I/We, Iman Bio Smir the owner of vehicle no. 804 3010

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop. Focus Auto Pte. Ltd

Signed and Acknowledge by:

Nric no. and signature of policyholder

Company Stamp

Date

25/6/18



SINGAPORE
POLICE FORCE



T/20180623/2158

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 5

Report No. T/20180623/2158

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/06/2018 23:22	Vide Report No.:	Station Diary No.: 186
--	------------------	---------------------------

Informant's Particulars

Name of Informant: IRWAN BIN ISNIN			Address: 1 JURONG EAST STREET 32 #04-02 SINGAPORE 609477		
ID Type / ID No.: NRIC NO / S7832354Z			Contact No.: Home/Office: Mobile: 92397895		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 39	Date of Birth: 29/10/1978	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: SYSTEM ENGINEER			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 23/06/2018 15:20	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY				
PIE TOWARDS CHANGI, NEAR TOH GUAN RD EXIT				
Weather: Cloudy		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJU3010Y	Car	TOYOTA	WISH 1.8X A	Red	Slightly Damaged	5
SKG8477M	Car				Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJU3010Y	AXA INSURANCE SINGAPORE PTE LTD	GA073485	14/03/2018	25/11/2018

Sketch Plan #5 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180623/2158

2 of 5

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20180623/2158

CONTINUATION OF REPORT

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA

Passenger

Name IRIS ALISHA BIN IRWAN

ID No. T1702584D

Related Vehicle SJU3010Y (Car)

Contact No. NIL

Hospital/Clinic NIL

Class of Driving
Licence &
Expiry Date
Class: NIL
Date of Expiry: NIL

Date Treatment NIL

Date Discharge NIL

No. of Days granted Medical Leave NIL

Degree of Injury NIL

Passenger

Name HARITH DANISH

ID No. T0835512B

Related Vehicle SJU3010Y (Car)

Contact No. NIL

Hospital/Clinic NG TENG FONG GENERAL HOSPITAL

Class of Driving
Licence &
Expiry Date
Class: NIL
Date of Expiry: NIL

Date Treatment 23/06/2018

Date Discharge 23/06/2018

No. of Days granted Medical Leave 03

Degree of Injury Slight

Passenger

Name HAZIQ DANIAL BIN IRWAN

ID No. T1130664G

Related Vehicle SJU3010Y (Car)

Contact No. NIL

Hospital/Clinic NG TENG FONG GENERAL HOSPITAL

Class of Driving
Licence &
Expiry Date
Class: NIL
Date of Expiry: NIL

Date Treatment 23/06/2018

Date Discharge 23/06/2018

No. of Days granted Medical Leave 03

Degree of Injury Slight

Sketch Plan #6 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180623/2158

Police Station Of Origin:

Jurong West N.P.C

700 Corporation Road SINGAPORE 649818

Tel No: 1800-2689999

3 of 5

Report No: T/20180623/2158

CONTINUATION OF REPORT

Driver			
Name	IRWAN BIN ISNIN	ID No.	S7832354Z
Related Vehicle	SJU3010Y (Car)	Contact No.	92397895
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B, 2A, 2, 3 Date of Expiry: NIL
Date Treatment	23/06/2018	Date Discharge	23/06/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Passenger			
Name	IRSALINA BTE IRWAN	ID No.	T0700104A
Related Vehicle	SJU3010Y (Car)	Contact No.	NIL
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	23/06/2018	Date Discharge	23/06/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Passenger			
Name	NORWANI BINTE SHEDEK	ID No.	S8403886E
Related Vehicle	SJU3010Y (Car)	Contact No.	NIL
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	23/06/2018	Date Discharge	23/06/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	TEO LIAP HUAT	ID No.	S0404603Z
Related Vehicle	SKG8477M (Car)	Contact No.	98455311
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180623/2158

4 of 5

Police Station Of Origin:

Jurong West N.P.C

700 Corporation Road SINGAPORE 649818

Tel No: 1800-2689999

Report No. T/20180623/2158

CONTINUATION OF REPORT

Brief Details.

On 23/06/2018 at about 1520hrs, I was driving my vehicle SJU3010Y on the middle lane along PIE towards Changi. Nearing Toh Guan Rd exit, there was another vehicle which cut in from the right lane into the lane in front of mine. After changing to my lane, the vehicle braked and came to a stop. As such, I also applied the brakes to stop my vehicle. Suddenly, another vehicle SKG8477M which was travelling behind mine, collided into the rear of my vehicle.

All my passengers including myself suffered some pain on our backs. We went to Ng Teng Fong General Hospital and were issued with 03 days MC. No Traffic Police or Ambulance were at scene. There is an in-car camera in my vehicle. The collision resulted in the rear bumper of my vehicle badly dented in.

Accident Sketch Plan Pg. 1

**SINGAPORE
POLICE FORCE**

T/20180623/2158

Police Station Of Origin:
Jurong West N.P.C.
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

5 of 5

Report No. T/20180623/2158

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J/

Staff Sgt IQBAL PRATAMA PUTRA BIN AZMAN

Signature Of Informant:

Signature Of Interpreter:
Not applicableDate/Time:
23/06/2018 23:22

Officer In Charge Of Case:

TP / AEIT /
Sgt 2 YEO KIA HUAT
Contact No.: 65476325

Classification Of Case:

Authentication Stamp
NP168

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: focus.autopte ltd@yahoo.com.sg

GST: 201004495R RCB NO: 201004495R

not Admitted
able
1/5 @ 6900.
27/6/18
2 hours after up-
74.

M/S : GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVENUE,
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Estimate No: EST0000648
Date: 26 Jun 2018
Policy No: GA073485
Veh Reg No: SJU3010Y
Make/Model: TOYOTA WISH
Chassis No: ZGE200010466
Engine No: 2ZR0430063
Reg. Date: 26-11-2009

p-7201.1
540082

ATTN: Motor Claim Department
Your Ref No: SJU3010Y
Claim Type: Third Party
Accident Date: 23-06-2018
TP Veh Reg No: SKG8477M

Estimate Repair Cost to Vehicle No :SJU3010Y

PAGE:1/2

Description	U/Price	Quantity	List Price SS	Amount SS
TOYOTA WISH 1.8				
List Price				
1 Rear Boot	1,295.00	1 PC	1,295.00	✓
2 Rear Boot Top Hinge	46.2000	2 PC	92.40	α
3 Rear Boot Shock Absorber	198.4000	2 PC	396.80	α
4 Rear Boot Reflector	320.0000	2 PC	640.00	1PC
5 Rear Boot Emblem	60.2000	1 PC	60.20	✓
6 Rear Boot Centre Logo	80.0000	1 PC	80.00	✓
7 Rear Boot Centre Moulding	326.4000	1 PC	326.40	✓
8 Rear Boot Inner Cover Board	365.0000	1 PC	365.00	✓
9 Rear Floor Panel	864.2000	1 PC	864.20	X
10 Rear Tail Lamp	245.0000	2 PC	490.00	✓
11 Rear Tail Lamp Clipse	8.5000	2 PC	17.00	X
12 Rear End Panel Inner	198.0000	1 PC	198.00	✓
13 Rear End Panel Outer	485.0000	1 PC	485.00	✓
14 Rear End Panel Top Garnish	305.0000	1 PC	305.00	✓
15 Rear Bumper	535.0000	1 PC	535.00	✓
16 Rear Bumper Side Retainer	85.0000	2 PC	170.00	✓
17 Rear Bumper Corner Bracket	110.0000	2 PC	220.00	1PC
18 Rear Bumper Bracket	85.0000	2 PC	170.00	1PC
19 Rear Windscreen Seal	150.0000	1 SET	150.00	✓
20 Rear Exhaust Silencer	995.0000	1 PC	995.00	✓
21 Rear Exhaust Rubber	60.0000	2 PC	120.00	✓
22 Rear Floor Panel Inner Garnish	285.0000	1 PC	285.00	✓
23 Rear Fender Inner Side Garnish	656.2000	1 PC	656.20	✓
24 Rear Bumper Reflector RH	69.7000	1 PC	69.70	✓
25 Rear Compartment Top Cover	581.6000	1 PC	581.60	X
26 Rear Fender RH	816.9000	1 PC	816.90	X
27 Rear Fender Inner Side Garnish	566.9000	1 PC	566.90	α
28 Rear Fender Air duct RH	156.9000	1 PC	156.90	X
29 Rear Exhaust Top Cover	127.2000	1 PC	127.20	✓
30 Rear Compartment Top Cover Support	189.4000	1 PC	189.40	X
31 Rear Boot Inner Pull Handle Cover	298.2000	1 PC	298.20	✓

(257)

68.10

128.10

7201.1

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: focus.autopte@focusauto.com.sg

GST:201004495R RCB NO:201004495R

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Play damaged part(s) during resurvey
- Prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate No: **EST0000648**

Date: 26 Jun 2018

Policy No: GA073485

Veh Reg No: **SJU3010Y**

Make/Model: TOYOTA WISH

Chassis No: ZGE200010466

Engine No: 2ZR0430063

Reg. Date: 26-11-2009

M/S : GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVENUE,
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

ATTN: Motor Claim Department

Your Ref No: SJU3010Y

Claim Type: Third Party

Accident Date: 23-06-2018

TP Veh Reg No: SKG8477M

Estimate Repair Cost to Vehicle No :SJU3010Y

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			11,723.00	
		Less 25%	2,930.75	8,792.25
Special Net				
32 Rear Floor Panel Top Insulator <i>ner</i>	150.0000	1 PC	150.00	1005.2
33 Rear Windscreen <i>Gum Sealant ner</i>	120.0000	1 PC	120.00	40
34 Rear Number Plate <i>ner</i>	50.0000	1 PC	50.00	40
35 Rear Number Plate Seal Pin <i>ner</i>	16.0000	1 PC	16.00	✓
36 Rear Bumper Sensor <i>shard</i>	300.0000	1 SET	300.00	200
37 Rear Reverse Camera <i>11</i>	450.0000	1 PC	450.00	X
			1,086.00	1,086.00
Labour				
38 Towing	50.0000	1 PC	50.00	✓
39 Panel Beating	1,600.000	1 PC	1,600.00	1200
40 Check Wiring	80.0000	1 PC	80.00	30
41 Rust Proofing	80.0000	1 PC	80.00	✓
42 To Remove & Refit Rear Windscreen	160.0000	1 PC	160.00	120
43 To Remove & Refit Rear Bumper Sensor And Camera	220.0000	1 PC	220.00	50
44 To Remove & Refit Rear Seat And Up-holestery	160.0000	1 PC	160.00	80
45 To Remove & Replace Exhaust Silenser	80.0000	1 PC	80.00	60
46 To Spray Painting	1,200.000	1 PC	1,200.00	1180
			3,630.00	3,630.00
			Total	SS 13,508.25

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND FIVE HUNDRED AND EIGHT AND CENTS TWENTY SEVEN ONLY

3240

For FOCUS AUTO PTE LTD
Focus Auto Pte Ltd
No 1 Kaki Bukit Ave 6 Auto Bay
#02-50 Singapore 417883
AUTHORISED SIGNATURE

[Signature]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18011724/Utd3n2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 01-08-2018



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKG 8477M	Veh. Inspected	SJU 3010Y
Policy No.		Coverage (\$)	0.00
Claim No.	SKG8477M	Excess (\$)	0.00
Assign From	KELVYNA NGIAN	Assign Date	27/06/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH OPC (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	ZGE200010466	Colour	RED
Odometer	80250	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R15	NEXEN	6 mm
L/H Front Tyre	205/65 R15	NEXEN	6 mm
R/H Rear Tyre	205/65 R15	NEXEN	6 mm
L/H Rear Tyre	205/65 R15	NEXEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/06/2018	Inspection Date	27/06/2018
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 3010Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT	BADLY DENTED	1,295.00	1,295.00
2	REAR BOOT TOP HINGE @\$46.20	NOT NECESSARY	92.40	-
2	REAR BOOT SHOCK ABSORBER @\$198.40	NOT NECESSARY	396.80	-
2	REAR BOOT REFLECTORS @\$320.00	O/S SCRATCHED	640.00	320.00
1	REAR BOOT EMBLEM	NECESSARY	60.20	60.20
1	REAR BOOT CENTRE LOGO	NECESSARY	80.00	68.10
1	REAR BOOT CENTRE MOULDING	CRACKED	326.40	326.40
1	REAR BOOT INNER COVER BOARD	CRACKED	365.00	365.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	864.20	-
2	REAR TAIL LAMPS @\$245.00	CRACKED	490.00	490.00
2	REAR TAIL LAMP CLIPSE @\$8.50	NOT NECESSARY	17.00	-
1	REAR END PANEL INNER	BADLY DENTED	198.00	198.00
1	REAR END PANEL OUTER	BADLY DENTED	485.00	485.00
1	REAR END PANEL TOP GARNISH	TWISTED	305.00	305.00
1	REAR BUMPER	DISTORTED	535.00	535.00
2	REAR BUMPER SIDE RETAINER @\$85.00	BENT	170.00	132.20
2	REAR BUMPER CORNER BRACKET @\$110.00	O/S DENTED	220.00	110.00
2	REAR BUMPER BRACKET @\$85.00	O/S DENTED	170.00	85.00
1	SET REAR WINDSCREEN SEAL	NECESSARY	150.00	128.10
1	REAR EXHAUST SILENCER	BENT / TWISTED	995.00	995.00
2	REAR EXHAUST RUBBER @\$60.00	NECESSARY	120.00	120.00
1	REAR FLOOR PANEL INNER GARNISH TOP	CRACKED	285.00	285.00
1	REAR FENDER INNER SIDE GARNISH RH	CRACKED	656.20	656.20
1	REAR BUMPER REFLECTOR RH	CRACKED	69.70	69.70
1	REAR COMPARTMENT TOP COVER	NOT NECESSARY	581.60	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	816.90	-
1	REAR FENDER INNER SIDE GARNISH LH	NOT NECESSARY	566.90	-
1	REAR FENDER AIR DUCT RH	NOT NECESSARY	156.90	-
1	REAR EXHAUST TOP COVER	BENT	127.20	127.20
1	REAR COMPARTMENT TOP COVER SUPPORT	NOT NECESSARY	189.40	-
1	REAR BOOT INNER PULL HANDLE COVER	MISSING	298.20	45.00

Report Ref No. CS/GAI18011724/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,930.75	-1,800.28
			8,792.25	5,400.82
	<u>SPECIAL NETT ITEMS</u>			
1	REAR FLOOR PANEL TOP INSULATOR (SN)	NECESSARY	150.00	100.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	120.00	40.00
1	REAR NUMBER PLATE (SN)	BENT	50.00	40.00
1	REAR NUMBER PLATE SEAL PIN (SN)	NECESSARY	16.00	16.00
1	SET REAR BUMPER SENSOR (SN)	SHORTED	300.00	200.00
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	450.00	-
			1,086.00	396.00
	<u>LABOUR</u>			
	TOWING.		50.00	50.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL AND REAR FENDER RH.		1,600.00	1,200.00
	CHECK WIRING.		80.00	30.00
	RUST PROOFING.		80.00	80.00
	TO REMOVE & REFIT REAR WINDSCREEN.		160.00	120.00
	TO REMOVE & REFIT REAR BUMPER SENSOR AND CAMERA.		220.00	50.00
	TO REMOVE & REFIT REAR SEAT AND UP-HOLESTERY.		160.00	80.00
	TO REMOVE & REPLACE EXHAUST SILENCER.		80.00	60.00
	TO SPRAY PAINTING.		1,200.00	1,180.00
			3,630.00	2,850.00
	GRAND TOTAL		13,508.25	8,646.82
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,900.00

Report Ref No. CS/GAI18011724/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.