

22/03/2002

ASS. REC. BY:

REF: CS/FCI18011736/Ktd3dz

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): cws May chua

of FCI

Date/Time: 27/6/18 @ 2.42pm

Estimated Cost:

Bill to:

OD ~~TP~~ WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GR1241L

Insured:

SHC 8110C

at Workshop m/s

Chew Geon Motor

Tel:

64841626

of Blk 10, AMK Ind. Park 2A Ave 5 #01-15

Policy No:

Claim No: D18001993 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 24/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up

28/6/2018

H.O.D. Endorsement:

Date/Time: 1.17pm @ 27/6/18

Person Contacted:

Grace

Vehicle ~~IN~~ OUT

Date/Time

Action/Instruction (✓) Estimate

GR1241L - X

SHC 8110C - CS/FCI13009895/Kyldl

DOA: 31/05/2013

6/8 11.5pm @ 2300 email &amp; confirm (Red: 2164.10; 48%)

(08/1/2010)  
Surveyor


REF: FCL

ASSIGNMENT

From: \_\_\_\_\_ Date: 28062018  
Estimated Cost: \_\_\_\_\_  
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: GR 1241L  
at Workshop m/s Chew Groom  
of B11c 10 AMK Ind Park 2A #01-15  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 16k  
IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
Est. Repairs: 04 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS 'WP'  
8/19  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT



Veh No: GR 1241L Yr Regn: 09 PP  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: NIS Astra c.c 2853  
Colour: Silver A/C: Insured / Std / NI / NA  
Sp.Reading: 478359 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: JNISIF41F2380001923  
Gen. Cond: ☒ Good / Fair / Poor / Burnt  
Steering: ☒ In order / Jammed / Leaked / Burnt or  
Brake: ☒ In order / Jammed / Leaked / Burnt or  
Modi: ☒ Nil / S/Rim / STD A/Rim or  
Tyre Size: F: GT 185R14X8  
R: Firestone 155R12X8(D)  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
R/Bal. 8 mm R/Bal. 11 mm  
L/Bal. 8 mm L/Bal. 11 mm  
D.O.A. 24/6/18 D.O.I. 28/6/18  
Survey held at \_\_\_\_\_  
Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
28/6	File pass to Customer
	MV: 16k
	LTA: 5097
	NV: 10923
	RECEIVED 07 SEP 2010

Date/Time, File Pass to? ☐ : Preli. Report  
1) 1/9 Typst ☒ : Final Report  
Date/Time, File Return to? \_\_\_\_\_  
2) \_\_\_\_\_  
Report Format : TP  
Lump Sum / I.B.I: (\$ 2300 )  
Days Of Repair: 4  
Resurvey No. of Trip: 1  
Add Fee: ☐ : Site Insp (\$ )  
☐ : Interview (\$ )  
☐ : Tech. Invs (\$ )  
☐ : Weekend (\$ )  
Survey Fee: 135  
Transportation: 50  
S + RS, SI: 50  
Photos: 16  
Others: \_\_\_\_\_  
TOTAL: 251



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18011736/Ktd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 27-06-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8110C	Veh. Inspected	GR 1241L
Policy No.		Coverage (\$)	0.00
Claim No.	D18004993MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	27/06/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	24/06/2018	Inspection Date	28/06/2018
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004993MFSH

Date: 5/7/2018

Our Ref: CS/FCI18011736/Ktd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. GR 1241L**

Please be informed that we had conducted the inspection of the abovementioned vehicle 3/7/2018 at the premises of M/s Chew Goon Motor and have the following to report: -

Workshop Estimate Amount	: S\$ 4,464.10
Revised Estimate Amount	: S\$ 2,890.30
"Check" Items Amount	: S\$ -
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the  
Rear portion.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

Date	26-06-2018	Our Ref No. D18004993MFSH
Accident Date	24-06-2018	Claim Type. Third Party
Insured Vehicle	SHC8110C	Third Party Vehicle. GR1241L
Survey Location	BLK 10, ANG MO KIO INDUSTRIAL PARK 2A AVE 5 #01-15,16,17 & #03-05AMK AUTOPOINT	
Contact Person.	GRACE	
Contact No.	64841626/ 0	Fax No. 64840465
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	CHEW GOON MOTOR	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Thursday, 5 July 2018 5:17 PM  
**To:** Admin-D (LKKAUTO); 'Claim Workflow System'; assignments  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18004993MFSH/1  
**Attachments:** PRELI ADVISED GR 1241L.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GR 1241L**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 27 June 2018 4:17 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18004993MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Wednesday, 27 June 2018 2:42 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [MAYCHUA@MSFIRSTCAPITAL.COM.SG](mailto:MAYCHUA@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18004993MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/06/2018 13:19
Date Of Accident	24/06/2018 10:40
Exact Location Of Accident	BEDOK NORTH AVE 3 TOWARDS TAMPINES
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GR1241L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WINTEX ENGINEERING COMPANY
Co Reg No	29376400W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64819637

### Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	0088481751-14
Cover Note Number	

### Driver

Name of Driver	LEE HOE HENG
NRIC No	S1842773G
Date Of Birth	07/04/1956
Occupation	OUTDOOR
Date Of Driving Pass	18/10/1980
Driving Experience	37 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96615973
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 914 TAMPINES STREET 91 #07-39
Postcode	520914
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LAU BOON HOENG
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS SLOWLY MOVE FORWARD AS TRAFFIC LIGHT TURN GREEN. SUDDENLY VEHICLE B (SHC8110C) HIT ONTO MY LORRY (GR1241L) BEHIND.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8110C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	WONG YEW SENG
NRIC/Passport Number	S1105739Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

CHIEF ENGINEERING COMPANY  
100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was slowly move forward as traffic light turn green, suddenly  
 Van R (STE 8110C) hit onto my Lorry (GR 1241L) behind

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S1842773G

Name  
LEE HOE HENG

李华兴

Race  
CHINESE

Date of Birth  
07-04-1956

Sex  
M

Country of Birth  
SINGAPORE

S1842773G

REPUBLIC OF SINGAPORE DRIVING LICENCE

S1842773G

LEE HOE HENG

Birth Date: 07 Apr 1956

Issue Date: 21 Dec 2011

002030313K

1512483

NRIC No. S1842773G

Blood Group  
O+

Date of issue  
15-12-1993

Address  
APT BLK 914 TAMPINES STREET 91 #07-39  
SINGAPORE 520914

NRIC No. S1842773G

Date: 16-09-1999

No. 9090256

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(IES)

EFFECTIVE DATE

Class 3 Motor Cars  $\leq$  3000kg with  $\leq$  7 passengers, exclusive of the driver; and other motor vehicles  $\leq$  2500kg 18 Oct 1990

Licence No: S1842773G

NP 428A

## Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number :** 0088481751-14

**Cover :** Third Party

- |  |                              |
|--|------------------------------|
| 1. Index mark and Registration Number of Vehicle   | : <b>GR1241L</b>             |
| Chassis Number   | : NOT KNOW                   |
| 2. Name of Policyholder  | : WINTEX ENGINEERING COMPANY |
| 3. Effective Date of Insurance   | : 15 Sep 2017                |
| 4. Expiry Date of Insurance  | : 14 Sep 2018                |
| 5. Persons or Classes of Persons entitled to drive#  |                              |
| (a) The Policyholder.  |                              |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission.<br>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. |                              |
| 6. Limitations as to Use#  |                              |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.  |                              |
| (b) Use for the carriage of passengers or goods in connection with the Policyholder's business.  |                              |

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
INSURE WITH COE	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : COMMERCIAL AGENCY PTE LTD (00000614425)

Date of Issue : 14 Sep 2017 11:14 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

\_\_\_\_\_  
Authorised Officer



\_\_\_\_\_  
Chief Executive

[> Back to OneMotoring](#)

## Enquire Transfer Fee

Vehicle Details

Vehicle No. :	GR1241L		
Vehicle Type :	B31 - Goods (Open) Lorry (Metal Body)/Pickup		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	NISSAN		
Vehicle Model :	CABSTAR		
Chassis No. :	JN1SF4F23Z0001923		
Propellant :	Diesel		
Engine No. :	QD32086878		
Engine Capacity :	3153 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	3350 kg		
Unladen Weight :	1500 kg		
Year Of Manufacture :	1999		
Original Registration Date :	15 Sep 1999		
Lifespan Expiry Date :	14 Sep 2019		
COE Category :	C - Goods Vehicle & Bus		
PQP Paid :	\$21,466.00		
COE Expiry Date :	31 Aug 2019		
Road Tax Expiry Date :	14 Sep 2018		
Inspection Due Date :	14 Sep 2018		
Intended Transfer Date :	10 Sep 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 14 Sep 2018. You may renew the road tax from 15 Jun 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 14 Sep 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 15 Sep 2018 to 14 Mar 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	24.00	-	24.00
Total Amount Payable :			49.00
Message			
This vehicle has a road tax Over Payment of \$57.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle			

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Business
Owner ID:	6400W

**Vehicle Details**

Vehicle No.:	GR1241L
Vehicle to be Exported:	No
Intended De-registration Date:	25 Jun 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR
Primary Colour:	Silver
Manufacturing Year:	1999
Engine No.:	QD32086878
Chassis No.:	JN1SF4F23Z0001923
Maximum Power Output:	-
Open Market Value:	\$20,491.00
Original Registration Date:	15 Sep 1999
First Registration Date:	15 Sep 1999
Transfer Count:	0
Actual ARF Paid:	\$1,025.00

**Intended PARF Rebate Details**

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

**Intended COE Rebate Details**

COE Expiry Date:	31 Aug 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$21,466.00
COE Rebate Amount:	\$5,077.00
<b>Total Rebate Amount:</b>	<b>\$5,077.00</b>

**Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 25 Jun 2018

OK

# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

*Not Noted*  
*11 Lmp @ 2300h*  
*Resurvey After Paint*  
*Today*

To: First Capital Insurance Limited  
  
  
**Accident Date : 24.06.2018**

Policy No: \_\_\_\_\_  
Date: 26.06.2018

Third Party

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
<b>Estimate Cost of Repair to "Nissan Cabstar" Reg. No. GR1241L Claiming Against Your Insured Veh. No. SHC8110C</b>			
2pcs	Taillamps Assy	272.00	544.00 N ✓
1pc	Taillamp Bracket LH		136.00 N ✓
1pc	Rear Number Bracket		195.00 N X
1pc	Tailgate		1,520.00 N ✓
1pc	Tailgate Sticker " Nissan "		109.00 N ✓
1pc	Tailgate Lower Square Stopper LH		13.00 N ✓
1pc	Rear End Panel Sticker " Nissan "		30.00 N ✓
1pc	Rear End Panel Sticker " Cabstar "		27.00 N ✓
	Less 10%		2,574.00
			257.40
			2,316.60
1pc	Rear Number Plate		45.00 SN ✓
1pc	Tailgate Sticker 70 KM		18.00 SN ✓
1pc	Tailgate Sticker 13 Pax		18.00 SN ✓
2pcs	Tailgate Reflective Stripe	30.00	60.00 SN X
1pc	Rear Exhaust Silencer		616.50 SN X
	To Dismantle / Refit Rear Tailgate Protective Plate, Supply Blind Rivets and Sealant etc		120.00 50
	To Repair / Replace & Align Muffler/Exhaust System and Conduct Carbon Monoxide Leakage Test		90.00 X
	Labour Charge - Panel Beating, Repairing Of Rear Chassis Cross Member, End Panel, Side Panel, Side Latch and Parts Replacement		600.00 500
	To Respray Affected Areas		580.00 400
	<b>Total :</b>		<b>4,464.10</b>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18011736/Ktd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-09-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 8110C	Veh. Inspected	GR 1241L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004993MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	27/06/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN CABSTAR	c.c	3153	
Engine No.	HIDDEN	Year of Reg.	1999	
Chassis No.	JN1SF4F23Z0001923	Colour	SILVER	
Odometer	478359	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185 R14X8	GT RADIAL	8 mm	
L/H Front Tyre	185 R14X8	GT RADIAL	8 mm	
R/H Rear Tyre	155 R12X8 (D)	FIRENZA	1/1 mm	
L/H Rear Tyre	155 R12X8 (D)	FIRENZA	1/1 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/06/2018	Inspection Date	28/06/2018	
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GR 1241L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
2	TAILLAMPS ASSY @\$272.00 (N)	N/S CRACKED	544.00	272.00
1	TAILLAMP BRACKET LH (N)	BENT	136.00	136.00
1	REAR NUMBER BRACKET (N)	TO REPAIR SEE LABOUR	195.00	-
1	TAILGATE (N)	BENT	1,520.00	1,520.00
1	TAILGATE STICKER "NISSAN" (N)	NECESSARY	109.00	109.00
1	TAILGATE LOWER SQUARE STOPPER LH (N)	MISSING	13.00	13.00
1	REAR END PANEL STICKER "NISSAN" (N)	NECESSARY	30.00	30.00
1	REAR END PANEL STICKER "CABSTAR" (N)	NECESSARY	27.00	27.00
	LESS 10% DISCOUNT		-257.40	-210.70
			2,316.60	1,896.30
<b>SPECIAL NETT ITEMS</b>				
1	REAR NUMBER PLATE (SN)	BENT	45.00	20.00
1	TAILGATE STICKER 70KM (SN)	NECESSARY	18.00	12.00
1	TAILGATE STICKER 13PAX (SN)	NECESSARY	18.00	12.00
2	TAILGATE REFLECTIVE STRIPE @\$30.00 (SN)	NOT NECESSARY	60.00	-
1	REAR EXHAUST SILENCER (SN)	TO REPAIR SEE LABOUR	616.50	-
			757.50	44.00
<b>LABOUR</b>				
	TO DISMANTLE/REFIT REAR TAILGATE PROTECTIVE PLATE,SUPPLY BLIND RIVETS AND SEALANT ETC.		120.00	50.00
	TO REPAIR/REPLACE & ALIGN MUFFLER/EXHAUST SYSTEM AND CONDUCT CARBON MONOXIDE LEAKAGE TEST.	NOT NECESSARY	90.00	-
	LABOUR CHARGE-PANEL BEATING,REPAIRING OF REAR CHASSIS CROSS MEMBER,END PANEL,SIDE PANEL,SIDE LATCH AND PARTS REPLACEMENT.INCLUSIVE OF THE REPAIR OF REAR NUMBER BRACKET AND REAR EXHAUST SILENCER.		600.00	500.00
	TO RESPRAY AFFECTED AREAS.		580.00	400.00
			1,390.00	950.00
<b>GRAND TOTAL</b>			<b>4,464.10</b>	<b>2,890.30</b>

Report Ref No. CS/FCI18011736/Ktd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,300.00
---	--	--	----------

Report Ref No. CS/FCI18011736/Ktd3e2

MARKET VALUE: \$16,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$5,077.00=NETT VALUE: \$10,923.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.