

22/03/2002

ASS. REC. BY:

REF: C83

MSG 18011743/2403/22

Special Instruction:

Surveyor
menmen

GR

ASSIGNMENT (Office)

From (Person):

Chhia Nyuk Pui

of

MSG

Date/Time:

27/6/18 @ 4:42pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV7 CS

To Inspect Vehicle No:

FBH 636 A

Insured:

SGL 8435E

at Workshop m/s

Tai Hin Enterprise

Tel:

8380 2233

of

10 Keki Bldg Rd 2 # 01-16

Policy No:

129 026313 QMX

Claim No:

562474

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/06/2018

CA / REV / REP. / REV 24 HRS

Wp

28/06/2018

H.O.D. Endorsement:

Date/Time:

5:35pm @ 27/6/18

Person Contacted:

jaeky

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

FBH 636 A - NA / INC 18011447/24

DUA: 19/06/2018

SGL 8435E - NA / INC 18011447/24

DUA: 19/06/2018

INSURANCE
MOTOR

INS

Handwritten signature

REF: MSLH

ASSIGNMENT

From: _____ Date: 28062018
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: FBH 636A
at Workshop m/s Tai Hin
of 10 Kaki Bukit Rd 2 # 01-16
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

Veh No: FBH 636A Yr Regn: 27 Feb 2013
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or Runner
Make: Diaggio 611ers c.c. 198
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 80657 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ZAPM 4640100007045
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: N/S / S/Rim / STD A/Rim or
Tyre Size: F: 120/70-14
R: 140/60-13
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front _____ Rear _____
R/Bal. 4 mm R/Bal. 4 mm
L/Bal. mm L/Bal. mm
D.O.A. _____ D.O.I. 28-06-18
Survey held at w/s 3pm
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
and.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$3000 - \$4000
29/6/18	Submit PRS Report

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee: 120

Transportation: \$ + RS. SI

Photos 10

Others

TOTAL 130

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jun 2018		27 Jun 2018 16:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHONG KHIAM KIAT, ID: S7523552F, Tel: +6593658293, Email: chong_khiam_kiat@moe.edu.sg		
Main Claimant:	MUHAMMAD HAMDAN BIN DUL JALIL, ID: S9106328Z		
Vehicle Reg. No.:	FBH636A	Date of Loss:	19/06/2018 17:00 - :59 [63 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 562474	Policy/Cover Note No.:	A29026313QMX (Comprehensive) Coverage: 28/09/2017 - 27/09/2018
Vehicle Reg. No. (Insured):	SGL8435E	Policy No. (Claimant):	
		Excess:	
Repairer:	Tal Hin Enterprise Co (KAKI BUKIT) 10 KAKI BUKIT ROAD 2, #01-16 FIRST EAST CENTRE, 417868 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/06/2018]		
Driver/Custodian (Insured):	CHONG KHIAM KIAT (42 / Male), NRIC: S7523552F, Tel: +6593658293		
Adj Asg. Remarks:	Liability is 100% head to rear. TP reject our SJE list. Proceed to appoint LKK as the SJE. Pls contact Mr Jacky Siah at 8380 2233.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18011743/Gz4d3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 27-06-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SGL 8435E	Veh. Inspected	FBH 636A
Policy No.	A29026313QMX	Coverage (\$)	0.00
Claim No.	562474	Excess (\$)	0.00
Assign From	MERIMEN(CHHIA NYUK PUI)	Assign Date	27/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/06/2018	Inspection Date
Survey held at	TAI HIN ENTERPRISE CO 10 KAKI BUKIT RD 2 #01-16 FIRST EAST CENTRE SINGAPORE 417868	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6328Z
Vehicle Details	
Vehicle No.:	FBH636A
Vehicle to be Exported:	No
Intended De-registration Date:	29 Jun 2018
Vehicle Make:	PIAGGIO
Vehicle Model:	GILERA RUNNER ST 200
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	M464M0010382
Chassis No.:	ZAPM4640100007045
Maximum Power Output:	-
Open Market Value:	\$3,307.00
Original Registration Date:	27 Feb 2013
First Registration Date:	27 Feb 2013
Transfer Count:	6
Actual ARF Paid:	\$497.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Feb 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,512.00
COE Rebate Amount:	\$713.00
Total Rebate Amount:	\$713.00

The information contained herein is correct as at 29 Jun 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jun 2018		27 Jun 2018 16:42 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHONG KHIAM KIAT , ID: S7523552F, Tel: +6593658293, Email: chong_khiam_kiat@moe.edu.sg								
Main Claimant:	MUHAMMAD HAMDAN BIN DUL JALIL , ID: S9106328Z								
Vehicle Reg. No.:	FBH636A	Date of Loss:	19/06/2018 17:00 - :59 [63 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 562474	Policy/Cover Note No.:	A29026313QMX (Comprehensive) Coverage: 28/09/2017 - 27/09/2018						
Vehicle Reg. No. (Insured):	SGL8435E	Policy No. (Claimant):							
		Excess:							
Repairer:	Tai Hin Enterprise Co (KAKI BUKIT) 10 KAKI BUKIT ROAD 2, #01-16 FIRST EAST CENTRE, 417868 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 28/06/2018]								
Driver/Custodian (Insured):	CHONG KHIAM KIAT (42 / Male), NRIC: S7523552F, Tel: +6593658293								
Adj Asg. Remarks:	Liability is 100% head to rear. TP reject our SJE list. Proceed to appoint LKK as the SJE. Pls contact Mr Jacky Siah at 8380 2233.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBH636A (562474)

[SGL8435E]

TP

MUHAMMAD HAMDAN BIN DUL JALIL

Jun 19 2018 5:00PM

[CHONG KHIAM KIAT]

Tai Hin Enterprise Co

Upload Documents Upload Photos Compose New Letter			View View in Browser <input type="button" value="v"/>	
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	27/06/18 11:07	Accident Statement From: SC - Reg. No: SGL8435E, Claimant: CHONG KHIAM KIAT	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
2	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
3	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
4	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
5	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
6	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
7	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
8	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
9	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
10	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
11	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
12	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
13	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
14	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
15	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
16	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
17	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
18	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
19	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
20	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
21	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
22	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
23	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
24	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
25	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
26	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
27	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
28	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
29	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
30	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
31	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>
32	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/06/18 11:07	FBH636A GIA Rpt From:SC - Reg. No: SGL8435E, Claimant: CHONG KHAM KIAT	Load PDF	
2	27/06/18 11:08	Email frm TP - PRI	Load PDF	
3	27/06/18 11:08	PRI	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18011743/GZ4D3E2

Date: 02/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29026313QMX

Claimant Vehicle No : FBH636A

Insured Vehicle No : SGL8435E

Date of Loss: 19/06/2018

Nature of Claim: TP

Claim No: 562474

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBH636A

Make & Model: PIAGGIO GILERA RUNNER, 198cc ST 200

Engine No: M464M0010382

Reg. Date: 27/02/2013 (Man. Year: 2012)

Chassis No: ZAPM4640100007045

Colour: Black

Odometer: 80657 km

Engine Capacity: 198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70-14

Rear Tyre Size: 140/60-13

Front Left Side: Michelin 4 mm

Rear Left Side: Michelin 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/06/2018

Date Inspected: 28/06/2018 Inspected At:

Tai Hin Enterprise Co (KAKI BUKIT)
10 KAKI BUKIT ROAD 2, #01-16 FIRST
EAST CENTRE
Singapore 417868

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Jun 2018)	
Parts:	N/A	PIAGGIO GILERA RUNNER 198cc ST 200 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBH636A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >