

22/03/2002

ASS. REC. BY:

REF: CS3 / MSG 18011744 / G24d3b

Special Instruction: ✓

Survivor: Manman

GA

ASSIGNMENT (Office)

From (Person):

Irene fan

of

MSG

Date/Time:

27/6/18 @ 9:20am

Estimated Cost:

Bill to:

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBE 6481E

Insured:

SLS 6392L

at Workshop m/s

MCS Auto

Tel:

62964038 / 62969939

of

1100 Sungepon Road

94318235

Policy No:

29029251AVW

Claim No:

562255

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/06/2018

CA / REV / REP. / REV 24 HRS

1up

28/06/2018 @ Insp: Lightning Bike: 257 A Jln Besar

H.O.D. Endorsement:

Date/Time:

5:40pm 27/6/18

Person Contacted:

Ah Chong

Vehicle: IN OUT

Date/Time

Action/Instruction (X) Estimate

FBE 6481E - X

SLS 6392L - X

Surveyor: Maximen MSL

ASSIGNMENT

From: _____ Date: 28/06/2018

Veh No: FOE6481E Yr Regn: TO 10 / Jul
Type: M/Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Estimated Cost: _____

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To Inspect Vehicle No: FBE 6481E

Make: KTM c.c. 398

at Workshop m/s: Lightning Bike

Colour: Blue A/C: Insured / Std / NI / NA

of: 267A Jim Besar

Sp. Reading: 75402 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: _____

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: M/S / Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 120/70 8 R17

R: 150/60 8 R17

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / (PIR) / SUMI / TOYO / YOKO or

Bal. or Market Value: _____

Front _____ Rear _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

R/Bal. 4 mm R/Bal. 4 mm

GIA / PR Seen: _____ Consistent?: Yes or No

L/Bal. _____ mm L/Bal. _____ mm

Est. Repairs: 4 days Res.: Yes or No

D.O.A. _____ D.O.I. 28-06-18

Lum Sum: 20 % 3 Val.: Yes or No

Survey held at _____ w/s 4:40pm

CA / REV / REP. / 24 HRS

Des. of Damages Fr / Rear / (O/S) N/S / UIC / Rooftop or

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$ 5000 - \$ 6000</u>
<u>29/6/18</u>	<u>Submit PRS Report</u>

Date/Time, File Pass to? : Preli. Report : Final Report

Days Of Repair: _____

1) Date/Time, File Return to?

Resurvey No. of Trip: _____

2) _____

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

Survey Fee: 120

Transportation: _____

\$ + RS. SI

Photos

Others 10

TOTAL 130

Report Format: _____

Lump Sum / I.B.I: (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jun 2018		27 Jun 2018 09:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NG GUO ZHONG, ID: S8414978J, Tel: +6591468968, Email: NOEMAIL								
Main Claimant:	MUHAMMAD RAZEEQ BIN MOHD FAZIL, ID: S9603183A								
Vehicle Reg. No.:	FBE6481E	Date of Loss:	22/06/2018 21:00 - :59 [95 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 562255	Policy/Cover Note No.:	29029251AVW (Comprehensive) Coverage: 29/09/2017 - 28/09/2018						
Vehicle Reg. No. (Insured):	SLS6392L	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Mcs Auto (HQ) 1100 Serangoon Rd, 328195 Serangoon - Tel: 62969939								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/06/2018]								
Driver/Custodian (Insured):	NG GUO ZHONG (34 / Male), NRIC: S8414978J, Tel: +6591468968								
Adj Asg. Remarks:	on WP. LIABILITY -80% TO 90% APPOINT LKK Auto Consultants CONTACT STEPHANIE @62964038								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18011744/Gz4d3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 27-06-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLS 6392L	Veh. Inspected	FBE 6481E
Policy No.	29029251AVW	Coverage (\$)	0.00
Claim No.	562255	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	27/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/06/2018	Inspection Date	
Survey held at	LIGHTNING BIKE-257A JALAN BESAR		
Repairer	MCS AUTO		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBE6481E		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	SUZUKI		
Vehicle Model :	DRZ400SM M		
Chassis No. :	SK44A105439		
Propellant :	Petrol		
Engine No. :	K419181454		
Engine Capacity :	398 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	-		
Unladen Weight :	135 kg		
Year Of Manufacture :	2008		
Original Registration Date :	08 Jul 2010		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$1,454.00		
COE Expiry Date :	07 Jul 2020		
Road Tax Expiry Date :	05 Aug 2018		
Inspection Due Date :	05 Aug 2018		
Intended Transfer Date :	29 Jun 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 05 Aug 2018. You may renew the road tax from 06 May 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 05 Aug 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 06 Aug 2018 to 05 Feb 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	55.00	-	55.00
Total Amount Payable :			80.00
Amount Payable (From 06 Aug 2018 to 05 Aug 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	110.00	-	110.00
Total Amount Payable :			135.00

You may print this page for reference.

OK

Print

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jun 2018		27 Jun 2018 09:20 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	NG GUO ZHONG, ID: S8414978], Tel: +6591468968, Email: NOEMAIL	
Main Claimant:	MUHAMMAD RAZEEQ BIN MOHD FAZIL, ID: S9603183A	
Vehicle Reg. No.:	FBE6481E	Date of Loss: 22/06/2018 21:00 - :59 [95 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 562255	Policy/Cover Note No.: 29029251AVW (Comprehensive) Coverage: 29/09/2017 - 28/09/2018
Vehicle Reg. No. (Insured):	SLS6392L	Policy No. (Claimant):
		Excess: S\$500.00
Repairer:	Mcs Auto (HQ) 1100 Serangoon Rd, 328195 Serangoon - Tel: 62969939	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 28/06/2018]	
Driver/Custodian (Insured):	NG GUO ZHONG (34 / Male), NRIC: S8414978], Tel: +6591468968	
Adj Asg. Remarks:	on WP. LIABILITY -80% TO 90% APPOINT LKK Auto Consultants CONTACT STEPHANIE @62964038	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBE6481E (562255)
 [SLS6392L]
 TP
MUHAMMAD RAZEEQ BIN MOHD FAZIL
 Jun 22 2018 9:00PM
 [NG GUO ZHONG]
 Mcs Auto

Upload Documents		Upload Photos	Compose New Letter	View View in Browser
Assessment Reports				1 per page <input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	26/06/18 15:56	Accident Statement From:OD - Reg. No: SLS6392L, Claimant: NG GUO ZHONG		Load HTM <input type="checkbox"/>
Photos/Images				3 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
2	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
3	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
4	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
5	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
6	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
7	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
8	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
9	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
10	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
11	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
12	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
13	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
14	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
15	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
16	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
17	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
18	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
19	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
20	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
21	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
22	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
23	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
24	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
25	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
26	29/06/18 16:05	General View		Load JPG <input checked="" type="checkbox"/>
27	29/06/18 16:06	General View		Load JPG <input checked="" type="checkbox"/>
28	29/06/18 16:06	General View		Load JPG <input checked="" type="checkbox"/>
29	29/06/18 16:06	General View		Load JPG <input checked="" type="checkbox"/>
30	29/06/18 16:06	General View		Load JPG <input checked="" type="checkbox"/>
31	29/06/18 16:06	General View		Load JPG <input checked="" type="checkbox"/>
32	29/06/18 16:06	General View		Load JPG <input checked="" type="checkbox"/>
33	29/06/18 16:06	General View		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
35	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
36	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
37	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
38	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
39	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
40	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
41	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
42	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
43	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
44	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
45	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
46	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
47	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
48	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
49	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
50	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
51	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
52	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
53	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
54	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
55	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
56	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
57	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>
58	29/06/18 16:06	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/06/18 15:55	TPD FBE6481E GIA REPORT.PDF	Load PDF	
2	26/06/18 15:55	Email 10 SURYVORS to TPD -FBE6481E.pdf	Load PDF	
3	26/06/18 15:55	Survey Disagreement email from TP- FBE6481E.pdf	Load PDF	
4	26/06/18 15:55	list of surveyor -FBE6481E.pdf	Load PDF	
5	26/06/18 15:55	PRI REJECT - FBE6481E.pdf	Load PDF	
6	26/06/18 15:55	PRI - FBE6481E.pdf	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18011744/GZ4D3E2

Date: 02/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29029251AVW
Claimant Vehicle No : FBE6481E	Insured Vehicle No :	SLS6392L
Date of Loss: 22/06/2018	Nature of Claim:	TP
		Claim No: 562255

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBE6481E		
Make & Model:	SUZUKI DRZ400SML0, 398cc	Engine No:	K419181454
Reg. Date:	08/07/2010 (Man. Year: 2008)	Chassis No:	SK44A105439
Colour:	Blue	Odometer:	75402 km
Engine Capacity:	398 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70Z R17	Rear Tyre Size:	150/60Z R17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	27/06/2018		
Date Inspected:	28/06/2018	Inspected At:	Mcs Auto (HQ) 1100 Serangoon Rd Singapore 328195
Estimated Period of Repair:	0.0 days		

Adjuster: XING GUO QIANG**Manager:** Ho Zhao Tian*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 29 Jun 2018)
Parts:	N/A	SUZUKI DRZ400SML0 398cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBE6481E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >