



Immediate Advice

To : AXA Insurance Pte Ltd

Date: 02/07/2018

Survey Details:

Date of loss	27-Jun-18
Date of appointment	28-Jun-18
Date of survey	28-Jun-18
Location of survey	COMFORTDELGRO ENGINEERING PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SH 6781Y
Make and Model	HYUNDAI I40
Date of registration	12/11/2015
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 1,075.12
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 25.28
Check items (estimate)	\$ -
Labour	\$ 300.00
Total	\$ 325.28
Lump Sum(if applicable)	\$ -

Number of days for repair	2
----------------------------------	----------



Remarks:

We have not authorized repairs.

Mandate:

Liability(TP)		%
Proposed repair cost	\$	
Loss of use	\$	
Loss of rental	\$	
Loss of income	\$	
LTA search fees	\$	
Others	\$	
Proposed Total		