

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305180598  
REGN NO : SHD3606S  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4)  
DATE OF REGN : 14.09.2016  
DATE/TIME IN : 27.06.2018 12:25  
ACCIDENT DATE : 27.06.2018

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

|                        |                         |   |          |       |          |
|------------------------|-------------------------|---|----------|-------|----------|
| 0001 04-01-0302-0594-G | WING MIRROR RH          | 1 | 1,374.00 | 25.00 | 1,030.50 |
| 0002 04-01-0302-0898-G | W/MIRROR OUTER COVER RH | 1 | 141.90   | 25.00 | 106.42   |
| 0003 04-01-0302-3932-G | FRT DOOR GLASS RH**     | 1 | 780.50   | 25.00 | 585.37   |

SUB-TOTAL : 1,722.29

## JOB NATURE

|             |                             |        |
|-------------|-----------------------------|--------|
| 0000 L      | PANEL BEATING               | 100.00 |
| 0001 23-502 | SPRAYPAINT ON AFFECTED AREA | 50.00  |

SUB-TOTAL : 150.00

TOTAL : 1,872.29



MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

COMFORTDELGRO ENGINEERING PTE LTD

Date: 27.06.2018

REPAIR ESTIMATE

Time: 15:16:45

Page: 1

Ang Aka - CP/P

LKK - Calvin

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305180598  
 REGN NO : SHD3606S  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(G4)  
 DATE OF REGN : 14.09.2016  
 DATE/TIME IN : 27.06.2018 12:25  
 ACCIDENT DATE : 27.06.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

|                        |                         |   |           |       |          |                      |
|------------------------|-------------------------|---|-----------|-------|----------|----------------------|
| 0001 04-01-0302-0594-G | WING MIRROR RH          | 1 | 1,374.00  | 25.00 | 1,030.50 |                      |
| 0002 04-01-0302-0898-G | W/MIRROR OUTER COVER RH | 1 | 141.90    | 25.00 | 106.42   |                      |
|                        | Front door glass (RH)   |   | \$ 780.50 |       |          |                      |
|                        |                         |   |           |       |          | SUB-TOTAL : 1,136.92 |

## JOB NATURE

|             |                             |
|-------------|-----------------------------|
| 0000 L      | PANEL BEATING               |
| 0001 23-502 | SPRAYPAINT ON AFFECTED AREA |
| 0002 17-01  | CHECK ALL LIGHTING          |

150.00 ~~100~~  
 150.00 ~~50~~  
 20.00 ~~X~~

SUB-TOTAL : 320.00

TOTAL : 1,456.92

MVA NAME &amp; SIGNATURE

DATE :

AUTHORISED : YES / NO  
 SURVEYOR NAME & SIGNATURE

DATE :

Kalina (LKK)  
 27/6/18 1538h.  
 1 Day  
 PIP  
 Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



|         |   |                     |               |   |                   |
|---------|---|---------------------|---------------|---|-------------------|
| VEHICLE | : | <u>SHD3606S</u>     | TYPE OF CLAIM | : | <u>TP</u>         |
| MODEL   | : | <u>TOYOTA PRIUS</u> | SURVEY BY     | : | <u>LKK-KALVIN</u> |
| JOB NO  | : | <u>305180598</u>    | DATE          | : | <u>27.06.18</u>   |

## SUPPLEMENTARY OF PARTS AND LABOUR COSTS

[illegible]