

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/06/2018 16:16
Date Of Accident	28/06/2018 10:30
Exact Location Of Accident	ALONG CTE TOWARDS JURONG
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR8071S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SIAH SING KONG
NRIC No	S1164892D
Email Address	SIAHSINGKONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96665360
Alternative Phone No	OFFICE-96665360

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088307372-01
Cover Note Number	

### Driver

Name of Driver	SIAH SING KONG
NRIC No	S1164892D
Date Of Birth	01/04/1956
Occupation	INDOOR
Date Of Driving Pass	10/04/1978
Driving Experience	40 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96665360
Fax Number	
Contact Number	OFFICE-96665360
Email Address	SIAHSINGKONG@GMAIL.COM

Address	BLK 117 BUKIT MERAH CENTRAL #07-3755
Postcode	150117
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	JDT4260 (COMMERCIAL VEHICLE)
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT MERAH WEST NPC
Police Station Address	<b>ROAD:</b> 500 BUKIT MERAH VIEW #01-01 , <b>POSTCODE:</b> 159682 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> - <b>FAX NO:</b>
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT T/20180628/2118

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JDT4260
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MASURI BIN SENIN
NRIC/Passport Number	780126-01-6711
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver) 1

## Accident Sketch Plan

### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 28th of June 2018, at around 10:30am, I was driving on the CTE towards Juru in the fast lane. (opposite lamp post 413F) when I was hit from behind by a Malaysian registered vehicle.

The van impacted the back of my vehicle, causing several scratches and internal structural damage to the back bumper

Malaysian Registered Van = JDT 4260  
my vehicle = SKR 80715

POLICE REPORT T/20180628/2118

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]* 1438 hrs  
Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]* 28/06/2018  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

1204888 - Standard form 2018



# POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20180628/2118

Police Station Of Origin:  
Bukit Merah West N.P.C  
500 Bukit Merah View #01-01 SINGAPORE  
159682  
Tel No: 1800-3779999

1 of 3

Report No. T/20180628/2118

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/06/2018 15:35	Vide Report No.:	Station Diary No.: 81
--	------------------	--------------------------

### Informant's Particulars

Name of Informant: SIAH SING KONG	Address: APT BLK 117 BUKIT MERAH CENTRAL #07-3755 SINGAPORE 150117		
ID Type / ID No.: NRIC NO / S1164892D	Contact No.: Home/Office: Mobile: 96665360		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 62	Date of Birth: 01/04/1956	Type of Informant: Driver
Race: Chinese	Language:		Institution / School Name:
Occupation: Horticulturist/Arborist	Driving Licence Information: Class:		Date of Expiry:

### General Information of the Accident

Type of Accident:	Non-injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 28/06/2018 10:30	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 CENTRAL EXPRESSWAY towards jurong				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

### Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JDT4260	Bus/Coach/Minibus				Slightly Damaged	0
SKR8071S	Car	TOYOTA	TOYOTA COROLLA ALTIS 1.6L CVT	Brown	Slightly Damaged	0

### Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

# POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20180628/2118

Police Station Of Origin:  
Bukit Merah West N.P.C  
500 Bukit Merah View #01-01 SINGAPORE  
159682  
Tel No: 1800-3779999

2 of 3

Report No. T/20180628/2118

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKR8071S	NTUC Income Insurance Co-Operative Limited	5088307372-01	11/03/2018	10/03/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Name	masuri bin senin		ID No.	780126-01-6711
Related Vehicle	JDT4260 (Bus/Coach/Minibus)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	SIAH SING KONG		ID No.	S1164892D
Related Vehicle	SKR8071S (Car)		Contact No.	96665360
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

### Brief Details.

On 28/6/2018 at around 1030hrs, I was travelling in lane 1 along CTE towards Jurong in my vehicle, bearing the registration number, SKR8071S. I slowed down my vehicle and suddenly the vehicle from behind, bearing the registration number, JDT4260, hit my rear of my car. As we were both still on the expressway, we continued driving until we reached Tiong Bahru area. At the Tiong Bahru area, we both got out of our vehicles to assess the damage and particulars. There were scratches and internal structural damage to the rear bumper. After exchanging particulars, we then both drove off.

I wish to state that I do not have an in-car camera in my vehicle.

# POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20180628/2118

Police Station Of Origin:  
Bukit Merah West N.P.C  
500 Bukit Merah View #01-01 SINGAPORE  
159682  
Tel No: 1800-3779999

3 of 3

Report No. T/20180628/2118

## CONTINUATION OF REPORT

### Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 WONG XIANG LONG, CLARENCE

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Signature Of Informant:

Date/Time:

28/06/2018 15:35

Classification Of Case:

Authentication Stamp

NP168

SINGAPORE POLICE FORCE

SN 41

SIGNATURE



## ACCIDENT PHOTO

On the 28<sup>th</sup> June 2018 at around 10.30am, I was driving on the CTE towards Jurong in the fast lane opposite lamppost 413F when I was hit from behind by a Malaysian registered Van JDT 4260.

The Van impacted the back of my vehicle, SKR 8071S, causing several scratches and internal structural damage to the back bumper.



*av 28/06/2018*

# ACCIDENT PHOTO

Roti Kuli

NEWLY TEN FOOD INDUSTRIES SDN.BHD				
JOB SCHEDULE FOR DELIVERY MAN				
PLACE: PERLING				
DATE: 27/06/2018				
	車牌	MILEAGE (KM)	TIMES	DRIVER SIGN
OUT 出	JD1460			
IN 回				

DRIVER NAME: MASURI

CUSTOMER'S NAME	NO	TIME TO DELIVERY	TRAY CODE					
			B.HITAM		4424			
			OUT	IN	OUT	IN	OUT	IN
Good Taste			2					



an 28/06/2018

ACCIDENT PHOTO



gn/28/06/2018



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo

