

22/03/2002

ASS. REC. BY:

REF: CS3/CT18011830/Gzilbez

Special Instruction:

SURVIVOR

Mafimen

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CT1

Date/Time:

27062018 10:45am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 5751E

Insured:

SJS 5794R.

at Workshop m/s

C.H. Motor

Tel:

6841 8841

of

Blk 3019A Ubi Rd 1 # 01-30

Policy No:

DMHCSN1760441700

Claim No:

SNM18D03136002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23062018

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

28062018 950am

Person Contacted:

Joe

Vehicle

IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLB 5751E - X

SJS 5794R - NA / INC17006248 / K4

DIA: 280617

(08/1/18)

INS

REF: CIL

Surveyor

mainen

XML

ASSIGNMENT

From: _____ Date: 28062018

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLB 5751E

at Workshop m/s C.H. Motor

of Blk 3019A Ubi Rd 1 #01-30

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 ~~20~~ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLB5751E Yr Regn: Jun / 2012

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volvo RS S60 c.c. - 1999

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 124300 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 28-06-18

w/s 2pm

Date / Time Action / Instruction

\$4000 - \$5000

29/6/18 Submit PRS Report

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

150

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Jun 2018		27 Jun 2018 10:45 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MT SINGAPORE CAR RENTAL PTE LTD, Co. Reg. No.: 201630785W		
Main Claimant:	MARK LIM ZHAN CHEN, ID: S7908781E		
Vehicle Reg. No.:	SLB5751E	Date of Loss:	23/06/2018 11:00 - :59
Claim Type:	TP / SNM18D03136C02	Policy/Cover Note No.:	DMHCSN1760441700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJS5794R	Policy No. (Claimant):	GA302507/1
		Excess:	S\$0.00
Repairer:	C.h.motor Vehicle Repair Training (HQ) BLK 3019A UBI ROAD 1 #01-30, 408713 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/07/2018]		
Driver/Custodian (Insured):	THAM WON HAO (28 / Male), NRIC: S8971660H, Tel: +6583991660		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
RAYNEY WONG KENG LEONG
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
SELWYN TAN YINGXIAN

Unique Entity Number: 200721148H

✓HEAD OFFICE

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)
✓: (65) 65355905 (Litigation)
E-mail : yvonnelim@visionlawllc.com

BRANCH

TEL : (65) 63580703
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE – PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: SLB 5751 E (PM)
Your Ref: SJS 5794 R

27 June 2018

BY FAX 6224 7478 ONLY

CHINA TAIPING INSURANCE (SG) PTE LTD
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
[Attention : Motor Claim Department]

Dear Sirs,

ACCIDENT INVOLVING MOTOR VEHICLE SLB 5751 E AND SJS 5794 R ON 23 JUNE 2018 ALONG
CTE SLIP ROAD TOWARDS BRADDELL AT ABOUT 1100 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email on even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Please be informed that the said vehicle can be inspected at:

Venue : C.H. MOTOR VEHICLE REPAIR TRAINING
Block 3019A Ubi Road 1
#01-30

Contact Person : Singapore 408713
Mr. Joe @ 6841-8841 / 6748-8888 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

JANICE HAN
(HEAD OFFICE)

cc: SLB 5751 E – By fax: 67436878 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

CONFIDENTIALITY
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS3/CTI18011830/Gz4b	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 28-06-2018	
		Code : CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SJS 5794R	Veh. Inspected	SLB 5751E
Policy No.	DMHCSN1760441700	Coverage (\$)	0.00
Claim No.	SNM8D03136C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	27/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/06/2018	Inspection Date	28/06/2018
Survey held at	C H MOTOR VEHICLE REPAIR TRAINING BLK 3019A UBI ROAD 1 #01-30 SINGAPORE 408713		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLB5751E		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	VOLVO		
Vehicle Model :	S60 T5 2.0 AUTO ABS D/AB 2WD 4DR TURBO		
Chassis No. :	YV1FS475BC2084241		
Propellant :	Petrol		
Engine No. :	B4204T71031712		
Engine Capacity :	1999 cc		
Maximum Power Output :	177.0 kW (237 bhp)		
Maximum Laden Weight :	2060 kg		
Unladen Weight :	1556 kg		
Year Of Manufacture :	2011		
Original Registration Date :	22 Jun 2012		
Lifespan Expiry Date :	-		
COE Category :	E - Open Category		
Quota Premium :	\$92,010.00		
COE Expiry Date :	21 Jun 2022		
Road Tax Expiry Date :	21 Dec 2018		
PARF Eligibility Expiry Date :	21 Jun 2022		
Inspection Due Date :	21 Jun 2019		
Intended Transfer Date :	29 Jun 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Jun 2018		27 Jun 2018 10:45 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	MT SINGAPORE CAR RENTAL PTE LTD , Co. Reg. No.: 201630785W								
Main Claimant:	MARK LIM ZHAN CHEN , ID: S7908781E								
Vehicle Reg. No.:	SLB5751E	Date of Loss:	23/06/2018 11:00 - :59 [72 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03136C02	Policy/Cover Note No.:	DMHCSN1760441700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJS5794R	Policy No. (Claimant):	GA302507/1						
		Excess:	S\$0.00						
Repairer:	C.h.motor Vehicle Repair Training (HQ) BLK 3019A UBI ROAD 1 #01-30, 408713 Ubi - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 06/07/2018]								
Driver/Custodian (Insured):	THAM WON HAO (28 / Male), NRIC: S8971660H, Tel: +6583991660								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB5751E (SNM18D03136C02)
[SJS5794R]
TP
MARK LIM ZHAN CHEN
Jun 23 2018 11:00AM
[MT SINGAPORE CAR RENTAL PTE LTD]
C.h.motor Vehicle Repair Training

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print
1	26/06/18 13:23	Accident Statement		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print
1	26/06/18 13:21	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	26/06/18 13:21	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	26/06/18 13:21	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	26/06/18 13:21	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	26/06/18 13:21	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print
1	26/06/18 13:22	Sketch Plan [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	26/06/18 13:22	Sketch Plan #2 [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	26/06/18 13:23	Common Statement [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	26/06/18 13:23	Individual Statement [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	26/06/18 13:23	POLICE REPORT PAGE 1 [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	26/06/18 13:23	POLICE REPORT PAGE 2 [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	26/06/18 13:23	POLICE REPORT PAGE 3 [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	26/06/18 13:23	CI [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	26/06/18 13:23	DRIVER NRIC & LICENSE [Linked Accident Report Documents]		Load TIF	

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/06/18 10:44	PRS		Load PDF	
2	27/06/18 10:45	OI GIA		Load PDF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/06/18 15:59	LKKPhotosIn6-1.pdf		Load PDF	















Linked Accident Report Documents

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print
1	26/06/18 13:23	Accident Statement		Load HTM	

Photos/Images					
---------------	--	--	--	--	--

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	26/06/18 13:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	26/06/18 13:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	26/06/18 13:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	26/06/18 13:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	26/06/18 13:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	26/06/18 13:22	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	26/06/18 13:22	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	26/06/18 13:23	Common Statement	 Load JPG	<input checked="" type="checkbox"/>
4	26/06/18 13:23	Individual Statement	 Load JPG	<input checked="" type="checkbox"/>
5	26/06/18 13:23	POLICE REPORT PAGE 1	 Load JPG	<input checked="" type="checkbox"/>
6	26/06/18 13:23	POLICE REPORT PAGE 2	 Load JPG	<input checked="" type="checkbox"/>
7	26/06/18 13:23	POLICE REPORT PAGE 3	 Load JPG	<input checked="" type="checkbox"/>
8	26/06/18 13:23	CI	 Load JPG	<input checked="" type="checkbox"/>
9	26/06/18 13:23	DRIVER NRIC & LICENSE	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18011830/GZ4BE2

Date: 02/07/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSN1760441700

Claimant Vehicle
No: SLB5751EInsured Vehicle
No: SJS5794R

Date of Loss: 23/06/2018

Nature of Claim: TP

Claim
No: SNM18D03136C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB5751E

Make & Model: VOLVO S60, 2.0 T5 (A)

Engine No: B4204T71031712

Reg. Date: 22/06/2012 (Man. Year: 2011)

Chassis No: YV1FS475BC2084241

Colour: Blue

Odometer: 124300 km

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/06/2018

Date Inspected: 28/06/2018 Inspected At:

C.h.motor Vehicle Repair Training (HQ)
BLK 3019A UBI ROAD 1 #01-30
Singapore 408713

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jul 2018)

Parts: 143 VOLVO S60 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLB5751E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >