

S. REC. BY:

REF: CS/MS(18011844 / Kvb02) Special Instruction:

ASSIGNMENT (Office)

From (Person): Irene Tan of MS16 Date/Time: 28062018 403pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDL 8138Z Insured: SLJ 4562Z

at Workshop m/s Cheng Hoe Motor Tel: 6755 6142

of BIK 2019 Yishun Ind Park A #01-374

Policy No: 2905 8678 DMY Claim No: 562629

Sum Insured: Excess:

Make of Veh: D.O.A. 27062018 (Client's Record)

CA / REV / REP. / REV 24 HRS WPI H.O.D. Endorsement:

Date/Time: 28062018 432pm Person Contacted: Sharon Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SDL 8138Z - CCH / LOR 17022299 / Kw03 DUA: 201117
	SLJ 4562Z - X

27/18 Send preli revised via merimen

27/8/18 11 Sup @ 1800 Carbone & feed/P (Reel 1831.50, 509)

Lum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Survey held at 0110 D.O.I. 20/6/18

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or O/S Rm

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
2/7	File pass to Catherine, GITA & check ready
	11 Sup @ 1800 Carbone & feed

RECEIVED 27 AUG 2018

Date/Time, File Pass to? : Preli. Report
 : Final Report

1) _____
 2) 27/8 - typist

Report Format: merimen
 Lump Sum / I.B.I: (\$) 1800

Days Of Repair: 4

Resurvey No. of Trlp: 2

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation: S + RS, SI	150
Photos	10
Others	
TOTAL	160