

22/03/2001

ASS. REC. BY:

REF: CS/MSG18011869/71vd322

Special Instruction:

Surveyor
merimen

Taufik

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time: 29/6/18 @ 10

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FU 3378J

Insured:

GX 5607H

at Workshop m/s

SG 98 Motor

Tel:

G 452 4898

of

Blk 4001 AMK Ind. Park 1 # 01-21

Policy No:

A288 G1944 TMV

Claim No:

562672

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/06/2018

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

10:23am @ 29/6/18

Person Contacted:

Pose

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

FU 3378J - X

GX 5607H - NA 1AIG 080174521S

DOA 13/6/2018

29/6/18

Informed Christina Wong pending workshop est via merimen

14/9/18

LS \$1400 confirmed by email (Recd 877.20, 38/10)

6/18/2018

Model
E220

Service Address

...

Primary Contact/Insured

KUNZRU GAUTAM
278 DUNEARN ROAD, 299549, Singapore
63002456
kunzru@live.com

Claim Handler

ANG Richard

richard.angbs@axa.com.sg
Additional Instructions
NON-REPORTED

Signature

Taym

REF:

ASSIGNMENT

CoE 2022 Jan.

2002 Jan.

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s

of

Insured:

Policy No.:

Claims No.:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

F433783

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Phantom

CC

197

Colour

Red

A/C

Insured / Std / NI / NA

Sp. Reading

2275

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

TA 200E 0005827

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

100/80R17

R:

130/90R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ~~PIR~~ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

28/6/16 @ 1730

Survey held at

S6 Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/9/18

w/s will pass estimate later
Send preli revised via merimen

RECEIVED 17 SEP 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 14/9 - typist

Report Format :

merimen

Lump Sum / I.B.I. (\$

1400/-

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$
☐ Interview (\$
☐ Tech. Invs (\$
☐ Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

190
10
160

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

JOB NO : 305155474
REGN NO : SHA4724T
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 30.12.2016
DATE/TIME IN : 02.05.2018 07:45
ACCIDENT DATE : 30.04.2018

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

QTY IND UNIT-PRICE DISC% AMOUNT

JOB / PARTS DESCRIPTION

PART REQUISITION

0001 04-01-0302-3932-G	PRIG4 GLASS SUB-ASSY FRT	1	780.50	25.00	585.37
0002 04-01-0302-0594-G	PRIG4 MIRROR ASSY OUTER R	1	1,374.00	25.00	1,030.50
SUB-TOTAL : 1,615.87					

JOB NATURE

0000 L	LABOUR	120.00			
0001 23-502	SPRAYPAINT ON AFFECTED AREA	120.00			
0002 17-01	WIRING CHARGE	50.00			
SUB-TOTAL : 290.00					

TOTAL : 1,905.87

AUTHORISED : YES / NO
DATE :
SURVEYOR NAME & SIGNATURE

MVA NAME & SIGNATURE
DATE :



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18011869/T1vd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 29-06-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GX 5607H	Veh. Inspected	FU 3378J
Policy No.	A28861944TMV	Coverage (\$)	0.00
Claim No.	562672	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	29/06/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/06/2018	Inspection Date	28/06/2018
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jun 2018		29 Jun 2018 10:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	EXCEL EVERLITE PTE LTD, Co. Reg. No.: 0		
Main Claimant:	MUHAMMAD SHAFIQ BIN ZAIDI, ID: S9516336Z		
Vehicle Reg. No.:	FU3378J	Date of Loss:	22/06/2018 17:00 - :59 [197 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 562672	Policy/Cover Note No.:	A28861944TMV (Third Party Only) Coverage: 06/01/2018 - 05/01/2019
Vehicle Reg. No. (Insured):	GX5607H	Policy No. (Claimant):	
		Excess:	
Repairer:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/06/2018]		
Driver/Custodian (Insured):	EE TEE KIAN (), NRIC: S7627713C, Tel: +6596799686		
Adj Asg. Remarks:	Liability is unclear. TP select LKK as the SJE. W/s contact no person: Rose 6452 4898.		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS [View All] Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Christina Wong	Date: 14 Sep 2018

Preliminary Advice

Insured Vehicle No : GX5607H	Accident Date : 22/06/2018
TP Vehicle No : FU3378J	Assignment Date : 29/06/2018
Make : HONDA PHANTOM 200M	Est. Duration of Repair : 4.00
Date of Inspection : 28/06/2018	
Inspection At : SG 98 MOTOR PTE LTD (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622	

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,277.20
Revised Amount	:S\$	1,400.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,400.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

Our reference 11-1212-374
Date 23/12/2011
Page 4

Section C: Summary Table of Total Repair Cost

Description		Cost
Damaged Parts Assessment (See section A)	Replace parts	\$760.97
	Further discount	20%
	Recommended cost of parts replacement	\$3,043.88
Labour Cost Calculation (See section B)		\$2,621.10
Total Repair Cost (Round off to hundred)		\$5,700.00

We would recommend a sum of \$5,700.00 and 8 working days for repair. No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.



Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)
B. Eng. (Hons, NUS)

Diploma, Mechanical, TTC, Mechanical & Electrical
NTC - Automotive Technology

MITS, Institute of Engineers, Singapore (#20100001)

MATL, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

ARC #1649, CLU, CGI

Team of Assessors:

Mike Loo ** Candy Tan ** Y.Y. Ee ** Gilbert Leow ** Andy Ho

View Sent Message

This mail is associated with :

***FU3378J (562672)**
[GX5607H]

TP
MUHAMMAD SHAFIQ BIN ZAIDI
Jun 22 2018 5:00PM
[EXCEL EVERLITE PTE LTD]
Sg 98 Motor Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 29/06/2018 11:57 AM.
To MSIG_CWSF1
Subject TP SURVEY FU 3378J

Dear Christina,

Please be informed that we have inspected the vehicle FU 3378J on 28/6/2018.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

Our Ref: CC6/AXA12000619/Mied

08 May 2012

TAN LAY PIN

Block 150 Ang Mo Kio Avenue 5

#10-3054

Singapore 560150

Dear Sir/Madam,

ACCIDENT INVOLVING SKA 5643B AND FBD 4524J ON 27/12/2011

We refer to the above accident where we are acting for AXA Insurance Singapore Pte Ltd (AXA) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Accordingly your No Claim Discount (NCD - if applicable) may not be preserved.

Please call us if you have further queries.

Yours faithfully,

[Signature]
Vic Alpeh Sanghian
Case Handler

DID: 6841 2157

FAX: 6741 4108

Email: vicalpeh@lkkauto.com

c.c. AXA Insurance Singapore Pte Ltd (AXA)
(Motor Claims Dept)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6336Z
Vehicle Details	
Vehicle No.:	FU3378J
Vehicle to be Exported:	No
Intended De-registration Date:	29 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	PHANTOM200
Primary Colour:	Blue
Manufacturing Year:	2001
Engine No.:	TA200E0005827
Chassis No.:	TA2000005827
Maximum Power Output:	-
Open Market Value:	\$3,500.00
Original Registration Date:	02 Jan 2002
First Registration Date:	02 Jan 2002
Transfer Count:	6
Actual ARF Paid:	\$525.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jan 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,909.00
COE Rebate Amount:	\$682.00
Total Rebate Amount:	\$682.00
Message	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit http://www.nea.gov.sg/mtc incentive or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 29 Jun 2018

OK

AxIA Insurance Singapore
PTI Ltd
Attn: Motor Claims Dept

Dear Sir/ Madam

ACCIDENT INVOLVING VEHICLE NO
F8D 4524J and SKA 5643B
ALONG Buangkok Green/110 Chu Kang Road
ON 27.12.11

We understand that you are the insurer of SFA 5643B vehicle.

I/We wish to inform you that my/our vehicle F8D 4524J have been completed repairs to my/our satisfaction by M/s EM-1 Auto Trade. I/We therefore propose to claim from you as follows:

1.	Cost of Repairs	S\$ 3650.00
2.	Loss of Use/Rental (S\$ 30 x 4 days)	S\$ 120.00
3.	LTA Search Fee/GIA Reports	S\$ -
TOTAL		S\$ 3770.00

Please let us have your reply soonest possible.

Thank you.

Yours faithfully



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/06/2018 15:59
Date Of Accident	22/06/2018 17:05
Exact Location Of Accident	TOH GUAN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FU3378J
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD SHAFIQ BIN ZAIDI
NRIC No	S9516336Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92335149
Alternative Phone No	OTHERS-92335149

Vehicle Particulars

Manufacturer	HONDA
Model	PHANTOM 200
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MSD/VMT/18-376523-CA
Cover Note Number	

Driver

Name of Driver	MUHAMMAD SHAFIQ BIN ZAIDI
NRIC No	S9516336Z
Date Of Birth	02/05/1995
Occupation	INDOOR
Date Of Driving Pass	06/12/2016
Driving Experience	1 YEAR AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92335149
Fax Number	
Contact Number	OTHERS-92335149
Email Address	NOEMAIL

Address	BLK 177 LOMPANG ROAD #06-10
Postcode	670177
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT PANJANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 42 FAJAR ROAD , POSTCODE: 679005 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8929999 - FAX NO: 67673650
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX5607H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	EE TEE KIAN
NRIC/Passport Number	S7627713C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD SHAFIQ BIN ZAIDI
Approximate Age	
Injuries Sustain	REFER POLICE REPORT
Injured person in which vehicle?	FU3378J
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

TOLL GIAN ROAD

Refer to Police Report no. J 20190622/2139.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



J/20180622/2139

1 of 2

POLICE REPORT (NP299)

Report No. J/20180622/2139

Police Station Of Origin
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Date/Time Report Made 22/06/2018 19:06	Vide Report No.	Station Diary No. 178	
Name Of Informant MUHAMMAD SHAFIQ BIN ZAIDI	Address APT BLK 177 LOMPANG ROAD #06-10 SINGAPORE 670177		
ID Type / ID No. NRIC NO / S9516336Z	Contact No. Home/Office	Mobile 92335149	
Nationality SINGAPORE CITIZEN	Email Address		
Occupation Student	Sex Male	Age 23	Date of Birth 02/05/1995
Institution/School Name Ngee Ann Polytechnic	Race Malay		
Date/Time Of Incident 22/06/2018 17:05 - 22/06/2018 17:10	Language		
	Location Of Incident 282 TOH GUAN ROAD TOH GUAN VIEW SINGAPORE 600282 The cross junction of Toh Guan Rd toward PIE		

Brief details.

On 22/06/2018 at about 1705hrs, i was riding my bike along Toh Guan Rd heading back home which is at Lompang Rd. As I was at Toh Guan Rd cross junction heading towards PIE, a white lorry was driving in front of me and was turning towards PIE. At that moment, the traffic light was showing amber. The lorry then suddenly stopped just after the white line and it caught me off guard. I was not able to stop in time thus my bike handle hit the back of the lorry. I then fell off towards the right side of my bike. The driver of

Signature Of Officer Recording The Report:

J / MUHAMMAD HAIQAL BIN SAAD

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

J / Jurong Police Divisional Investigation Branch /
Insp MILA ALYSSA BINTE MOHD ALI NOORDIN
Contact No.: 68910000

Authentication Stamp

SN 117

Singapore Police Force

Signature Of Informant:

Date/Time:
22/06/2018 19:06

Classification Of Case:



**SINGAPORE
POLICE FORCE**



J/20180622/2139

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20180622/2139

the lorry then get off his vehicle and made a check on me. We then moved to the side of the road and discussed on how to settle the issue. We then came into conclusion to lodge a police report and claim from our insurance.

I wish to state that i did not suffered any major injuries but only suffered some minor bruises on my right thigh and on my chest. I also acknowledged that this report will have no investigations made and it's mainly for insurance claim purposes.

Subjects Involved	
Victim	
Person Name	MUHAMMAD SHAFIQ BIN ZAIDI (Informant)

Signature Of Officer Recording The Report:

J / MUHAMMAD HAIQAL BIN SAAD

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
J / Jurong Police Divisional Investigation Branch /
Insp MILA ALYSSA BINTE MOHD ALI NOORDIN
Contact No.: 68910000

Signature Of Informant:

Date/Time:
22/06/2018 19:06

Classification Of Case:

Authentication Stamp

SN 117



Signature :

Singapore Police Force

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 2 July 2018

To : LKK

By Fax: 6256-4315

Attn: Taufikh
Tel : 97495749

1 Email: Taufikh@LKK Auto-Care

VEHICLE NO : FU 3378J
ACCIDENT DATE: 22 June 2018

Honda Phantom 200

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Headlamp	1	195.00 x un
2 Handle Bar	1	145.00 bt
3 LH Light Switch Assy	1	215.00 one
4 Clutch Lever	1	78.00 out
5 Mirror	1 set	130.00 out
6 LH Front Signal	1	95.00 out
7 LH Engine Cover	1	135.00 dd
8 Fuel Tank	1	485.00 dd
9 Front LH Fork Tube	1	230.00 R
Sub-Total		1,708.00 1283
Less 10%		170.80
Sub-Total		1,537.20 1154.70



VEHICLE NO : FU 3378J

Honda Phantom 200

Nett items

1 Towing fee	40.00 ✓
2 Labour to remove & replace necessary parts, to knock out & repair fuel tank	280.00 200
3 Putty & respray paint, touch up	300.00 200
4 Remove & replace front fork & top up fork oil	120.00 ✓
Sub-Total	740.00 560
Nett Total	2,277.20

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

:LG

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1714.70

4/54/400 #

4 days

[Signature]
1/9/18

[illegible]

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 14 September 2018 4:55 PM
To: 'Sg motor enterprise Giam'
Cc: SUR
Subject: RE: FU 3378J-DOA: 22/6/2018

Dear Rose,

Noted with thanks.

Kindly send Final invoice and all supporting documents to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sg motor enterprise Giam <sg_motor_enterprise@yahoo.com.sg>
Sent: Friday, 14 September 2018 3:48 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re: FU 3378J-DOA: 22/6/2018

Hi Veron,

ok acceptance , pls proceed accordingly.

thank you

rose

On Friday, 14 September 2018, 3:43:31 PM GMT+8, Sg motor enterprise Giam
<sg_motor_enterprise@yahoo.com.sg> wrote:

Hi Veron,

attached after repaired photo of FU 3378J.

On Wednesday, 12 September 2018, 10:08:33 AM GMT+8, Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
wrote:




Dear Rose,

WITHOUT PREJUDICE

GY3858H



Impreg. / Indus
C. Colombo



Offer Lump Sum \$1400/- @ 4 working days.

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd


Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

GY3858H



Empire Industries
A Division of



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jun 2018		29 Jun 2018 10:00 Edit Adj Rpt	S\$1,400.00 Edit Estimates	S\$1,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: EXCEL EVERLITE PTE LTD , Co. Reg. No.: 0									
Main Claimant: MUHAMMAD SHAFIQ BIN ZAIDI , ID: S9516336Z									
Vehicle Reg. No.: FU3378J		Date of Loss: 22/06/2018 17:00 - :59 [197 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 562672		Policy/Cover Note No.: A28861944TMV (Third Party Only) Coverage: 06/01/2018 - 05/01/2019							
Vehicle Reg. No. (Insured): GX5607H		Policy No. (Claimant): Excess:							
Repairer: Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 29/07/2018]									
Driver/Custodian (Insured): EE TEE KIAN () , NRIC: S7627713C, Tel: +6596799686									
Adj. Asg. Remarks: Liability is unclear. TP select LKK as the SJE. W/s contact no person: Rose 6452 4898.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FU3378J (562672)
[GX5607H]
TP
MUHAMMAD SHAFIQ BIN ZAIDI
Jun 22 2018 5:00PM
[EXCEL EVERLITE PTE LTD]
Sg 98 Motor Pte Ltd

Upload Documents

Upload Photos



Compose New Letter

View

View in Browser

































Assessment Reports

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/06/18 11:49	Accident Statement From: SC - Reg. No: GX5607H, Claimant: EXCEL EVERLITE PTE LTD	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/09/18 17:07	Adjuster Immediate Advice	 Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
2	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
3	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
4	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
5	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
6	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
7	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
8	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
9	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
10	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
11	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
12	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
13	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
14	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
15	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
16	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
17	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
18	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
19	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
20	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
21	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
22	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
23	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
24	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
25	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
26	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
27	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
28	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
29	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
30	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
31	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
32	07/08/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
34	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
35	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
36	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
37	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
38	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
39	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
40	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
41	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
42	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
43	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
44	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
45	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
46	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
47	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
48	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
49	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
50	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
51	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
52	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
53	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
54	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
55	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
56	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
57	07/08/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
58	14/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	14/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	14/09/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/06/18 11:49	FU3378J GIA Rpt From: SC - Reg. No: GX5607H, Claimant: EXCEL EVERLITE PTE LTD	Load PDF	
2	28/06/18 11:49	PRI Memo	Load PDF	
3	28/06/18 11:50	Email frm TP - PRI	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18011869/T1VD3E2

Date: 17/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28861944TMV

Claimant Vehicle No : FU3378J

Insured Vehicle No : GX5607H

Date of Loss: 22/06/2018

Nature of Claim: TP

Claim No: 562672

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FU3378J

Make & Model: HONDA PHANTOM 200M, 197cc (M)

Engine No: TA200E0005827

Reg. Date: 02/01/2002 (Man. Year: 2001)

Chassis No: TA2000005827

Colour: Red

Odometer: 2225 km

Engine Capacity: 197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 100/80 R17

Rear Tyre Size: 130/90 R15

Front Left Side: Pirelli 5 mm

Rear Left Side: Pirelli 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,537.20	1,154.70	382.50	24.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	740.00	560.00	180.00	24.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,277.20	1,714.70	562.50	24.70
Approved Total (Overridden) (S\$)		1,400.00		
Nett Amount (S\$)	2,277.20	1,400.00	877.20	38.52

INSPECTION

Date of Assignment: 29/06/2018

Date Inspected: 28/06/2018 Inspected At:

Sg 98 Motor Pte Ltd (HQ)
BLK 4001 ANG MO KIO INDUSTRIAL
PARK 1 #01-21
Singapore 569622

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 17 Sep 2018)
Parts: N/A HONDA PHANTOM 200M 197cc (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for FU3378J)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	Not Necessary	195.00 FL	*- FL
2	1		*HANDLE BAR	Bent	145.00 FL	*145.00 FL
3	1		*LH LIGHT SWITCH ASSY	Cracked	215.00 FL	*215.00 FL
4	1		*CLUTCH LEVER	Cut	78.00 FL	*78.00 FL
5	1		*SET MIRROR	Cut	130.00 FL	*130.00 FL
6	1		*LH FRONT SIGNAL	Cut	95.00 FL	*95.00 FL
7	1		*LH ENGINE COVER	Dented	135.00 FL	*135.00 FL
8	1		*FUEL TANK	Dented	485.00 FL	*485.00 FL
9	1		*FRONT LH FORK TUBE	Repair	230.00 FL	*- FL
Sub Total (S\$)					1,708.00	1,283.00
- List Item Discount on L Items 10.00/10.00% (S\$)					170.80	128.30
Total Parts (S\$)					1,537.20	1,154.70

F=Franchise part, L=ListItemDisc

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	40.00	40.00
2	LABOUR TO REMOVE & REPLACE NECESSARY PARTS, TO KNOCK OUT & REPAIR FUEL TANK	New	280.00	200.00
3	PUTTY & RESPRAY PAINT, TOUCH UP	New	300.00	200.00
4	REMOVE & REPLACE FRONT FORK & TOP UP FORK OIL	New	120.00	120.00
Gross Labour Cost (\$\$)			740.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

