15/5/2010

INS. CASE OWNER: CC3 / A16 180 11885 / K1ea3

LKK:

IDAC:

ASSIGNMENT

Surveyor: AWK

DOI: 28/6/18

Date / Time : 28/6/18

Registered in Merimen: 29/6/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SLW 1978J

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :S$

D.O.A : 23-6-18

Place of Accident :

Is driver the owner? (YES / NO)

Nature of Accident :

If **NO**, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : %

Final ? Yes / No

SHA7522P → ____ → ____ → ____



INSRS:
WSP: Crane Loyang.
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	
	SHA7522P - CC3/FQ1/7008435/K1Ka392 ; DOA 26/6/18
	- CC4/1111/6508186/FPA392 ; DOA 1/5/16
	SLW1978J - X

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	

Documentation Check List:	**Handler**	**Typist**
Notification ltr (if non-pickup)	☐	☐
After call ltr to OI:	☐	☐
Authorisation To Act:	☐	☐
Release Voucher:	☐	☐
Final Repair Bill:	☐	☐
Car Rental Invoice:	☐	☐
Towing Invoice	☐	☐
LTA / GIA :	☐	☐
Medical Bill:	☐	☐
PIR:	☐	☐
Mandate/Reject Instruction:	☐	☐
LOD	☐	☐
Payment Breakdown Form:		☐
Post-Repair Photos:	☐	☐
Others:	☐	☐

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: S$ (days) Reduction: % Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: Confirm with Email ☐ Call ☐

Final Liability:	% (Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost:	S$	
Loss of Rental (LOR):	S$ (days)	
Loss of Use (LOU):	S$ ($ x days)	
Loss of Income (LOI):	S$ ($ x days)	
LOR only ☐ LOU only	☐ LOR + LOU ☐ LOR + LOI ☐ **[Tick only one]**	
GIA/LTA Search	S$	
Medical:	S$	1) Claim status: Normal/Reject/Private Settle
Disbursement:	S$ (e.g. Tow/ Independent)	2) Report Format:
Legal Cost	S$	3) Survey fee:
Total:	S$ **Global Sum S$:**	

FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐

Payee 1:	S$	Name 1:	
Payee 2: (Strike if N.A.)	S$	Name 2:	
Payee 3: (Strike if N.A.)	S$	Name 3:	

(08/11/13)

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insped Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHA 7522P Yr Regn: 23 Apr / 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Hyundai Sonata i40 c.c 1685

Colour Blue A/C: Insured / Std / NI / NA

Sp.Reading 487353 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLB41AAF406810O

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size; F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Hankook

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	23/6/15	D.O.I.	28/6/15

Survey held at CDRE (Loyang)

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	AZA
	EAS

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Report Format : _____

Lump Sum / I.B.I: ($ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Survey Fee:	
Transportation:	
___S + RS, ___SI	
Photos	
Others	
TOTAL	

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755
Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
6 Defu Avenue 1 Singapore 539537
320 Upper Jurong Road Singapore 638369

Date/Time: 28.06.2018 14:46 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305179251

STOMER

/MS COMFORT TRANSPORTATION PTE LTD
STOMER NO. 7010045
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

(R) (O)
(P)

COUNT CARD NO.

REGN NO.: SHA7522P	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 23.06.2018 01:45
YR OF MANU. 23.04.2015	TARGET DATE
CHASSIS CODE KMHLB41UMFU068100	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 23.06.2018
NATURE: 3P 23.06.18 *TRAFFIC POUND*

S/NO	LABOR CODE	DESCRIPTION

ECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

owledgement Slip

e:
o.:
le No.: SHA7522P CHIANG

e of Service Advisor

Signature/Date

e returned to Service Reception upon collection

Exit Pass

Vehicle No.: SHA7522P

Name of Service Advisor

Date

To be kept by Security Guard