

Surveyor

REF:

CC3/MST18011936/NP 92

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured SH 6967L

Policy No. A29069766 NKF

Claims No. 567622


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR. Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Veh No: SMB 1512 T Yr Regn: Oct 2014

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAN cc 10518

Colour Green A/C Insured / Std / NI / NA

Sp. Reading 335115 T. Radio: Insured / Std / NI / NA

Eng/No: 50338332043835

C/No: WMAA222Z3E7002290

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N / S/Rim / STD A/Rim or

Tyre Size F: 275/70 R22.5

R: 275/70 R22.5

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A 27/6/2018 D.O.I. 29/6/2018

Survey held at: SMRT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SMB 1512 T - NS / INC 16096671 / K14302

DA: 060316

SH 6967L - X

On 2/8 @ 7.41pm revised to email GIA to estimate to Christina Wong and Hoon Kianah.
LS \$2450, 3 days CPed @ 2058.10, 46%.

RECEIVED 01 AUG 2018

[Signature]
1/8/18

Date/Time File Pass to?

☐ Preli. Report
☐ Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

3 = RS 3

Phone:

Smart:

TOTAL:

Q:

Add Fee:

☐ Site Insp. \$
☐ Interview \$
☐ Tech. Ins. \$
☐ Weekend \$

Report Format:

MEL-TP

Lump Sum / I.B. / S

2450

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 2 July 2018 2:41 PM
To: Christina Wong; Hasrianah Binte Hassan
Cc: KKLau; SUR; Accounts (LKKAUTO)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICES PTE LTD (TP VEHICLE: SMB 1512T, INSURED VEHICLE: SLH 6967L, DOA: 27-06-2018)
Attachments: CC3MSG18011936Vqb.pdf; SMB1512 EST.pdf; SMB1512 GIA.pdf

Dear Christina and Hasrianah,

Please be informed that we had inspected the vehicle **SMB 1512T** at M/s: **SMRT AUTOMOTIVE SERVICES PTE LTD**, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705.

Enclosed herewith a copy of TP's GIA report and estimate.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: Please advise

Date: 02nd July 2018

Our Ref: CC3/MSG18011936/Vqb

The Motor Claims Department
MSIG Insurance Singapore Pte Ltd

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SMB 1512T

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/06/2018 at the premises of M/s SMRT and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,508.10</u>
Revised Estimate Amount	: S\$ <u>3,095.92</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

We have not authorized repair.

Yours faithfully

Sathya Sai
Automotive Assessor

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SMB1512T
Vehicle Type :	H20 - Public Transport Bus/Coach/Minibus
Vehicle Attachment 1 :	Air-Conditioned
Vehicle Scheme :	OmniBus (SMRT - ARF-exempted)
Vehicle Make :	MAN
Vehicle Model :	NL 320F (A22) 11L AUTO ABS TURBO
Chassis No. :	WMAA22ZZ3E7002290
Propellant :	Diesel
Engine No. :	50338332043835
Engine Capacity :	10518 cc
Maximum Power Output :	-
Maximum Laden Weight :	18000 kg
Unladen Weight :	11260 kg
Year Of Manufacture :	2014
Original Registration Date :	27 Oct 2014
Lifespan Expiry Date :	26 Oct 2031
Road Tax Expiry Date :	26 Oct 2018
Inspection Due Date :	26 Oct 2018
Intended Transfer Date :	02 Jul 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/06/2018 09:15
Date Of Accident	27/06/2018 11:55
Exact Location Of Accident	JUNCT. OF PENDING RD TO PETIR RD (AFT BS44229)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB1512T
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MAN
Model	MAN A22
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090224MFBP
Cover Note Number	

Driver

Name of Driver	EDMUND KONG
Work Permit No	G7071355T
Date Of Birth	10/05/1983
Occupation	OUTDOOR
Date Of Driving Pass	25/04/2016
Driving Experience	2 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name: BALQISH
NRIC/FIN No.: S8340325Z

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1512T
 Ref. No : BUS/06/18/5045
 Reg. Date : 29/06/2018
 Vehicle Type : BUS -12M
 Make : MAN
 Model : MAN
 Name of Driver : Edmund Kong
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 27/06/2018 11:55:00 AM
 Accident Reported Date / Time : 28/06/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : MSIG
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC,if any :
 SMB1512T - REAR PORTION
 SLH6967L (TP) - INSURED WITH MSIG
 Prepared Date : 29/06/2018 09:42:02 AM



Satya Sai
 29/6/2018

3 days

- Part by Part repair
- Photo before paint.


 2/7/18

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Amount
TO REPAIR REAR PORTION	1,590.00	0.
Total Labour	1,590.00	0.

02/7
0

0 * C
1,681.92 +
=
1,681.92 *

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Amount
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	480.00	0.
Total Spray Painting & Panel Beating	480.00	0.

0 * C
1,060. +
354. +
=
1,414. *

Part 3 - Other Costs - Accident and Accident Repair Related Expenses


Job Scope	Quotation from ARC	Amount
Total Other Costs		

0 * C
1,681.92 +
1,414. +
=
3,095.92 *

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1512T
Ref. No : BUS/06/18/5045
Reg. Date : 27/10/2014
Vehicle Type : BUS -12M
Make : MAN
Model : MAN
Name of Driver : Edmund Kong
Type of Accident : HEAD TO REAR
Date / Time of Accident : 27/06/2018 11:55:00 AM
Accident Reported Date / Time : 28/06/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : MSIG
Vehicle is Towed Back? : No
Towed Back Date/Time : 01/01/2000
Replacement Vehicle Issued? : No
Accident Repair Job Card No : 000024096792
Special Instruction to ARC, if any :
SMB1512T - REAR PORTION
SLH6967L (TP) - INSURED WITH MSIG
Prepared Date : 29/06/2018 09:42:02 AM



$$\begin{array}{r}
 1308.16 \\
 - \quad 20\% \\
 \hline
 1046.53 \\
 + 1060 \\
 + 354 \\
 \hline
 2460.53
 \end{array}$$


L/s - \$2450 @ 3 days
confirmed.

Section A - To be Completed by Customer, Accident Repair Centre

Chassis No : Mileage : 0
Work Shop : Repair Completed Date / Time : 01/01/2000

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,590.00	1,060.00
Total Spray Painting Charges	: 480.00	354.00
Total Material Charges	: 1,046.53	1,046.53
Other Charges	: 0.00	0.00
TOTAL	: 3,116.53	2,460.53
Lump Sum Total	: 3,100.00	2,450.00
No. of Repair Days	: 3.00	3.00
Prepared / Adjusted By	: Sim Kim Bock	sathya sai
Arc / Surveyor Sing Off Date	: 29/06/2018 12:02:00 PM	29/06/2018 05:54:12 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 29/06/2018 12:01:47 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,590.00	1,060.00
Total Labour	1,590.00	1,060.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	480.00	354.00
Total Spray Painting & Panel Beating	480.00	354.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
F01001-CW274		6010084	REAR BUMPER CENTER	1	1,868.80	30.00	1,308.16	Replace	Replace	No
S01001-CW002		6010464	ATTACHMENT BRACKET	1	569.30	100.00	0.00	Replace	Repair	No
TOTAL MATERIALS							1,308.16	1,308.16		
TOTAL MATERIALS(Discounted)							1,046.53	1,046.53		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jun 2018		01 Aug 2018 08:36 Edit Adj Rpt	S\$2,450.00 Edit Estimates	S\$2,450.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	SMRT BUSES LTD, Co. Reg. No.: 198202292D								
Vehicle Reg. No.:	SMB1512T	Date of Loss:	27/06/2018 12:00 - :59 [44 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 563622	Policy/Cover Note No.:	A29069766MKF (Comprehensive) Coverage: 01/02/2018 - 31/01/2019						
Vehicle Reg. No. (Insured):	SLH6967L	Policy No. (Claimant):							
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sathya Sai Kathirrasen] ... [Imm.Advice due 02/08/2018]								
Driver/Custodian (Insured):	KANG KIAN SIN (), NRIC: S7143048J, Tel: +6591835796								
Adj Asg. Remarks:	Direct Survey done on 02/07/2018.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMB1512T (563622)**
[SLH6967L]
TP
SMRT BUSES LTD
Jun 27 2018 12:00PM
[GRAB RENTALS PTE LTD]
SMRT Automotive Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail		Print
1	01/08/18 08:36	Accident Statement <small>From: SC - Reg. No: SLH6967L, Claimant: GRAB RENTALS PTE LTD</small>		Load HTML	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail		Print
1	01/08/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>
2	01/08/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>
3	01/08/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>
4	01/08/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>
5	01/08/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>
6	01/08/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>
7	01/08/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>
8	01/08/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>
9	01/08/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>
10	01/08/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>
11	01/08/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>
12	01/08/18 09:52	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
13	01/08/18 09:52	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
14	01/08/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>
15	01/08/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>
16	01/08/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>
17	01/08/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>
18	01/08/18 09:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
19	01/08/18 09:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
20	01/08/18 09:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
21	01/08/18 09:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
22	01/08/18 09:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
23	01/08/18 09:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
24	01/08/18 09:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail		Print
1	01/08/18 08:36	SMB1512T GIA Rpt <small>From: SC - Reg. No: SLH6967L, Claimant: GRAB RENTALS PTE LTD</small>		Load PDF	
2	01/08/18 08:38	LKK Preliminary Advice		Load PDF	
3	01/08/18 08:38	Estimate		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18011936/VQBQ2

Date: 03/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29069766MKF

Claimant Vehicle No : SMB1512T

Insured Vehicle No : SLH6967L

Date of Loss: 27/06/2018

Nature of Claim: TP

Claim No: 563622

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMB1512T

Make & Model: MAN NL320F (A22), 10.5 D ABS TURBO (A)

Engine No: 50338332043835

Reg. Date: 27/10/2014 (Man. Year: 2014)

Chassis No: WMAA22ZZ3E7002290

Colour: Green

Odometer: 335115 km

Engine Capacity: 10518 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,438.10	1,308.16	1,129.94	46.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,070.00	1,414.00	656.00	31.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,508.10	2,722.16	1,785.94	39.62
Approved Total (Overridden) (S\$)		2,450.00		
Nett Amount (S\$)	4,508.10	2,450.00	2,058.10	45.65

INSPECTION

Date of Assignment: 01/08/2018

Date Inspected: 29/06/2018 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: Sathya Sai Kathirrasen

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Aug 2018)	
Parts:	N/A	MAN NL320F (A22) 10.5 D ABS TURBO (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMB1512T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER CENTER	Dented	1,868.80 F	*1,868.80 FL
2	1		*ATTACHMENT BRACKET	Repair	569.30 F	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					2,438.10	1,868.80
- List Item Discount on L Items 0.00/30.00% (\$\$)					0.00	560.64
Total Parts (\$\$)					2,438.10	1,308.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR REAR PORTION	New	1,590.00	1,060.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	480.00	354.00
Gross Labour Cost (\$\$)			2,070.00	1,414.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >