

ASS. REC. BY

REF

CS/MSG 180 11940/Ktdzer

Special Instructions

SMV/VOY
Member

From (Person)

Kenneth

Jocelyn Ng

ASSIGNMENT (Office)

of MSG

Date/Time 2/7/18 @ 10:07am

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGC 2800X

Insured:

at Workshop in/

SMRT

Tel: 6858 1234

of

60 woodlands Ind. Park E4

Policy No:

B28868473MCX

Claim No:

562331

Sum Insured

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A. 20/06/2018

CA (REV)

/ REP. / REV 24 HRS

Insp: 176 Sim Ming Drive # 04-16

H.O.D. Endorsement:

Date/Time:

10:56am @ 2/7/18

Person Contacted:

susan

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	Pls obtain last service record and check brake & tyre condition.
	SGC 2800X-X
3/7@	Revert via menimen
	Submit uneconomical total loss

ASS. REC. BY:

REF: *MSC/**Kenneth*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of *04-16*

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: *5000*

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *8/17K 17500K*

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: *Use*

Vehicle: IN/OUT

Veh No: *SGC 2800X* Yr Regn: *01, 06*Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *SA*Make: *Toy Vios* c.c. *1892*Colour: *N. Blue* A/C: Insured / Std / NI / NASp. Reading: *180630* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *NR053147 420. 4167615*Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: *mic*R: *Nexen 175/65R14*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. *9* mm R/Bal. *7* mmL/Bal. *9* mm L/Bal. *7* mmD.O.A. *20/6/18* D.O.I. *2/7/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop orThe UIC / Chassis frame / Body Structure affected due to collision. ☒

Date / Time Action / Instruction

*3/7 File pass to Catherine**2/7 obtain loan source record, books, etc.*

MV: *17,500*
 LTA: *4,310*
 NV: *3,190*

RECEIVED 16 JUL 2018

Date/Time, File Pass to?

☐ : Prel. Report1) *16/7 Typist*☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format: *OD-TL*

Lump Sum / I.B.I: (\$)

*200**10**210*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18011940/Ktd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 02-07-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SGC 2800X
Policy No.	B28868473MCX	Coverage (\$)	0.00
Claim No.	562331	Excess (\$)	500.00
Assign From	MERIMEN (JOCELYN NG)	Assign Date	02/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	20/06/2018	Inspection Date	02/07/2018
Survey held at	176 SIN MING DRIVE#04-16		
Repairer	SMRT AUTOMOTIVE SERVICES PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jun 2018 Sendback Est	29 Jun 2018 15:29 \$10,055.29	02 Jul 2018 10:07 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	TMS ALLIANCES PTE LTD, Co. Reg. No.: 200410149N		
Vehicle Reg. No.:	SGC2800X	Date of Loss:	20/06/2018 18:00 - :59 [149 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 562331	Policy/Cover Note No.:	B28868473MCX (Comprehensive) Coverage: 13/01/2018 - 12/01/2019
		Excess:	S\$500.00
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/07/2018]		
Driver/Custodian:	CHEW SOH SUAN (38 / Female), NRIC: S8015657Z, Tel: +6596306395		
Adj Asg. Remarks:	Car in at 176 Sin Ming #04-16, Sin Ming Autocare S(575721). I Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please obtain last service record and check brake & tyre condition. Please revert with market value, thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 02 Jul 2018

Preliminary Advice

Vehicle No	: SGC2800X	Accident Date	: 20/06/2018
Make	: TOYOTA VIOS	Policy No.	: B28868473MCX
Assignment Date	: 02/07/2018	Excess	: S\$500.00
Date of Inspection	: 02/07/2018	Est. Duration of Repair	: 16.00
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident. The body structure affected due to collision.

Repairer's Estimate (Gross)	:S\$	10,055.29
Revised Amount	:S\$	7,002.00
Check Items (Estimated)	:S\$	2,585.00
Total	:S\$	9,587.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	17,500.00
COE / PARF Rebate	:S\$	14,310.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,190.00

Remarks

- (x) The vehicle is not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.
- (x) According to our surveyor, his static tests on the steering system, braking system reveal no abnormality. The condition of the tyres were also in serviceable condition with a remaining tread depth of approximately Front 9mm & Rear 7mm.

Repairer is asking repair cost at lump sum \$5,500/-

Please note the margin repair is \$3,190/-

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	0149N

Vehicle Details

Vehicle No.:	SGC2800X
Vehicle to be Exported:	No
Intended De-registration Date:	02 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E A
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	1NZX358715
Chassis No.:	MR053HY4204167615
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,903.00
Original Registration Date:	13 Jan 2006
First Registration Date:	13 Jan 2006
Transfer Count:	1
Actual ARF Paid:	\$14,194.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	12 Jan 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$28,317.00
COE Rebate Amount:	\$14,310.00
Total Rebate Amount:	\$14,310.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Jul 2018

OK



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

TMS ALLIANCES PTE LTD
8 CHANGI NORTH STREET 1
ISOTEAM BUILDING, SINGAPORE 498829

Tax Invoice : VM013365

Invoice Date : 03/05/2018
Vehicle Num : SGC2800X
Make/Model : TOYOTA VIOS 1.5E A
Mileage(Km) : 177365
PO/VO/RO# :
Ref./Remark : D.O.3360

Contact : 67470220 96922664 / 97585135 Fax No. : 67470110

S/N	Quantity	Particular	Unit Price	Amount S\$
	1	ENGINE OIL		
	1	OIL FILTER		
1.	1	WATER PUMP	72.00	72.00
2.	1	WATER PUMP PULLEY	36.00	36.00
3.	2	FAN BELT	23.00	46.00
4.	1	REAR BRAKE PAD	68.00	68.00
		SERVICE CHANGE ENGINE OIL AND OIL FILTER		108.00
		LABOUR TO CHANGE REAR BRAKE PAD, FAN BELT AND WATER PUMP		60.00

SingDollars : Four Hundred Seventeen & Cents Thirty Only

Total S\$: 390.00
GST S\$: 27.30
Amount Due S\$: 417.30
=====

Terms : 30 Days


COMPLETE VMS PTE LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 21/06/2018 11:33
Date Of Accident 20/06/2018 18:40
Exact Location Of Accident BKE TOWARDS KJE
Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGC2800X
Insured/Policyholder
Name Of Registered Owner TMS ALLIANCES PTE LTD
Co Reg No NA (20040149N)
Email Address SERENE.CHEW@ISO-TEAM.COM
Mobile Phone No
Alternative Phone No OFFICE-96306395

Vehicle Particulars

Manufacturer TOYOTA
Model VIOS
Exact Purpose for which vehicle was being used at time of accident WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number B 28868473 MCX
Cover Note Number

Driver

Name of Driver CHEW SOH SUAN
NRIC No S8015657Z
Date Of Birth 10/05/1980
Occupation OUTDOOR
Date Of Driving Pass 09/05/2008
Driving Experience 10 YEARS AND 1 MONTH
Gender FEMALE
Mobile Number (LOCAL) +65-96306395
Fax Number
Contact Number
Email Address SERENE.CHEW@ISO-TEAM.COM

Address	BLK 653C JURONG WEST STREET 61 #09-458
Postcode	643653
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	SIDE WALL
Details Of Properties	
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report promptly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the judgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

SKETCH PLAN



A -> 56C2800X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along BKE entering KTE. Suddenly lost vehicle lost control ^{accident} next moment my veh & skidded and hit onto Side wall.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policeholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policeholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:



4647213



NRIC No. S80156572

Date of issue
06-11-2010

Address

APT BLK 653C JURONG WEST STREET 61
#09-45B
SINGAPORE 643653

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

PASS DATE

Class 3A Motor cars without clutch pedals (Auto) =< 3000kg
with =< 7 passengers, exclusive of the driver, and
other motor vehicles without clutch pedals =< 2500kg 09 May 2008

NP 428A

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S80156572

Name

CHEW SOH SUAN
(ZHOU SUXUAN)

周素璇

Race

CHINESE

Date of birth

10-05-1980

Sex

F

Country of birth

SINGAPORE

S80156572

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S80156572

Name

CHEW SOH SUAN
(ZHOU SUXUAN)

Valid Date 10 May 1980

Issue Date 09 May 2008



00160035941



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, #18-01, Singapore 068807
 Tel: +65 6527 7000, Fax: +65 6527 7001
 Co Reg. No. 200412212G, UEN No. 200412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 OR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
 Company: Commercial

MOTORMAX-COMMERCIAL
 Comprehensive

Certificate No. A 28868473 MCX

Excess : SGD500
 Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
 3GC288684

2. Name of Policyholder
 TMS Alliance Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act
 13/01/2018

4. Date of Expiry of Insurance
 12/01/2019

5. Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
 The Policy will not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG
 AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
 Approved Insurers

for Chief Executive Officer

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SGC2800X
Vehicle Type:	N18 - Passenger (Co) Company Car (Single Rate)
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E A
Chassis No.:	MR053HY4204167615
Propellant:	Petrol
Engine No.:	1NZX358715
Engine Capacity:	1497 cc
Maximum Power Output:	80.0 kW (107 bhp)
Maximum Laden Weight:	1480 kg
Unladen Weight:	1020 kg
Year Of Manufacture:	2005
Original Registration Date:	13 Jan 2006
Lifespan Expiry Date:	-
COE Category:	A - Car (1600cc & below)
PQP Paid:	\$28,317.00
COE Expiry Date:	12 Jan 2021
Road Tax Expiry Date:	12 Jan 2019
Inspection Due Date:	12 Jan 2019
Intended Transfer Date:	30 Jun 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Registration: 200410149N

**SMRT AUTOMOTIVE
SERVICES PTE LTD
60 WOODLANDS
INDUSTRIAL PARK E4
757705**

Claim Reference: UBT/JUNE2018/002
Assessment Number: CTI10141
Version: SMRTAUTO/1
Date Calculated: 29/06/2018 06:17

Full Report - V1
Registration: SGC2800X
Printed: 29/06/2018 13:18

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Eng Hock Peh	Date of Incident:	20/06/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	UBT/JUNE2018/002	Estimated Repair Time:	
Policy Number:	B 28868473 MCX	Quote Due Date:	
Order Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Vios
Sub Model:	E
Model Sheet Number:	YF3 02
Registration:	SGC2800X
Registration Month:	January
Registration Year:	2006
VIN Number:	MR053HY4204167615
Manufacture Year:	2005
Odometer:	Not Known
Colour:	
Engine Number:	1NZX358715
Fuel Level:	%

Model Specs

60/40 SPLIT R-SEAT	1.5 LTR 80 KW
5 SPEED GEARBOX	SIDE SKIRT



Rec

*Not withain
1/1 km 87
Repair After Paint
Ex 8500 16 days
Fax: 62564315*

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	28/06/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: UBT/JUNE2018/002

Assessment Number: CTI10141



Version: SMRTAUTO/1

Date Calculated: 29/06/2018 06:17

Full Report - V1

Registration: SGC2800X

Printed: 29/06/2018 13:18



Primary Impact
Secondary Impact

Addresses

Cost Summary

Total Labour	\$2,785.00
Total Paint/Material	\$177.49
Total Parts	\$7,092.80
Excess:	TBA
Grand Total Exc GST:	\$10,055.29
7 % GST:	\$703.87
Grand Total Inc GST:	\$10,759.16

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	ALIGNMENT CPL BEFORE REPAIR	12.0	60.00
M250ZAX	R + R REAR ASSEMBLIES INCLUDES: R + R REAR AXLE, BLEED BRAKE SYSTEM	20.0	100.00
B310)	RENEW L/R SIDE PANEL (COMPOSITE WORK FOR END PANEL)	54.0	270.00
B310)	RENEW R/R SIDE PANEL (COMPOSITE WORK FOR END PANEL)	54.0	270.00
NO NUMBER	RENEW L/R WHEELHOUSE REINFORCEMENT	5.0	25.00
NO NUMBER	RENEW R/R WHEELHOUSE REINFORCEMENT	5.0	25.00
B420)	R + R REAR BUMPER REINFORCEMENT	1.0	5.00
B290	RENEW REAR END PANEL (BUMPER REMOVED) INCLUDES: BOTH REAR LAMPS, FLOOR MAT BOOT COMPARTMENT AND ALL TRIMS IN REPAIR AREA REMOVE AND REFIT	35.0	175.00
B310)	RENEW BOTH TAILAMP BRACKET	3.0	15.00
B350	R + R TOP-CASE LID	5.0	25.00
B360)	RENEW BOOTLID (REMOVED) INCLUDES: NUMBER PLATE, LOCK CYLINDER AND ALL REQUIRED ATTACHED PARTS REMOVE AND REFIT	3.0	15.00
B370	R + R L/BOOTLID HINGE	2.0	10.00
B370	R + R R/BOOTLID HINGE	2.0	10.00
NO NUMBER	RENEW RR/NO-PLATE	1.0	5.00

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: UBT/JUNE2018/002

Assessment Number: CTI10141

Version: SMRTAUTO/1

Date Calculated: 29/06/2018 06:17

Full Report - V1

Registration: SGC2800X

Printed: 29/06/2018 13:18

Preparation Comp. Work Plastic	3.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	126.0	
Total Paintwork Labour	12.6HRS	\$630.00
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$96.48
New Part Painting - Plastic K1R		\$34.20
Surface-/Blend Paint		\$19.71
Material-Const Main Work Metal		\$18.10
Material-Const Comp. Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$177.49
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$177.49

PARTS

				Price Valid: 01/06/2015	
Side No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
2581	1	REAR BUMPER	52159 0D983		0% 156.00* L
2619	1	L/R BUMPER BRACKET	52576 0D070		0% 22.00* -
2620	1	R/R BUMPER BRACKET	52575 0D070		0% 22.00* -
2696	1	PARKING HELP SYSTEM	NO NUMBER		0% 180.00* L
2702	1	REAR NUMBER PLATE	KNPL6		0% 50.00* L
2711	1	REAR PANEL	58307 0D101		0% 45.00* L
2931	1	BOOTLID	64401 0D090		0% 260.00* L
2944	1	BOOTLID SEAL	64461 0D050		0% 45.00* L
2953	1	L/R HINGE	64503 12150		0% 35.00* -
2954	1	R/R HINGE	64503 12150		0% 35.00* -
2977	1	BOOT/TAILOUT LOCK	64610 0D030		0% 55.00* -
3013	1	REAR MANUFACT BADGE	90975 02063		0% 25.00* -
3014	1	VERSION BADGE	75444 0D100		0% 25.00* -
3016	1	BADGE	75432 0D010		0% 20.00* -
3017	1	MODEL STICKER	75442 0D070		0% 20.00* -
3151	1	REAR SCREEN	64801 0D903	Shatter	0% 190.00* L
3169	1	LWR REAR WINDOW MLDG	64813 52080		0% 80.00* -
3171	2	CLIP FASTENING	56116 22050		0% 3.96U -
3172	2	CLIP FASTENING	56115 30100		0% 4.04U -
3191	1	HI-LEVEL BRAKELAMP	81570 0D070B0		0% 70.00* 7
3281	1	L/R LAMP ASSY	81560 0D220		0% 105.00* -
3282	1	R/R LAMP ASSY	81550 0D220		0% 105.00* -
3361	1	L/NUMBER PLATE LAMP	81270 06052		0% 35.00* X
3362	1	R/NUMBER PLATE LAMP	81270 06052		0% 35.00* X
3481	1	L/R SIDE PANEL	61602 0D170		0% 380.00* -
3482	1	R/R SIDE PANEL	61601 0D150		0% 380.00* -
3571	1	L/R LAMP PANEL	61064 0D010		0% 85.00* -
3572	1	R/R LAMP PANEL	61063 0D010		0% 85.00* -
3785	1	L/R VENT INSERT	62940 06030		0% 170.00* -
3901	1	REAR FLOOR PANEL	58311 52210		0% 150.00* -
3989	1	L/R SIDE MEMBER CPL	57602 0D111		0% 480.00* L
4161	1	L/R OUTER WHEELHOUSE	61632 52140		0% 380.00* 7
4162	1	R/R OUTER WHEELHOUSE	61631 52140		0% 380.00* 7
4175	1	L/R W-HOUSE REINF	61642 0D070		0% 35.00* 7
4176	1	R/R W-HOUSE REINF	61641 0D070		0% 35.00* 7
4907	1	BOOTLID TRIM	64719 0D030C0		0% 260.00* X
4978	1	LUGG COMPART CARPET	64711 0D060C0		0% 120.00* 7

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: UBT/JUNE2018/002

Assessment Number: CTI10141

Version: SMRTAUTO/1

Date Calculated: 29/06/2018 06:17

Full Report - V1

Registration: SGC2800X

Printed: 29/06/2018 13:18

G020	R + R REAR SCREEN INCLUDES: REAR PARCEL SHELF AND REQUIRED TRIMS REMOVE AND REFIT	28.0	140.00
B410	R + R REAR BUMPER	4.0	20.00
B420)	RENEW REAR BUMPER	1.0	5.00
M260	R + R FUEL TANK	10.0	50.00
B280	RENEW LEFT/REAR INNER WHEELHOUSE	31.0	155.00
B280	RENEW RIGHT/REAR INNER WHEELHOUSE	31.0	155.00
B330	RENEW BOOT FLOOR PANEL	67.0	335.00
NO NUMBER	RENEW L/RR S-MEMBER CPL	25.0	125.00
B450	R + R REAR SEAT BACKREST (S/CUSHION REM)	2.0	10.00
B450)	R + R RIGHT REAR SEAT REST	1.0	5.00
NO NUMBER	R + R REAR PROTECTION PANEL	1.0	5.00
M240)	R + R FRONT EXHAUST PIPE	2.0	10.00
M240	R + R REAR EXHAUST SECTION	2.0	10.00
40	R + R REAR SILENCER, ASSOCIATED WORK	1.0	5.00
471551)	RENEW L/R BRAKE ANCHOR PLATE (WHEEL REMOVED) INCLUDES: R + R BRAKE DRUM, WHEEL HUB AND BRAKE SHOES	8.0	40.00
471551)	RENEW R/R BRAKE ANCHOR PLATE (WHEEL REMOVED) INCLUDES: R + R BRAKE DRUM, WHEEL HUB AND BRAKE SHOES	8.0	40.00
481251)	R + R LEFT REAR SHOCK ABSORBER	1.0	5.00
481251)	R + R RIGHT REAR SHOCK ABSORBER	1.0	5.00
NN	PARKING HELP SYSTEM R&R / NEW PARTS	5.0*	25.00 ✓
LABOUR COST			
	Total Work Units	431.0	
	Panel / Mechanical Labour	41.9HRS	\$2,095.00
	Visual Alignment Labour	1.2HRS	\$60.00
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	43.1HRS	\$2,155.00
	Paint Labour	12.6HRS	\$630.00
	Total Labour	55.7HRS	\$2,785.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number	Description	WU	Cost Price (\$)
2711	REAR PANEL NEW PART PAINTING	20.0	
2931	BOOTLID NEW PART PAINTING	14.0	
3481	L/R SIDE PANEL NEW PART PAINTING	20.0	
3482	R/R SIDE PANEL NEW PART PAINTING	20.0	
3901	REAR FLOOR PANEL SURFACE PAINT	7.0	
4161	L/R OUTER WHEELHOUSE SURFACE PAINT	4.0	
4162	R/R OUTER WHEELHOUSE SURFACE PAINT	4.0	
4175	L/R W-HOUSE REINF SURFACE PAINT	4.0	
4176	R/R W-HOUSE REINF SURFACE PAINT	4.0	
2581	REAR BUMPER NEW PART PAINT K1R	9.0	
LABOUR COST - PAINT			
	TIME(PAINT)	106.0	
	Preparation Main Work Metal	17.0	

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: UBT/JUNE2018/002

Assessment Number: CTI10141

Version: SMRTAUTO/1

Date Calculated: 29/06/2018 06:17

Full Report - V1

Registration: SGC2800X

Printed: 29/06/2018 13:18

4979	1	SPARE WHEEL COVER	64770 0D120	0%	320.00*	7
4985	1	END PANEL TRIM	58387 0D010	0%	200.00*	7
8833	1	REAR SILENCER	17430 0M061	0%	260.00*	7
8846	1	REAR PROTECT PANEL	58327 0D081	0%	20.00*	7
9081	1	REAR AXLE SUBFRAME	42110 0D171	0%	520.00*	7
9181	1	L/R WHEEL HUB/BRG	42410 0D040	0%	170.00*	7
9182	1	R/R WHEEL HUB/BRG	42410 0D040	0%	170.00*	7
9201	1	L/R SPRING LEG	48530 0D251	0%	95.00*	7
9202	1	R/R SPRING LEG	48530 0D251	0%	95.00*	7
1000	1	RR BOOT LIP LOCK STI	Renew	0%	35.00*	7
f: OEM Parts				Sub Total	\$6,448.00	
g: Original				Mark Up From Cost (10 %)	\$644.80	
h: Secondhand				Total Parts	\$7,092.80	
p: Parallel						
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras \$0.00

Final Calculation

Total Parts	\$7,092.80
Labour	
Total Panel/Mechanical	\$2,095.00
Total Paintwork	\$630.00
Total Visual Alignment work	\$60.00
Total Labour	\$2,785.00
Total Paint/Material Costs	\$177.49
Grand Total Excludes GST	\$10,055.29
GST @ 7 %	\$703.87
Grand Total Includes GST	\$10,759.16

Assessment Notes

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged car(s) during resurvey
- Parts prices are subject to confirmation
- Third party liability is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplemental claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: UBT/JUNE2018/002
Assessment Number: CTI10141
Version: SMRTAUTO/1
Date Calculated: 02/07/2018 08:53

Full Report - V1
Registration: SGC2800X
Printed: 02/07/2018 15:54

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	20/06/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	UBT/JUNE2018/002	Estimated Repair Time:	
Policy Number:	B 28868473 MCX	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	



Vehicle Details

Vehicle	Model Specs
Manufacturer:	60/40 SPLIT R-SEAT
Model:	5 SPEED GEARBOX
Sub Model:	1.5 LTR 80 KW
Model Sheet Number:	SIDE SKIRT
Registration:	
Registration Month:	
Registration Year:	
VIN Number:	
Manufacture Year:	
Odometer:	
Colour:	
Engine Number:	
Fuel Level:	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	28/06/2018
Pre-Accident Damage:	
Tyres Condition:	Tread Depth RHF:
Tread Depth LHF:	Tread Depth RHR:
Tread Depth LHR:	Direction of Impact:
Damage Areas:	



Addresses

Cost Summary

Total Labour	\$2,785.00
Total Paint/Material	\$177.49
Total Parts	\$6,625.30
Excess:	TBA
Grand Total Exc GST:	\$9,587.79
7 % GST:	\$671.15
Grand Total Inc GST:	\$10,258.94

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
 Price/Dent = \$50.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	ALIGNMENT CPL BEFORE REPAIR	12.0	60.00
M250ZAX	R + R REAR ASSEMBLIES INCLUDES: R + R REAR AXLE, BLEED BRAKE SYSTEM	20.0	100.00
B310)	RENEW L/R SIDE PANEL (COMPOSITE WORK FOR END PANEL)	54.0	270.00
B310)	RENEW R/R SIDE PANEL (COMPOSITE WORK FOR END PANEL)	54.0	270.00
NO NUMBER	RENEW L/R WHEELHOUSE REINFORCEMENT	5.0	25.00
NO NUMBER	RENEW R/R WHEELHOUSE REINFORCEMENT	5.0	25.00
B420)	R + R REAR BUMPER REINFORCEMENT	1.0	5.00
B290	RENEW REAR END PANEL (BUMPER REMOVED) INCLUDES: BOTH REAR LAMPS, FLOOR MAT BOOT COMPARTMENT AND ALL TRIMS IN REPAIR AREA REMOVE AND REFIT	35.0	175.00
B310)	RENEW BOTH TAILAMP BRACKET	3.0	15.00
B350	R + R TOP-CASE LID	5.0	25.00
B360)	RENEW BOOTLID (REMOVED) INCLUDES: NUMBER PLATE, LOCK CYLINDER AND ALL REQUIRED ATTACHED PARTS REMOVE AND REFIT	3.0	15.00
B370	R + R L/BOOTLID HINGE	2.0	10.00
B370	R + R R/BOOTLID HINGE	2.0	10.00
NO NUMBER	RENEW RR/NO-PLATE	1.0	5.00
G020	R + R REAR SCREEN INCLUDES: REAR PARCEL SHELF AND REQUIRED	28.0	140.00

	TRIMS REMOVE AND REFIT		
B410	R + R REAR BUMPER	4.0	20.00
B420)	RENEW REAR BUMPER	1.0	5.00
M260	R + R FUEL TANK	10.0	50.00
B280	RENEW LEFT/REAR INNER WHEELHOUSE	31.0	155.00
B280	RENEW RIGHT/REAR INNER WHEELHOUSE	31.0	155.00
B330	RENEW BOOT FLOOR PANEL	67.0	335.00
NO NUMBER	RENEW L/RR S-MEMBER CPL	25.0	125.00
B450	R + R REAR SEAT BACKREST (S/CUSHION REM)	2.0	10.00
B450)	R + R RIGHT REAR SEAT REST	1.0	5.00
NO NUMBER	R + R REAR PROTECTION PANEL	1.0	5.00
M240)	R + R FRONT EXHAUST PIPE	2.0	10.00
M240	R + R REAR EXHAUST SECTION	2.0	10.00
M240	R + R REAR SILENCER, ASSOCIATED WORK	1.0	5.00
471551)	RENEW L/R BRAKE ANCHOR PLATE	8.0	40.00
	(WHEEL REMOVED)		
	INCLUDES: R + R BRAKE DRUM, WHEEL HUB		
	AND BRAKE SHOES		
471551)	RENEW R/R BRAKE ANCHOR PLATE	8.0	40.00
	(WHEEL REMOVED)		
	INCLUDES: R + R BRAKE DRUM, WHEEL HUB		
	AND BRAKE SHOES		
481251)	R + R LEFT REAR SHOCK ABSORBER	1.0	5.00
481251)	R + R RIGHT REAR SHOCK ABSORBER	1.0	5.00
NN	PARKING HELP SYSTEM R&R / NEW PARTS	5.0*	25.00

LABOUR COST

Total Work Units	431.0	
Panel / Mechanical Labour	41.9HRS	\$2,095.00
Visual Alignment Labour	1.2HRS	\$60.00
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	43.1HRS	\$2,155.00
Paint Labour	12.6HRS	\$630.00
Total Labour	55.7HRS	\$2,785.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number	Description	WU	Cost Price (\$)
2711	REAR PANEL NEW PART PAINTING	20.0	
2931	BOOTLID NEW PART PAINTING	14.0	
3481	L/R SIDE PANEL NEW PART PAINTING	20.0	
3482	R/R SIDE PANEL NEW PART PAINTING	20.0	
3901	REAR FLOOR PANEL SURFACE PAINT	7.0	
4161	L/R OUTER WHEELHOUSE SURFACE PAINT	4.0	
4162	R/R OUTER WHEELHOUSE SURFACE PAINT	4.0	
4175	L/R W-HOUSE REINF SURFACE PAINT	4.0	
4176	R/R W-HOUSE REINF SURFACE PAINT	4.0	
2581	REAR BUMPER NEW PART PAINT K1R	9.0	

LABOUR COST - PAINT

TIME(PAINT)	106.0
Preparation Main Work Metal	17.0
Preparation Comp. Work Plastic	3.0

Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	126.0	
Total Paintwork Labour	12.6HRS	\$630.00
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$96.48
New Part Painting - Plastic K1R		\$34.20
Surface-/Blend Paint		\$19.71
Material-Const Main Work Metal		\$18.10
Material-Const Comp. Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$177.49
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$177.49

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
2581	1	REAR BUMPER	52159 0D983		0%	156.00*
2619	1	L/R BUMPER BRACKET	52576 0D070		0%	22.00*
2620	1	R/R BUMPER BRACKET	52575 0D070		0%	22.00*
2696	1	PARKING HELP SYSTEM	NO NUMBER		0%	180.00*
2702	1	REAR NUMBER PLATE	KNPL6		0%	50.00*
2711	1	REAR PANEL	58307 0D101		0%	45.00*
2931	1	BOOTLID	64401 0D090		0%	260.00*
2944	1	BOOTLID SEAL	64461 0D050		0%	45.00*
2953	1	L/R HINGE	64503 12150		0%	35.00*
2954	1	R/R HINGE	64503 12150		0%	35.00*
2977	1	BOOT/TAILOUT LOCK	64610 0D030		0%	55.00*
3013	1	REAR MANUFACT BADGE	90975 02063		0%	25.00*
3014	1	VERSION BADGE	75444 0D100		0%	25.00*
3016	1	BADGE	75432 0D010		0%	20.00*
3017	1	MODEL STICKER	75442 0D070		0%	20.00*
3151	1	REAR SCREEN	64801 0D903		0%	190.00*
3169	1	LWR REAR WINDOW MLDG	64813 52080		0%	80.00*
3171	2	CLIP FASTENING	56116 22050		0%	3.96U
3172	2	CLIP FASTENING	56115 30100		0%	4.04U
3191	1	HI-LEVEL BRAKELAMP	81570 0D070B0		0%	70.00*
3281	1	L/R LAMP ASSY	81560 0D220		0%	105.00*
3282	1	R/R LAMP ASSY	81550 0D220		0%	105.00*
3481	1	L/R SIDE PANEL	61602 0D170		0%	380.00*
3482	1	R/R SIDE PANEL	61601 0D150		0%	380.00*
3571	1	L/R LAMP PANEL	61064 0D010		0%	85.00*
3572	1	R/R LAMP PANEL	61063 0D010		0%	85.00*
3785	1	L/R VENT INSERT	62940 06030		0%	170.00*
3901	1	REAR FLOOR PANEL	58311 52210		0%	150.00*
3989	1	L/R SIDE MEMBER CPL	57602 0D111		0%	480.00*
4161	1	L/R OUTER WHEELHOUSE	61632 52140		0%	380.00*
4162	1	R/R OUTER WHEELHOUSE	61631 52140		0%	380.00*
4175	1	L/R W-HOUSE REINF	61642 0D070		0%	35.00*
4176	1	R/R W-HOUSE REINF	61641 0D070		0%	35.00*
4978	1	LUGG COMPART CARPET	64711 0D060C0		0%	120.00*
4979	1	SPARE WHEEL COVER	64770 0D120		0%	320.00*
4985	1	END PANEL TRIM	58387 0D010		0%	200.00*
8833	1	REAR SILENCER	17430 0M061		0%	260.00*

8846	1	REAR PROTECT PANEL	58327 0D081	0%	20.00*
9081	1	REAR AXLE SUBFRAME	42110 0D171	0%	520.00*
9181	1	L/R WHEEL HUB/BRG	42410 0D040	0%	170.00*
9182	1	R/R WHEEL HUB/BRG	42410 0D040	0%	170.00*
9201	1	L/R SPRING LEG	48530 0D251	0%	95.00*
1000	1	RR BOOT LIP LOCK STI	Renew	0%	35.00*

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Sub Total

Mark Up From Cost (10 %)

Total Parts

\$6,023.00

\$602.30

\$6,625.30

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras

\$0.00

Final Calculation**Total Parts** \$6,625.30**Labour**

Total Panel/Mechanical

\$2,095.00

Total Paintwork

\$630.00

Total Visual Alignment work

\$60.00

Total Labour

\$2,785.00

Total Paint/Material Costs

\$177.49

Grand Total Excludes GST

\$9,587.79

GST @ 7 %

\$671.15

Grand Total Includes GST

\$10,258.94

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

Total Loss

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	21 Jun 2018	29 Jun 2018 15:29 S\$10,055.29	02 Jul 2018 10:07 Edit Adj Rpt	S\$7,002.79 Edit Estimates	S\$7,002.79 View Rpt	Pending for Survey Report

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	TMS ALLIANCES PTE LTD, Co. Reg. No.: 200410149N		
Vehicle Reg. No.:	SGC2800X	Date of Loss:	20/06/2018 18:00 - :59 [149 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 562331	Policy/Cover. Note No.:	B28868473MCX (Comprehensive) Coverage: 13/01/2018 - 12/01/2019
		Excess:	S\$500.00
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 01/08/2018]		
Driver/Custodian:	CHEW SOH SUAN (38 / Female), NRIC: S80156572, Tel: +6596306395		
Adj Asg. Remarks:	Car in at 176 Sin Ming #04-16, Sin Ming Autocare S(575721). I Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please obtain last service record and check brake & tyre condition. Please revert with market value, thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- MSIG_SG (16/07/2018): Alert - Adj Mandate Revoked - SGC2800X - Claim Handler: Jocelyn Ng Shin Bun

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGC2800X (562331)
 OD
 Jun 20 2018 6:00PM
 [TMS ALLIANCES PTE LTD]
 SMRT Automotive Services Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)		Thumbnail	Print
1	29/06/18 15:29	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/07/18 09:32	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/07/18 09:33	General View		Load JPG	☒
2	03/07/18 09:33	General View		Load JPG	☒
3	03/07/18 09:33	General View		Load JPG	☒
4	03/07/18 09:33	General View		Load JPG	☒
5	03/07/18 09:33	General View		Load JPG	☒
6	03/07/18 09:33	General View		Load JPG	☒
7	03/07/18 09:33	General View		Load JPG	☒
8	03/07/18 09:33	General View		Load JPG	☒
9	03/07/18 09:33	General View		Load JPG	☒
10	03/07/18 09:33	General View		Load JPG	☒
11	03/07/18 09:33	General View		Load JPG	☒
12	03/07/18 09:33	General View		Load JPG	☒
13	03/07/18 09:33	General View		Load JPG	☒
14	03/07/18 09:33	General View		Load JPG	☒
15	03/07/18 09:33	General View		Load JPG	☒
16	03/07/18 09:33	General View		Load JPG	☒
17	03/07/18 09:33	General View		Load JPG	☒
18	03/07/18 09:33	General View		Load JPG	☒
19	03/07/18 09:33	General View		Load JPG	☒

Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	12/07/18 18:27	Signed DV		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/07/18 17:33	SERVICING RECORD		Load PDF	
2	03/07/18 09:34	estimate		Load PDF	
3	03/07/18 09:47	audatex		Load PDF	

Linked Accident Report Documents

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	21/06/18 12:00	Accident Statement		Load HTM	

Assessment Reports			1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
Photos/Images			3 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	21/06/18 11:41	Accident Photo	 Load JPG	☒
2	21/06/18 11:41	Accident Photo	 Load JPG	☒
3	21/06/18 11:41	Accident Photo	 Load JPG	☒
4	21/06/18 11:41	Accident Photo	 Load JPG	☒
5	21/06/18 11:41	Accident Photo	 Load JPG	☒
6	21/06/18 11:41	Accident Photo	 Load JPG	☒
7	21/06/18 11:41	Accident Photo	 Load JPG	☒
8	21/06/18 11:41	Accident Photo	 Load JPG	☒
9	21/06/18 11:41	Accident Photo	 Load JPG	☒
10	21/06/18 11:41	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	21/06/18 11:41	Sketch Plan	 Load TIF	
2	21/06/18 11:41	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18011940/KTD3E2

Date: 20/07/2018

REFERENCE

Insured/Claimant:	TMS ALLIANCES PTE LTD	Policy No:	B28868473MCX	Claim No:	562331
Date of Loss:	20/06/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGC2800X	Engine No:	1NZX358715
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY4204167615
Reg. Date:	13/01/2006 (Man. Year: 2005)	Odometer:	180630 km
Colour:	Metallic Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R14	Rear Tyre Size:	175/65 R14
Front Left Side:	Michelin 9 mm	Rear Left Side:	Nexen 7 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,092.80	4,040.30	3,052.50	43.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,332.49	2,332.49	0.00	0.00
Paintwork Labour	630.00	630.00	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,055.29	7,002.79	3,052.50	30.36
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	9,555.29	6,502.79	3,052.50	31.95
+ GST 7.00/7.00% (S\$)	668.87	455.20	213.67	31.94
Nett Amount (S\$)	10,224.16	6,957.99	3,266.17	31.95

INSPECTION

Date of Assignment:	02/07/2018	
Date Inspected:	02/07/2018 Inspected At:	176 SIN MING DRIVE#04-16 Repairer : SMRT Automotive Services Pte Ltd (Woodlands)
Estimated Period of Repair:	0.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$17,500.00
OMV : \$12,903.00
PARF Rebate (1) : \$0.00
Quota Premium Paid : \$28,317.00
COE Rebate (2) : \$14,310.00
Total Rebate (1) + (2) = : \$14,310.00

The total amount incurred will be Market Value \$17,500.00 minus Total Rebate \$14,310.00 = \$3,190.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(EXCLUDE CHECK ITEMS S\$2,585.00 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jul 2018)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGC2800X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS (WCP)		7,092.80 F	*3,673.00 F
Sub Total (S\$)					7,092.80	3,673.00
+ Margin on L,N Items 0.00/10.00% (S\$)					0.00	367.30
Total Parts (S\$)					7,092.80	4,040.30

F=Franchise part

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	PAINTWORK LABOUR	New	630.00	630.00
<u>Labour Items</u>				
2	LABOUR	New	2,332.49	2,332.49
Gross Labour Cost (S\$)			2,962.49	2,962.49

Report was unsubmitted during this print-out.

< END OF ESTIMATES >