

CS/FCI 18011951/7140302

Surveyor

cws

Zubich

ASSIGNMENT (Office)

From (Person)

Lurene jaw

of

FCI

Date/Time

29/6/18 @ 10:23 pm

Estimated Cost

Bill to

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SKR 8066 H

Insured

SHC0727B

at Workshop m/z

Prime Auto

Tel

686 10908

of

No. 5 Benoi place

Policy No.

Claim No.

DIB005069MFSH

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A.

27/06/2018

CA / REV / REP. / REV 24 HRS

(DS)

1/7/2018 @ 1pm

H.O.D. Endorsement

Date/Time

9:40am @ 2/7/18

Person Contacted

pei yee

Vehicle IN / ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SKR 8066H - CC3/TMI150/1291/Hlvbdl DOA: 4/7/2015
	SHC0727B - X
06/7/18 @ 1:14pm	verified to Lurene by email.
26/7/18 @ 4:23pm	Confirmed with Alice final fig \$730, 3 days by email.
	(led \$730, 30%)
	No lump sum

(08/11/13) wef

ASS. REC. BY:

Taufik

REF: FCI

ASSIGNMENT

From: Date: 4/7/2018

Estimated Cost:

On ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKR 8066H

at Workshop m/s

of

Prime Auto
No. 6 Beroi Place

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

lpm

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'Ds'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKR 8066H Yr Regn: 2015, March.

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c.

1797

Colour:

Green

A/C: Insured / Std / NI / NA

Sp. Reading

132/12

T/Radio: Insured / Std / NI / NA

Eng/No:

132112

C/No:

ZVW 4000 144 12.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16.

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Goodride.

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

4/7/18 @ lpm.

Survey held at

Prime Auto

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 23 JUL 2018

Labour Only

20/7/2018

Date/Time, File Pass to?

☐

Preli. Report

17/7/2018 lpm

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

100

50

50

19

219

Report Format:

Lump Sum / I.B.I. (\$

7p

730



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18011951/T1qd3		
36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877		Date : 02-07-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 727B	Veh. Inspected	SKR 8066H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005069MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	02/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/06/2018	Inspection Date		
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005069MFSH

Date: 06 July 2018

Our Ref: CS/FCI18011951/T1qd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKR 8066H .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/07/2018 at the premises of M/s PRIME AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,050.00</u> .
Revised Estimate Amount	: S\$ <u>730.00</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the o/s portion.



Yours faithfully

Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	28-06-2018	Our Ref No. D18005069MFSH
Accident Date	27-06-2018	Claim Type. Third Party
Insured Vehicle	SHC0727B	Third Party Vehicle. SKR8066H
Survey Location	NO. 5 BENOI PLACE	
Contact Person.	PEI YEE	
Contact No.	68610908/ 0	Fax No. 65152948
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	
Contact Number.	NA	Fax No. 68416315

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PRIME AUTO CLAIMS SERVICE PTE. LTD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241877)



PRI Documents



Close X

PRI Header Details

Claim No	D18005069MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & PRIME AU LTD.
Workshop Name	PRIME AUTO CLAIMS SERVICE PTE. LTD. (Contact Person : PEI YEE)	Survey Location & Contact Details	NO. 5 BENOI PLACE Mobile: 0 , Phone: 68610908 , Fax: 65152948 EmailId: PEIYEE@PRIMEAUTOCLAIMS.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0727B	TP Vehicle No	SKR8066H
PRI Recieved Date	29-06-2018 02:55:37 PM	Surveyor Appointed Date	29-06-2018 10:22:09 PM	Surveyor Accept Date	02-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	02-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 20 July 2018 4:23 PM
To: Alice Leong; Taufikh (LKKAuto)
Cc: Admin A; SUR
Subject: RE: FINALIZE TO SKR8066H *** LKK REF: CS/FCI18011951/T1qd3

Dear Alice,

WITHOUT PREJUDICE

Confirm final fig \$730.00 and 3 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)
Sent: Monday, 9 July 2018 9:45 AM
To: Alice Leong <aliceleong@primeautoclaims.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: FINALIZE TO SKR8066H *** LKK REF: CS/FCI18011951/T1qd3

Dear Sir / Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/FCI18011951/T1qd3	Shiau Chan

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alice Leong [<mailto:aliceleong@primeautoclaims.com>]
Sent: Monday, 9 July, 2018 9:41 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 6 July 2018 1:14 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005069MFSH/1
Attachments: CSFCI18011951T1qd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SKR 8066H.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 2 July 2018 9:44 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005069MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 29 June 2018 10:23 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005069MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 04.07.2018

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SKR8066H TOYOTA PRIUS ALPHA 1.8 (2014)

L/charge

1) To tuff kote	\$	50.00	30
2) To knock, welding right rear fender, repair rear bumper. Align & adjust right rear fender & rear bumper.	\$	400.00	300
3) To putty, respray painting right rear fender & rear bumper. To polish	\$	600.00	400
Sub total L/charges		\$ 1,050.00	730
		\$ 1,050.00	#

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495749
WP
4/7/18 1pm
Resurvey after repair
3 days
sur@lkkauto.com



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 04.07.2018

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SKR8066H TOYOTA PRIUS ALPHA 1.8 (2014)

L/charge

- | | | | |
|--|---|--------|-----|
| 1) To tuff kote | S | 50.00 | 30 |
| 2) To knock, welding right rear fender, repair rear bumper. Align & adjust right rear fender & rear bumper. | S | 400.00 | 300 |
| 3) To putty, respray painting right rear fender & rear bumper. To polish | S | 600.00 | 200 |

Sub total L/charges	S	1,050.00	730.00
	S	1,050.00	

Tanfer 97495749
wp

4/7/18 1pm

Reamy after repair

3 days

sur@klbnt.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18011951/T1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 727B	Veh. Inspected	SKR 8066H	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005069MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	29/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	ZVW400014412	Colour	GREY	
Odometer	132112	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	GOODRIDE	6 mm	
L/H Front Tyre	205/60 R16	GOODRIDE	6 mm	
R/H Rear Tyre	205/60 R16	GOODRIDE	6 mm	
L/H Rear Tyre	205/60 R16	GOODRIDE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/06/2018	Inspection Date	04/07/2018	
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 8066H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO TUFF KOTE.		50.00	30.00
	TO KNOC,WELDING RIGHT REAR FENDER,REPAIR REAR BUMPER.ALIGN & ADJUST RIGHT REAR FENDER & REAR BUMPER.		400.00	300.00
	TO PUTTY,RESPRAY PAINTING RIGHT REAR FENDER & REAR BUMPER.TO POLISH.		600.00	400.00
			1,050.00	730.00
	GRAND TOTAL		1,050.00	730.00
RECOMMENDED COST OF REPAIRS				730.00

Report Ref No. CS/FCI18011951/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.