#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	02/07/2018 14:14
Date Of Accident	30/06/2018 17:45
Exact Location Of Accident	CARPARK OF BLK 702 WEST COAST ROAD
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SJR974B
Insured/Policyholder	
Name Of Registered Owner	SEE THO MING FOONG
NRIC No	S1675188Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96890760
Alternative Phone No	OTHERS-96890760
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	SCIROCCO 1.4L AT TSI 1372Q5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093452035
Cover Note Number	
Duliver	

#### Driver

Name of Driver SEE THO MING FOONG

NRIC No S1675188Z

Date Of Birth 25/08/1964

Occupation INDOOR

Date Of Driving Pass 02/03/1988

Driving Experience 30 YEARS AND 3 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-96890760

Fax Number

Contact Number OTHERS-96890760

EMail Address NOEMAIL

BLK 701 WEST COAST ROAD Address

#11-307 120701

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured **OWNER** 

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

**General Information of the Accident** 

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED Type Of Accident

Weather Conditions **CLEAR** Road Surface DRY

Other Information

Postcode

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

NO

YES Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO 0

YES

Number of Passengers (Including Driver)

**Details of Police Action** 

Was the accident reported to the police?

If Yes, Please state which Police Station

Police Station Name CLEMENTI NEIGHBOURHOOD POLICE CENTRE

ROAD: NO. 20 CLEMENTI AVENUE 5, POSTCODE: 129858, COUNTRY: Police Station Address

**SINGAPORE** 

TEL NO: 1800-8729999 - FAX NO: 67748639 Police Station Contact

Was notice of intended Prosecution given?

If Yes, against whom?

NO

#### **Circumstances of Accident**

PLS REFER TO THE POLICE REPORT: T/20180630/2136

Attachment(s)

YES Are accident photos available for attachment? Was there any video captured by Car Camera? YES

Remarks/ Reasons: REFER TO WORKSHOP

Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number SJR5861K

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

**Contact Number** 

Address

Postcode

Insurance Company Name

Page 2 of 29

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.:

### Sketch Plan #2

SKETCH PLAN	2074B					
	SJR9748	Car Park BIL702 West Good Road				
	[A]	West Coact Road				
	B					
	55R5861K					
DESCRIBE CIRCUMSTANC						
	1	Soy.				
	Volice 1.	230				
	× × 180 630 /					
	Der 1 30/80					
15						
81						
/						
DECLARATION I/We declare the foregoing pa	orticulars are true in every respect.					
Policyholder's Signature	Driver's Signature Reporting	ng Centre Personner's Signature				
Date & Time:	(If driver is not the policyholder) Name: Date & Time: NRIC/FII					

#### Sketch Plan #3





----

Police Station Of Origin: Clementi N.P.C

Report No. T/20180630/2136

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8729999 CONTINUATION OF REPORT

Vehicle Owner				100	ZIEW.	
Name	SEE THO MING FOONG			ID No		S1675188Z
Related Vehicle	NIL			Conta	ct No.	96890760
Hospital/Clinic	NIL			Class Drivin Licend Expiry	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL Date Disc			harge	NIL	
No. of Days gran	lo. of Days granted Medical Leave NIL			f Injury	NIL	

#### Brief Details.

On the 29/06/2018, my vehicle bearing registration number, SJR974B, was parked at lot number 81, at carpark of Blk 702 West Coast Road. On 30/06/2018, at about 1745hrs, I went down the to the said parking lot as I was planning to use my vehicle. I saw my vehicle was slightly positioned out of the parking lot, and the whole rear of my vehicle was severely dented, with an opening at my car boot and my rear lights are damaged.

I had an in-built camera in my vehicle and thus I made a check. The camera captured a video of another vehicle which was actually reversing to park in a parking lot that was opposite my vehicle's lot. The vehicle which was reversing is bearing registration plate number, SJR5861K. The video also captured that the driver of vehicle, SJR5861K, actually alighted and turned to look at my vehicle for awhile. After which, he did not provide any notes or particulars to account for this accident. The driver then drove off afterwards. I wish to inform that I am able to provide the video footage of the whole incident. I am lodging this report also for claiming insurance purpose.










































#### **Police Report**





Police Station Of Origin: Clementi N.P.C

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8729999

1 of 3 Report No. T/20180630/2136

# REPORT OF A TRAFFIC ACCIDENT

	Date/Time Report Made: 30/06/2018 19:42		Vide Report No.:	Station Diary No. 199		
Informan	t's Partic	ulars		The second second second		
	Informant: MING FO		Address: APT BLK 701 WEST COAS 120701	T ROAD #11-307 SINGAPORE		
ID Type / ID No.: NRIC NO / S1675188Z			Contact No.: Home/Office: Mobile: 96890760			
Nationality: SINGAPORE CITIZEN		EN	Email:			
Sex: Age: Date of Birth: Female 53 25/08/1964			Type of Informant: Vehicle Owner			
Race: Chinese			Language:	Institution / School Name:		
Occupation: SALES EXECUTIVE		E	Driving Licence Information: Class:	Date of Expiry:		

	nation of the Accider			
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 30/06/2018 17:45	Type of Location Car Park
Location: Along Road 1 WEST COAS  At the carpark Weather:	T ROAD of Blk 702 West coas	t road Road Surface:		
Clear		2.00	10	load Speed Limit:
Clear		Dry		load Speed Limit:
		2.00		load Speed Limit:
Clear Traffic Flow: Type of Collis	on:	Dry	T	ASSESSMENT OF THE STATE OF THE

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SJR5861K	Car					0
SJR974B	Car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

#### **Police Report**





Police Station Of Origin: Clementi N.P.C

2 of 3 Report No. T/20180630/2136

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8729999 CONTINUATION OF REPORT

Vehicle Owner						
Name	SEE THO MING FOONG			ID No	).	S1675188Z
Related Vehicle	NIL			Conta	ct No.	96890760
Hospital/Clinic	NIL			Class Drivin Licend Expire	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL Date Dis			harge	NIL	
No. of Days granted Medical Leave NIL		NIL	Degree of			

### Brief Details.

On the 29/06/2018, my vehicle bearing registration number, SJR974B, was parked at lot number 81, at carpark of Blk 702 West Coast Road. On 30/06/2018, at about 1745hrs, I went down the to the said parking lot as I was planning to use my vehicle. I saw my vehicle was slightly positioned out of the parking lot, and the whole rear of my vehicle was severely dented, with an opening at my car boot and my rear lights are damaged.

I had an in-built camera in my vehicle and thus I made a check. The camera captured a video of another vehicle which was actually reversing to park in a parking lot that was opposite my vehicle's lot. The vehicle which was reversing is bearing registration plate number, SJR5861K. The video also captured that the driver of vehicle, SJR5861K, actually alighted and turned to look at my vehicle for awhile. After which, he did not provide any notes or particulars to account for this accident. The driver then drove off afterwards. I wish to inform that I am able to provide the video footage of the whole incident. I am lodging this report also for claiming insurance purpose.

#### **Police Report**





Police Station Of Origin: Clementi N.P.C 20 Clementi Avenue 5 SINGAPORE 129858 Tel No: 1800-8729999

3 of 3 Report No. T/20180630/2136

CONTINUATION OF REPORT

### Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: D / TAN ZHI YONG, THOMAS	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 30/06/2018 19:42
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt ESTHER CHONG Contact No.: 65476368	Classification Of Case:
Authentication Stamp	