



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

TPVD TOYOTA ESTIMA AERAS (SLA8549J)

Date of Loss

27 June 2018

Time of Loss

16.45

Loss Description

FBL3881S (INSD) C/W SLA8549J

Comment

Workshop Details

Total Rebate Amount

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *



Days of work completion *



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SLA8549J

Registration State

SINGAPORE

Mileage

118025

CATEGORY

Manufacturing Year

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Make

Purchase Date

dd/mm/yyyy



Registration Date *

01/01/1990



Age of Vehicle

28

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

CAMPBELL CATHERINE LEIGH

POST SURVEY INF...

POLICY INFORMAT... TPVD TOYOTA

ASSESSMENT INFO... TOYOTA

CATEGORY Model

POLICY INFORMAT... ESTIMA AERAS

ASSESSMENT INFO... ESTIMA

CATEGORY Type

POLICY INFORMAT...
ASSESSMENT INFO... ▼

CATEGORY Type of Paint

POLICY INFORMAT...
ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT...
ASSESSMENT INFO... ACR500116793

CATEGORY Date of Birth

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy 

CATEGORY Age

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF... ▼

CATEGORY Driving Experience

CATEGORY Engine No

POLICY INFORMAT...

ASSESSMENT INFO...

HIDDEN

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO...

0

CATEGORY Market Value

POLICY INFORMAT...

ASSESSMENT INFO...

0

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY

Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

License Issue Date

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

License Expiration Date

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

Address

FNOL INFORMATI... Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... G5312599P

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

03/07/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

215/55R17

Condition of Vehicle at time of survey

General condition

Fair

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Fair

Tyre Condition

Spare wheel

Rear Tyre Size

215/55R17

Front left side

DUNLOP6mm

Front right side

DUNLOP6mm

Rear left side

FALKEN6mm

Rear right side

FALKEN6mm



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
AXA INSURANCE PTE LTD		Ref: CS3/ASM18011977/Vz4be2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date: 06-07-2018	
ATTN : ERNEST TAY		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	FBL 3881S	Veh. Inspected	SLA 8549J
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00MME	Excess (\$)	0.00
Assign From	ERNEST TAY	Assign Date	02/07/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ESTIMA	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	ACR500116793	Colour	WHITE
Odometer	118025 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	DUNLOP	6 mm
L/H Front Tyre	215/55 R17	DUNLOP	6 mm
R/H Rear Tyre	215/55 R17	FALKEN	6 mm
L/H Rear Tyre	215/55 R17	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information			
Accident Date	27/06/2018	Inspect Date / Time	03/07/2018 (11:27 AM)
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1#01-24 SINGAPORE 408934		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/ASM18011977/Vz4be2

Inspected By



SATHYA SAI KATHIRASEN

Asst. Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.