

Your Ref: AEMD/105/009/2017/133B

Date: 13th July 2018

Our Ref: CS1/SPF18011987/Bqbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SDG 2002Y INSURED VEHICLE: QX 747B ACCIDENT DATE: 21/09/2017**

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SDG 2002Y from M/s CL Appraiser Pte Ltd.
- b) Colour damaged vehicle photographs of SDG 2002Y.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SDG 2002Y
Make & Model	: Audi A7
Year of Registration	: 2016
Chassis Number	: WAUZZZ4G2GN081540
Engine Capacity	: 1984 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.